

ACC

10000 | 120 | 3740

ST

10000/120/3740

STG/61

Miscellaneous

(1232)

Oct. 15, 1945

Subject:-- 1 CTA Coy.--

SAT MMIA LO., N.W. ITALY
c/o Signal Office,
GENOVA

STG/53

15 October 1945

To:--A.D.S.T. MMIA, ROME.--

Reference your ST/1010 dated 29th Sept 45.--

1. A visit was paid on the 10th Oct to 1 Territorial Command Transport Coy Turin and appended belows are comments relating to the report of the DADF.--

2. The POL point is working under 1 MCO and 2 OR's; the records being kept by Colonel Barberino (Cape Ufficio Servizio); this is considered unsatisfactory. Territorial HQ state they have informed the Ministry of War of this.

3. Efficient Vehicle State as at 10th Oct is as follows:

Staff cars: 6
Load carriers: 20
Motorcycles: 4

Inefficient vehicles are still being shown in the strength of the Transport Coy.

4. New type Work Ticket have now been received and are in use.

5. The Efficient Vehicle Park has 3 load carriers in it; instructed them to be issued to the Transport Coy. It appears that the Ufficio Servizio is not clear on how to deal with Efficient and Inefficient Vehicles. Also require to know what to do with Windshield Labels removed from Inefficient Vehicles. The strength of the Park is 1 Officer and 20 OR's and is considered a wastage in view of there being no Efficient Vehicles in it.

1. A visit was paid on the 10th Oct to 1 Territorial Command Transport Coy Turin and appended belows are comments relating to the report of the DADT.-

2. The POL point is working under 1 NCO and 2 OR's; the records being kept by Colonel Barbarino (Capo Ufficio Servizio); this is considered unsatisfactory. Territorial HQ state they have informed the Ministry of War of this.

3. Efficient Vehicle State as at 10th Oct is as follows:

Staff cars:	6
Load carriers:	20
Motorcycles:	4

Inefficient vehicles are still being shown in the strength of the Transport Coy.

4. New type Work Ticket have now been received and are in use.

5. The Efficient Vehicle Park has 3 Load carriers in it; instructed them to be issued to the Transport Coy. It appears that the Ufficio Servizio is not clear on how to deal with Efficient and Inefficient Vehicles. Also require to know what to do with Windshield labels removed from Inefficient Vehicles. The strength of the Park is 1 Officer and 20 OR's and is considered a wastage in view of there being no Efficient Vehicles in it.

If the Repair Unit was in possession of Spare parts and Tyres much work could be carried out. This unit requires the following labels: 13 and 5 extra for testing vehicles.

AC/gc

[Signature] Captain, RASC.,
S&T MIA IO.,
N.W. Italy

1232

0 2 9 5