

ACC

10000 | 120 | 4720

10000 | 120 | 4720

CRD/38

OBSERVATIONS VEHICLE SPARES

June - Sept. 1945

4927
4945

- camere d'aria 28 x 3,201 N. 4.
 - dischi di gomma 10,50x16 N. 4.

Con Indent 3 G.T.C./58 datato 5-7-45 si è prelevato alle ADOS di Roma (Via Etruria) il seguente materiale relativo ai citati B.L.R. 8/8 e 9/B:

- copertoni 10,50 x 16 N. 15 anziché 10
 - camere d'aria 10,50 x 16 N. 7 " 8

Il rimanente materiale, che non è stato restituito con la richiesta sopra citata, è stato richiesto con successivo Indent 3 GTC/102 datato 10 agosto 1945.-

L'indent 3 GTC/109 datato 6 settembre 1945, che si allega, riassume tutte le deficienze di materiale non distribuite dall'ADOS in relazione alla richiesta 3 GTC/58.-

L'UFFICIALE AL MATERIALE

F/to Cap.no Foce Giusto

XX
 COMANDO DIVISIONE "PIC ENO"

C.A.C.F.I.C.

-Ufficio Servizi - Sez.Auto-

N. 08/1401/S/AUT. di prov.

P.M.92,11 18 settembre 1945

AL "F" B.L.T.U. R.T.C. I.C.F. = S E D E

Riferimento al foglio Ref. ORD/38/9 data 18-8-1945.-

Si trasmette la risposta pervenuta dal 3° Reparto Trasporti relativa alla discrepanza esistente fra i quantitativi dei materiali elencati nella richiesta e quelli dei certificati B.L.R.-

Si allega l'Indent 3 GTC/109, che riassume tutte le deficienze di materiale non distribuito dall'ADOS in relazione alla richiesta 3 GTC/58.-

d'ordine:



IL CAPO UFFICIO SERVIZI
 (Ten. Col. S. Campa)

4945

COMANDO DIVISIONE "PICENO"
C.A.C.F.I.C.
-Ufficio Servizi - Sez.AUTO-

38/14

N. 08/300/S/AUT. di prot.

P.M.92, li 28 agosto 1945

OGGETTO: Richiesta sostituzione pneumatici.-

AL 'F' B.L.T.U. R.T.C. I.C.F.

S E D E

Riferimento foglio ORD/38/13 del 23 agosto 1945.-

Si ~~restituisce~~ ^{retorna} la richiesta n. 22/23 in cui sono state apportate le correzioni circa le quantità di materiali richiesti, secondo quanto risulta dall'unità ricevuta.

d'ordine:

CAPO UFFICIO SERVIZI
(Ten. Col. S. Campa)1945
244
300

Subject:- Indents for Tyres.

To: Hq. RTC, ICF.

"F" British Liaison & Training
Unit, RTC, ICF.

Ref: ORD/38/13

August 23rd 1945.

Indents 22/27, 28, and 38, from 152 Infantry School are returned for the following reasons:-

22/27 & 28 Indents made out for 3 covers and 2 inner tubes.
Receipt by RSD for 3 covers and 1 inner tube only is enclosed. Please send receipt for the other inner tube.

22/38 Receipt is required to indicate that BLR inner tube has been returned to RSD.

JM/WES
File.

H.H. COLE
Major

D.A.D.O.S.

4913

COMANDO DIVISIONE " PIERRO"
C.A.C.P.I.C.
-Ufficio Servizi - Sez.Auto-

N. 08/1254/S/AUT. di prot.

P.K. 22,11 20 agosto 1945

OGGETTO: Richiesta sostituzione materiale automobilistico dichiarato
B.L.R.-

AL 'F' B.L.T.U. R.T.C. I.C.F.
e, per conoscenza:

S E D E

AL COMANDO SCUOLA FANTERIA

S E D E

Si trasmette allegata la richiesta per la sostituzione di una camera d'aria dichiarata B.L.R.-

d'ordine:
IL CAPO UFFICIO SERVIZI
(Ten. Col. S. Campa)

4942

COMANDO DIVISIONE " FICENO"
C.A.C.F.I.C.
-Ufficio Servizi - Sez. Auto-

N. 08/ 1265 /S/AUT. di prot.

P.M.92, li 21 agosto, 1945

OGGETTO: Richiesta sostituzione materiale automobilistico dichiarato B.L.R.-

AL 'F' B.L.T.U. R.T.C. I.C.F.


S E D E

Si trasmette l'acclusa richiesta per la sostituzione di materiale automobilistico dichiarato B.L.R.-

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1246 1945

File ADMA



d'ordine:
IL CAPO UFFICIO SERVIZI
(Ten. C. S. Canpa)

4941

Subject:- Non-availability of Stores.

TO: HQ. RTC, ICF.

"F" British Liaison & Training
Unit, RTC, ICF.

For information to:
M.T.O., "F" BL & TU.

Ref: ORD/38/10

August 20th 1945.

Reference Indents Nos. RTC/203/A dated 29/6/45.

1. Information has been received from 557 B.O.D. that the undermentioned stores are not available at present, but will be issued when stocks permit:-

<u>Part No.</u>	<u>Designation.</u>	<u>Quantity.</u>
LV6/MT1 TT/TYPE POM POM B	Gun	150
LV6/MT1 TT/TYPE POM POM A	Gun	50

WES/-
File.

H.H. COLE.
Major.
D.A.D.O.S.

4940

Subject:- Demands.

To: HQ. RTC, ICF.

"F" British Liaison & Training
Unit, RTC, ICF.

Ref: ORD/38/9
August 18th 1945.


Reference Indent No. 3GTC/102 dated 10/8/45, attached.

1. It is noted that the BLR certificates covers the following items:-

Covers Outer	1050 x 16	16
	26 x 3.25	1
Tubes Inner	1050 x 16	7
	26 x 3.25	3
Rubber pads	1050 x 16	4

2. Will you please give the reason for the difference between the quantities on the BLR certificates and on the indents.

JM/WES
File.


H.E. COLE.
Major

D.A.D.O.S.

4939

Subject:- Observations on Indents.

"F" British Liaison & Training

To: HQ. RTC, ICF.

Unit, RTC, ICF.

Ref: ORD/38/9

August 18th 1945.

Reference Indents Nos. 3GT/51, 52, dated 1/7/45 and 3GT/38/a
dated 21/6/45.

1. Information has been received from 557 B.O.D. that the undermentioned stores are not available at present, but will be issued when stocks permit :-

<u>Part No.</u>	<u>Designation.</u>	<u>Quantity.</u>
AC.15242299	Petrol Pump	2
GA.0759	Padlocks I.G. 1.1/2-in	173
FA.17055	Spanners Box 5/8-in x 3/4-in	8

H.H.COLE.

Major D.A.D.O.S.

WES/-

Subject:- Observations on Indents.

To: HQ. RTC, ICF.

"F" British Liaison & Training
Unit, RTC, ICF.

Ref: ORD/38/8

July 30th 1945.

Reference Indents Nos. 22/27 and 22/28 dated 26th July 1945
from 152 Italian Infantry School.

1. In the case of locally condemned stores B.L.R. the receipted documents proving that such stores have been returned to Ordnance must be attached.

MWJ/WES
File.


M.W. JEFFERY.

Major

D.A.D.O.S.

4937
4938

COMANDO DIVISIONE "PICENO"
C.A.C.F.I.C.
-Ufficio Servizi - Sez. Auto-

N. 02/ 1121 /S/AYT. di prot.

P.M. 92,11 27 luglio 1945

OGGETTO: Richiesta sostituzione materiale dichiarato B.L.R.

✓ AL COMANDO "P" B.L.T.U. R.T.C. I.C.F.
e, per conoscenza:

AL COMANDO SCUOLA ARTERIA

Si trasmette, allegata, la richiesta per la sostituzione
di materiale automobilistico dichiarato B.L.R.-

d'ordine:
IL CAPO UFFICIO SERVIZI
(Ten. Col. S. Campa)

4936

COMANDO DIVISIONE "FICENO"
C.A.C.F.I.C.
- Ufficio Servizi - Sez. Auto -

N. 02/1115/S/AUT. di pret.

P.M. 32,11 27 luglio 1945

OGGETTO: Richiesta sostituzione materiale dichiarato B.L.R.-

— AL 'F' B.L.T.U. R.T.C. I.C.F.

= S E D E

e, per conoscenza:

AL COMANDO SCUOLA FANTERIA

= S E D E

Si trasmette, acclusa, la richiesta per la sostituzione
di materiale automobilistico dichiarato B.L.R.-

d'ordine:
IL CAPO UFFICIO SERVIZI
(Teh. Col. S. Campa)

4935

COMANDO DIVISIONE "PICENO"
C.A.C.F.I.O.
-Ufficio Servizi - Sez.Auto-

N. 08/1105/S/AUT. di prot.

P.M. 92, li 27 luglio 1945

OGGETTO: Richiesta materiale automobilistico.-

AL 'F' B.L.T.U. R.T.C. I.C.F.

S E D E

Riferimento foglio n. ORD/38/6/ ^{811/13} in data 25 c.m.-

Si restituiscono, approvate da questo Comando,
le richieste per materiali automobilistici in sostituzione di quel-
li dichiarati B.L.R.-

d'ordine:

IL CAPO UFFICIO SERVIZI
(Ten. Col. S. Campa)



DADOS

2651

~~34~~

Subject:- Indents.

"F" British Liaison & Training

To: Hq. RTC, ICT.

Unit, RTC, ICF.

Ref: ORD/38/6

July 25th 1945.

Reference attached Indent 319/001.

As there is no evidence of this having been
approved by you, indent is returned.

JM/WES

File.


M.W. JEFFERY.

Major

D.A.D.O.S.

4933

Subject:- Observation on Indents.

To: HQ, RTC, ICF.

"F8 British Liaison &

Training Unit, RTC, ICF.

Ref: ORD/38/5

July 17th 1945.

Reference your Indent 12/17 dated 13th July 1945 returned herewith.

1. This demand is not understood.
2. Why does HQ. 2 Italian Inf Reinforcements Regiment require a Petrol Pump with 18 foot delivery hose ?, Who has authorised it ? .

LWJ/WES

File.


M.W. JEFFREY.

Major

D.A.D.O.S.

4938

COMANDO DIVISIONE "PIEMONTE"
C.A.C.M.I.C.
-Ufficio Servizi - Sez. Auto-

38/4

N. 08/ 1041 /S/AUT.di prot. P.M.92,11 13 luglio 1945

OGGETTO: Richiesta materiali.-


• AL 'F' B. L. T. U.

e, per conoscenza:

AL COMANDO 2° REGT. ADD. FANTERIA (336)
(Scuola Specialisti)

Si trasmette allegata la richiesta
per n. 1 pompa per rifornimento carburante.-

2335
DADOS



d'ordine:
IL COLONNELLO CAPO DI S.M.
- L. Malavasi -

Malavasi

4934

Subject: Demands.

To: - I.Q.,
R.T.C. I.C.F.

38/3
'F' British Liaison & Training
Unit, RTC, ICF.

Ref ORD/22/1/3.
July 2nd 1945.

The following observation has been made on Indent Nos
3GTC/38A & 39A dtd 21/6/45 by A.D.O.S. RAAC.

'Batteries as follows have been demanded on the above quoted
indents.

LV7/AN 24/3592 Batteries complete	qty 4
LV7/DG 687766 Battery	" 3
LV7/FD 4071 10657 Battery	" 4

If these are to replace unserviceable BLR certificates in respect of
u/s items should accompany demand.

The above have been deleted accordingly.'

Please instruct unit to re-indent via your office attaching BLR
certificates as required.

JL/vg

File

A.W. JEFFERY

Major

D.A.D.O.S.

4930

COMANDO DIVISIONE " PICENO "

C.A.C.F.I.C.

Uff. Servizi - Sez. Automob.

-----000-----

N° 08/381/S/Aut.

OGGETTO: Richiesta materiali.

P.M. 92 li, 25/6/945

- AL "F" BIDU RTO ICF

S E D E

~~~~~  
Si trasmettono allegate N° 7 richieste per il sottono=  
tato materiale: -

|                                     |        |     |
|-------------------------------------|--------|-----|
| <del>Tyre</del> Repair Outfits..... | No     | 200 |
| Brake Fluid.....                    | Galls. | 20  |
| Head Comp assembly--Ford.....       | "      | 3   |
| Head Comp assembly..Dodge.....      | "      | 3   |
| Gasket bowl.....Dodge.....          | "      | 10  |
| Oil filter assy.....                | "      | 10  |
| Fuel pump repair package.....       | "      | 10  |
| Grease guns.....                    | "      | 3   |
| Tyre Pressure Gange.....            | "      | 60  |

I 60 Tyre Pressure Gange saranno ripartiti fra tutti  
i reparti del C.A.C.F.I.C.

d'ordine

IL COLONNELLO CAPO DI S.M.

- L. Malavasi -

tato materiale: -

|                                |        |     |
|--------------------------------|--------|-----|
| Tyre Repair Outfits.....       | No     | 200 |
| Brake Fluid.....               | Galls. | 20  |
| Head Comp assembly--Ford.....  | "      | 3   |
| Head Comp assembly.....        | "      | 3   |
| Head Comp assembly..Dodge..... | "      | 10  |
| Gasket bowl.....               | "      | 10  |
| Oil filter assy.....           | "      | 10  |
| Fuel pump repair package.....  | "      | 3   |
| Grease guns.....               | "      | 60  |
| Tyre Pressure Gange.....       | "      |     |

I 60 Tyre Pressure Gange saranno ripartiti fra tutti i reparti del C.A.C.F.I.C.

d'ordine  
IL COLONNELLO CAPO DI S.M.  
- L. Malavasi -

*file*  
4220

1805  
DADOS.

Subject:- Indents or Vehicle Spares.

To:- H.Q.,

R.T.C. I.C.F.

38/22/1  
'F' British Liason & Training

Unit, R.T.C. I.C.F.

Ref. ORD/22/1/1

June 30th 1945.

The following indents are not approved and returned to you for the reasons stated.

1. Nos 12/3 & 12/4, 2° Italian Inf Reinf Regt.

Complete head assemblies should not be demanded direct by units, but by the workshops effecting repairs and the make, type and W.D. nos of vehicles under repair should be quoted.

2. No 10/6, H.Q. 1° Italian Reception Regt.

The same remarks are applicable as in para 1 above.

3. No 10/5, H.Q. 1° Italian Reception Regt.

1/7, H.Q. R.T.C. I.C.F.

These indents are quite in order, but I am returning them as I have of my own accord demanded approximately 200 sets of vehicle tool kits which will include these items. the list of items actually demanded is at Appendix 'A', for your information. When the stores arrive they can be distributed as needed.

4. No 15/9, 4 Arty Refs Depot & Arty School.

Solution vulcanizing and Rubber Sheets for tyre repairs can only be demanded by units possessing Vulcanizing Plants. In this centre, this applies only to workshops and the stores would be quite useless to anybody else. Other units are entitled to Tyre Repair Outfits: This item is included in the list at Appendix 'A'.

5. It must be impressed upon Unit Commanders that demands for Vehicle Spares and accessories must conform to the universal rule of reason and common sense.

1. Nos 12/3 & 12/4, 2<sup>o</sup> Italian Inf Reinf Regt.

Complete head assemblies should not be demanded direct by units, but by the workshops effecting repairs and the make, type and W.D. nos of vehicles under repair should be quoted.

2. No 10/6, H.Q. 1<sup>o</sup> Italian Reception Regt.

The same remarks are applicable as in para 1 above.

3. No 10/5, H.Q. 1<sup>o</sup> Italian Reception Regt.

1/7, H.Q. R.T.C. I.C.F.

These indents are quite in order, but I am returning them as I have of my own accord demanded approximately 200 sets of vehicle tool kits which will include these items. the list of items actually demanded is at Appendix 'A', for your information. When the stores arrive they can be distributed as needed.

4. No 15/9, 4 Arty Refs Depot & Arty School.

Solution vulcanizing and Rubber Sheets for tyre repairs can only be demanded by units possessing Vulcanizing Plants. In this centre, this applies only to workshops and the stores would be quite useless to anybody else. Other units are entitled to Tyre Repair Outfits: This item is included in the list at Appendix 'A'.

5. It must be impressed upon Unit Commanders that demands for Vehicle Spares and accessories must conform to the universal rule of reason and common sense.

WJ/vs  
Internal  
File  
Float.

M. W. JEFFERY, Major DADO  
for Col. COAD  
British Liaison &  
Training Unit.

## Appendix 'A' - ORD/22/1/1 of 30th June 1945.

## Vehicle Spares demanded by DADOS on 29th June 1945.

|          |                                               |     |
|----------|-----------------------------------------------|-----|
| PA 1711  | SAE spanners open jaw DE 7/32 X 15/64.....    | 100 |
| 17113    | " " " " 1/4 X 9/32.....                       | 100 |
| 17119    | " " " " 3/8 X 7/16.....                       | 100 |
| 17099    | " " " " 3/4 X 7/8.....                        | 100 |
| 17101    | " " " " 5/16 X 1.....                         | 100 |
| 17052    | " " Box Tubular DE 3/8 X 7/16.....            | 10  |
| 17053    | " " " " 1/2 X 9/16.....                       | 10  |
| 17055    | " " " " 5/8 X 3/4.....                        | 10  |
| 17057    | " " " " 7/8 X 15/16.....                      | 10  |
| LV6/MT6  | Tyre repair outfits car size.....             | 167 |
| 16286    | Tyre Repair outfits Motor cycle size;;;       | 50  |
| 16287    | Tyre Repair outfits Motor cycle size;;;       | 50  |
| LV6/MT14 | Wheel braces Ford (car).....                  | 50  |
| "        | " Dodge.....                                  | 50  |
| "        | " Bedford.....                                | 50  |
| "        | " Chevrolet.....                              | 50  |
|          | Valve Removing Key.....                       | 200 |
| LV6/MT2  | 1736 BSW Spanners Open Jaw DE 1/2 X 9/16..... | 100 |
|          | 284 Tool Bag.....                             | 200 |
| LV6/LT2  | 4185 Tyre Pressure gauge.....                 | 200 |
| 17002    | Adjustable Spanner 6ins.....                  | 200 |
| 16786    | Screw Driver 5ins blade.....                  | 200 |
| 15877    | Pliers 8ins.....                              | 200 |
| 31443    | Jack.....                                     | 200 |
| 45447    | Tyre Levers.....                              | 200 |
| 17225    | DE Spanner BSW Box Tubular 1/8 X 3/16.....    | 100 |
| 17226    | " " " " 1/4 X 5/16.....                       | 100 |
| 17227    | " " " " 3/8 X 7/16.....                       | 100 |
| 17228    | " " " " 1/2 X 9/16.....                       | 100 |
| 17229    | " " " " 5/8 X 3/4.....                        | 100 |
| 17231    | " " " " 7/8 X 1.....                          | 100 |
| 17579    | Spanners Box Tommy no 2.....                  | 100 |
| 1733     | BSW Spanners Open Jaw DE 1/8 X 3/16.....      | 100 |
| 1734     | " " " " 1/4 X 5/16.....                       | 100 |

|          |                                                 |                                           |     |
|----------|-------------------------------------------------|-------------------------------------------|-----|
| 16286    |                                                 | Tyre Repair outfits Motor cycle size; ; ; | 50  |
| LV6/MT14 | Wheel braces Ford (car)                         |                                           | 50  |
| "        | " Dodge                                         |                                           | 50  |
| "        | " Bedford                                       |                                           | 50  |
| "        | " Chevrolet                                     |                                           | 50  |
|          | Valve Removing Key                              |                                           | 200 |
| LV6/MT2  | 1736 BSW Spanners Open Jaw DE I/2 X 9/16        |                                           | 100 |
|          | 284 Tool Bag                                    |                                           | 200 |
| LV6/MT2  | 4185 Tyre Pressure gauge                        |                                           | 200 |
| 17002    | Adjustable Spanner 6ins                         |                                           | 200 |
| 16786    | Screw Driver 5ins blade                         |                                           | 200 |
| 15877    | Pliers 6ins                                     |                                           | 200 |
| 31443    | Jack                                            |                                           | 200 |
| 45447    | Tyre Levers                                     |                                           | 200 |
| 17225    | DE Spanner BSW Box Tubular 1/8 X 3/16           |                                           | 100 |
| 17226    | " " " " 1/4 X 5/16                              |                                           | 100 |
| 17227    | " " " " 3/8 X 7/16                              |                                           | 100 |
| 17228    | " " " " 1/2 X 9/16                              |                                           | 100 |
| 17229    | " " " " 5/8 X 3/4                               |                                           | 100 |
| 17231    | " " " " 7/8 X 1                                 |                                           | 100 |
| 17579    | Spanners <del>Box</del> Tommy no 2              |                                           | 100 |
| 1733     | BSW Spanners Open Jaw DE 1/8 X 3/16             |                                           | 100 |
| 1734     | " " " " 1/4 X 5/16                              |                                           | 100 |
| 1735     | " " " " 3/8 X 7/16                              |                                           | 100 |
| LV6/MT1  | TT Type Pom Pom A Grease Gun                    |                                           | 200 |
| 19627    | Oil can 1/2 pint                                |                                           | 200 |
| 12442    | Air Pump Foot                                   |                                           | 200 |
| 2258     | Insulation Tape                                 |                                           | 200 |
| 2212     | Fire Extinguisher                               |                                           | 200 |
| 46655    | " " Brackets                                    |                                           | 200 |
| LV6/MT6  | 16287 Material Tyre Repair Outfits M/cycle size |                                           | 100 |
| LV6/MT1  | TT/Type/7MC Type 7 MO Gun                       |                                           | 100 |
| LV6/MT2  | 2217 Extractors Rivet Rotter chain Motor cycle  |                                           | 100 |
| 2154     | " Pin Cotter for <del>Spank</del>               |                                           | 100 |
| 5063     | Keys nipple motor cycle 3 way                   |                                           | 100 |
| 351      | Levers Tyre Motor Cycle Flat                    |                                           | 100 |
| 18571    | " " Spoon Type                                  |                                           | 100 |
| 521      | Lifters Valve Spring Motor cycle size           |                                           | 100 |

07041

07041