

ACC

10000 | 120 | 2976 RE/z/11

Jan. - Oct

10000/120/2976 RE/2/11 Italian Eng. School Training Etc... R.T.C - I.C.F.

Jan. - Oct. 1945

5244
5316

C.H.S., C.M.F.

SUBJECT: Termination of Military Responsibility 6320/3/Q(Maint)
for Highway Maintenance.

TEL: PERSPOH 290

19 Oct 45

TO : HQ Allied Commission

1. You are notified that with effect from the 15th Nov, the British Military Authorities can no longer take any responsibility for further supervising or working with the maintenance of roads in Italian Govt territory.

2. In consequence, on the 15th Nov, the following action will be taken by British Military Comds concerned:

- (a) British RE teams at present supervising road maintenance will be withdrawn.
- (b) WD vehicles at present on loan to the Italian Civil Authorities for road maintenance, will remain on loan to the appropriate civil authority, but the RASC maintenance teams will be withdrawn.
- (c) WD engineer plant at present on loan to contractors, etc, engaged on road maintenance, will be withdrawn. In any case where alternative civil plant is not immediately available, the local CBE will be authorised to extend the loan up to 31 Dec 45.
- (d) Bitumen held as Military stocks and allocated for road maintenance up to 31 Dec, will be released to the Genio Civile monthly **5346** tons. After the 31st Dec, no bitumen will be available from Military sources.

3. It is requested that you notify the Italian Govt of the above arrangements. In addition, it is requested that you inform them that the roads listed in AFHQ letter AG 511/531 A(Maint)-O dated 25 July 45 Appendix "A" are of MILITARY importance and must be maintained in an efficient state of repair. These roads include the majority of main trunk roads and are therefore possibly of even

2. In consequence, on the 15th Nov, the following action will be taken by British Military Comds concerned:

- (a) British NE teams at present supervising road maintenance will be withdrawn.
- (b) WD vehicles at present on loan to the Italian Civil authorities for road maintenance, will remain on loan to the appropriate civil authority, but the RASC maintenance teams will be withdrawn.
- (c) WD engineer plant at present on loan to contractors, etc, engaged on road maintenance, will be withdrawn. In any case where alternative civil plant is not immediately available, the local CHE will be authorised to extend the loan up to 31 Dec 45.
- (d) Bitumen held as Military stocks and allocated for road maintenance up to 31 Dec, will be released to the Genio Civile monthly **5316** demand. After the 31st Dec, no bitumen will be available from Military sources.

3. It is requested that you notify the Italian Govt of the above arrangements. In addition, it is requested that you inform them that the roads listed in AFHQ letter AG 611/531 A(Maint)-O dated 25 July 45 Appendix "A" are of MILITARY importance and must be maintained in an efficient state of repair. These roads include the majority of main trunk roads and are therefore possibly of even greater importance to the civil economy.

4. In addition to roads listed in above quoted letter, the HQ of Districts and Areas will, from time to time, indicate to the local Genio Civile, certain other roads which are of local Military importance, requiring a high priority for maintenance. It is requested that the Italian Govt be asked to issue the necessary instructions to ensure that the Genio Civile take appropriate action on receipt of these requests. In addition the instructions to the Genio Civile should cover the question of providing the local Military with advance information of any intention to close any road.

TAJF/HSE

Distribution as over.

M.C.E. SHARP, Brigadier,
for Major General,
MGA

Subject: Artillery School - R.T.C. I.S.P.

LAND FORCES SUB COMMISSION, A.O.
(N.E.I.A.)

ROME.

G/TRE/12/5.

15 NOV 45.

To: MINISTRY OF WAR.

Reference your 3552/3/6 of 10 October.

1. The move of the Signal School to CROCHIGNOLE is agreed to in principle, but you will have heard that certain formalities necessary to the American Authorities with regard to barrack fittings will first have to be completed. It is anticipated that these will take about 15 days to complete.

Pending agreement on these matters between the American and Italian Authorities, sanction cannot be given for the occupation of the barracks in question.


2. Engineer authorities at this H.Q. are of the opinion that PIETRALATA Area does not offer the best available terrain for Engineer training. It is suggested therefore that Genio at your H.Q. should further discuss the location of this school with Staff Officer R.S. at this H.Q.

Internal:

'Q'

SCHE

RPG/rja


Major General
N. M. I. A.

46

HQ MIA
File 24/11/2
25
Oct 65

TO : G(100)
Copy to : G(100)
q

JS

Reference the Minutes of the conference held on 22 Oct (G/100/A of 23 Oct).

1. Ref. para. 1(a).

I visited the Militaria Barracks, near Rome on 23 Oct. They are at present occupied by 56 West Com. The buildings are in good repair and could hold about 4000 men. There is no suitable 'square' or training ground in the immediate vicinity covered area. Accommodation exists for some 20 vehicles and includes a building suitable for a small workshop.

The site is not suitable for the Italian Air School.

2. Ref. para. 1(f).

From a conversation on 24 Oct with Gen. CHITALLERA - Near City Hall Territorial Command, the situation regarding the water supply at 000000 is as follows:-

- (a) 2600 galls per day is pumped from the public water main which takes water from Lake 000000 to 0000.
- (b) A further 4500-6000 galls per day is pumped from various wells in the area. The output of these is likely to increase after some rain.
- (c) Another well with a small output will be in operation in a few days time when the pump is repaired.
- (d) The 000000 Directorate of the 0000 Com. Command state that the water supply as above is fit for drinking. **5310**
- (e) Various schemes for the improvement of the water supply are under consideration.

3. Other accommodation.

I visited the CASALDI barracks, near Rome on 23 Oct. They are at present occupied by 36 West Coy. The buildings are in good repair and could hold about 4000 men; there is no suitable square or training ground in the immediate vicinity; covered garage accommodation exists for some 20 vehicles and includes a building suitable for a small workshop. The site is not suitable for the Italian High School.

2. Ref. para. 4 (c)

From a conversation on 24 Oct with Gen. CASCILLANA - High Offr Main Territorial Command, the situation regarding the water supply at CASANO is as follows:-

- (a) 2500 galls per day is pumped from the main water main which takes water from Lake ~~Vulturno~~ to Rome.
- (b) A further 4500-5000 galls per day is pumped from various wells in the area. The output of these is likely to increase after some rain.
- (c) Another well with a small output will be in operation in a few days time when the pump is repaired.
- (d) The Medical Directorate of the 10th Army Command state that the water supply as above is fit for drinking. **5318**
- (e) Various schemes for the improvement of the water supply are under consideration.

3. Water consumption.

The following information was obtained from ROME Com. Command:-

- (a) At BRIGLIA, Cassino. CASALDI formerly Reserve Officers School. In good condition will hold about 1500.
- (b) At KIMBI, Cassino V. Cassino II formerly an Italian Air Force barracks. In good condition will hold about 1000.
- (c) At FUSCI, (1) Cassino S. Theresa; damaged by air attack. Will hold about 200 men.
(2) Cassino Irigiano and Dep. V. Cassino II; unusable owing to war damage.
(3) Cass. Pirva. Now used as a civil hospital.

Mary Bank
1090
1090

R. C. P. M. J.

S.O.M.S.
H.M.I.S.

M.S.I.A.
RR 11/2
11 Oct 45

Q2 (thru' C(SD))

Copy to C (NY)

Italian Army Accommodation at VITERBO.

1. Exploring the possibility of moving the Italian Engineer Training School from BRACCIANO to VITERBO, on 9 Oct I visited the three barracks at VITERBO.
2. On the outskirts of the town on the BARCHIA road are the old barracks formerly occupied by a Paracoste Unit. These will hold about a 100 men, but need a lot of work done to make them satisfactory: windows non-existent, latrines unhygienic, etc. These buildings are now occupied by a party (about 50 strong) from CASANO who are doing guards and duties for the Military Tribunal which is sitting at VITERBO.
3. The main barracks near the northern gate of the town are badly damaged by bombing and at present hold some 70 men of the Rome Territorial Internal Security Brigade. Reconstruction of these barracks would be a major task and would take many months. A contractor is at present working on the habitable part of the buildings, carrying out repairs to roofs and other minor work.
4. The third barracks is situated 3 miles out of the town near the aerodrome. The buildings consist of single storey barrack blocks and are occupied by some 700 men of the Guard Bns. Many of the buildings are damaged by bombing or shelling: there are few windows or doors.
5. (a) The latter site would be the best of the three for converting into a school but, owing to the amount of repair work to be done apart from any new buildings required, cannot be recommended.
(b) From the training aspect, although field engineering and demolition training could be carried out on the airfield (assuming the airport is not required for other purposes), there is no site suitable for training in bridging or in watermanship.
6. It is considered that VITERBO is not a suitable location for the Engineer School should it be necessary to move it from BRACCIANO, for

Training School from PUSKUNO to VITKUNO, on 9 Oct F visited the three barracks at VITKUNO.

2. On the outskirts of the town on the BAMBAYA road are the old barracks formerly occupied by a Parachute Unit. These will hold about a 100 men, but need a lot of work done to make them satisfactory: windows non-existent, latrines unhygienic, etc. These buildings are now occupied by a party (about 50 strong) from OUSANO who are doing guard and duties for the Military Tribunal which is sitting at VITKUNO.
3. The main barracks near the northern gate of the town are badly damaged by bombing and at present hold some 70 men of the Territorial Internal Security Brigade. Reconstruction of these barracks would be a major task and would take many months. A contractor is at present working on the habitable part of the buildings, carrying out repairs to roofs and other minor work.
4. The third barracks is situated 3 miles out of the town near the aerodrome. The buildings consist of single storey barrack blocks and are occupied by some 700 men of the Guard Reg. Many of the buildings are damaged by bombing or shelling: there are few windows or doors.
5. (a) The latter site would be the best of the three for converting into a school but, owing to the amount of repair work to be done apart from any new buildings required, cannot be recommended.
 (b) Even the training aspect, although field engineering and demolition training could be carried out on the airfield (assuming airport is not required for other purposes), there is no site available for training in bridging or in watermanship.
6. It is considered that VITKUNO is not a suitable location for the Engineer School should it be necessary to move it from BRACUNO, for

- (a) Lack of suitable try areas
- (b) Lack of accommodation.

HLZ
 S.O.P.E.
 M.H.I.S.

11/1
Monthly Progress Report - Engineer Training

1st BRITISH MILITARY ENGINEERING TRAINING UNIT, HQ IOF

Ref: G/A.3/734

31 August, 1945

R.F.

Commander,
1st British Mission and
Training Unit, HQ IOF.
APO (Engineer Section)
Commandant, Engz Eng Est,
MIA (For SIBS)

4. GENERAL PROGRESS

1. Da a great many reports this month has been a repetition of the last with practically no Engineer Training having been carried out, largely resultant upon the re-organization of the whole of the Army Technical Centre. With the exception of a three-week course in Mine Warfare run for six (6) officers, the intake has been negligible. The training of 50 officers and 100 WOCs in Mine Clearance, two 2-week courses sanctioned by the Ministry of War and designed to continue on 20 August were postponed through our inability to procure the required students.

2. However, planning for basic recruit training (12 weeks) and various courses designed to be put into operation on the re-organization of the Scuola Artieri to the new W2, has proceeded speedily and progress for all types of instruction have been produced and are now in process of being discussed with Scuola Artieri. Lists of additional equipment, necessary through this expansion in the scope of training, are being prepared and will be ready for immediate submission if and when the new establishment is approved by Higher Authority.

3. During the month the position concerning the strength of the Scuola Instructional Staff has considerable cause for apprehension, the instructional staff - originally trained by the British Instructors' Team - consisting from a total of twelve to the last known figure of six. The causes for this are various, the chief of which being through (a) the individuals tour of duty with the Italian Army continuing with consequent release from the Army, and (b) the individuals going on leave and failing to report back. In order to correct the position, both request was made to HQ (Eng) IOF for additional instructors, both officers and WOCs, to be furnished as quickly as possible. Apparently the request is from the Scuola Catechisti, and Graggi, if

5313

A. GENERAL PROGRESS

1. In a great many respects this month has been a repetition of the last with practically no Engineer Training having been carried out, largely resultant upon the re-organization of the whole of the Army Training Centre. With the exception of a three-week course at the Staff College for six (6) officers, the intake has been negligible. The training of 50 officers and 100 NCOs in Mine Clearance, the 2-week courses instigated by the Ministry of War and designed to commence in 20 August were postponed through our inability to produce the required students.

2. However, planning for basic recruit training (12 weeks) and various courses designed to be put into operation on the re-organization of the Scuola Artieri to the new WE, has proceeded apace and arrangements for all types of instruction have been produced and are now in process of being discussed with Scuola Artieri. Lists of additional equipment, necessary through this expansion in the scope of training, are being prepared and will be ready for immediate submission if and when the new establishment is approved by Higher Authority.

3. During the month the position concerning the strength of the Scuola Instructional Staff gave considerable cause for apprehension. The instructional staff - originally trained by the British, instructed in terms - dwindling from a total of twelve to the last known figure of nine. The causes for this are various, the chief of which being through (a) the individual tour of duty with the Italian Army terminating with consequent release from the Army, and (b) the individual going on leave and failing to report back. In order to correct this position request was made to HQ (SFG) AFV IOP for additional instructors, both officers and NCOs, to be furnished as quickly as possible. Apparently the sole source is from the Gruppi Carabinieri, and Grigoli, if compelled, can supply either British trained instructors, who would only require refresher courses to bring them up to the necessary standard of highest training in British methods and use of equipment, and/or men of sufficient quality that could be trained by the Scuola Artieri. The urgency of this problem has been impressed upon the right authority and also the need for high quality men who are young and keen and who are in the Army for a career.

5313

B. COURSES

In the main, basic training and courses are enumerated in the July monthly progress report.

In addition, the Italian War Office envisaged Mine Clearance courses commencing in the near future and training a total of 50 officers and 100 NCOs (due to courses 20 Aug 45, but postponed through failure of source of students).

Further/.....

B. BARRACKS (cont'd)

Further, it would appear that courses for instructors in equipment present Scuola Artieri instructors would have to be held very closely, type and scope dependent upon individual requests.

C. INFANTRY

- (1) Practically no intake this month.
- (2) A field engineering Refresher course commenced in July and was completed in the early part of August, 15 students completing the course.
- (3) A three-week Rifle Warfare course was completed, six officers attending.

D. EQUIPMENT

No. 4 and 5 pumpout sets, referred to in last month's report, were repaired and collected this month.

Two small parts have been missing from the Motor Provision plan since this was initially collected from the depot by the Scuola Artieri. Steps have been taken to procure the parts and this is being achieved in the near future.

No other equipment is outstanding.

E. AMMUNITION

- (1) Association

Contractors continue to work steadily on barrack improvements although they are very slow. However, a definitely marked improvement in the operations under which the Scuola Artieri now lives and works has been made.

- (2) Lyrics

No change

- (3) Warfare

At the present there is no warfare for the Italian troops.

completing the course
(5) 2 three-week Mine Warfare course was completed, six of these
attended

D. RESULTS

No. 4 and 5-pything sets, referred to in last months report,
were released and collected this month.

The anti parts have been missing from the Water Purifier Plant
Plant since this was initially collected from the depot by the Seoul
office. Steps have been taken to procure the parts of this plant
at collection in the near future.

No other equipment is outstanding.

E. ANALYSIS

(1) Documentation

Constructors continue to work steadily on barracks improvements,
although they are very slow. However, a definitely tactical improvement
in the construction which the Seoul Artillery now knows and works
has been made.

(2) Medical

No changes

(3) Welfare

At the present there is no salary for the Italian soldiers.
The Seoul Artillery is very conscious of this and is making every effort
to do everything constructive in this direction, but with little success
so far, due mainly to lack of money, and the high expenditure in
the Italian War Office.

Original

Interval

Pile

Flout

See in Report

E.T. LANGRISH, Major EM,
S.A.

1st BRITISH LIAISON AND
TRAINING UNIT, S.S.I. UNIT

5312

44

TRANSLATION

FROM : MINISTRY OF WAR
TO : H M I A

Ref. No. 237254/11
220-18-3

Date: August 10, 1945

SUBJECT: Cesano - Estimate of work during the month of August.

In compliance with your verbal request we enclose memoranda showing the progress of work which will presumably be carried out at Cesano during the current month.

Signed : LOMBARDI

Ch. Lombardi

To see

A WP

G MT

GTT

5311

return to AE

Metel
(F)

RAC
Q. I think C of S would like to see MT

TRANSLATION

Memorandum

Casano-Evaluste of work progress during August.

The awarding of contracts for building projects concerning the 111 and 1V lot of the Chemical City will take place on the 13th inst.

In the event the private competitive bidding takes place and the three lots are awarded, it may be presumed that work will be started around the 20th inst.. Figuring a minimum period of 5 to 6 days for the organization of the workshope and the arrival of workmen and material.

Thus there remain 10 working days during which the following work is expected to be performed:

III. lot - comb - shaped building

1. Beginning of construction work on third row of latrines and washrooms.

2. Laying down of 1500 square meters of flooring:

IV. lot - necessary services

3. Digging of foundations for laundry

4. Digging of foundations for morgue.

5. Start of brick-laying work-rooms for CR's

6. Preparation of material

V. lot - installation of 335th Inf. Regt.

7. Digging of foundations for 3 new battalions

8. Work to complete new physical education school

9. Start of work on regimental infirmary

10. Sundry work.

5310

Translation

From: Mr of War
To: MMIA

Ref. No. 217754/II
220-18-9

Date: August 10, 1945

Subject: Cesars - Estimate of work during
the month of August.

In compliance with your verbal
request we enclose memorandum showing the
program of work which will presumably be carried
out at Cesars during the current month.

Signed: Lambert

Copy 

Wick

5309

Translation
Memorandum

Cessna - Estimate of works progress during August.

The awarding of contracts for building projects concerning the III and IV lot of the Chemical City will take place on the 15th inst.

In the event the private competitive bidding takes place and the three lots are awarded, it may be presumed that work will be started around the 20th inst., figuring a minimum period of 5 to 6 days for the organization of the workshops and the arrival of workmen and materials.

Thus there remain 10 working days during which the following work is expected to be performed:

III lot - comb-shaped building.

1. Beginning of construction work on third row of latrines and washrooms.
2. Laying down of 1500 square meters of flooring.

IV lot - accessory services.

3. Digging of foundations for laundry.
4. Digging of foundations for morgue.
5. Start of brick-laying work, area for OR's.
6. Preparation of materials.

- ① (2)
- 10 lot - installation of 336TH Inf. Regt.
7. Digging of foundations for 3 new Battalion Kitchens.
 8. Work to complete new physical education school.
 9. Start of work on regimental infirmary.
 10. Sunday work.

————— o —————

Work

CI/46



MINISTERO DELLA GUERRA

Gabinetto

Circ. N. 217254 / 11 Allegati 1 1800, 10 AGO 1955
220-18/3
Risposta al disp. del
OGGETTO. Casano - Previsione lavori nel mese di agosto -

85

Ha LONDE FORCES SUB COMMISSION A.C.
(M.M.I.A.)

ROMA

G.

In esito a richiesta verbale si allega l'unito promemoria dal quale risulta il programma dei lavori che saranno presumibilmente eseguiti nel corrente mese a Casano.

d'ordine
IL CAPO DI CABINETTO

P. S. ...

TRANSEATION	
IN	T. 1100
	U. 15/8
OUT	T. 1120
	U. 15/11

P R O G N O S T I C A

Cesano - Previsione avanzamento lavori nel mese di agosto

L'appalto dei lavori murari relativi al III e IV lotto della Città Chimica avrà luogo il giorno 13 corr. mese.

Qualora le gare e licitazione private abbiano regolare svolgimento ed i tre lotti vengano aggiudicati, si può presumere che i lavori saranno iniziati verso il 20 c.m., considerando un periodo minimo di 5 o 6 giorni per l'organizzazione dei cantieri e l'afflusso degli operai e dei materiali.

Risangono quindi 10 giorni lavorativi, durante i quali si prevede:

III° lotto - fabbricato a pettine

- 1 - Inizio lavori costruzione terza colonna di latrine e lavatoi.
- 2 - Costruzione di 1500 mq. di pavimentazione.

IV° lotto - servizi accessori

- 3 - Scavo fondazioni lavanderia
- 4 - Scavo fondazioni camera mortuaria
- 5 - Inizio opere murarie cucina truppa
- 6 - Ammannimento materiali.

IV° lotto - sistemazione 336° reg. Itr.

- 7 - Scavo fondazioni delle 3 nuove cucine per battaglione.
- 8 - Lavoro di completamento delle nuova scuola di educazione fisica.
- 9 - Inizio lavori della infermeria reggimentale.
- 10 - Lavori vari.

5308

File 1000

671

40

MEMORANDUM: Monthly Progress Report - Engineer Training

7th ENGINEER TRAINING AND TRAINING UNIT, HQU ICG

REF: C/A.3/650

29 July 1945

Commander,
7th Engineer Battalion and
Training Unit, HQU, ICG
COMUSMACV (over HQU)

RC

A. GENERAL COMMENTS

1. From the point of view of actual physical engineer training, the month has been a negative one. There has been no lecture and the single party under training has dwindled away to practically nothing. Despite this, however, a considerable amount of planning has been carried out in connection with the future functioning of the school and at the present preparation are being made for the commencement of courses to train (a) students from the Group's *Sanitization* and (b) instructors in *Infantry* planning.

2. The whole way training center is, at the moment, undergoing considerable changes which not unaturally affect the status of engineer training. The *Sanitization* is expected to expand to deal with 650 men, i.e. 500 under recruit training and 150 on courses of instruction; recruits training increased to 12 weeks; and all recruits to have had 6 weeks basic training at an all area center before coming to the engineer school. The advantages of this system are so obvious as need no comment. New establishments are being drawn up for approval by higher authority.

3. The lack of discipline remains a big fault. Recently 16 men who had been only 25% trained were posted away because they were among the more subversive elements in their party. A weaker form of discipline is hard to imagine.

B. COURSES

The following courses are under preparation and students have been requested for:-

- (4) *Sanitization and Fieldwork* to last 12 days for officers and 100h.
- (11) *March* to last 12 days for 100h.
- (111) *Elementary Drill* to last 6 days for 100h and 5307
- (14) *Basic and Organization of Unit* to last 12 days for officers only.

single party under training has facilities easy to maintain by holding. Duplication this, however, a considerable amount of planning has been carried out in connection with the future functioning of the school and of the present preparations are being made for the announcement of courses to train (a) students from the (b) (c) (d) (e) (f) (g) (h) (i) (j) (k) (l) (m) (n) (o) (p) (q) (r) (s) (t) (u) (v) (w) (x) (y) (z) (aa) (ab) (ac) (ad) (ae) (af) (ag) (ah) (ai) (aj) (ak) (al) (am) (an) (ao) (ap) (aq) (ar) (as) (at) (au) (av) (aw) (ax) (ay) (az) (ba) (bb) (bc) (bd) (be) (bf) (bg) (bh) (bi) (bj) (bk) (bl) (bm) (bn) (bo) (bp) (bq) (br) (bs) (bt) (bu) (bv) (bw) (bx) (by) (bz) (ca) (cb) (cc) (cd) (ce) (cf) (cg) (ch) (ci) (cj) (ck) (cl) (cm) (cn) (co) (cp) (cq) (cr) (cs) (ct) (cu) (cv) (cw) (cx) (cy) (cz) (da) (db) (dc) (dd) (de) (df) (dg) (dh) (di) (dj) (dk) (dl) (dm) (dn) (do) (dp) (dq) (dr) (ds) (dt) (du) (dv) (dw) (dx) (dy) (dz) (ea) (eb) (ec) (ed) (ee) (ef) (eg) (eh) (ei) (ej) (ek) (el) (em) (en) (eo) (ep) (eq) (er) (es) (et) (eu) (ev) (ew) (ex) (ey) (ez) (fa) (fb) (fc) (fd) (fe) (ff) (fg) (fh) (fi) (fj) (fk) (fl) (fm) (fn) (fo) (fp) (fq) (fr) (fs) (ft) (fu) (fv) (fw) (fx) (fy) (fz) (ga) (gb) (gc) (gd) (ge) (gf) (gg) (gh) (gi) (gj) (gk) (gl) (gm) (gn) (go) (gp) (gq) (gr) (gs) (gt) (gu) (gv) (gw) (gx) (gy) (gz) (ha) (hb) (hc) (hd) (he) (hf) (hg) (hh) (hi) (hj) (hk) (hl) (hm) (hn) (ho) (hp) (hq) (hr) (hs) (ht) (hu) (hv) (hw) (hx) (hy) (hz) (ia) (ib) (ic) (id) (ie) (if) (ig) (ih) (ii) (ij) (ik) (il) (im) (in) (io) (ip) (iq) (ir) (is) (it) (iu) (iv) (iw) (ix) (iy) (iz) (ja) (jb) (jc) (jd) (je) (jf) (jg) (jh) (ji) (jj) (jk) (jl) (jm) (jn) (jo) (jp) (jq) (jr) (js) (jt) (ju) (jv) (jw) (jx) (jy) (jz) (ka) (kb) (kc) (kd) (ke) (kf) (kg) (kh) (ki) (kj) (kk) (kl) (km) (kn) (ko) (kp) (kq) (kr) (ks) (kt) (ku) (kv) (kw) (kx) (ky) (kz) (la) (lb) (lc) (ld) (le) (lf) (lg) (lh) (li) (lj) (lk) (ll) (lm) (ln) (lo) (lp) (lq) (lr) (ls) (lt) (lu) (lv) (lw) (lx) (ly) (lz) (ma) (mb) (mc) (md) (me) (mf) (mg) (mh) (mi) (mj) (mk) (ml) (mm) (mn) (mo) (mp) (mq) (mr) (ms) (mt) (mu) (mv) (mw) (mx) (my) (mz) (na) (nb) (nc) (nd) (ne) (nf) (ng) (nh) (ni) (nj) (nk) (nl) (nm) (nn) (no) (np) (nq) (nr) (ns) (nt) (nu) (nv) (nw) (nx) (ny) (nz) (oa) (ob) (oc) (od) (oe) (of) (og) (oh) (oi) (oj) (ok) (ol) (om) (on) (oo) (op) (oq) (or) (os) (ot) (ou) (ov) (ow) (ox) (oy) (oz) (pa) (pb) (pc) (pd) (pe) (pf) (pg) (ph) (pi) (pj) (pk) (pl) (pm) (pn) (po) (pp) (pq) (pr) (ps) (pt) (pu) (pv) (pw) (px) (py) (pz) (qa) (qb) (qc) (qd) (qe) (qf) (qg) (qh) (qi) (qj) (qk) (ql) (qm) (qn) (qo) (qp) (qq) (qr) (qs) (qt) (qu) (qv) (qw) (qx) (qy) (qz) (ra) (rb) (rc) (rd) (re) (rf) (rg) (rh) (ri) (rj) (rk) (rl) (rm) (rn) (ro) (rp) (rq) (rr) (rs) (rt) (ru) (rv) (rw) (rx) (ry) (rz) (sa) (sb) (sc) (sd) (se) (sf) (sg) (sh) (si) (sj) (sk) (sl) (sm) (sn) (so) (sp) (sq) (sr) (ss) (st) (su) (sv) (sw) (sx) (sy) (sz) (ta) (tb) (tc) (td) (te) (tf) (tg) (th) (ti) (tj) (tk) (tl) (tm) (tn) (to) (tp) (tq) (tr) (ts) (tt) (tu) (tv) (tw) (tx) (ty) (tz) (ua) (ub) (uc) (ud) (ue) (uf) (ug) (uh) (ui) (uj) (uk) (ul) (um) (un) (uo) (up) (uq) (ur) (us) (ut) (uu) (uv) (uw) (ux) (uy) (uz) (va) (vb) (vc) (vd) (ve) (vf) (vg) (vh) (vi) (vj) (vk) (vl) (vm) (vn) (vo) (vp) (vq) (vr) (vs) (vt) (vu) (vv) (vw) (vx) (vy) (vz) (wa) (wb) (wc) (wd) (we) (wf) (wg) (wh) (wi) (wj) (wk) (wl) (wm) (wn) (wo) (wp) (wq) (wr) (ws) (wt) (wu) (wv) (ww) (wx) (wy) (wz) (xa) (xb) (xc) (xd) (xe) (xf) (xg) (xh) (xi) (xj) (xk) (xl) (xm) (xn) (xo) (xp) (xq) (xr) (xs) (xt) (xu) (xv) (xw) (xx) (xy) (xz) (ya) (yb) (yc) (yd) (ye) (yf) (yg) (yh) (yi) (yj) (yk) (yl) (ym) (yn) (yo) (yp) (yq) (yr) (ys) (yt) (yu) (yv) (yw) (yx) (yy) (yz) (za) (zb) (zc) (zd) (ze) (zf) (zg) (zh) (zi) (zj) (zk) (zl) (zm) (zn) (zo) (zp) (zq) (zr) (zs) (zt) (zu) (zv) (zw) (zx) (zy) (zz)

2. The whole way training course is, at the present, undergoing considerable changes which will naturally affect the future of engineer training. The Faculty HIGGINS is expected to expand to deal with 600 men, i.e. 300 under present training and 300 on courses of instruction; additional training increased to 12 weeks; and all records to have had 6 weeks basis training at an all arms centre before sending to the engineer school. The advantages of this system can be obvious to most no comment. Few establishments are being drawn up for approval by higher authority.

3. The lack of discipline remains a big fault. Recently 16 men who had been only 25% trained were posted away because they were among the more subordinate elements in their party. A weaker form of discipline is hard to imagine.

B. COURSE

The following courses are under preparation and students have been requested for :-

- (1) Resolutions and Fieldwork to last 12 days for officers and NCOs.
- (1A) Issues to last 12 days for NCOs.
- (1A1) Elementary Drill to last 6 days for NCOs and 5207.
- (1A2) Issues and Organisation of Work to last 12 days for officers only.

(Copy of suggested syllabus submitted to AFM and MTD for information).

It is hoped to commence :-

- (a) A water supply course (when equipment outstanding is delivered)
- (b) A component tools and maintenance course.

C. HIGGINS HILL.

There being no infra and the single party under training has declined to 15 men.

D. HIGGINS.

No.4 pumping set and No.5 pumping set are still outstanding.

- 2 -

2. DISCUSSION.

- (A) Accumulation - no change.
- (AA) Expense - Expense in itself is quite good but general economy, due largely to possibility of savings in post.
- (AAA) Reserve - no change.

L. H. ...

301/103

Internal

File
Front

Major MR
JMR
C/O BRITISH LEGATION &
FRANKING UNIT NEW DELHI

5306

COMBINED SYLLABUS FOR OFFICERS IN-TRAINING
AND ORGANIZATION OF WORK COURSE

Day.

Subject.

1 (1) An introduction to recon; the planning of a recon and the kit to be taken.

(2) A short practical recon or recon exercise indoors of an elementary nature to be carried out by the students to bring out the points of the lecture.

(3) Instruction in the preparation of recon reports.

2 (1) Map reading - Theory and practice.

(2) Use of air photos in planning and recon.

(3) Instruction in the preparation of sketch maps.

3 (1) Exercise - The production of a sketch map. This should be carried in the classroom as an enlargement and detail then put in on the ground.

4 (1) Exercise - Reconnaissance. Students to be set a recon to carry out (say for demolition deployment or river crossing) and to produce a complete report together with sketch map.

5 (1) Instruction in the preparation of work tables and boards for stores, tools, transport and labour.

(2) Tables for the construction of a single defensive position (say a platoon position well dug in and wired).

6 (1) Prepare work table and necessary demands for stores, etc, for construction of position recon'd on previous day.

(2) Instruction in the organization of an elementary bridging operation.

7 (1) Recon and production of plan for erection of T1 Bailey bridge at a previously selected site.

5304

(5) Instruction in the preparation of sketch maps.

3 (1) Exercise - The production of a sketch map. This should be started in the classroom as an enlargement and detail then put in on the ground.

4 (1) Exercise - Reconnaissance. Students to be set a route to carry out (say for demolition deployment or river crossing) and to produce a complete report together with sketch map.

5 (1) Instruction in the preparation of work tables and boards for stores, tools, transport and labour.

(2) Exercise for the construction of a simple defensive position (say a platoon position well dug in and wired).

6 (1) Prepare work table and necessary demands for stores, etc, for construction of position recon'd on previous day.

(2) Instruction in the organization of an elementary bridging operation. 5306

7 (1) Recce and production of plan for erection of IV Bailey bridge at a previously selected site. 5373

8 (1) Instruction : Bridge Classification.

(2) Exercise : Bridge Classification.

9 Home Advanced Map reading.

10 Project : Students to produce plan, sketch map, work table, and drawings, incidents for tools, transport etc, for same appreciable engineer task, e.g. removal of dismantled steel girder bridge from roadway.

11 Exercise bridge classification of an area.

12 Return of 10th day's project. Description.

NOTES BY SOME OF THE COURSE

1. In designing this course I have paid attention, not so much to methods used in the field, as to the results we wish to obtain, which are to produce an officer who will think clearly and logically and far enough ahead to plan his work efficiently. Whether or not he will use work tables in the field or notebook, in these days of radio communication, neat and copious report reports, is immaterial. If he has been well taught his mind will follow the same mental processes and he should arrive at the same conclusion as if he had written it all out. Therefore, let us insist in this course on the reasoning out, careful planning and neat execution of all our instruction, and demand a similar standard from the students.
2. The course is one which lends itself to competition, as there are so many report reports, maps and projects which can be awarded marks. I suggest, therefore, that students are marked for their work and we will thus (a) be able to estimate the value of our instruction and (b) give commanding officers some idea of the proficiency of the students they send to us and the value of the course.
3. It will be appreciated that if this course is to be carried out on the lines I suggest, there will have to be a vast amount of preparation done beforehand by the instructional staff, and I feel that this should be commenced now while we have little to do at the School. I shall be very pleased to give any further advice or assistance in the more detailed preparation of the course, should it be required.
4. In accordance with what we are going to teach, a survey should be made of all materials, stores, transport, etc, which will be required and steps taken now to obtain whatever additional items may be considered necessary.

Richl.

24 Jul 45

Major JH

3000

'P' BRITISH HEADQUARTERS AND TRAINING UNIT

RSC ICP

5304
5303

SUBJECT: Courses - Scuola ARTIGIANI

'P' BRITISH LIAISON AND TRAINING UNIT, RND IOP

Ref: C/O.11/617

17 July 1945

GSD.XI (Ttg)

'P' British Liaison and Training Unit, RND, IOP Commandante, Scuola Artieri, G.M.F.I.C. ROMA (Per SOHN)

1/2
29

1. The Scuola ARTIGIANI will be prepared to run the following courses for Officers and for NCOs.

Course.	No of students.	Duration in working days	Remarks.
Recon. Organization of work. Bridge Classification.	10 - 20	12 days	Officers only. To instruct officers in the art of planning ahead and organizing work efficiently and economically.
Mines.	20 - 30	10 days	Officers and NCOs
Resolutions. Fieldworks.	30 - 40	12 days	NCOs
Elementary Bailey.	40 - 50	6 days	NCOs
Pioneer Instructors.	20	24 days	To produce Instructors capable of teaching Infantry Pioneers.

2. The number of these courses that can be run concurrently will depend upon the number of recruit parties under training at any time. With the present establishment of the Scuola Artieri the maximum number of courses and/or parties that can be run simultaneously will be six. However, until the organization is functioning efficiently the school is unable to accept more than 2 courses in addition to any recruit parties there may be.

2303

3. These courses will be of immense value to officers and NCOs in the Gruppi Combattimento, particularly that in Recon, and organization.

at/.....

- 2 -

of work, and the Group should be encouraged to take advantage of them in every way possible.

4. May the necessary machinery be set in motion to obtain students for these courses, please.

SM/MSJ

[Signature]
Major RE
JONES
"F" British Liaison and
Training Unit, MPO IOP

~~INTERNAL~~

File
Float

5302

5302

85

Monthly Progress Report - Regime Training

7th British Indian and
Training Unit, INC ERP
Ref: G/12/503
1 July 1945

BE
3/7

Commander,
7th British Indian and
Training Unit, INC ERP
ASST (Regime Section)
Commander, INC, ERP
MOLLA (Per 5001)

Ref G/12/502 dated 5 April 1945, herewith progress report.

1. GENERAL SITUATION

(a) The high light of regime training at BANGALORE since the formation of the 300th AITRIAL was five weeks ago, covered on Sunday, 26 June - Robert Frost's day of the Gaiety. The turnout of troops was superb, the marching was the best seen to-date, the barracks had been well and truly cleaned out and smartened up, and, best of all, the parade and decorations were well organized. There was quite good demonstration of support training, a PT display and a remarkable march past. Every attempt to keep the standard up will be made.

(b) (i) A considerable part of regime training that was taken up in foot and arm drill practice for weeks long. This was greatly encouraged, as basic training has never been considered sufficiently important by the Italians.

(c) Improvements to the facilities of the regime training ground have been made by the erection of a new canteen and a training office. A canteen, kitchen and a postroom also are in process of construction. Work in the training ground are being made with locally quarried stone.

(d) Criticism of lack of enforcement of discipline by a senior officer still exists as the main training fault.

(e) The reports of JTB, Posters, etc., in Italian is being held up by lack of suitable supplies of printing paper.

2. CONCLUSIONS

No systems for the Camp are being run but these could

530
1 July 45
M.A.P.

1. GENERAL COMMENTS

(a) The high level of equipment training at HAWAIIAN shows the transition of the HAWAIIAN group from five machine shops, mounted on Junky, 24 June - HAWAIIAN built a way of the South. The turnout of troops was smart, the marching was the best seen to date, the barracks had been well and truly cleaned out and unoccupied by, well, most of all, the parents and demonstrators were well organized. There were quite good demonstrations of support training, a PT display and a commendable march past. Every attempt to keep this standard up will be made.

(b) Quite a considerable part of equipment training that was taken up in feet and was still practice for David Day. This was probably unexcused, as basic training has never been considered sufficiently important by the HAWAIIAN.

(c) Improvements to the facilities of the HAWAIIAN Training Ground have been made by the cessation of a few discussions and a training office. A curriculum, MACHINERY and a maintenance shop are in process of construction. Needs in the training ground are being made with locally quarried stone.

(d) Satisfaction of lack of enforcement of discipline by a center over a number still exists on the side training front.

(e) The reports of IFFI, Weston, etc., in HAWAIIAN is being held up by lack of sufficient supplies of printing paper.

530
[Handwritten notes: 12.9.75, speak, etc.]

2. GENERAL

No comment for the Group was being run but these could start, if HAWAIIAN as desired in IFFI/A.10/75 dated 17 April 1965.

3. GENERAL

As already stated, the situation is now such that the HAWAIIAN has been for a month, well. Under training there is only 1 party. All training can now be in process of being passed to the Group.

4. GENERAL

The following list of equipment received in IFFI letters are contained:

- Item No. 90 No. 4 Machine Set.
- Item No. 91 No. 5 Machine Set.

5/.....

- 2 -

2. ~~XXXXXXXXXX~~

- (a) ~~XXXXXXXXXX~~ - ~~XXXXXXXXXX~~. This now in use. ~~XXXXXX~~
have been started.
- (b) ~~XXXXXX~~ - ~~XXXXXX~~.
- (c) ~~XXXXXX~~ - ~~XXXXXX~~ of ~~XXXXXX~~ and ~~XXXXXX~~ in ~~XXXXXX~~.

J. H. ...

Major SS
SMB
107 British Columbia &
Fredericton, N.B. 100 100

~~XXXXXX~~

~~XXXXXX~~
~~XXXXXX~~
~~XXXXXX~~

GORE

1. Please give me your estimates of ~~XXXXXX~~ ~~XXXXXX~~ courses required in ~~XXXXXX~~.
2. Courses should start for them as soon as possible.

J. H. ...

Major MG
USA British Liaison &
Training Unit, APO KSC

202/100

100
100
100

GORE

1. Please give me your estimates of
refresher courses required in GORE.
2. Courses should start for the course
as soon as possible.

Alfred G.

NO. 5300

Monthly Progress Report - Nightwear Training

11/2
34

11/20/50 REP
Ref: HIL/10/333
30 May 1945

11/20/50 REP
(In triplicate)
AREA (Night wear)
Commanding, HIL, CDR
MILA (Per DCSN)

RE.
116

Ref 0/6/322 dated 3 April 1945.

1. GENERAL INFORMATION

- (a) Little or no progress was made during the month due to:
 - (1) Nightwear collection for Victory in Europe and survival of the German forces in Italy (accounting for the first half of the month).
 - (2) Lack of information concerning the policy in regard to the fathers of the Italian army (accounting for the second half of the month).
 - (3) Heavy losses.
 - (4) Demobilization of over 30's, increase in authorized and unauthorized leave.

(b) For more training is now being done by the Italians themselves though the standard of instruction is not as high as it should (and could) be. Practical men receive training (especially in the specialties below) does not appear to be selected to instill confidence in the students who are allowed to ignore safety precautions and run away from a lighted charge. Instructors do not make students work sufficiently hard.

(c) The main training fault is lack of discipline (which accounts for criticism in para (d)). Junior officers and NCOs very rarely enforce discipline. This morning a case was noted when the orderly officer, wearing the obvious blue hat, passed close by a private soldier who was urinating against the wall. Both was aware of the other but the proceedings carried on undisturbed.

- (d) Business School
 - (1) In default of any statement from higher authority, a policy of "working time" or technical training and trying to make an effort to show a soldier and especially an engineer (as opposed

(a) Little or no progress was made during the month due to
(A) Nighttime observations for Victory in Europe and surrender
of the German forces in Italy (accounting for the first
half of the month).

(11) Lack of information concerning the policy in regard to the
future of the Italian army (accounting for the second half
of the month).

(111) Three months
(iv) Demobilization of over 30's, increases in materiel and
unsubscribed loans.

(b) For some training is now being done by the Italians themselves
though the standard of instruction is not as high as it should (and could)
be. Practical new warfare training (especially in the specialist
school) does not appear to be calculated to instill confidence in the student
who are allowed to ignore safety precautions and run away from a lighted
charge. Instructors do not make students work sufficiently hard.

(c) The main training fault is lack of discipline (which accounts for
criticisms in para (b)). Junior officers and NCOs very rarely enforce
discipline. This means a case was noted when the (British) officer,
receiving the obvious blue hand, passed it on to a private soldier who was
urging against the wall. Such was more of the other but the proceedings
carried on unchanged.

(d) MEASURE TAKEN

(1) In default of any statement from higher authority, a policy
of "waiting time" on technical training and trying to make an
officer first a soldier and secondly an engineer (as opposed
to the reverse which had formerly to be the policy due to the
admitted urgent need for trained engineers) has been 15209

(11) Well and physical training are still not receiving a quarter
of the attention they should.

(111) Special lectures and seminars for officers have been introduced.

(e) Lack of efficient Italian drivers, vehicle maintenance and vehicles
repair has seriously handicapped British and Italian Staffs. The situation
was particularly acute this month. The Commandant of the Engineer School
rides round in a compressor when this vehicle is not being used for training.

2. CONCLUSIONS

The situation remains as at the start of last month. No progress
for August was being made elementary progress can be expected now as
stated in my 1071/4. 10/175 dated 27 April 1945

3/.....

3. PERSONNEL

- (a) Weekly Intake. In spite of representations to many quarters only one party (55 men) were taken into training during the month.
- (b) Under training. Three parties of theoretically 55 each. Actually approximately 130.
- (c) Trained. Four parties of "trained" recruits are at BRACKLAWO. Some have been there for nearly two months in spite of efforts to get them posted or put into some useful work. (See last month's report). The actual strength of these parties gradually diminishes the longer they remain at BRACKLAWO.

4. EQUIPMENT

The following items of equipment are still outstanding:-

- Item No. 98 No. 4 Pumping Set.
- Item No. 99 No. 5 Pumping Set.

5. WELFARE

- (a) Accommodation. Improved by construction work. Bunk beds are still lying idle waiting to be furnished. Messes (tables, stoves and messes) would be sufficient) are badly needed as men eat now in their sleeping quarters and leave refuse scattered over the camp.
- (b) Latrines. Latrines enormously improved and now really deep. Lids are always left open.
- (c) Supplies. Still no KAAPI (razor blades, cigarettes, chocolate, and toothpaste badly needed). Postal services not good but the Regiment has done much to improve this. Suggestions for organized sports including facilities for betting in the lake, do not bear much fruit.
- (d) Health. Not so high as formerly.

6. GENERAL (ADMINISTRATIVE)

The translation and rehabilitation of technical engineering publications and drawings have made steady progress.

[Handwritten Signature]
 Major US
 5298

Land Forces Sub Comm AG (MIA)
RE II/2
25 May 45

Il Generale Comandante del Genio
Comando Territoriale di ROMA

On receipt of your promemoria of 21 May, I contacted Lt Matchett and put the case to him.

The lack of bitumen has contributed to the delay in the work. Supplies should be forthcoming during the next few weeks.

Regarding the proposal to alter the contracts for work on the BRACCIANO - CESANO roads, if Ing. Grottarossa would like to put forward his case to Lt Matchett, the latter will certainly give the matter his close consideration.

Lastly, Lt Matchett states that he himself, as soon as he is able, will visit the works in question to obtain first hand information.

~~202~~ 5297

gsh

SORE
Land Forces Sub Comm AG (MIA)

Bozza 33
da 2-33

PROMEMORIA DI SERVIZIO PER IL MAGG. COMPLETION DELLA

A.O.

Per interessamento della Autorità Alleata Iuffic
Ticino Tecnico della Provincia di Roma sia eseguendo
lavori di sistemazione nel tronco stradale che della
Braccianese parte al centro di addestramento di Ce-
sano, per un importo preventivo di L.3.200.000.

I lavori suddetti avrebbero dovuto avere termine

per il 31 maggio P.V.

appaltata di lavori

Al contrario l'impresa Cordetto non ha effet-
tato finora che un Km. di riassetto della strada
in questione (in confronto dei Km. 6,5 di percorso)
ed anche questo in maniera niente affatto risponden-
te ai voluti requisiti tecnici.

L'impresa stessa eccome quale giustificata al-
lo stato solito riferito dei lavori, la mancata es-
ecuzione del bitume che secondo l'impegnativa,
avrebbe dovuto essere fornito dalle autorità allea-

Ufficio Tecnico della Provincia di Roma sta eseguendo lavori di sistemazione nel tronco stradale che della Braccianese porta al centro di addestramento di Cessano, per un importo preventivo di L.3.200.000.

I lavori stessi avrebbero dovuto avere termine per il 31 maggio P.V.

appaltata dai lavori

Al contratto l'Impresa Corbelli & C. ha effettuato finora che un Km. di riassetto della strada in questione (in contrada del Km. 6,5 di periferia) ed anche questo in cantiera niente affatto rispondente ai voluti requisiti tecnici.

L'Impresa stessa eccome quale giustifica allo stato colto ritardo dei lavori, la mandata assegnazione del bilancio che secondo l'impegnativa, avrebbe dovuto essere fornito dalla autorità alle-

5296

te. Sta da fatto che l'Ufficio Tecnico della Provincia (e per lui l'Ing. Proterossa Direttore dei lavori) ha già affidata l'impresa per il riavvio e la cattiva organizzazione del lavoro, rinviandola di eseguire i lavori di Ufficio.

D'altra parte lo scrivente è stato eccl-

tato dal Maggiore Inglese Gelardi ad intervenire
per risolvere la questione tanto più che, dato il
prezzo stato della strada in argomento, risulta
che circa 140 automobili sono andati fuori servizio.

Pertanto lo scrivente sarebbe venuto nell'av-
vio, ed in ciò in perfetto accordo coll'ing. Grom-
baska dell'Ufficio Tecnico Provinciale, di divi-
dere il lavoro in due parti, il primo tratto (dal-
l'abitato della Braccianese verso Cesano) che doves-
se essere affidato all'impresa Cornetto ed il se-
condo tratto (verso Cesano), dove l'Impresa Cornet-
to non ha fatto niente) da affidare ad altra Impre-
sa tecnicamente attrezzata, che sia affidamento di
eseguire i lavori con la desiderata sollecitudine.
In tal modo potrebbe ancora sperarsi che l'Impresa
Cornetto, col lavoro ridotto al primo tronco, e col-
l'esecuzione di una impresa veramente attrezzata, ed
ideata per l'esecuzione del secondo tronco possa
portare a termine la parte di lavoro affidatale.

visato, ed in ciò in perfetto accordo coll'Ing. Grob-
tarsosa dell'Ufficio Tecnico Provinciale, di divi-
dere il lavoro in due parti, il primo tratto (del-
l'inizio della bracciale verso Cesano) che dovrà
de rimanere affidato all'impresa Cornetto ed il se-
condo tratto (verso Cesano), dove l'Impresa Cornet-
to non ha fatto niente) da affidare ad altra Impre-
sa tecnicamente attrezzata, che dia affidamento di
eseguire i lavori con le desiderate sollecitudini.

In tal modo potrebbe ancora sperarsi che l'Impresa
Cornetto, col lavoro ridotto al primo tratto, e coll'
l'esempio di una impresa veramente attrezzata ed
idonea per l'esecuzione del secondo tratto possa
portare a termine la parte di lavoro affidatale.

In tal modo lo scrivente ha prospettato la
questione al rappresentante dell'Ing. Cornetto (Ing.
Cattaneo) il quale aveva promesso di dare risposta
entro ieri sera.

Dallo stesso vengo oggi informato che l'Ing.
Cornetto intende sottoporre la decisione al Gen.

4212
5022

./.

americano Matchett comandante della 104^a Coy del
quale egli avrebbe avuto le direttive iniziali per
il lavoro. Lo stesso Ing. segnala che l'Ing. Cornet
non ~~ha~~ potuto avere il colloquio col Ten.
Maronati perché quest'ultimo trovandosi attualmente
all'ospedale.

Poiché allo stato attuale la questione è ferma,
e sembra che l'Ing. Cornetto tenda a tergiversare
rappresentando la necessità dell'intervento del
predetto Tenente Matchett ora assediato, presso l'in-
terseimento di V.S. perché venga risolta la que-
stione nel senso sopraindicato e con l'urgenza
che viene al riguardo fatta dal predetto Signor
Maggiore Galardi.

Anguini

IL GENERALE COMANDANTE DEL GENIO
DEL COMANDO TECH. LE DI ROMA

(S. Cortellesa)

Maronati

Roma, il 21/5/45

AP 32

TRANSLATION

From - Terr Engr HQ Rome
To - MCV Engr Seo
Terr HQ Rome
MMIA for Maj Copleston
Direzione Lav Genio
2/7988
9 May 45

Subject:- BRACCIANO Barracks

I fwd copy of letter sent to me for info from P BLU IRTG ICP dated 3 inst to which was att a report from Capt Gould giving particulars of the state of work and proposals for its completion.

I reply to the points brought up in the order set out in said letter:

1) I have noted Capt Gould's remarks but it must be pointed out that the destination of the fixtures indicated in his report do not seem to conform to the intentions of the present Reg HQ although they are a modification of other previous projects. In view of this the continuation of the work advised by Capt Gould should undergo some change.

2) The works programme should suit the changing exigencies of the Centro, and for this reason I have always laid down that the Direzione Lavori concerned follow the instructions as they come from Reg HQ.

They tell me now that Lt Col Persica has examined the programme with a view to setting it out and allocating works so that manpower ~~is~~ and materials which are daily being delivered are not dispersed.

On the 7 inst together with Lt Col Persica, the Capo Sezione and the firm's representatives I carried out a thorough inspection on the job in order to adopt the measures suggested by Capt Gould where they were not contrary to the differences of the programmes.

3) ~~Weight supply~~ and sanitary plant is as follows:-

- a) the general distribution ~~of~~ ^{5.294} has been completed. must be remembered that this existed only in part and therefore its completion has caused a great deal of work and the use of much tubing.
- b) the distribution ~~of~~ in 4 huts (Nos 1,2,5,6) has been completed, another is being completed (No 4) and has not

I reply to the points brought up in the order set out in said letter:

1) I have noted Capt Gould's remarks but it must be pointed out that the destination of the fixtures indicated in his report do not seem to conform to the intentions of the present Reg HQ although they are a modification of other previous projects.

In view of this the continuation of the work advised by Capt Gould should undergo some change.

2) The works programme should suit the changing exigencies of the Centro, and for this reason I have always laid down that the Direzione Levori concerned follow the instructions as they come from Reg HQ.

They tell me now that Lt Col Persica has examined the programme with a view to setting it out and allocating works so that manpower ~~taxa~~ and materials which are daily being delivered are not dispersed.

On the 7 inst together with Lt Col Persica, the Capo Sezione and the firm's representatives I carried out a thorough inspection on the job in order to adopt the measures suggested by Capt Gould where they were not contrary to the differences of the programmes.

3) ~~Water supply~~ and sanitary plant is as follows:-

5294

a) the general distribution ~~works~~ has been completed. ~~must be remembered that this existed only in part and therefore its completion has caused a great deal of work and the use of much tubing.~~

b) the distribution ~~works~~ in 4 huts (Nos 1,2,5,6) has been completed, another is being completed (No 4) and has not been started in another (No 3) because its ultimate use has not yet been decided.

c) water supply comes from existing cistern to which water has never and has not yet been laid on. This has caused some lively discussion and although I have done my best a rather serious delay has occurred.

It was a matter of increasing the pressure in the municipal aqueduct with an new electric pump; this has been installed and difficulties re the installation of a transformer for this pump have been overcome but even now the matter is not settled.

In fact only recently Bracciano municipality has reported a leak in the water main and the underground tunnel (40 metres deep) in which the water main lays had to be inspected; unfortunately a break in the tunnel was found which appears to have caused the break of some junctions.

I immediately got a contractor to carry out repairs and work started the 7 inst and in the meantime I have ordered a tryout with the electric pump taking all possible care to see if it can work for a few hours a day; results will be forwarded in a week.

In conclusion the water and sanitary fittings previously completely pinched by persons unknown have been made good, only the taps have not been fixed to avoid theft and these will be given to CC Barracks

4) Service hutting comprises:-

- showers
- ORs ~~mess~~ cookhouse
- Mess

Showers have been completed as regards water supply, only the elbows and roses have not been fixed to avoid theft before handing over.

Troops cookhouse on the other hand has not been renovated; it consists of 4 large kitchens capacity 1000 which are without soyer stoves and part of the cast iron plates and other important items. To avoid the large expense which renovation would have cost I have arranged, as in all the other barracks, for the sending of an adequate number of field kitchens type De Micheli. Allied HQ has asked for the earthenware tiling of the whole kitchen; the firm has obtained the tiles but cannot start work as the field kitchens are placed against the walls.

I have arranged for the field kitchens to be placed under the porch so that work can begin at once. At the same time a reliable firm will renovate two existing kitchens and replace the 'piestre' and soyer stoves missing, in order to avoid further use of the ~~old~~ ^{old} kitchens.

It must be pointed out that the officers mess is at present using the ORs ~~mess~~ cookhouse and the places earmarked for ration stores, thus it is necessary to quickly finish the little work still outstanding at the mess in Hut No 2 so that it can be transferred there. Capt Gould has put this last on his list and it would be a good thing to modify this point to speed up works generally.

4) Service hutting comprises:-

- showers
- ORs ~~mess~~ cookhouse
- Mess

Showers have been completed as regards water supply, only the elbows and roses have not been fixed to avoid theft before handing over.

Troops cookhouse on the other hand has not been renovated; it consists of 4 large kitchens capacity 1000 which are without soyer stoves and part of the cast iron plates and other important items. To avoid the large expense which renovation would have cost I have arranged, as in all the other barracks, for the sending of an adequate number of field kitchens type De Micheli. Allied HQ has obtained the earthenware tiling of the whole kitchen; the firm has obtained the tiles but cannot start work as the field kitchens are placed against the walls.

I have arranged for the field kitchens to be placed under the porch so that work can begin at once. At the same time a reliable firm will renovate two existing kitchens and replace the 'piastre' and soyer stoves missing, in order to avoid further use of the ⁵²⁹³ kitchens.

It must be pointed out that the officers mess is at present using the ORs ~~kitchen~~ cookhouse and the places earmarked for ration stores, thus it is necessary to quickly finish the little work still outstanding at the mess in Hut No 2 so that it can be transferred there. Capt Gould has put this lest on his list and it would be a good thing to modify this point to speed up works generally.

The mess will be fitted up almost at the same time as the Cookhouse unless it is used for something else.

5) I have acted on recommendation in the letter. I must add that the firm Lasciale di Costruzione which has the contract has been slow to get moving particularly because the ENAC has had been difficult to renewing of 'permessi di circolazione' for its trucks. I have had to set 3 trucks for the firm from Com Mil Terr but they are not enough. Finally on the 7th ENAC released two permits and promised a third for the 8th but has done nothing about the fourth with trailer.

I personally went to EMAC on the 8th and found it closed; an energetic and authoritative approach would appear to be necessary to cut through the red tape.

I assure you that if the above permits are issued or if 8 vehs are assigned for the current month instead of six as asked by me through NMTA work will be speeded up considerably.

CORTELLESA

From - P BLU IRTC ICP
To - OC RTC ICP
Gen Cortellesa

AQ/3/48I

3 May 45

Subject:- Bracciano Barracks

- 1) Att is a report by Capt Gould on the hutting at Bracciano
- 2) Such a report shows that a proper programme has not been got out or is not suitable.
- 3) Request for latrines and ablutions contracted properly has been made very strongly by me and by every other British offr who has visited the camp but this work is very much behind and nothing has been done. This must have priority.
- 4) My DAA & QMG has spoken to Gen Cortellesa with Lt Col Piscicero with Maj Bucchi and with others of HQ HTG ICP pointing out the disgraceful state of the cookhouse and recommending that it be properly cleaned tiled and tidied up.
Everyone agreed but no action has been taken.
It is astonishing that senior offrs responsible for the Regt del Genio allow their men to be fed from such a filthy cookhouse and do nothing about improving it, especially when so much has been done in the Regts offrs mess.
- 5) I strongly recommend that priorities laid down by Capt Gould in his report be adopted immediately and work arranged accordingly.



N. 2046 (1945) del Genio
(R. 1911 - Anno XXI)

P.M. 3800,

9 MAG. 1945

COMANDO GENIO MILITARE
TERRITORIALE DI ROMA

MINISTERO DELLA GUERRA
Direzione Generale del Genio

R O M A

Risposta al foglio del

Prot. N.

2/7988

Allegati 1

Div.

Sez.

N.

Oggetto: BRACCIANO: caserma funzionale.-

e, per conoscenza:

AL COMANDO MILITARE TERRITORIALE DI
AL COMANDO DELLA DIVISIONE "PICENO"
ALLA M.M.I.A. (per il Sig. Magg. Coppleston)
via Veneto
ALLA DIREZIONE LAVORI GENIO MILITARE

R O M A
CELANO

R O M A
SEDE

Trasmetto copia della lettera qui pervenuta, per conoscenza, dal "F" Blu Irte Icf in data 3 c.m. a cui è stato allegato un rapporto del Cap. Gould circa i rilievi particolareggiati sullo stato dei lavori nei singoli fabbricati e le proposte di successiva graduazione dei lavori di completamento.-

Risponde ai singoli rilievi, nell'ordine fissato dalla citata lettera:

- 1) - Ho preso nota di quanto ha riferito nel rapporto il Cap. Gould però occorre far presente che la destinazione dei fabbricati, indicata nel rapporto stesso, non sembra conforme agli intendimenti del Comando di reggimento attuale, pur rappresentando questi ultimi una modificazione di altri progetti precedenti.-

In relazione a tale fatto la successione dei lavori consigliata dal Cap. Gould dovrebbe subire qualche variante.-

- 2) - Il programma di lavoro deve rispondere alle esigenze graduali del Centro, e per questo ho sempre disposto che la dipendente Direzione Lavori seguisse le prescrizioni, non meno che venivano dal Comando di reggimento.-

Attualmente mi consta che il Ten. Col. Persica ha ripreso in esame il programma allo scopo di giungere alla sua definizione e conseguente graduazione dei lavori per evitare una dispersione della mano d'opera e dei materiali che giornalmente affluiscono.-

Al riguardo il giorno 7 c.m. ho compiuto insieme al predetto Ufficiale Superiore, al Capo Sezione ed ai rappresentanti della Impresa un sopralluogo minuzioso per adottare tutti i provvedimenti suggeriti dal Cap. Gould purchè non contrastanti con la diversità dei programmi.-

- 3) - Gli impianti idraulici e sanitari sono a questo punto:
- a)-la rete generale di distribuzione è stata completata.- Si deve rammentare che essa esisteva solo in parte e perciò il suo completamento ha richiesto un lavoro considerevole e l'impiego di un forte quantitativo di tubazione;
 - b)-la rete di distribuzione interna in 4 casermette (numeri 1-2-5-6) si sta completando in un'altra (numero 4) e non è stata eseguita nell'ultima (numero 3) perchè ancora non è stata confermata la sua destinazione definitiva;
 - c)-l'alimentazione generale avverrà dal serbatoio già esistente ed al quale l'acqua non è mai pervenuta in passato e non vi è ancora affluita nel presente.- La questione ha subito inoltre vicissitudini e malgrado il mio interessamento si è avuto un ritardo piuttosto rilevante.-

Si trattava di aumentare la pressione nell'acquedotto municipale a mezzo di una nuova elettropompa; l'installazione è stata fatta, sono state superate difficoltà per la posa di un trasformatore adatto per questa elettropompa e giunti a questo punto non si è risolto ancora interamente il problema.- Infatti soltanto recentemente è stata segnalata dal Comune di Bracciano una perdita dalla tubazione principale e si è dovuto ispezionare il cunicolo sotterraneo (alla profondità di circa 40 metri) entro cui si sviluppa la tubazione; purtroppo si è verificato il franamento del cunicolo che potrebbe aver provocato la rottura di qualche giunzione.-

Ho subito interessato un'impresa per lo sgombero della frana ed il rifacimento del tombino ed i lavori sono stati iniziati il 7 c.m. intanto ho predisposto una prova della elettropompa con tutte le cautele possibili per constatare se è possibile o meno di funzionare per qualche ora al giorno; si riferirà in settimana.

Concludendo: gli impianti idraulici e sanitari già completamente asportati da ignoti sono ora quasi completamente ricostruiti, non sono stati messi a posto i subinetti soltanto per evitarne l'asportazione prima che l'acqua venga immessa nelle tubazioni e si possano dare in consegna al Comandante della caserma.-

- 4) - Il fabbricato servizi comprende:
- bagno e doccia
 - cucina trappa
 - refettorio



N. 2090 (200 del Cav.)
(R. 1941 - Anno XX)

194 - Anno

Risposta al foglio del

Prot. N.

Allegati

Dir.

Seq.

N.

Oggetto

Il bagno a doccia è stato completamente ripristinato per la parte idraulica, non si sono applicati i bracci con le cipolle per evitarne l'asportazione, prima che si possa consegnare l'impianto.-

La cucina truppa invece non è stata ancora ripristinata; essa comprende 4 grandi cucine da 1000 razioni ciascuna, prive di tutte le marmitte e di parte delle piastre in ghisa e di altre parti importanti.- Per non affrontare l'ingente spesa del ripristino avevo provveduto, come in tutte le altre caserme, a far affluire un congruo numero di cucine da campo tipo De Micheli.- Il Comando alleato ha richiesto l'applicazione delle piastrelle di maiolica per l'intero sviluppo della cucina; l'impresa è riuscita ad approvvigionare le piastrelle ma non ha potuto iniziare il lavoro perchè le cucine da campo funzionano addossate ai muri.-

Ho disposto perchè nella corrente settimana le cucine da campo vengano collocate sotto al porticato, così da lasciare libero il locale all'impresa che potrà iniziare subito i lavori.- Contemporaneamente un'impresa di fiducia riparerà due cucine esistenti e costruirà le piastre e le marmitte mancanti, in modo da poter evitare l'ulteriore impiego delle cucine da campo.-

Si deve rilevare che la mensa ufficiali usufruisce attualmente della stessa cucina truppa e dei locali destinati a ripostiglio viveri, di modo che è necessario ultimare i pochi lavori ancora necessari alla mensa stessa nella casermetta n.2 perchè vi possa essere trasferita.- Il Cap. Gould ha previsto il completamento della mensa come penultimo dei lavori da farsi e perciò ³²⁹⁰ bene modificare questo punto, a tutto vantaggio della celerità dei lavori.-

Il refettorio sarà ripristinato quasi contemporaneamente alle cucine truppa a meno che non debba avere altra destinazione.-

N. 2000 (200 del Cav.)
(R. 100) - Anno 200

104 - Anno

Risposta al foglio del

Prot. N.

Allegati

Div.

Sez.

Oggetto

Il bagno a doccia è stato completamente ripristinato per la parte idraulica, non si sono applicati i bracci con le cipolle per evitarne l'asportazione, prima che si possa consegnare l'impianto.-

La cucina truppa invece non è stata ancora ripristinata; essa comprende 4 grandi cucine da 1000 razioni ciascuna, prive di tutte le marmitte e di parte delle piastre in ghisa e di altre parti importanti.- Per non affrontare l'ingente spesa del ripristino avevo provveduto, come in tutte le altre caserme, a far affluire un congruo numero di cucine da campo tipo De Micheli.- Il Comando allente ha richiesto l'applicazione delle piastrelle di maiolica per l'intero sviluppo della cucina; l'impresa è riuscita ad approvvigionare le piastrelle ma non ha potuto iniziare il lavoro perchè le cucine da campo funzionano addossate ai muri.-

Ho disposto perchè nella corrente settimana le cucine da campo vengano collocate sotto al porticato, così da lasciare libero il locale all'impresa che potrà iniziare subito i lavori.- Contemporaneamente un'impresa di fiducia riparerà due cucine esistenti e costruirà le piastre e le marmitte mancanti, in modo da poter evitare l'alteriore impiego delle cucine da campo.-

Si deve rilevare che la mensa ufficiali usufruisce attualmente della stessa cucina truppa e dei locali destinati a ripostiglio viveri, di modo che è necessario ultimare i pochi lavori ancora necessari alla mensa stessa nella casermetta n.2 perchè vi possa essere trasferita.- Il Cap. Gould ha previsto il completamento della mensa come penultimo dei lavori da farsi e perciò bene modificare questo punto, a tutto vantaggio della celerità dei lavori.-

Il refettorio sarà ripristinato quasi contemporaneamente alle cucine truppa a meno che non debba avere altra destinazione.-

./.

5) - Ho preso atto della raccomandazione espressa nella ripetuta lettera. Ritengo doveroso soggiungere che l'impresa Laziale di Costruzione, che ha assunto l'appalto dei lavori ha stentato un poco ad organizzarsi soprattutto perchè l'E.N.A.C. ha frapposto molte difficoltà al rinnovo dei permessi di circolazione degli autoveicoli. - Sono stato costretto ad assegnare all'impresa 3 degli autocarri che giornalmente vengono messi a disposizione dal Comando Mit. Territoriale, ma non bastano. -

Finalmente l'E.N.A.C. ha concesso all'impresa il permesso di circolazione di due autocarri, ha promesso per il giorno 8 c.m. di rilasciare il permesso per un terzo autocarro e nulla ha fatto per il quarto con rimorchio. - Mi sono recato personalmente all'E.N.A.C. il giorno 8 ma ho trovato chiuso; occorrerebbe un intervento energico ed autorevole per eliminare questi intralci burocratici inammissibili ed inopportuni. -

Assicuro che se verranno rilasciati i permessi anzidetti oppure verranno assegnati per tutto il corrente mese 8 autocarri in luogo dei 6 da me richiesti tramite la M.M.I.A. nel mese corrente i lavori riceveranno un impulso considerevole.

IL GENERALE DI BRIGATA COMANDANTE
(R. Cortellesa)

[Handwritten signature]

232

BEST COPY POSSIBLE

UNITED STATES AIR FORCE
REC 89/3/181

3 May 45

AL GENERALE COMANDANTE R.T.G. I.C.F.

e per conoscenza:

ALL'UFFICIO LAVORI GENIO MILITARE

(Per il Generale Cortellesa)

OGGETTO: Bracciano - Caserma Tusnelliana.-

- 1°)- Qui allegato è una copia di un rapporto del Capitano Gould, su i barroccamenti del Reggimento del Genio a Bracciano
- 2°)- Tale rapporto segnala che un appropriato programma di lavoro non è stato concretato, oppure non è rispondente.
- 3°)- Le richieste di latrine e di lavandini costruiti come si deve è stata caldeggiata ripetutamente dallo scrivente e da ogni altro Ufficiale (inglese) che è stato alle Caserme Funzionari ma evidentemente i lavori delle latrine e dei lavandini è molto ritardato nell'ordine dei lavori e nessun provvedimento è stato preso.

Questo è il lavoro che dovrebbe avere la priorità.

Il mio D.A.A. e Q.M.G. ha personalmente parlato col Generale Cortellesa, col Ten. Col. Fisicaro, col Magg. Bucchi e con appartenenti al Comando RTG SCP, additando il disgraziato stato delle latrine, e raccomandando caldamente che la stessa fosse accuratamente fatta, coperta di tegole e collocata.

Su questo erano d'accordo tutti, ma nessuna azione di nessun tipo è seguita.

E' stupefacente che ufficiali superiori responsabili del

(Per il Generale Cortellana)

OGGETTO: Bracciano - Caserma funzionali.-

- 1°)- Qui allegato è una copia di un rapporto del Capitano Gould, su i baraccamenti del Reggimento del Genio a Bracciano
- 2°)- Tale rapporto segnala che un appropriato programma di lavoro non è stato concretizzato, oppure non è rispondente.
- 3°)- Le richieste di latrine e di lavandini costruiti come si deve è stata caldeggiata ripetutamente dallo scrivente e da ogni altro Ufficiale (inglese) che è stato alle Caserme Funzionali ma evidentemente i lavori delle latrine e dei lavandini è molto ritardato nell'ordine dei lavori e nessun provvedimento è stato preso.

Questo è il lavoro che dovrebbe avere la priorità.

4°)- Il mio D.A.A. e Q.M.C. ha personalmente parlato col Generale Cortellana, col Ten.Col. Pisciardo, col Magg. Bucchi e con appartenenti al Comando HTG ECF, additando il disgraziato stato della Cucina e raccomandando caldamente che la stessa fosse accuratamente ripulita, coperta di tegole e collocata.

Su questo erabo d'accordo tutti, ma nessuna azione di nessuna sorte è seguita.

Il stupefacente che ufficiali superiori responsabili del Reggimento del Genio, debbano permettere che i loro uomini si meritino da una così rivoltante cucina, e non facciano nessun sforzo per migliorarla, specialmente quanto tanto lavoro è stato fatto nella mensa degli Ufficiali del Reggimento.

5°)- Raccorrendo nel modo più energico possibile che l'ordine di precedenza stabilito nel rapporto del Capitano Gould sia stato immediatamente e l'andamento del lavoro regolato conseguentemente.

Ten.Col.

(F.to illeggibile)

A circular stamp is partially visible, containing some illegible text. Below it, there is a handwritten signature in dark ink, which appears to be 'G. Cortellana'.

2
3 (Ting)
 To see
 on MS: (Bogdan
 QII WAK
QII
QII
 J

30

SUBJECT:- Monthly Training Progress Report - April 1945
(Scuola Artieri)

'H' BHI IRTG ICP

AA & QMG
'F' HLU IRTG ICP (In triplicate).

Ref: BTL/A.10/175

APINQ (Engineer Section)
Commandant, Engr Trg Est., CMP.
SORE, MMIA.

27 April 1945

1. GENERAL PROGRESS.

- (a) Headway has been made and the Italians are doing much more themselves.
- (b) Recruit training is the only training in progress.
- (c) An Officers refresher course is being superimposed on the recruits training with additional lectures and schemes (rough syllabus with you).
- (d) An effort to smarten up the training ground with flags and white paint is having a beneficial effect.
- (e) Recruit training is now 8 weeks - programme attached.
- (f) Percentage attendance is still bad.
- (g) Junior officers still do not enforce discipline.

2. COURSES.

- (a) No courses for Gruppi have been started but it is considered that it should be possible to start soon. Suggested date May 28th.
- (b) The following courses could be run. May MMIA please be asked to give a priority. Duration 2 weeks.

Officers.	Refresher. (Man management, Organisation of work, recess, etc.).
Officers and NCOs.	Bailey Elementary.
Officers and Senior NCOs.	Mine Warfare.

5288

- (c) It is assumed that Advanced Bailey, Wet Bridging, Rafting and Assault Crossings courses which would require extra equipment and a course of instruction at SMX for instructors, are not required.
- (d) No men from Scuola ARTIERI are attending outside courses in engineering.

3. NUMBERS HELD.

- (a) Weekly intake. Theoretically 55 but last 2 weeks have been missed.
- (b) Under training. 4 parties of theoretically 55 each. Actually approximately 180.
- (c) Trained. 2 parties of theoretically 55 each. Actually approximately 100. It has been asked that for morale purposes that these 2 parties are sent up to the front with much trumpet blowing as they are our first "trained" recruits. They are still at BRACOLANO.

4. INSTRUCTIONAL STAFF.

- (a) No deficiencies to WE but officers instructors have a habit of changing which is most depressing.
- (b) Standard of instruction is improving.

5. EQUIPMENT.

- (1) The following items of equipment are still outstanding.

Item No.

45	Chest, tool, filled, painters.
46	" " " fitters.
47	" " " electricians.
50	Anvil.
51	Field Forge, heavy.
57	Tarpaulin, 30' x 30'
72	Kit of hand tools, blacksmiths.
98	No.4 Pump set.
99	No.5 Pump set.
56	S tanks. 3

- (11) Water Supply training is being held up by lack of Pumping sets and S Tanks.

6. ADMINISTRATION.

- (a) Accommodation. Improved. Beds have arrived. No room for messes.
- (b) Hygiene. Still bad.
- (c) Welfare. Not apparent.
- (d) Morale. Surprisingly high.

5287

Major RE
3088

File 29
PA

Report on Work Progress at
BRACCLAND Signals and Engineer
Training Centre.

Description.

The Training Centre consists of six main buildings and three ancillaries. The main buildings, for reference, are:-

- 1. Signals School,
- 2. Officers' Mess,
- 3. Signals School living accommodation,
- 4. " " "
- 5. Engineer School " " "
- 6. " " "

The ancillary buildings are:-

- (a) Main cook-house, ablutions and latrines,
- (b) Guard Room,
- (c) Administrative Headquarters.

The bulk of the work consists of:-

- (i) Replacing all doors and windows,
- (ii) Replastering and redecorating all buildings,
- (iii) Repair and refitting all ablutions and latrines,
- (iv) Cleaning all drains,
- (v) Replacement of electrical fittings,
- (vi) Renovations to Signals School and officers' mess.

Each building will be dealt with separately giving details of work already completed and work still required to be done.

1. SIGNALS SCHOOL.

A considerable amount of work has already been done to this building. The original layout has been changed completely necessitating a considerable amount of work. This work is now practically completed. Doors and windows still remain to be fitted. Repainting is in progress. Essential electrical fittings have been installed. No work has been done on the latrines or ablutions.

2. OFFICERS' MESS.

Work on this building is very advanced. It would appear that this building has had priority. All that now remains to be done is for the windows to be glazed and a small amount of redecorating. Very little effort has been made to repair the latrines and ablutions. These are still not working.

The military buildings are:-

- (a) Main cook-house, ablutions and latrines.
- (b) Guard Room.
- (c) Administrative Headquarters.

The bulk of the work consists of:-

- (i) Replacing all doors and windows.
- (ii) Replastering and redecorating all buildings.
- (iii) Repair and refitting all ablutions and latrines.
- (iv) Clearing all drains.
- (v) Replacement of electrical fittings.
- (vi) Renovations to Signals School and cdfloors' mess.

Each building will be dealt with separately giving details of work already completed and work still required to be done.

1. SIGNALS SCHOOL.

A considerable amount of work has already been done to this building. The original layout has been changed completely necessitating a considerable amount of work. This work is now practically completed. Doors and windows still remain to be fitted. Repainting is in progress. Essential electrical fittings have been installed. No work has been done on the latrines or ablutions.

2. OFFICERS' MESS.

Work on this building is very advanced. It would appear that this building has had priority. All that now remains to be done is for the windows to be glazed and a small amount of redecorating. Very little effort has been made to repair the latrines and ablutions. These are still not working.

5286

3. } SIGNALS SCHOOL LIVING ACCOMMODATION.
4. }

These buildings have not yet been touched. All windows and doors require replacement or repairs. The walls are badly pitted and require replastering and rewashing. Latrines and ablutions are not working and no attempt has been made to get them into working order.

5. ENGINEER LIVING ACCOMMODATION.

The bulk of this building has been replastered and rewashed. Doors have been installed above the sleeping bunks. Doors and windows still require fitting. No attempt has been made to repair the latrines and ablutions which are not working.

6. ENGINEER LIVING ACCOMMODATION.

One wing of this building is at present unoccupied. Workmen are busy replastering and rewashing the walls. It would appear that some attempt is being made to repair the ablutions and latrines not working at present.

(a) MAIN COOK-HOUSE, AMMUNITION AND LATRINES.

The main cookhouse is in a disgraceful state. The original layout provided for four (4) big built-in cooking ranges. These ranges are still in the building but unused. The main centre top-plates of each range are missing. Replacement of these - even the use of mild steel plates - should bring the ranges back into commission again. The cooking is being done at present by means of odd boyer stoves and floor fires arranged around the walls of the building. This building requires remodelling, cleaning and the stoves repaired.

Abutions and latrines.

No attempt has been made to bring these into working order again. All taps are missing. The wash basins and showers all require fittings. The latrines all require cisterns. A fair amount of retilling is necessary. This building - at the time of our visit - was being used by the cooks as a vegetable preparation room.

(b) & (c) GUARD ROOM AND AMMUNITION.

These buildings were originally single storied. The building of the second storey is half completed. This work has stopped. The original storey requires doors, windows and redecorating.

GENERAL.

The water supply for the camp comes from a concrete tank situated just outside the camp fence. The water is then piped - 2 No 3" mains - into the camp. The mains and the draw off points have been completed. The drainage appears to be satisfactory.

REMARKS.

The buildings are all habitable and could be brought up to a very high standard. The general layout of the camp and buildings is excellent. A great deal of work has been done to date. At a conservative estimate it will take another two months to complete the work already undertaken. The work done to date has been of a fairly high standard. The only criticism to be offered is that the sequence of the work has been wrong. Too much labour and material has been used getting the officers' mess completed, while no attempt has been made to provide cooking, latrine and ablution facilities for the men.

RECOMMENDATIONS.

That the existing priorities be scrupled forthwith and that the following be adapted:-

5282

All boys are sleeping. The mess building and kitchen are being completed. The latrines all require distones. A fair amount of retubing is necessary. This building - at the time of our visit - was being used by the cooks as a vegetable preparation room.

(b) & (c) GUARD HOUSE AND APPROX 100.

These buildings were originally single storied. The building of the second storey is half completed. This work has stopped. The original storey requires doors, windows and re-insulating.

GENERAL.

The water supply for the camp comes from a concrete tank situated just outside the camp fence. The water is then piped - 2 No 3" mains - into the camp. The mains and the drain off points have been completed. The drainage appears to be satisfactory.

REMARKS.

The buildings are all habitable and could be brought up to a very high standard. The general layout of the camp and buildings is excellent. A great deal of work has been done to date. At a conservative estimate it will take another two months to complete the work already undertaken. The work done to date has been of a fairly high standard. The only criticism to be offered is that the sequence of the work has been wrong. Too much labour and material has been used getting the Officers' mess completed, while no attempt has been made to provide cooking, latrine and ablution facilities for the men.

RECOMMENDATIONS.

That the existing priorities be scrapped forthwith and that the following be adopted:-

- (1) Main ablutions and latrines.
- (2) Cook-house (Mens).
- (3) Latrines and ablutions - mens' living quarters.
- (4) Latrines and ablutions for Officers.
- (5) Latrines and ablutions for Signals School.
- (6) Completion of Signals School.
- (7) Completion of Mens' living quarters.
- (8) Completion of Officers' Mess.
- (9) Remaining works.

Note: The latrines in use at present are neither fly-proof nor of the deep-trench variety. Unless something is done to eliminate these during the next fortnight a plague of flies will result.

LWJ/edj
2 May 45

W.F. SAMS (GOC HQ),
Capt.

5285

5282

DE/RR



28
11/2

Comando Genio del ~~Corpo d'Armata~~ di Roma

N 3/6120

di prot.

Roma, 2 APR 1945

104 x

Allegati:

Risposta al

N.

del

Divisione

Sezione

OGGETTO Costruzione di un teatro sgomtabile all'aperto. - PRO MEMORIA -

A/SIGNOR MAG. GELANDI - Comandante Inglese
Centro Addestramento - CESANO
e, per conoscenza:

AL SIGNOR MAGG. COPESTON - LAND FORCES SUB COM-
MISSION ENGINEERING SECTION (M.M.I.A.) EX
PALAZZO CORPORAZIONI ROMA
ALLA DIREZIONE LAVORI G.M. ROMA

In relazione all'interessamento spiegato dalla S.V. è stato possibile ottenere ieri a Roma con buono di prelevamento della 104 C.M.I. i materiali sottoelencati occorrenti per il costruendo teatro all'aperto per il soldato:

- Window - Lite - un foglio della lunghezza di m. 30 per l'altezza di m. 0,90
- Tela Messica - rotoli della lunghezza ^{50,97} ~~52,82~~ pressiva di m. 182 (pari a yard 200) per l'altezza di m. 1 mq. 182

I quantitativi occorrenti di tali materiali erano già stati segnalati in mq. 100 di Window-

Lite e mq.200 di tela Hesslon

Particolare interesse riveste particolarmente la tela Hesslon senza di cui non sarebbe possibile assolutamente costruire il teatro.

Si prega vivamente di esaminare la possibilità di far cadere da parte Allesta per lo meno la tela Hesslon ancora occorrente, se non nella misura massima dei mq.1518 necessari per completare i mq.2000 già ordinati almeno in misura ridotta di mq.1600-1700 sempre in aggiunta di quanto già ricevuto.

IL GENERALE DI BRIGATA COMANDANTE
(R.Cortellana)

M. Cortellana

2312

C O P I A/in

= TELEGRAMMA =

4 APR. 1945 **IN**

AT FRAZIONE MAGAZZINO GENIO = FRANCAVILLA F. =

GUERRAGENIO N. II/ 22269/M DI PROT. CAPITANO INGLESE
LEPOCQ EST AUTORIZZATO A RITIRARE DA CODESTA FRAZIO
NE CAMPIONI MINE ET INCENDIVI NEI QUANTITATIVI DALLO
STESSO RICHIESTI PER SCUOLA ADDESTRAMENTO BRACCIANO
PUNTO SEGNALARE QUANTITA' ET TIPI MATERIALI RITIRATI
ALT CRIVARO

Handwritten initials

XWX

MINISTERO DELLA GUERRA
Direzione General del Genio
--- Divisione Materiali ---

N. II/ 22269/M di prot. Roma, li 4 APR. 1945

→ ALLA LAND FORCES SUB COMMISSIONE A.C. (MMIA)
(Rif. autorizzazione n. 121 del 31.3.45)

AL COMANDO GENIO MILITARE = RCMA =
ALLA DIREZ. LAV. GENIO MILITARE = BARI =
= BARI =

.....

.....per conoscenza.-

Handwritten signatures and initials

IL MINISTRO
(Col. G. Picone)
Handwritten signature

SUBJECT: Italian Instructors.

Land Force Cdn Gen A.C.

RE

50 British Liaison Unit
RM/34
13 Mar 45

25
11/2

1. Ref your RM/11/7, dated 2 Mar 45.
2. The Eng Lt Col FRANK IOD has been approached regarding the possibility of providing instructors for the Eng school at BRACCLANO, and has replied that he has at the moment no suitable offers or NCO's.

[Handwritten Signature]

Capt RM.
50 BRU.

RG/123.

SUBJECT:- Engineer Training - ICF

"H" Brit Div Incr
IRTC ICF

Major B. ^{Hoffman} ~~Hoffman~~, MC, RN,
Engineering Section,
AFHQ.

Ref: DTL/G.4/32

19 March 1945

Dear

1. Re: the query re the length of recruit training at the Engineering Training Centre, BRACCIANO. Original verbal instructions received from Comd RTU were to run a 6 weeks course for the recruits and a 6 weeks programme was drawn up and submitted to DFT.

2. I have prepared another draft (attached) of the intended syllabus for a recruits course as the original programme is not suitable, being too hastily prepared. I think that it should be possible to cover the ground in 6 weeks, but if approval is given, the extra subjects mentioned could be added. The Italians are quick to learn.

3. The weeks weapon training is purely for parties Nos 1 to 5 who came from disbanded artieri companies and not through reception regts

Yours,

JCH/anj.

Copy to:
Major H.C. Copleston, RA,
MIA.

5282

5281

Engineer Training - Italian Combat Force.

"H" HHC ICF.
Ref: HFI/G-4/35
19 March 1945

DC, AFHQ.
Copy to:
Eng Sect, AFHQ.
SIA.

Engineer

(a) Recruits.

1. A programme of 6 weeks training has already been drawn up and submitted to you.
2. In the light of experience the programme is being republished to cover the following syllabus:-

Fieldwork. (2 weeks)

- Care of tools.
- Knots and lashings.
- Levelling.
- Sand bag walling.
- Field geometry.
- Constructing of fire trench.
- Revetment.
- Drainage.
- Blocks and tackles.
- Anchorages.
- Derricks and shears.
- Triple and Lambert Fuses (including night work).
- Double Apron Fuses.
- Laying of Semerfield Track and Coir matting.
- Road repair without special equipment.
- Use of water supply equipment issued to British Field Units E.

Use of Compressor.

- Elementary Bailey (excluding triple story and pier supported bridges) including night work.
- ~~Construction of 20-ft Bailey Piers~~
- Construction of short span BSF approved bridges.
- Use of Bridging Crib.

Mine warfare. (2 weeks).

- Common British Explosives.
- Methods of initiating charges.
- Practical demolition in cutting and mined charges.
- Use of Berdies.

(a) Recruits.

- 1. A programme of 6 weeks training has already been drawn up and submitted to you.
- 2. In the light of experience the programme is being reestablished to cover the following syllabus:-

Fieldwork. (2 weeks)

- Care of tools.
- Flags and lashings.
- Leveling.
- Sand bag walling.
- Field gunnery.
- Constructing of fire trench.
- Revetment.
- Drainage.
- Alco's and tackles.
- Aschovags.
- Derricks and Sheers.
- Triple and Desert Fuses (including night work).
- Double Apron fence.
- Laying of Somerset Track and Cord matting.
- Road repair without special equipment.
- Use of water supply equipment issued to British Field Units UK.
- Use of Compressor.

Bridging. (2 weeks).

- Elementary Bailey (excluding Triple story and pier supported bridges) including night work.
- Construction of ~~20 ft~~ Bailey Piers.
- Construction of short span H&J improvised bridge.
- Use of Bridging Girders.

Mine warfare. (2 weeks).

- Common British Explosives.
- Methods of initiating charges.
- Practical demolition in cutting and sined charges.
- Use of Bechives.
- Demolition in situ of unexploded bombs, grenades, etc.
- Introduction to standard allied and enemy mines.
- Laying and recording of British Mines. (Mk IV, Surymol and GP Mines) (including night work).
- Neutralising and disarming enemy mines.
- Use of Producers and Detectors electric.
- Maintenance and tuning of No. 3, No. 4 and U.S. Detectors.
- Gap marking equipment.
- Minefield geyring drill. (including night work).
- Road clearing drills.
- Flaits to mine tunnels.
- Laying of Booby Traps.
- Delousing of booby trapped houses.

5281

3. The following subjects are not included but could be if extra time and equipment were authorized.

- Use of road surfacing experiments.
- Preparation of concrete at a given mix.
- Sand mixing.
- Camouflage. (other than personal).
- Assault Dressing.
- Battermanship.
- Sniffing.

Butley Field Instructor
 + 1st DEB/02/4/01 dated 13 Feb 45 - Training directive for 1 of 6 Italian Engineer units.

(b) Courses.


The date at which it will be possible to run courses at the Engineer Training Centre will depend on how soon the Italian instructors can completely take over the recruits training and the release of extra equipment can be made.

Infantry Courses.

1. A similar programme to the 3 weeks Mini Warfare for the Engineer Recruits is being prepared for the Infantry Platoon.
2. The following subjects could also be taught at a later date provided extra time and the equipment could be provided.
 - 1 week Fieldcraft.
 - Assault Dressing.
 - Battermanship.

DEB/003.

W. R. ...
 MAJOR, GOC, II,
 Training.



Ministero della Guerra
Direzione Generale Genie

Divisione Mater. Sc.
Tel. 7.11/41454/41455

Reparto al Topo del
Genio

ALL'UFFICIO STRALCIO O.M.T.
ED I.M.S.P.

- ROMA

OGGETTO Anterizzazione distribuzione materiali.-

57 per conoscenza:

- ALLA LAND FORCES SUB COMMISSION (rif. fo R.3./11/2 del 2/3/45) **Re** - ROMA
- ALLC S.M.S.E. - Ufficio C.A. **18/3** - P.M.3800
- AL COMANDO GENIO MILITARE - ROMA
- ALLA DIREZ. LAVORI GENIO MILITARE - ROMA

8

La Lande Forces Sub Commission con sua lettera R.3./11/2 in data 2 marzo 1945 ha chiesto di dare assistenza alla Società Anonima Industrie Chimiche Nazionali Riunite nelle sue ricerche di ml. 1200 di cavo elettrico Ø 4 + 5 m/a per linea elettrica corrente per urgenti lavori che la stessa sta eseguendo per conto della dipendente Direzione Lavori.

Non essendo disponibile il cavo con le caratteristiche richieste, l'incaricato della ditta a suo tempo interessato ha ora fatto conoscere che può essere egualmente impiegato il cavo in alluminio da 13 m/m q. disponibile presso il dipendente ufficio Stralcio dell'O.M.T.

In conseguenza, e seguito degli accordi intercorsi ~~col~~ ^{con il} Comandante del Genio di Roma, si autorizza la distribuzione di:

ml. 1200 di cavo in alluminio Ø 13 m/mq.

alla Direzione Lavori che provvederà a soddisfare la richiesta della M.M.I.A. Prelevamento a cura della Direzione Lavori dipendente.-

5279

P. IL MINISTRO

OGGETTO Autorizzazione distribuzione materiali.-

di per conoscenza:

ALLA LAND FORCES SUB COMMISSION
(rif. Po R.E./II/E del 2/3/45)
ALLO S.M.E.E. - Ufficio C.A.
AL COMANDO GENIO MILITARE
ALLA DIREZ. LAVORI GENIO MILITARE

- ROMA

- P.M. 3800

- ROMA

- ROMA

8

La Landg Forces Sub Commission con sua lettera R.E./II/2 in data 2 marzo 1945 ha chiesto di dare assistenza alla Società Americana Industrie Chimiche Nazionali Riunite nella sue ricerche di ml. 1200 di cavo elettrico Ø 4 e 5 m/m per linee elettrica corrente per urgenti lavori che la stessa sta eseguendo per conto della dipendente Direzione Lavori.

Non essendo disponibile il cavo con le caratteristiche richieste, l'incaricato della ditta a suo tempo interessato ha era fatto conoscere che può essere egualmente impiegato il cavo in alluminio da 13 m/m q. disponibile presso il dipendente ufficio Stralcio dell'G.M.F.

In conseguenza, a seguito degli accordi intercorsi ^{con il} Comandante del Genio di Roma, si autorizza la distribuzione di:

ml. 1200 di cavo in alluminio
Ø 13 m/mq.

alla Direzione Lavori che provvederà a soddisfare la richiesta della M.M.I.A..

Prelevamento a cura della Direzione Lavori dipendente.-

5279

P. IL MINISTRO
(COLLOFICONE)

Carabinieri

MEMORANDUM :- Trg Mgmt - B Vels - Compressor.

REC
0 11/2
91

'C' Trg Unit to Italian Army
C. M. P.
Ref BTU/D1/133

14 Mar 45.

INT

CONS. ✓

1. Your BT/88/1/211 of 20 Feb released amongst other vels one truck 15 cwt 4 x 2 Compressor of 1X from 408 RVP. No vels of this category is available at the RVP and we are infm that there is little likelihood of one becoming so in the near future.

2. As nearly all the accessories for a compressor have now been received and are useless without the unit, could you please arrange for a special release in order that trg may begin soon?

GEG/rww

[Handwritten Signature]
A. G. *[Handwritten]*

5278

ENGINEER SECTION (Br)
A.P.H.Q.
C.M.F.
Tele. No. Freedom 335

112
20

SUBJECT: Trg Egt-Rft Trg Centre.
- Italian Combat Force.
TO : HQ Land Forces Sub-Commission AO
(MIA)

RE
12/3
ENG/815
3 Mar 45

Reference visit of Major Holloway to Italian Reinforcement Training Centre on 25 Feb 45 when the question of outstanding training equipment was raised.

A list of stores released is contained in Ordinance (Br) AFHQ letter DOS/2017/3 (Ord 2) dated 20 Feb 45, addressed to 3 Sub Depot, 557 BGD, copy to you.

R.W. Deans
R.W. DEANS,
Captain, R.E.,
for M.G.R.E.

F?

Copy to: Rft Trg Centre - Italian Combat Force.

5277

SUBJECT:- Weekly Progress Report on Engineering Training at E.T.C.,
I.C.F., BRACCIANO - week ending 10 March 1945.

19
11/2

"H" BTL., RTO., ICF.,
c/o Land Forces Sub Com.,
AC, (ISMA), ROME.

Ref: BTL/A.1/20

12 March 45.

Commander,
"F" S.L.U., RTO., ICF.

Copies to:
Chief of Staff Trg, RTO., ICF.
Col Gayer, RE, RFE, CMB.
Major S. Holloway, MC, RE,
Engineer Section, AMHQ.
Major R.C. Copleston, RE, SCRE,
Land Forces Sub Com., AC (ISMA).

1. GENERAL.

Administrative problems held up training during week ending 10 March 45. The 7-weeks training of parties Nos 1, 2, and 3 commenced on 5 March, but issues of kit during training hours, unannounced alterations to meal times, inability to work in the wet due to lack of suitable clothing preparations for Field Marshall Alexander's visit and alterations to the medical rolls of the aimed at 55 men in each of the parties Nos 1, 2, and 3 had considerably hampering effects. It is hoped that all these obstacles have been overcome, but there is much to be done on the Allied side.

2. MINE WARFARE.

It will not be possible to start the Demolitions and Mine Warfare training until 19 March.

The visit to 8 Army Area was quite successful in obtaining enemy mines and the mine museum at the Engineer Training Centre will be opened at the end of the week. Attached list gives the principal deficiencies in the museum at the present time. The mine detectors received were deficient in batteries but it is expected that these batteries will be forthcoming this week.

3. RAILS.

The party working on the elementary Bailey has put in some hard work and good training value has been given to the men. Officers show a slight improvement and as soon as is feasible they will be given individual instruction.

4. FIELDWORKS.

Again some good work has been put into the first weeks work. The following stores are still required:-

Water Supply Equipment. (Holding up training in this subject).
Compressor. (Tools have arrived had a release note for the
15 set but there is not one in the H.C. rep pack).

4. PERSONNEL (Cont'd)

C.P. Holdfast.

5. ITALIAN INSTRUCTORS.

To date one Italian GPFloor and seven M.T.O.s have shown themselves capable of becoming instructors.

6. MILITARY INSTRUCTORS.

The authorized increase in staff is urgently required.

7. TRAINING OF PERSONNEL.

Due to the non-arrival of the increased staff of British instructors, nothing has yet started in training the Infantry Miners. A cadre of 5 are being introduced into the No. 5 Party on Mine Warfare on 19 March.

FIELD,
JUN/53.

[Handwritten signature]
JUN/53

List of Outstanding Mines and Igniters required for the Mine Section, M.T.O., BRANLISCO.

Submarine.	Aluminium 1/2" Mine (3 Igniter mine)
T.M. 35 (Ballistics No. 4)	Long delay Igniter J-Radar 504.
French 1/2" Mine. Light Infantry.	Italian Molemine Mine.
" " " Heavy Infantry.	ONE Mine.
Full and tension wire Igniter 200.35	Light Mine.
EDM 200 20 Igniter.	

5275

ALLIED FORCE LOCAL RESOURCES SECTION
AFHQ

RE. 1073
11/2/48

LRN/234/327

Postal Address:
AFHRS,
ROME AREA ALLIED COMMAND, COM.

SUBJECT: Material for work on
Barracks at Cesano.

Telephone: ROME 66429.

TO: Land Forces Sub-Commission HQ AC,
(M.M.I.A.)

9 Mar 45.

Reference your RE 11/2 dated 7 Mar 45.

1. Confirming conversation, Major Copleston - Major Brahan, of 8th March, it is confirmed that a bid for all controlled items must be put in through your usual channels against availabilities at the Engineering Materials Committee Meeting.

G. M. Brahan
Major

G. M. Brahan, Major, DAQRT,
for Chief of Section,
A.P.L.R.S.

GMB/osa.

List of materials & Part 10 attached.

5273

ATTACHMENTS
ALLIED CONTROL COMMISSION
COMBUSTIBLE SUBS-COMMISSION
ACC 374

Date: 9 March

1. DEMAND FOR CONTROLLED SUBSTANCES.

2. AML/ACC FORMATION **MIHA on behalf of Italian Ministry of War**

3. QUANTITY DEMANDED **see attached list 'A'**
(Give particulars of special location or mode of use)

4. QUANTITY RECEIVED: (In volume form or other suitable unit)

- (a) Single lot demand: **see attached list 'A'**
- (b) Next Month
- (c) Second Month
- (d) Third Month

5. JUSTIFICATION: (Detail this information on back of Form). **see separate sheet**

6. SOURCES OF SUPPLY (if known). Give particulars:

- (a) Has material been located? **Yes**
- (b) Is locally - **Italy** **Spolettificio S.A. Via Fiorentina 1000**
- (c) Is elsewhere in liberated Italy (including Sicily & Sardinia) - **Yes**
- (d) If blocked, give name of establishment and Military Unit concerned, quantities available, etc.: **N.A.**

7. ADDRESS FOR DELIVERY: **To be removed by -**

Origin: **Industrie Chimiche Selenitiche**
Address: **Rome**

Large Order No. 5274

8. It is certified that ticks supplied and stored are required for **(insert name of person or persons)** (Provide this name with application).

Date: 5 May 45 Signature: **Robbison Not Re**

(c) Second Month
(d) Third Month

3. IDENTIFICATION: (Detail this information on back of form). **see separate sheet**

6. SOURCE OF MATERIAL (if known). Give particulars:

(a) Has material been located? **Yes**

(b) If locally - Where? **Spolettificio S.S. Via Flaminia Roma**

(c) If anywhere in liberated Italy (including Sicily & Sardinia) - Where?

(d) If located, give name of establishment and Military Unit concerned, quantities available, etc.: **N.A.**

7. ADDRESS FOR DELIVERY: **To be removed by -**

Commissaire: **Industrie Chausse-Restonard**

Address: **Reunite**

Large Order ID 5274

8. It is certified that these supplies and stores are required for (URGENT) **RE**
(~~any other~~) purpose. (Strike out words not applicable).

Date: **5 MAR 43** Signature: **Bob [unclear] RE**
Sark, Pella, Giffon.

9. MEDICAL APPROVAL: _____ Date: _____

FOR USE OF LOCAL RESOURCES OFFICE (Complete Sub-Organization).

ATLANTA Release Order No. _____ Date: _____

_____ Date: _____

REMARKS:

FORM NO. 10

List 'A'

<u>Description</u>	<u>Quantity</u>	<u>Unit</u>
Filo nero IC/IO	3.000	mt.
" " I2/IO	3.800	"
" " I3/IO	2.200	"
" " 20/IO	250	"
" " 25/IO	1.500	"
" " 28/IO	800	"
Cavo sottopieno 3x20/IO	250	"
" " 3x25/IO	200	"
Interuttori e cristallo	120	n.
" Siemens Pacco completi di manovre	50	"
Scatole 26x18x7	3	"
" 8 x 5	30	"
" per interruttori innozzo	40	"
Morsetti a sentello	500	"
Pulsante crista I2/I5	550	"
" " I4/I7	900	"
" " I6/20	670	"
Cavo sottopieno Ix23/IO	103	"
Rifletto R.L.M.	187	"
Portalampe ottone	215	"
Capicorda alluminio 150 mm	70	"
" " 200 mm	130	"
Scatole bakelite 2 fori	22	"
" " 4 "	70	"
" " 4 "	40	"
Interruttori bak. etagni	60	"
Cassette O & C.6	4	"
Lamelle flessibili argentone	150	"
Caffette p.tubo bergmann	148	"
Morsetti unipolari da 6 bak.	500	"
Valvole a Maniglia p. quadro IOCA	17	"
" " 50A	9	"
" " 30A	9	"
Contatori vario superaggio	22	"
Viti a legno grosse	5	"
Chiodi	15	"
Interruttori su base erdesis 3x20	1	"
" " 3x200	1	"
Manicotti assortiti p.tubo Bergmann	500	"
Valvola Automatica Saus 5. IC.20.30A	30	"
Interruttori tripolari Saus 35A	20	"
Contatori per volt	15	"

5272

Catenacci diversi per chiusura porte e finestre	n.	125
Serrature da infilare	"	47
Ribattini ferro essertiti pacchi	"	43
Cernieri ferro varie pacchi	"	25
" " " "	"	17
" " " "	"	28
" " " "	"	9
Serrature da infilare	"	37
Cerniere varie pacchi	"	17
" " " "	"	26
" " " "	"	17
5 cassette con chiodi sciolti essertiti	"	185
n.80 pacchi da 5 kg. chiodi (100 x 20)	"	400
n.22 pacchi da 5 kg. chiodi essertiti	"	110
n.1 gabbie con un serbatoio a pressione per verniciatura a spruzzo	"	I
n.1 gabbia idem c.e.	"	I
Valvole Jenkins in bronzo da 1/4"	"	21
idem inelastate da 1/4"	"	4
" Jenkins in bronzo da 1"	"	38
" I 1/2"	"	15
" I 1/4"	"	18
" 2"	"	20
" 3"	"	10
Stagno vergine - in pani da kg. 25 circa - pani	"	I

5271

5271

This material is urgently required for construction work at the Italian Combat Force Reinforcement Centre, CHSANO.

This centre is beginning to train recruits now and it is requested that the material be released forthwith so that the barracks may be put into a fit state to accommodate the numbers involved.

5 Mar 45

M.H.I.A.

5270

HEADQUARTERS
ALLIED CONTROL COMMISSION
COMMERCE SUB-COMMISSION
L20 376

Date: 5 March

1. QUANTITY FOR CONVERSION MATERIALS.
2. NAME/ADDRESS: **MMIA on behalf of Italian Ministry of War**
3. COMMODITY IDENTIFIER: **see attached List 'A'**
(Give particulars of specification on back of form)
4. QUANTITY REQUIRED: (In metric tons or other suitable unit)
 - (a) Single lot demand: **see attached List 'A'**
 - (b) Next Month
 - (c) Second Month
 - (d) Third Month

5. JUSTIFICATION: (Detail this information on back of form). **see separate sheet**

6. SOURCES OF SUPPLY (if known). Give particulars:

- (a) Are National Stock Loosers? **Yes**
- (b) If locally - Where? **Spolettificio L. S. Via Flaminia ROMA**
- (c) If elsewhere in liberated Italy (including Sicily & Sardinia) - Where?

(d) If blocked, give names of establishment and Military Unit concerned
quantities available, etc.: **U.S.A.**

7. ADDRESS FOR DELIVERY: **To be removed by -**

Commissions: **Industria Chimica Nazionale**
Address: **Rome**

Large Order No: **ROME 5269**

8. It is certified that these supplies and stores are required for (SUBJECT),
(Priority) ~~essential~~ purpose. (Strike out words not applicable).

Signature: **Robt. ... Maj. R.E. M.M.A.**

- (c) Second Month
- (d) Third Month

5. JUSTIFICATION: (Obtain this information on back of Form). **see separate sheet**

6. SOURCES OF SUPPLY (if known). Give particulars:

- (a) Has material been located? **Yes**
- (b) If locally - Where? **Spectificio S.B. Via Flaminia ROMA**
- (c) If anywhere in Liberated Italy (including Sicily & Sardinia) - Where? **---**
- (d) If hidden, give names of establishment and Military Unit concerned, quantities available, etc.: **U.S.A.**

7. ADDRESS FOR DELIVERY: **To be removed by -**

Company: **Industria Chimiche Nazionali**
Address: **Rennite**

Largo Ghigi 19 ROMA 5269

8. It is certified that these supplies and stores are required for (ARMY), (NAVY), (AIR FORCE), (MARINE CORPS), (COAST GUARD) purposes. (Strike out words not applicable).

Date: **5 Mar 45** Signature: **Robert Maj DE** (Stamp: **MMMA**)
Rank, Title, Office: **Major, Staff, Officer.**

9. OFFICIAL APPROVAL: _____ Title _____ Date _____

FOR USE OF LOCAL BUSINESS SECTION (Complete and Submit).

AMERICAN BUSINESS ORDER NO. _____ Our Business Order No. _____

Date _____ Date _____

REMARKS:

Released under record
Ultra Secret
MAICNR

List 'A'

Description	Quantity
Filo nero 10/10	3,000
" " 12/10	3,800
" " 18/10	2,200
" " 20/10	250
" " 25/10	1,500
" " 28/10	800
Cavo sottopiembo 3x20/10	250
" " 3x25/10	200
Interruttori e crimallo	120
" " Cinesse Pecco completi di ricambio	50
Scatole 25x18x7	3
" " 6 x 5	30
" " per interruttori in uso	40
Morsetti a metallo	500
Faloxite smista 12/18	550
" " 14/17	900
" " 16/20	670
Cavo sottopiembo 1x23/10	103
Rifletto R.L.M.	187
Sortelampade ottone	215
Capicorda alluminio 150 mm	70
" " 200 mm	130
Scatole bakelite 2 fori	22
" " " 4 "	70
Interruttori bak. stagni	40
Cassette C E C.6	60
Lucelle fusibili argentine	4
Caffette p.tubo bergmann	150
Morsetti anipolieri da 6 bak.	148
Vaivole a Maniglia p. quadro 100A	500
" " 50A	17
" " 30A	9
Contattori vario esperaggio	9
Viti a legno grosse	22
Chiodi	5
Interruttori su base ardesia 3x20	15
" " 3x200	1
Manicotti assicurati p.tubo Bergmann	1
Vaivole Automatiche Zema 5.10.20.30A	500
Interruttori tripolari 300 350	30
Cs' anodi per p.r.a	20
" "	15

5268

Palumbo
Palumbo
 AC 2538
 7 mas.
 DC
 AC P-16
 Form. P-16
 10
 P-16

5268

Palafitta braga 12/15	150
" " 14/17	900
" " 15/20	670
Cavo sottopiombo 1x23/10	103
Rifletto R.L.M.	187
Portalsapsa ottone	215
Capicorda alluminio 150 mm	70
" " 200 mm	130
Sostole bakelite 2 fcri	22
" " " 4 "	70
" " " " "	40
Interruttori bak. stagni	60
Cassette O.E.C.6	4
Lamelle fusibili ergonous	150
Cassette p.tubo bergmann	148
Morsetti bipolari da 6 bak.	500
Valvole e Maniglia p. quadro 100A	17
" " 50A	9
" " 30A	9
Contatori vario amperaggio	22
Viti a legno grosse	5
Chiodi	15
Interruttori in base ardemia 1x20	1
" " 3x200	1
Manicotti assortiti p.tubo Bergmann	500
Valvola Automatica Zeu. S.I.C.20.304	30
Interrattori tripolari Zeu. 35+	20
Cas'naoci per porta	15
" " "	16
Viti ferro a legno 5x35	28
" " assortiti	44
" " " "	31
" " " "	19
" " " "	45
" " " "	66
" " assortiti	29
Congegni di chiusura finestre:	
tipo patent pacchi	11
" Alfa	14
" A.T.	5

2558
4 man.
10
10
10
10

Catensoci diversi per chiusura porte e finestre	n.	125
Serrature da infilare	"	47
Ribattini ferro assortiti pacchi	"	43
Cernieri ferro varie pacchi	"	25
"	"	17
"	"	28
"	"	9
"	"	37
"	"	17
"	"	26
"	"	17
5 cassette con chiodi sciolti assortiti	"	185
n. 20 pacchi da 5 kg. chiodi (100 x 20)	"	400
n. 22 pacchi da 5 kg. chiodi assortiti	"	110
n. 1 gabbia con un serbatoio a pressione per verniciatura a spruzzo	"	1
n. 1 gabbia Icam C.S.	"	1
Valvole Jenkins in bronzo da 1/4"	"	21
idem inclinate da 1 1/4"	"	4
" Jenkins in bronzo da 1"	"	30
" I 1/2"	"	15
" I 1/4"	"	18
" 2"	"	20
" 3"	"	10
Stagno varcine - in pani da kg. 25 circa - pacchi	"	1

520766

14

Work on Progress at Engineer Training Centre, Italian Coast: Marco, Biscaglia,

6 March 45.

1. Units. The disbanded 152 and 162 Artillery Bays arrived at MARCELLINO on 1 March 45 unloading the total of supplies in the barracks to approximately 400. Five parties have been formed (numbered 1 - 5), each party consisting of 25 men for training.
 2. Training. Up to 5 March 45, the only training which has been done by Bailey consisting with a small party of some 40 men. This squad has been used to prepare the training area and also act as guides when in a vain attempt to find suitable Italian Officer Instructors.
 3. Equipment. Equipment is coming slowly in. The main deficiencies at the moment are:
 - Water supply equipment.
 - Heavy mines. A J Tanker is now towing forward areas.
 - Tool kits. A number of tools have been obtained from Italian sources.
 - 3 Bailey Gilligan boats.
 4. Italian Instructors. Not one suitable Italian Officer Instructor has yet come to light. ~~Not~~ Junior Engineer officers at MARCELLINO show no technical knowledge, keenness or interest. They appear quite deficient in the normal attributes of an officer.
 - Quite a number of suitable MO's have been found and with the increased British Staff, the training of recruits should be satisfactorily carried out.
 - Good Instructors are also required for Italian Pioneer Training and the schools will at a later date require 'top notch' Engineer Instructors.
 5. British Instructors. The MS understood to be approved for the British Instructors include:

COPI	1
Surgeons	4
Officers	4
Privates	1
- The fourth sergeant, the clerk and storemen are still omitted.
- It is understood that approval has been given to have 1 Officer, extra MO's and 10 men stationed to assist initial training. This party is being berthed.
- There has been little opportunity to

2.5.5

5266

Under the...
many lines. A 3 Towner is now touring forward areas.
Tool kits. A number of tools have been obtained
from Italian sources.
J Bailey College Louis.

4. Italian instructors. Not one suitable Italian Officer
instructor has yet come to light. ~~Not~~ Junior Engineer officers at BRINDISI
show no technical knowledge, however or interest. They appear quite deficient
in the normal attributes of an officer.

Quite a number of suitable NCO's have been found and with the
increased British staff, the training of recruits should be satisfactorily
carried out.

Good instructors are also required for Italian Pioneer training
and the British will at a later date require 'top notch' Engineer instructors.

5. British instructors. The 75 understood to be approved for the
British Document include :-

Quail	1
Sergeant	4
Clerks	1
Stewards	1

5266

The fourth sergeant, the clerk and steward are still untried.
It is understood that approval has been given to have 1 Officer,
extra NCO's and 10 men attached to assist initial training. This party is
being hastened.

6. Situation of recruits. There has been little opportunity to
study the new intake, but the first impression is that they are strong,
hardworking, quick to learn and amenable to discipline. When properly trained,
they will not fall far short of the British soldier.

7. Training. A week's weapon training at BRINDISI has been added
to two 2 weeks Malheur (including Ammunition Water Supply), 2 weeks Elementary
Demolition and Signalling and 2 weeks Bailey and improvised bridging. Parties
1, 2 and 3 have commenced training (one at Brindisi, one on bridging and one
on weapon training). It is intended to start off party No 4 on Signalling on
March 12, party No 5 on March 19 etc.

Approved programmes for the 7 weeks training are now being
prepared.

8. BRINDISI Barracks. Work on accommodation is proceeding at an
increased rate, but there is still much to be done.

...../8.

- (a) Full Water supply is guaranteed by 15 March 45.
- (b) Shower Baths and and some wash benches are now in operation.
- (c) Latrines have been improved, but are not yet fly-proof.
- (d) The Contractor cannot get glass for Barrack windows.
- (e) Beds are still awaited.
- (f) The kitchens are not yet operating.

Jeff Wheeler

Major ME.
SOME,
BTI RTO ICF.

JCB/rav

Distribution.

Commander 'P' HIB RTO ICF.
AMHQ (Engineer Section)
EMIA (For attention SOME)
Commander RTO ICF.
Commander RTO BRACCIANO
D.M.F. (via 64)

5264

5265

13

U R G E N T

Subject:- Material for work on Barracks at CESANO

Land Forces Sub Comm A.C. (MMIA)
 RE II/2
7 Mar 45

APLRS ROME

Reference conversation Braham - Copleston.
 Enclosed is a list of material urgently required for repair and reconstruction of Italian army barracks at CESANO.

These barracks are occupied by the Italian Combat Force Reinforcement Training Centre and it is considered imperative that the work on the barracks is no longer delayed, in order that training may proceed unhampered.

The materials required are to be found in the Spolettificio R.E., Via Flaminia, Rome: other relevant details are to be found on Form MAT-10 enclosed.

It is requested that an immediate release be granted in this case.

[Handwritten Signature]
 526
 Maj Gen

Land Forces Sub Comm A.C. (MMIA)

gsh

U R G E N TSubject:- Release of Materials.Land Forces Sub Commission A.C.
(M.M.I.A.)
RE/11/26 MAR 45
-----Commerce Sub Commission.

Reference conversation MACKENZIE - COLESTON.

Attached are forms MAT 10 requesting the release of material urgently required for work at the Reinforcement Training Centre, Italian Combat Force, CREANG.

It is requested that these stores be made the subject of an emergency release, as the contractors are not able to continue work without them. It is regretted that correct release action was not taken earlier.

Major General.
M. M. I. A.

5263

REGULATIONS
ARMED SERVICES COMMISSION
WARREN SUP-COMMISSION
AFM 284

Date: 5 March

- 1. MEANS FOR COMMERCE: ITALY
- 2. AS/ASO SPAIN ASIA on behalf of Italian Ministry of War
- 3. QUANTITY UNLIMITED SEE ATTACHED LIST 'A'
(Give particulars of specification on back of form)
- 4. QUANTITY REQUIRED: (In metric tons or other suitable unit)
(a) Single lot ASIA SEE ATTACHED LIST 'A'
(b) Next Month _____
(c) Second Month _____
(d) Third Month _____

- 5. JUSTIFICATION: (Detail this information on back of form). SEE SEPARATE SHEET
- 6. SOURCE OF SUPPLY (If known). Give particulars:
(a) Has material been located? YES
(b) If locally - Where? SPOLITTOLE S.S. VIA PIETOLA 2003
(c) If known in liberated Italy (including Sicily & Calabria) - Where? _____
(d) If known, give name of establishment and military unit concerned, quantities available, etc.: _____

7. ADDRESS FOR DELIVERY: TO BE RETURNED BY -

Countryside: INDUSTRIE CHIMICHE FOSCOMA
 Address: ROMA
201262

8. It is certified that these supplies and stores are required for (US/ASO),
 (AS/ASO) purposes. (Strike out words not applicable).
 Date: 5 MAR 45 Signature: Robert May Jr

(1) Date Recd _____
(2) Secord Month _____
(3) Third Month _____

5. JUSTIFICATION: (Detail this information on back of Form). see separate sheet

6. SOURCES OF SUPPLY (if known). Give particulars:

- (a) Has material been located? **Yes**
- (b) If locally - Where? **Spolettificio P.B. Via Flaminia ROMA**
- (c) If anywhere in liberated Italy (including Sicily & Sardinia) - Where? **_____**
- (d) If known, give names of establishments and Military Unit concerned, quantities available, etc.:

To be removed by -

7. ADDRESS FOR DELIVERY:

Comptroller: **Industria Mineraria Nazionale**
Basilite
Address: **Largo Galpi 19 5262**

8. It is certified that those supplies and stores are required for (purpose),
(specify purpose). (Strike out words not applicable).

Date: **5 Mar 45** Signature: **Robert May Jr**
Rank, Title, Office.

9. REGIONAL APPROVAL _____ Title _____ Date _____
 FOR USE OF LOCAL RESOURCES SECTION (Domestic Sub-Commission).
 AREA(S) Release Order No _____ Date Release Order No _____
 Date _____

REMARKS:

List 'A'

<u>Description</u>	<u>Quantity</u>
Filo nero 10/10	3.000
" " 12/10	3.800
" " 13/10	2.200
" " 20/10	250
" " 25/10	1.500
" " 28/10	800
Cavo sottopiembo 3x20/10	250
" " 3x25/10	200
Interuttori a cristallo	120
" Siemens Pace completi di manovre	50
Boutole 26x18x7	3
" 8 x 5	30
" per interruttori incasso	40
Morsetti a mentelle	500
Falaxite armata 12/15	550
" " 14/17	900
" " 16/20	670
Cavo sottopiembo 1x23/10	103
Rifletto R.L.M.	187
Portalampede ottano	215
Cappicorda alluminio 150 mm	70
" " 200 mm	130
Scatole bakelite 2 fori	22
" " 4 "	70
Interruttori bak. stagni	40
Cassette 0 E C.6	60
Lamelle fusibili argenteo	4
Caffette p. tubo bergmann	150
Morsetti unipolari da 6 bak.	148
Valvole a Keniglia p. quadro 100A	500
" " 50A	17
" " 30A	9
Contatori vario impiego	9
Viti a legno grosse	22
Chiodi	5
Interruttori su base ardesia 1x20	15
" " 1x200	1
Mancetti assestati p. tubo Bergmann	1
Valvola Automatica Zeas 5.1C.2C.30A	300
Interruttori tripolari Zeas 15A	30
Cabineggi per porte	20
	15

Catenucci diversi per chiudere porte e finestre	n.	125
Serrature da infilare	"	47
Ribattini ferro assortiti pacchi	"	43
Cernieri ferro varie pacchi	"	25
"	"	17
"	"	28
"	"	9
"	"	37
"	"	17
"	"	26
"	"	17
"	"	185
"	"	400
"	"	110
"	"	I
"	"	I
"	"	21
"	"	4
"	"	38
"	"	15
"	"	18
"	"	20
"	"	10
"	"	I

5 cassette con chiodi scelti assortiti
n.80 pacchi da 5 kg. chiodi (100 x 20)
n.22 pacchi da 5 kg. chiodi assortiti
n.1 gabbia con un serbatoio a pressione per
verniciatura a spruzzo
n.1 gabbia idem c.s.
Valvole Jenkins in bronzo da 3/4"
idem inclinate da 1 1/4"
" Jenkins in bronzo da 1"
" I 1/2"
" I 1/4"
" 2"
" 1"

Stagno vergine - in pani da Kg. 25 circa - pani

5259

5260

2

This material is urgently required for construction work at the Italian Combat Force Reinforcement Centre, OSSARO.

This centre is beginning to train recruits now and it is requested that the material be released forthwith so that the barracks may be put into a fit state to accommodate the numbers involved.

5 Mar 45

N.M.I.A.

5259

UNCLASSIFIED
NATIONAL DEFENSE AGENCY
COMMERCE SUB-COMMISSION
APO 294

Date: 5 APR 45

- 1. DEMAND FOR QUANTIFIED MATERIALS.
- 2. SIG/ACC INFORMATION: None on behalf of Italian Ministry of War
- 3. COMMODITY IDENTIFIED: 1200 meters of fabric
(Give particular of composition, weight, etc.)
- 4. QUANTITY REQUIRED: (In metric tons or other suitable unit)
(a) Single lot desired: 1200 meters
(b) First Month: _____
(c) Second Month: _____
(d) Third Month: _____

- 5. JURISDICTION: (Detail this information on back of Form).
- 6. SOURCE OF OFFER (if known). Give particulars:
(a) Has material been located? No
(b) If locally - Where? _____
(c) If anywhere in liberated Italy (including Sicily & Sardinia) - Where? _____
(d) If blocked, give names of establishment and Military Unit concerned, quantities available, etc.:

7. ADDRESS FOR DELIVERY:

Originator: Industria Chimica Nazionale
Address: Rome

8. It is certified that these supplies and stores are required for (URGENT), (MATERIAL), (STOCK-PILING) purpose. (Strike out words not applicable).
Date: 5 Apr 45
Signature: Asst. Dir. Maj.
5258

- (b) Host Name: _____
- (c) Second Name: _____
- (d) Third Name: _____

5. **SUBJECTS:** (Detail this information on back of form).
6. **WORDS OF INTEREST (if known).** Give particulars:
- (a) Has material been located? **NO**
 - (b) If locally - Where? _____
 - (c) If anywhere in liberated Italy (including Sicily & Sardinia) - Where? _____
 - (d) If known, give names of establishment and Military Unit concerned, quantities available, etc.?

7. **ADDRESS FOR DELIVERY:**

Country: Lausztio-Christophe Casierelli

Address: Reunite

_____ Large Chigi St - 4-448

8. It is certified that these supplies and stores are required for (USUR), (ACR), (SAC-FIN) purposes. (Strike out words not applicable). **5258**

Date: 5 Mar 45 Signature: Roseph ...

_____ Gen, Milan, Officer.

9. **NATIONAL AGENCY:** _____ Date: _____

_____ OFFICE OF LOCAL RESOURCES SERVICE (Commonwealth Commission).

APR(1) Release Order No: _____ Date: _____

_____ Order No

_____ Date

REMARKS:

Material Recommended

1800 metres copper wire 4-5 mm dia.
for electric overhead distribution system

Qualification

Acquired for urgent work at ~~XXXXXX~~. ~~XXXXXX~~ ~~XXXXXX~~ ~~XXXXXX~~
Maintenance Training Centre DUBLIN.

REQUISITION
NEEDS CONTROL COMMISSION
COMMERCE DEPT-COLUMBIA
AG 374

Date: 5 March 45

- 1. QUANT FOR COMBUSTIBLE MATERIALS.
- 2. MS/ACC SITUATION WIA on behalf of Italian Ministry of War
- 3. COMBUSTIBLE REQUIRED 1000 metric tons of heavy oil
(Give percentage of supply if known of each)
- 4. QUANTITY REQUIRED: (In metric tons or other suitable unit)
 - (a) Single lot amount: 1000 metric tons
 - (b) First month
 - (c) Second month
 - (d) Third month

- 5. JUSTIFICATION: (Insert this information on back of form).
- 6. SOURCE OF SUPPLY (if known). Give particulars:
 - (a) Has material been located? No
 - (b) If locally - Where?
 - (c) If available in liberated Italy (including Sicily & Sardinia) - Where?

(d) If blocked, give names of establishments and Military Unit concerned, quantities available, etc.

7. ADDRESS FOR DELIVERY:

Consignee: Industria Chimica Italiana
 Remite
 Address: _____

8. It is certified that these supplies and stores are required for (insert),
 (insert) naval purposes. (Strike out words not applicable).
 Date: 5 Nov 45
 Signature: R. O. Hunt - mg

(a) Second Month
(b) Third Month

- 5. JUSTIFICATION: (Detail this information on back of form).
- 6. SOURCE OF SUPPLY (if known). Give particulars:
 - (a) Was material from occupied? **No**
 - (b) Is locally - Where?
 - (c) Is anywhere in liberated Italy (including Sicily & Sardinia) - Where?
 - (d) If located, give name of establishment and Military Unit concerned, quantities available, etc.:

7. ADDRESS FOR DELIVERY:

Originator: Industria Chimica Nazionale

Address: Reverite

Large Chigi 22 ROME

8. It is certified that these supplies and stores are required for (URGENT), ~~essential~~ purposes. (Strike out words not applicable).

Date: 5 Nov 45 Signature: R. S. Pleck - mg Date: 5257

Title: Asst. Dir., Office

9. ORIGINAL RECEIPT

FOR USE OF LOCAL RESOURCES SECTION (Common Use-Certification)

ARR(1)'s Release Order No. _____ Our Release Order No. _____

Date _____ Date _____

REMARKS:

Form 100-101 36, 40

Material Required

2250 metres copper wire 4-5 mm diam.
for electric overhead distribution system

Qualification

Required for original work of ~~engineer~~ Italian Coastal Force
Narcissus Training Centre 00160.

SOCIETA' ANONIMA

INDUSTRIE CARICHE ELETTRICHE

ROMA - LARGO GHIGI 12 - ROMA
Tel. ~~06-681595~~ - 681595

Bartoloni

, 15 febbraio 1945.

Spett.le
M.M.I.A.
Via Veneto

R O M A

SC/ob

OGGETTO: domanda di sblocco per materiale vario di ns. proprietà esistente nei magazzini dello Spoletificio R.C. di Via Flaminia.

La nostra consorella "Imprese Generale Costruzioni - Ing. Giuseppe Cornetto" deve eseguire nelle zone industriale di Cesena di Roma lavori varf per l'alloggiamento e la sistemazione dei servizi del Gruppo addestramento al Combattimento delle Divisione Piceno.

I lavori di cui sopra comprendono tra l'altro anche l'esecuzione degli impianti elettrici e delle rete idrica di distribuzione acqua, per questi impianti che hanno carattere di estremo urgenza, chiediamo lo sblocco del materiale sottelencto, da prelevarsi fra quello di nostra proprietà esistente nei magazzini dello Spoletificio R.C. di Via Flaminia, materiali attualmente bloccati dalla Sottocommissione per il Commercio:

Numero d'ord. dei colli.	Numero contrassegno dei sigle ecc.	NATURA DEL MATERIALE	Unità di misura	Quantità

SC/eb

Spett.le
M.M.I.A.
Via Veneto
R O M A

OGGETTO: domanda di sblocco per materiale varlo di ns. proprietà esistente nei magazzini dello Spoletificio R.E. di Via Flaminio.

Le nostre consorelle "Impresa Generale Costruzioni - Ing. Giuseppe Cornetto" deve eseguire nella zona Industriale di Ceseno di Roma lavori varf per l'alloggiamento e la sistemazione dei servizi del Gruppo eddestramento al Combattimento dello Divisione Piceno.

I lavori di cui sopra comprendono tre l'altro anche l'esecuzione degli impianti elettrici e della rete ldrica di distribuzione acque; per questi impianti che hanno carattere di estremo urgenza, chiediamo lo sblocco del materiale sott-elencato, da prelevarsi fro quello di nostro proprietà esistente nei magazzini dello Spoletificio R.E. di Via Flaminio, materiali attualmente bloccati dalla Sottocommissione per il Commercio.

Numero d'ord. dei sigle ecc.	Numero contressegno	NATURA DEL MATERIALE	Unità di misura	Quantità si Netto
no 83		Filo nero 10/10	mt.	3.000
" "		" " 12/10	"	3.800
" "		" " 18/10	"	2.200
" "		" " 20/10	"	250

segue lettera del 15/2/45
Spett.le M.M.I.A.
R O M A

Numero d'ord. del coll	Numero contressigno ecc.	NATURA DEL MATERIALE	Unità di misura	Quantità al Netto.
n° 83		Filo nero 25/10	mt.	3.500
"		" " 28/10	"	800
" 115		Cavo sottopiombo 3X20/10	"	250
"		" " 3X25/10	"	200
" 103		Interruttori e cristallo	n.	120
112/113	134	" Siemens Pecco completi di manovre	"	50
"	154	Scatole 26 x 18 x 7	"	3
"	"	" 8 x 5	"	30
"	134	" per interruttori in- cesso	"	40
"	133	Morsetti a mantello	"	500
n° 91		Fulxite ermaf 12/15	"	550
" 90		" " 14/17	"	900
" 89		" " 16/20	"	670
" 115		Cavo sottopiombo 1 x 23/10	"	103
" 86		Riflettori R.L.M.	"	187
"	131	Portalampade ottone	"	215
"	107	Capicorde alluminio 150 mm.	"	70
"	104	" " 200 "	"	130
"	129	Scatole bakelite 2 fori	"	22
"	"	" " " 4 "	"	70
"	130A	Interruttori bak.stegni	"	40
"	130A	Cassette C E C.6	"	60
"	152	Lamelle fusibili argentone	"	4
"	156	Coffette p.tubo bergmann	"	150
"	133	Morsetti unipolari da 6 bak.	"	148
"	135	Valvole a Maniglia p.quadro 100A.	"	500
"	"	Valvole a Maniglia p.quadro 50 A.	"	9
"	"	Valvole a Maniglia p.quadro	"	9

5256

no	descrizione	mt.	valore
83	Filo nero 25/10	"	1.500
"	" 28/10	"	800
115	Cavo sottopiombo 3X20/10	"	250
"	" 3X25/10	"	200
103	Interruttori e cristallo	n.	120
112/113	" Siemens Pacco completi di manovra	"	50
"	Scatole 26 x 18 x 7	"	3
"	" 8 x 5	"	30
"	" per Interruttori in-casso	"	40
133	Morsetti a mantello	"	500
"	Fuloxite armate 12/15	"	550
"	" 14/17	"	900
"	" 16/20	"	670
"	Cavo sottopiombo 1 x 23/10	"	103
"	Riflettori R.L.M.	"	187
131	Portalampade ottone	"	215
107	Capicorde alluminio 150 mm.	"	70
104	" 200 "	"	130
129	Scatole bakelite 2 fori	"	22
"	" " 4 "	"	70
130A	Interruttori bak.stegni	"	40
"	Cassette C E C.6	"	60
"	Lemelle fusibili argentone	"	4
152	Coffette p.tubo bergmann	"	150
156	Morsetti unipolari da 6 bak.	"	148
133	Valvole a Maniglia p.quadro 100A.	"	500
135	Valvole a Maniglia p.quadro 50 A.	"	9
"	Valvole a Maniglia p.quadro 30 A.	"	9
136	Contatori vario amperaggio	"	522
"	Viti a legno grosse	"	15

5256

segue lettera del 15/2/45
Spett. le M.M.I.A.
R O M A

Numero d'ord. dei colli	Numero controsse- gno al- gio ecc.	MATURA DEL MATERIALE	Unità di misura	Quantità al Netto
n° 76	Mollettiere	Chiodi Interruttori su base erde- sio 3 x 20	Kg.	15
" 77		Interruttori su base erde- sio 3 x 200 Manicotti assortiti p.tubo Bergmann	n.	1
	cosse n.130 A	Valvole Automatiche Zeus 5.10.20.30 A.	"	500
	" "	Interruttori tripolari Zeus - 35 A.	"	30
n° 39	cosse	Catenacci per porta	"	20
" 40	n. 143	" " "	n.	15
" 43	" 144	" " "	"	16
" 44	" 1	Viti ferro e legno 5x35	gros.	28
" 45	" 2	Viti ferro e legno assort.	"	44
" 46	" 3	" " "	"	33
" 47	" 4	" " "	"	19
" 48	" 5	" " "	"	45
" 49	" 6	" " "	"	66
" 50	" 7	" " " ossforite"	"	29
	" 151	Congegni di chiusura fine stre: tipo patent pacchi	"	11
" 51	" 120	" Alfo "	n.	14
" 52	" 118	" Al. "	"	5
" 53	" 125	Catenacci diversi per chiusure porte e finestre Serretture da infilare Ribattini ferro assortiti pacchi	"	125
" 54	" 116	Catenacci ferro assortiti pacchi	"	47
" 55	" 117	Catenacci ferro assortiti pacchi	"	43

n°	collettore	Chiodi	Kg.	15
76		Interruttori su base ordesio 3 x 20	n.	1
77		Interruttori su base ordesio 2 x 200	"	1
		Manicotti assortiti p. tubo Bergmann	"	500
	casse n. 130 A	Valvole Automatiche Zeus 5.10.20.30 A.	"	30
	" "	Interruttori tripolari Zeus - 35 A.	"	20
39	casse n. 143	Catenacci per porta	n.	15
40	" n. 144	" " "	"	16
43	" 1	Viti ferro a legno 5x35	gros.	28
44	" 2	Viti ferro a legno assort.	"	44
45	" 3	" " "	"	33
46	" 4	" " "	"	19
47	" 5	" " "	"	45
48	" 6	" " "	"	66
49	" 7	" " assortite	"	29
50	" 151	Congegni di chiusura fine strefi	"	
		tipo patent piccoli	n.	11
		" Alfa "	"	14
		" Al. "	"	5
51	" 120	Catenacci diversi per chiusure porte e finestre	"	125
52	" 118	Serrature da infilare	"	47
53	" 125	Ribattini ferro assortiti pacchi	"	43
54	" 116	Cerniere ferro varie peccchi	"	25
55	" 155	" " "	"	17
56	" 112	" " "	"	5298
57	" 117	Serrature da infilare	"	37
				1.

segue lettera del 15/2/45
Spett.le M.M.I.A.
R.O.M.A

Numero d'ord. del coll.	Numero controsigillo ecc.	NATURA DEL MATERIALE	Unità di misura	Quantità al netto.
n° 58	caso 113	Cerniere varie pacchi	n.	17
" 59	" 114	" "	"	26
" 60	" 111	" "	"	17
dai n. 1 al n. 5		5 cassette con chiodi scelti assortiti	"	185
n° 6		n.80 pacchi da 5 Kg. chiodi (100 x 20)	"	400
n° 7		n.22 pacchi da 5 Kg. chiodi assortiti	"	110
n° 8	M.T.4	n.1 gabbia con un serbatoio e pressione per verniciatura e spruzzo	"	1
n° 9	6	n.1 gabbia Idem c.s.	"	1
n° 48	caso s.n.	Valvole Jenkins in bronzo da 3/4"	"	21
		idem inclinate da 1 1/4"	"	4
		" Jenkins in bronzo da 1"	"	38
		Idem 1 1/2"	"	15
		" 1 1/4"	"	18
		" 2"	"	20
		" 3"	"	10
n°138		Stegno vergine - in pentole da Kg. 26 circa - pentole	"	1

Nelle speranze che l'autorizzazione richiesta ci venga concessa con l'urgenza imposte dai lavori in corso, distintamente saluti.

n°	cosse	Cerniere varie peccchi	n.	17
n° 58	"	"	"	26
n° 59	"	"	"	17
n° 60	"	"	"	185
del n. 1 al n. 5		5 cassette con chiodi sciolti assortiti	"	400
n° 6		n. 80 peccchi da 5 Kg. chiodi (100 x 20)	"	110
n° 7		n. 22 peccchi da 5 Kg. chiodi assortiti	"	1
n° 8	M.T. 4	n. 1 gabbia con un serbatoio a pressione per verniciatura a spruzzo	"	1
n° 9	6	n. 1 gabbia Idem c.s.	"	21
n° 48	cosse s.n.	Valvole Jenkins in bronzo da 3/4"	"	4
		idem inclinate da 1 1/4"	"	38
		" Jenkins in bronzo da 1"	"	15
		idem 1 1/2"	"	18
		" 1 1/4"	"	20
		" 2"	"	10
		" 3"	"	1
n° 138		Stagno vergine - in peni da Kg, 26 circa - peni	"	

Nelle speranze che l'autorizzazione richiesta ci venga concessa con l'urgenza imposta dai lavori in corso, distintamente saluti.

SOCIETA' ANONIMA
INDUSTRIE CHIMICHE NAZIONALI RIUNITE
25 Via Garibaldi
Montecatini (Pisa)

5254
Y. Borelli

B

This material is urgently required for construction work at the Italian Combat Force Reinforcement Centre, OMBANO.

This centre is beginning to train recruits now and it is requested that the material be released forthwith so that the barracks may be put into a fit state to accommodate the numbers involved.

5 Mar 45

N.M.I.A.

Handwritten signature or initials

10
14

SUBJECT: Instra for Engr School BRACIANO

DIRECTORATE OF MILITARY TRAINING
AFHQ, CMC

Tel: 11667

DBT/60/6/MT1

1 Mar 45.

HQ MSHA

6

Reference BTU/A10/10 dated 26 Feb 45.

This Directorate's view is that not more than one instructor from each Group should be diverted to the RTC and then only after consultation with the Group concerned.

However if trained rfts are to be provided for the Groups they must be prepared to assist by surrendering experienced instructors to the RTC.

H. W. Felt
Major
Brig.,
D.M.T.

DBT/bs

5252

a

Subject: Provision of Italian Instructors
at HQU IGF.

Land Forces Sub Comd A.C.
(M.H.I.A.)
M/11/2
2 MAR 45

NOGR 50 BLU
" 51 "
" 52 "
" 53 "

~~sent~~
Copy to: HYS HQ IGF (your ALQ/10 of 26 Feb refered)

1. There is a pressing need for suitable and competent Italian instructors, both officers and NCOs, for the Engineer School, BRACCIANO.
2. Although the most suitable men would probably be those who have already completed a course at the S.M.R.S., it is realised that these men are still required for assisting in the training of the units they are in now.
3. If, after taking up this question with the Engr SQ Cadre, you find any men who can be spared now and are considered suitable for employment as instructors, please forward details to this H.Q. so that action may be taken to get them transferred.

RBC Pluton
maj

S. O. B. E.
M. H. I. A.

520

8

URGENT

Subject:- Work at GERANO - RTG ICF.

Land Forces Sub Commission AD

(M.H.I.A.)

22/11/52

2

MAR 45

MINISTRY OF DEF.

Dir. Gen. del Genio.

Societa Italiana Industrie Chimiche Nazionali Riunite, now engaged on work at the RTG ICF, has requested this H.Q. to obtain 1200 metres of electric cable 4 - 5 mm diameter in order to put in order the electric power distribution line.

You are requested to give every assistance in this respect as this line is required urgently.

Robert
79

for Major General.
M. H. I. A.

copy to: A/Q 86

5250

5250

SUBJECT :- Instrs for Engr School BRACCIANO.

6 11/2

British Training Unit HQ ICF.
c/o Land Forces Sub Com
AC (M&IA) RCMN.
Ref BTU/A10/10

26 Feb 45.

Land Forces Sub Com AC (M&IA) ROME. ✓

DMT.

1. The following Italian offrs and NCO's did well on a recent Engr Course at CAPUA :-

(a) From CREMONA GP.

Serg Magg IMPERO. L.
Cap Magg D'ELLA. E.
Serg BRUSSOU P.

RE
7/12

(b) From TRIULI

Ten VIDOSSI.
S. Ten MANSOLI.
Serg. LUCCHETTI.

(c) From MANTUA.

S. Ten FERRARI.
Serg Magg MARONI.
Serg LA FRANCO

(d) From PULCORE.

Serg Magg ANCHISI.
Cap. PROVANNI.

2. May arrangements please be made to have as many as possible of the above posted to the Engr School at BRACCIANO as instrs.

AVG/rw

5249
Alfainelli
Col.
British Training Unit.

5

RB 11/2

Special Section

Ref (a) of attached letter. Copies of two of the pamphlets concerned are attached.

Both these pamphlets are long-sided and contain information that is not essential for training rifts.

The scale of issue of these pamphlets to the British Army is generally (excepting RE) officers only.

It is suggested that it would be a waste of time and effort to translate these in toto, and it is for consideration whether the preparation of some posters showing commoner types of weapon slit, obstacle etc. would not be of more value.

I have no copy of REF No. 47 'Mechanized Movement by Road'. I always understood this to be of interest mainly to unit comdros and above but extracts might be translated for transport HQs, drivers etc.

REC
57

SECRET
CONFIDENTIAL

28 Feb 55

The scale of issue of these pamphlets to the British Army is generally (excepting RA) officers only.

It is suggested that it would be a waste of time and effort to translate these in toto, and it is for consideration whether the preparation of some posters showing various types of weapon slit, obstacle etc. would not be of more value.

I have no copy of MIF No. 47 'weakened movement by road'. I always understood this to be of interest mainly to unit commanders and above but extracts might be translated for transport HQs, drivers etc.

28 Feb 45

Rec

SQRS
MIA

5248

4

Land Forces Sub Comm A.C. (MMIA)
EE II/2
12 Feb 45

SCORE
BLU RTO ICF

- 1. Herewith an advance copy of AFHQ Eng Sec Poster No. 4. No other copies available at present.
- 2. Also enclosed is a copy of BILBY BR Special Uses for your retention.

RLR

gsh

SCORE
Land Forces Sub Comm A.C. (MMIA)

5247

ENGINEER SECTION (BR)
A.F.H.Q.
C.M.F.
Tel. No.: FREEDOM 335

1173

SUBJECT : Training Posters
TO : M.M.I.A., C.M.F.

ENG/1202
15 Feb 45

Herewith one advance copy of AFHQ Engineer Section Poster No.4,
for information.

J.R.M. KWEN,
Captain, R.E.,
for M.G.R.E.

Encl: As stated

5246

Subject:- Trg Eqpmt - Rfts Trg Centre, I.C.F.

Land Forces Sub Comm A.C. (MMIA)
RE II/2
15 Feb 45

Director of Military Training,
AFHQ

Ref your DMT/88/6/I/MTI of 29 Jan 45.

The items detailed in your memo of above reference have been released and removed to Engr Trg Centre, Rft Trg Centre, ICF, with the following exceptions:-

Plain Wire	- Not available locally in Italian Depots - obtained through Engr channels.
Nails assorted	- 6" only available. Remainder obtained as above.
Pliers	- 3 No only. Sufficient to commence trg.
Wire Cutters	- These have still to be obtained. Believed to exist at BARI.
Timber	- Not available
Gabions	- Will be moved when required.
Compasses	- Not available.

RB Spenser
to

Land Forces Sub Comm A.C. (MMIA)

SUBJECT: Trg Eqpmt - Rft Trg Centre, Italian Combat Forces.

DIRECTORATE OF MILITARY TRAINING
A.P.H.Q., C.M.F.

Tel : 11656

RE.

Y/V

DMT/83/6/1/MT.1

Lead Forces Sub Commission (MCLA) C.M.F.

29 Jan 45

Copy to : Engr Sec AFHQ (your ENG/815 of 19 Jan refers).
Rft Trg Centre, Italian Combat Forces.

1. The undermentioned eqpt is required for Engr Trg purposes at the Rft Trg Centre, Italian Combat Forces.
2. It is understood from Engr Sec AFHQ that these items can be supplied from Italian resources.
3. May arrangements please be made for the release of this eqpt to Rft Trg Centre, Italian Combat Forces, as soon as ever possible.

Axes Pick	25	✓
Shovels R.E.	25	✓
Pickets Long	100	✓
" Short	200	✓
Barbed Wire	320 kg	✓
Plain Wire	15 kg	NA
Nails Assorted	30 kg	- bin only
Hammer	10	✓
Pliers	10	- 3 only
Wire Cutters	5	- NA
Hand Axes	5	✓
Timber 4"x3" x 12'	50	lengths - NA
" 9"x2" x 12'	100	" - NA
Sandbags	300	✓
Gabions	50	- not reqd
Compasses	5	

5244

RY/AS

[Signature]
Brig.,
D.M.T.

| 1 9 2 |