

10000/20/3952

ACC

10000/20/3952

4161D

4/G/RR1011



Dec. 1945 - July 1946

25
Subject:- Baley Bridge- Ciamon B 241063

4.B.L.H.

4/3/2D-25

17 July 46.

To:- 83 AREA (For 77 C.A.E. works).

Ref. your #/19 of 16 April 1946.

Herewith attached are translations of replies from "PRINLI "

Engineers and from Territorial Headquarters.

2346

E. J. Bralley

E. J. BRALLEY

MAJOR INTELKS

(for Lt. Col. GS.)

Translation

4 Mil Terr Comd of Bolzano

Ref: 01/3838/OP/E.3

Bolzano 14 July 46

Subject:-Bailey bridge on Cismon(locality 3241065)

To:- 4 EBU

Ref your 4/6/PD-21 dated 24 April 46 and further to our 01/3510/OP dated 20 June.

The Road Maintenance Office of Venice has informed us that the s/m bridge cannot be lifted for lack of suitable timber.

Nevertheless the construction of the permanent bridge will be carried out just the same.

By Order of the
Chief of General Staff
Col. Duranti

2345



IV COMANDO MILITARE TERRITORIALE DI BOLZANO

Stato Maggiore - Sez. Operazioni e Addestramento

N. 01/3839/OP/E.3. di prot.

Bolzano, li 14 luglio 1946

Allegati N.

OGGETTO: Ponte Bailey sul Cismon(località 3241065).-

AL COMANDO IV° B.L.U.

S E D E

- Riferimento n.4/G/FD-21 del 24 aprile c.a. ed a seguito n.01/3510/OP. del 20 giugno us.-
- L'Ufficio viabilità stradale di Venezia ha comunicato che, per mancanza di legname adatto, non può effettuare il sollevamento del ponte in oggetto.-
- Ciononostante la gittata del ponte permanente verrà egualmente effettuata.-

d'Ordine

IL CAPO DI STATO MAGGIORE 2344
(Col. Enrico Duranti)

- registrato
- formulato
- est. D. Magli V

416/FD-23

Translation / Ls

MILITARY TERRITORIAL COMMAND POLZANO (IV)
G.S. - Operation and Training Office

Ref. M/3340/CE/2.3

Polzano, 20 June 46

SUBJECT: Bailey Bridge over Cismon (locality B 241065)
TO : L. S.L.M. POLZANO.

Your letter 416/FD-21 dtd. 24 April curr. to Div. FAIOLI Comd.
and via 2407/Op dated 8 May curr.

Copy of a report of the Commander of the mixed Engineers Bty.
of Div. FAIOLI concerning the lifting of the s/w bridge.

Information will be given when the work will be completed.

HEAD OF GENERAL STAFF
(Col. Enrico Duranti)
sgd.???

2343

C O P Y

Translation / LG

Infantry Division "PARIUT"
Engineers Battalion Command

Ref. 4465/1

Belgrade, 11 June 1946.

SUBJECT: RAILWAY BRIDGE OVER RISSAN.

TO : "PARIUT" Div. Comd.
Operation Office
L E V I C O .

Letter 2407/Op. of 8 May comm. of that Command refers.

On 15 May comm. I personally -- in contact with HQB 86 Area LAMTID -- arose among the possible solutions the most convenient one as regards the availability of specially needed material.

At the end of the conference the s/m Command aimed for a period of eight days in order to be able to assign what is necessary.

On 26 May the metal parts were delivered; however, the s/m Command was not able to supply the necessary timber for temporary supports and moreover assigned two lifting-beams which needed repair.

As agreed, the timber was given to the management of the Civil Engineers ("State of the Roads" Section 34334/0)

As soon as this timber will be ready (at the least in two weeks at best) this Command will transport it with the proper means to the place of work.

The work of lifting will be finished within two days.

2342

those along the possible solutions the best convenient one as regards the availability of specially needed material.

At the end of the conference the a/m Command asked for a period of eight days in order to be able to assign what is necessary.

On 28 May the metal parts were delivered; however, the a/m Command was not able to supply the necessary timber for temporary supports and moreover assigned the lifting-jacks which needed repair.

As agreed, the timber was given to the management of the Civil Engineers ("State of the Roads" Section BASSANO)

As soon as this timber will be ready (at the least in two weeks at best) this Command will transfer it with the proper means to the place of work.

The task of lifting will be finished within two days. 2342

HEAD OF THE SERVICE
Lt. Col. L. Senja.

COMMANDER MILITARY BATTALION
Maj. Lt. Col. G. Marchetti.

SE/ma

COMANDO MILITARE TERRITORIALE DI BOZZANO (IV)
S.M. - Sezione Operazioni e Addestramento

4/55/11

N. 01/3510/OP/E.3 di prot.

Bozzano, 11 20 Giugno 1946

O G G E T T O : Ponte Bailey sul Tisone (località B 241065).

AL COMANDO 4° B.L.U.

S E D E

- Riferimento foglio n.4/G/FD-21 in data 24 aprile c.a. di co-desto B.L.U., diretto al Comando Div. "Friuli" ed a seguito foglio n.2407/Op in data 3 maggio c.a. del Com.Div. "Friuli".
- Si trasmette copia di una relazione compilata dal comandante del btg. misto genio della Div. "Friuli", relativa al sollevamento del ponte in oggetto.
- Riserva di comunicazioni a lavoro ultimato.

d'ordine

CAPO DI STATO MAGGIORE
(Col. Enrico Duranti)

2341



*registri
transferta
mag*

C O P I A

DIVISIONE DI FANTERIA "FRIULI"
Comando Battaglione M. Genio

N. 4465/2 di prot.

OGGETTO: Ponte Bailey sul Ciamon.-

AL COMANDO DIVISIONE DI FANTERIA "FRIULI"
Sezione Operazioni

Levico, li 11 giugno 1945

LEVICO

Riferimento foglio N. 2407/Op dell'8 maggio u.s. di codesto Comando.

Personalmente, in data 15 maggio u.s. presi contatto con l'HQRE 35^ Area in Mestre e tra le possibili soluzioni venne scelta quella più conveniente in relazione alla disponibilità di materiali specie lì occorrenti.

Detto Comando mi richiese a conclusione della conversazione otto giorni di tempo per poter conseguire quanto necessario.


In data 23 maggio venne effettuato il prelevamento delle parti metalliche; detto comando non fu in grado però di approvvigionare il legname occorrente per i sostegni provvisori ed inoltre consegnò due martinelli (jack) che avevano bisogno di riparazione.

Il legname, come da ulteriori accordi, verrà fornito dalla Direzione del Genio Civile competente (Sezione della viabilità di Bassano).

Alpenz detto legname sarà pronto (nel caso favorevole almeno fra due settimane) questo Comando ne effettuerà con i propri mezzi il trasporto e più d'opera.

Il lavoro del sollevamento verrà, da detto momento, portato a termine entro un paio di giorni.

IL COMANDANTE IL ETS. GENIO
F.to Ten. Col. G. Marchetti



2340

Più conveniente in relazione alla disponibilità di materiali speciali occorrenti.

Detto Comando mi richiede a conclusione della conversazione otto giorni di tempo per poter consegnare quanto necessario.


In data 28 maggio venne effettuato il prelievo delle parti metalliche; detto comando non fu in grado però di approvvisionare il legname occorrente per i sostegni provvisori ed inoltre consegnò due martineelli (jack) che avevano bisogno di riparazione.

Il legname, come da ulteriori accordi, verrà fornito dalla Direzione del Genio Civile competente (Sezione della viabilità di Basano).

Appena detto legname sarà pronto (nel caso favorevole almeno fra due settimane) questo Comando ne effettuerà con i propri mezzi il trasporto a più d'opera.

Il lavoro del sollevamento verrà, da detto momento, portato a termine entro un paio di giorni.

AL COMANDANTE IL BTG. GENIO
f/to Ten. Col. G. Marchetti



2340

Proc./Esp.

9 May.

COMANDO
DIVISIONE DI FANTERIA "TRIULI"
Ufficio del Capo di Stato Maggiore
Sezione Operazioni

4/G/FD-22

Levico, 8 maggio 1943

Oggetto: ponte Bailey sul Cismon.

B O I L A N O

AL COMANDO IVED.I.E.

e, per conoscenza:

AL GENIO MILITARE TERRITORIALE IV° BOLZANO

AL COMANDO GENIO DIVISIONE "TRIULI" LEVICO

Riferimento foglio n. 4/G/FD-21 del 24 aprile u.s. (allegato in copia per il compilatore di Bolzano e per il comando genio divisionale).

I lavori di riattamento del ponte Bailey sul Cismon sono stati ultimati fin dal 27 aprile u.s.

Non fu però provveduto al suo ulteriore sollevamento di un metro.

Tale operazione, in accordo con la direzione del genio civile competente, potrà essere compiuta dalle dipendenti unità del genio; in proposito il comando genio prenderà diretti accordi anche con il HQ RE 86^a Area per la assegnazione di quei mezzi necessari che si rendessero necessari.

Sarà cura di questo comando segnalare inizio ed ultimazione dei lavori stessi.



d'ordine
IL TEN. COL. CAPO DI S.M.
- G. Verando -

18/5/43

2222

Riferimento foglio n. 4/G/7D-21 del 24 aprile U.S. (Allegato in copia per il comilitar di Bolzano e per il comando Genio divisionale).

I lavori di riattamento del ponte Bailey sul Cismon sono stati ultimati fin dal 27 aprile U.S.

Non fu però provveduto al suo ulteriore sollevamento di un metro.

Tale operazione, in accordo con la direzione del genio civile competente, potrà essere compiuta dalle dipendenti unità del genio; in proposito il comando genio prenderà direttive speciali anche con il HQ RE 86 Area per la esecuzione di quei materiali che si rendessero necessari.

Sarà cura di questo comando segnalare inizio ed ultimazione dei lavori stessi.



d'ordine
IL TEN. COL. CAPO DI S.M.
- G. Verando -

14/5/46

2339

The work of reconstructing the Bailey Bridge on Cismon was finished 27 Apr 46. The bridge has not been raised 1 meter. This work can be done by the dependant units of Engineers with the assistance of the Division of Civil Engineering and by contacting HQ RE 86 Area for the purpose of obtaining release of necessary materials. This HQ. will inform you when this work commences + when completed.

21

Subject: - GISSON Bridge

Headquarters
4 B.L.U.
B o l z a n o
Ref.: 4/G/ED-21

24 April 1946

To: - Hq. Fifth Div

Herewith copy of Hq K3 86 area letter W/19 of 16 Apr 1946
forwarded to you for information and possible action.

Please inform this Hq if your engineers are able to carry
out the work outlined in a/q letter.

[Signature]
Lt Col
GS

2338

nie

4/G/FD-20

Subject :- Bailey br over the CISON
at B 241068

HQ RE 86 Area
 C M F
 Ref :- W/19
16 April 1946

4 BLU, FRIULI DIV, BOLZANO

13 Apr 46

Stores were recently issued to the FRIULI Div in order that the false decking of the Bailey at CISON could be renewed.

USVS have now requested that the bridge be raised one metre in order that they can start rebuilding the original bridge underneath.

Could you please inform us if the Engineers of the Friuli Div would be prepared to carry out this work. If you are prepared to do this work any stores you may not have available will be issued from our our Stores Dump at MESTRE.

*Copy to
 Comd
 report from
 1st Div
 1st Div
 1st Div
 1st Div*

Re: Fast ants

Major RE ACRE,
 for Lt-Col RE,
 Comdr,
 77 CRE Works.

2337

Subject: Repairs to Bridge over CISON.

19
Headquarters
4 B L U
BOLZANO
Ref: 4/G/ED-19
26 Mar 46

To: HO FRIULI INF DIV

Reference your 5116/OP dated 28 Dec 45
herewith release note for stores required to effect above
repairs.

1. In order to carry out the necessary repairs
the following stores are released to H^o FRIULI Inf. Div. from
15 Stores Sec RE, MESTRE.

12 no. Bailey br. cheases.
1300 ft super 3" timber (approx. 9 cu. metres).
100 lb. 6 in. nails.

This is sufficient to replace cheases as
necessary and to lay 2 no. 1 metre wide strips of skin deck-
ing for the whole length of the brs. and ramps.

2. In addition to replace missing panel pins
the following stores are also released

8 no. panel pins.
140 4" nails (in lieu of center pins).
2 sledge hammers.
4 chord jacks.

The sledge hammers and chord jacks should
be returned on completion of the job.

3. Please inform this HQ when the above works
have been completed.

2336
Major
for Lt Col

GS

Subject :- Bailey Br. App. Ref. E 245070.

HQ RE 86 Area
C M F
Ref :- 7/19
21 MAR 46.

4/9/ED

18

HQ 4 BUL BOLZANO.

Copy to :- RE (Ops) Main 13 Corps (Yr 513/RE(0) of 13 Mar 46
RE (Wks) Rear 13 Corps.

28 hrs.

Ref your 4/6/ED 17 of 8 Mar 46 to 296 Works Sec RE.

1. A record of the above mentioned Bailey has shown that the skin-docking has been worn away and will require completely replacing and that though the chasses are also worn only a few require replacing.
2. The bridge consists of 2 No. 30' DS Baileys in series with 10 ft ramps and a short 5 ft length of improvised docking joining the ramps between the two bridges.
3. In order to carry out the necessary repairs the following stores are released to HQ PRINLI Inf. Div. from 15 Stores Sec RE, MASTRE.
12 no. Bailey br. chasses.
1300 ft super 3" timber (approx. 9 cu. metres).
100 lb. 6 in. nails.

This is sufficient to replace chasses as necessary and to lay 2 no. 1 metre wide strips of skin docking for the whole length of the brs. and ramps.

4. In addition to replace missing panel pins the following stores are also released

8 no. panel pins.
140 4" nails (in lieu of cotter pins).
2 sledge hammers.
4 chord jacks.

The sledge hammers and chord jacks should be returned on completion of the job.

5. Please inform this HQ when the above works have been completed.

Major RE AGRE,
for Lt-Col RE,
Comdr,
77 CRE Works.

2335

*Forward
the release are
13 Formals + 1601
3, 4 + 5 of 1601
LH 22.*

Ref 488 ants.

Subject: Bridge over the CISON

To: 296 Works Section RE
BOLOGNA.

Headquarters
4 BLU BOLZANO
Ref 4/C/PD-17
Mar 8 '46 17

Ref your 541 dated 21 Feb '46 herewith reply, received from 4 Military Territorial Command BOLZANO forwarded for information and such action as you consider necessary.

It would be appreciated if the ~~information~~ in this HQ letter of even reference dated 5 Feb. '46 may now be made available,

[Signature]
Lt. Col.
G.S.

2334

4 M.L. Stern HQ Bolga.

4/9/50

Ref 04/2327/Ser.



1/3/46 16

Subject: Bridge over the Gwaman

To: 4 B.K.V.

Ref. — of Feb. 27/46. - 15

The French Div. who are able to assume maintenance of the above bridge, have signalled that in their opinion the material requested as per their Ref. 5116/OT of 28th Dec. is necessary for making this bridge serviceable again & not for lengthening it.

2333

4/6/52.

COMANDO MILITARE TERRITORIALE DI BOLZANO (IV)
Stato Maggiore = Ufficio Servizi

AND/F

n.04/2327/Serv.

BOLZANO

1/3/1946

Oggetto: ponte sul Cison.

AL 4° B L U

S E D E

~~~~~

Rif. f° s.n. del 27 febbraio u.s.

Il comando divisione Friuli che può assumere la manutenzione del ponte in oggetto, ha segnalato che - a suo avviso - il materiale richiesto con f° n.5116/Op. del 28 dicembre s. e. è necessario per la rimessa in efficienza del ponte e non per il suo allungamento.



d'ordine

STATO MAGGIORE  
Enrico Duranti

2332

Oggetto: Ponte Gisson

HQ 4 L.L.U. 15

UNIA

B o l z a n o

27.2.1946.

Al Comando Militare Terr.

Ufficio Servizi

B o l z a n o .

In riferimento alla lettera 610/OP del 28.  
Gen. 46 del Com. Div. Friuli, unisco copia della lettera ricevuta dal 296 Works Section RE.-

Prego voler dare una risposta tramite questo comando.-

Captain

DAAR OMG.

2331

Oggetto: Riparazioni al Ponte Cismon  
MR B 244 0

296 Works Section RI  
B o l o g n a  
21.5.1946.

Ref.: 541

Al Comando 4 B.I.D.  
B o l z a n o .

In riferimento alla vostra 4/G/F D13 in data 7.Feb.  
46 al HQ 217 ARKA.

Un incaricato di questo Reparto ha ispezionato il  
Ponte Tipo Bailey al MR 6244070 e suggerisce di in-  
caricare della manutenzione la Div. Friuli.

Dall' ammontare dei materiali richiesti, sembra che  
abbiate intenzione di allungarlo, si prega di in-  
formarne questo ufficio, addurendo le ragioni.

Capt. RE.

2330

4/G/FD

14

Subject:- Repairs to CISON Bridge  
MR B244070

25 Feb 46

296 Works Section RE  
BOLOGNA

Ref:- 541

21 Feb 46

To:- HQ 4 BLU. /  
POLZANO

Reference your 4/G/FD-13 dated 7 Feb 46  
to HQ 217 Area.

A representative from this Unit has  
inspected the Bailey Bridge at MR B244070 and it  
is suggested the FRIULI Div carry out the necessary  
maintenance.

By the amount of stores asked for it  
seems you wish to lengthen the bridge, if so,  
please inform this office giving reasons.

  
A/DORE 296 Works Section RE

Capt RE

Copy to: HQ 217 Area

2329

H. A. 3110,  
Ref. A/Q/ED -13  
5 Feb 1946.

13

Subject. Repairs to bridge over the Glimon B24401

217 Area  
Major Derbyshire for G.A.S.

Reference to H. letter of even reference dated 3 Jan to 217 Area only.  
It is pointed out that the bridge in question is now considered dangerous.  
Labour is available (manpower) in of the 217th Italian Infantry Division.  
Can materials be made available or is work to be carried out by British arrangements.

12/

0 0 11

Copy Translation (for information Major Derbyshire)

Subject. Repairs to bridge over the Glimon.

H. 21101 Inf Div  
Ref. 3116/ed di prot  
Luvino. 14 73  
28 Jan 45

10 4 1110

Examination of the Bailey Bridge over the Glimon, about 1 mile from Glimon (which is in urgent need of repair) showed that the following materials are essential for repairing the bridge in safety.

40 Planks for Bailey bridge

2328

Cold Circulation ( for information Major Verityshire)

H, Verity Div  
Ref. 3116/07 dt prot  
Service. 24 72  
23 Dec 45

Subject. Repairs to bridge over the Clifton.

To H. 4 UU

Inspection of the Bailey bridge over the Clifton, about 1 mile from Clifton (which is in urgent need of repair) proved that the following materials are essential for repairing the bridge in relatively

40 planks for Bailey bridge  
200 cubic metres of 3 on planks  
4 jacks for Bailey with handles  
3 bolts for Bailey panel  
2 sledge hammers  
3 kilob of 7 on nails  
140 cotter pins for Bailey bolts

2328

We inform you of the above as this H. would like to arrange the necessary repairs. If the above mentioned material may be made available to this H., repairs will be carried out by our Engineering Unit.

It is pointed that the repairs are of an urgent nature.

Signed. J. Verando Lt. Col.  
Chief of Staff.

4/9/F) 10

SERVIZIO TELEFONICO MILITARE

N. 2916 (213-A) del Catal  
(R. 1911 - Anno XIX)

## FONOGRAMMA

N. \_\_\_\_\_ da \_\_\_\_\_ il \_\_\_\_\_

da 4° B.L.U.

a Comando Div. Friuli

4/G/F)-8

Riferimento fono 136 O.P. data 7 Gennaio  
com. di cotesto comando alt confermo  
che anche depositi C.E.M. sono passati  
at dipendenze 4 Comiliter

Maj FENN

Trasmette

Riceve

Rivisto (\*)

Il Telefonista

(\*) Dal fattorio o dall'appuntato

2327

4/9/59 9

SERVIZIO TELEFONICO MILITARE

N. 1910 (213-A) del Catal.  
(R. 1911 - 1919 X1X)

## FONOGRAMMA

N. \_\_\_\_\_ di \_\_\_\_\_ il \_\_\_\_\_ ore \_\_\_\_\_

Da emanando Finelli Luvino  
 al 4° blu Bolzano  
 N° 126/CP. Rif. vostro foglio 4/G./E.D. & data 8  
 conurb. Sugasi precisare se anche gestione depositi  
 b.e.m. est pensato al 4° conurb. et se di  
 conurb. dovevano più esser inviati e questo  
 blu. att

Direttore Bartamaggion  
 Finelli

Trasmette  
biaini on 2040Riceve  
Bartamaggion 8-1-46

Il Esclusivo

Il Esclusivo

2326

Ricevuto (3)

(C) Dal fattidino o dall'appurato.

Subject: Change of Command

Non-Confidential

4 A. 1. 1.

RECEIVED

Ref: 47, FD-7

3 Jan 66

To: HQ WEST Inf Div

4 Territorial Command

1. At 2000 hours 31 Dec 65 operational command of WEST Inf Div passed to Italian Government i.e. to 4 Territorial Command.

2. All future communications and orders will be direct between HQ WEST Inf Div and Territorial Command.

26/1

2325

Subject: Repairs to bridge over the Cison.

1- Headquarters

4- B.L.H.

100-11-10

Ref: 4/8/79 - 6

3 Jan 45

To: HQ 217 Area  
HQ 60 sub area

Attached herewith is a copy of a letter received from PRULI Inf Div on the above subject for your info and necessary action.

*262*  
Lt Col  
68

Copy of translation.

Subject: Repairs to bridge over the Cison.

HQ PRULI Inf Div  
Ref: 5416/Op di prot  
Devico P 79  
28 Dec 45

To: HQ 4 B.L.H.

Examination of the Bailey bridge over the Cison, about 1 kilometre from OTS ON (which is in urgent need of repair) proved that the following materials are essential for repairing the bridge immediately:-

- 40 planks for Bailey bridge
- 200 cubic metres of 3 cm planks
- 4 Jacks for Bailey and handles for same.
- 8 Bolts for Bailey panel
- 2 Slotted washers for same
- 5 kilos 7 mm nails
- 140 Cotter pins for Bailey bolts

We inform you of the above as this HQ would like to arrange for necessary repairs. If the above mentioned material be allotted this HQ, repairs will be carried out by our engineers unit.

It is pointed out that the above repairs are of an urgent nature.

2324

(Signed) C. Verrado  
Lt. Col. CAPT D. S.M.

Examination of the Bailey bridge over the Clinch, about 4 miles from CIA ON (which is in urgent need of repair) proved that the following materials are essential for repairing the bridge immediately:--

40 planks for Bailey bridge  
 200 cubic metres of 3 cm planks  
 4 jacks for Bailey and handles for same.  
 8 bolts for Bailey panel  
 2 sleds for same  
 5 sleds for same  
 140 better pins for Bailey bolts

We inform you of the above as this HQ would like to arrange for necessary repairs. If the above mentioned material be allotted this HQ, repairs will be carried out by our Engineers unit.

It is pointed out that the above repairs are of an urgent nature.

2324

(Signed) G Verardo  
 Lt. Col. G. Verardo  
 Lt. Col. G. Verardo

Roc./Esp.

COMANDO DIVISIONE DI FANTERIA "F. ULI"  
Ufficio del Capo di Stato Maggiore  
Sezione Operazioni

4/9/45

n. 5116/OP di prot.

Levico - P.M. 79, 28 dicembre 1945

OGGETTO: sistemazione ponte sul Cismon



AL COMANDO 4° B.L.U.  
e, per conoscenza

BOLZANO

AL COMANDO MILITARE TERRITORIALE (IV°) BOLZANO

Da una ricognizione effettuata al ponte "bailey" sul Cismon, sito ad un Km. circa da Cismon - che ha necessit  di urgenti riparazioni,   risultato che occorrono i seguenti materiali per la sua pronta rimessa in efficienza:

- n. 40 tavole per ponte "bailey"
- mq. 200 di tavole da 3 cm.
- n. 4 cricchii per "bailey" ed aste per detti
- n. 8 perni per pannello "bailey"
- n. 2 mazzette per detti
- Kg. 5 di chiodi da cm. 7
- n. 140 coppie per perni per "bailey"

Tanto si segnala perch  codesto comando voglia cortesemente disporre per le riparazioni conseguenti.

Qualora il predetto materiale fosse assegnato a questo comando, i lavori sarebbero effettuati a cura di un dipendente reparto genio.

Si rappresenta che le riparazioni di cui sopra hanno carattere di urgenza.

Da una ricognizione effettuata al ponte "bailey" sul Cisonon, sito ad un Km. circa da Cisonon - che ha necessit  di urgenti riparazioni,   risultato che occorrono i seguenti materiali per la sua pronta rimessa in efficienza:

- n. 40 tavole per ponte "bailey"
- mq. 200 di tavole da 3 cm.
- n. 4 cricchi per "bailey" ed aste per detti
- n. 3 perni per pannello "bailey"
- n. 2 mazzette per detti
- Kg. 5 di chiodi da cm. 7
- n. 140 coppiglie per perni per "bailey"

Tanto si segnala perch  codesto comando voglia cortesemente disporre per le riparazioni conseguenti.

Qualora il predetto materiale fosse assegnato a questo comando, i lavori sarebbero effettuati a cura di un dipendente reparto genio.

Si rappresenta che le riparazioni di cui sopra  
2323  
hanno carattere di urgenza.



d'ordine  
TEN. COL. CAPO DI S.M.  
- G. Verando -

*[Handwritten signature]*

Subject:- Code Sign Documents.  
-----

HQ 2 District, CMF.  
2559 X.

4/G/FD.

4 BLU.  
-----

22 Dec 45.

Reference your 4/G/FD - 2 dated 19 Dec 45.

1. The following errors were observed in your letter:-

Column Sequence Chart Z Dec 45 Copy No 24  
should read Copy No 22.

Column Sequence Chart Z Dec 45 Copy No 28  
should read Nov 45.

2. In view of the urgency of this return and the fact that these errors were obviously due to carelessness it has been necessary to alter these figures.

3. Please ensure that these certificates are accurate in future.

2322

  
Colonel,  
Chief Signal Officer,  
No. 2 District.

WFM.

| ARMY FORM C2136 (Small)                                 |          |      | MESSAGE FORM                     |              | Register No.                             |
|---------------------------------------------------------|----------|------|----------------------------------|--------------|------------------------------------------|
| Call                                                    | Srl. No. | Prio | Transmissi                       | Instructions |                                          |
|                                                         |          |      |                                  |              |                                          |
| <b>ABOVE THIS LINE FOR SIGNALS USE ONLY</b>             |          |      |                                  |              |                                          |
| <b>FROM</b><br>(AV) 60 SUB AREA                         |          |      | <b>Originator</b><br>13 ATK REGT |              | <b>Date - Time of Origin</b><br>14/11/54 |
| <b>TO</b><br>DISTWD 217 AREA                            |          |      | <b>For Action</b><br>4 BLU ✓     |              | <b>Message Instructions</b><br>GR        |
| <b>Originator's No.</b><br>G 34 0 13 ATK REGT           |          |      |                                  |              |                                          |
| <b>THIS MESSAGE MAY BE SENT AS WRITTEN BY ANY MEANS</b> |          |      |                                  |              |                                          |
| <b>EXCEPT</b>                                           |          |      |                                  |              |                                          |
| <b>WIRELESS</b>                                         |          |      |                                  |              |                                          |
| <b>SIGNED</b>                                           |          |      |                                  |              |                                          |
| <b>ORIGINATOR'S INSTRUCTIONS</b><br>DEGREE OF PRIORITY  |          |      |                                  |              |                                          |
| <b>Time</b>                                             |          |      |                                  |              |                                          |
| <b>System</b>                                           |          |      |                                  |              |                                          |
| <b>Op.</b>                                              |          |      |                                  |              |                                          |
| <b>THI or TOR</b>                                       |          |      |                                  |              |                                          |
| <b>Time cleared</b>                                     |          |      |                                  |              |                                          |

Subject. Code Sign Documents

To: CSO 2 District

Headquarters

A. B. D. U.

MEMORANDUM

Ref: 4/C/ED - 2

19 Dec 45

Re: your letter 2559X dated 14 Dec 45.

Certificates are attached in accordance with your instructions.

*Rh*  
Lt. Col.  
C.S.

2320

*CPL Warden* *6 ref* *1/3/45*

Subject:- Code Sign Documents.

HQ 2 District, CMF.  
2559 X.

4 BLU.  
-----

14 Dec 45.

1. It is understood that you are now responsible for FRULI combat group.
2. Will you please render a certificate in duplicate showing the following documents held by FRULI Combat Group at 1 Dec 45.

Army Code Sign Book 4 Serial 9 Copy No 22  
Column Sequence charts Z Nov 45 Copy No 23  
" " " Z Dec 45 Copy No 22

3. A certificate should be rendered showing the destruction of column sequence chart Z Nov 45 Copy No 23.

4. It is essential that the certificate in respect of FOLGORE is submitted by you.

5. Will you therefore please render a certificate in duplicate showing the following documents as held by FOLGORE Combat Group at 1 Dec 45.

Army Code Sign Book 4 Serial 9 Copy No 29  
Column Sequence Chart Z Nov 45 Copy No 29  
" " " Z Dec 45 Copy No 29

and the following documents as held by you:-

Column Sequence chart Z Nov 45 Copy No 28.

6. Will you please treat the submission of these certificates as urgent.

2319

*[Signature]*  
Colonel,  
Chief Signal Officer,  
No. 2 District.

WFH.



The diagram illustrates a 1D lattice chain. A horizontal line represents the lattice, with several vertical bars indicating the positions of lattice sites. Arrows above the line show the hopping of particles between adjacent sites. One site is specifically labeled with the index 'i'.