

ACC

10000 | 120 | 3961

10000 | 120 | 3961

EME / 2

General

Dec. - July 1945

10000
120
3961

Copy: July 68

122	CAN
123	AN
145	CAN
146	AN
157	CAN
170	AN
173	AN
155	CAN

2674
2682

Folio	Date
10000	120 / 3 961
THIS FOLDER CONTAINS PAPERS FROM DEC 45 TO JULY 46 CATALOGUE.	

										<u>BROUGHT FORWARD</u>			
										FOALIO	FOALIO	TO WHOM	SIC
1	2	3	4	5	6	7	8	9	10				
11	12	13	14	15	16	17	18	19	20				
21	22	23	24	25	26	27	28	29	30				
31	32	33	34	35	36	37	38	39	40				
41	42	43	44	45	46	47	48	49	50				
51	52	53	54	55	56	57	58	59	60				
61	62	63	64	65	66	67	68	69	70				
71	72	73	74	75	76	77	78	79	80				
81	82	83	84	85	86	87	88	89	90				
91	92	93	94	95	96	97	98	99	100				
101	102	103	104	105	106	107	108	109	110				
111	112	113	114	115	116	117	118	119	120				
121	122	123	124	125	126	127	128	129	130				
131	132	133	134	135	136	137	138	139	140				
141	142	143	144	145	146	147	148	149	150				
151	152	153	154	155	156	157	158	159	160				
161	162	163	164	165	166	167	168	169	170				
171	172	173	174	175	176	177	178	179	180				
181	182	183	184	185	186	187	188	189	190				
191	192	193	194	195	196	197	198	199	200				
201	202	203	204	205	206	207	208	209	210				
211	212	213	214	215	216	217	218	219	220				
221	222	223	224	225	226	227	228	229	230				
231	232	233	234	235	236	237	238	239	240				
241	242	243	244	245	246	247	248	249	250				
251	252	253	254	255	256	257	258	259	260				
261	262	263	264	265	266	267	268	269	270				
271	272	273	274	275	276	277	278	279	280				
281	282	283	284	285	286	287	288	289	290				
291	292	293	294	295	296	297	298	299	300				
301	302	303	304	305	306	307	308	309	310				
311	312	313	314	315	316	317	318	319	320				
321	322	323	324	325	326	327	328	329	330				
331	332	333	334	335	336	337	338	339	340				
341	342	343	344	345	346	347	348	349	350				
351	352	353	354	355	356	357	358	359	360				
361	362	363	364	365	366	367	368	369	370				
371	372	373	374	375	376	377	378	379	380				
381	382	383	384	385	386	387	388	389	390				
391	392	393	394	395	396	397	398	399	400				
401	402	403	404	405	406	407	408	409	410				
411	412	413	414	415	416	417	418	419	420				
421	422	423	424	425	426	427	428	429	430				
431	432	433	434	435	436	437	438	439	440				
441	442	443	444	445	446	447	448	449	450				
451	452	453	454	455	456	457	458	459	460				
461	462	463	464	465	466	467	468	469	470				
471	472	473	474	475	476	477	478	479	480				
481	482	483	484	485	486	487	488	489	490				
491	492	493	494	495	496	497	498	499	500				

SUBJECT :- P.O.L. (G.I.P.)

126
Land Forces Sub Comm. A.C.
(M.M.I.A.) R O M B.
ME/31/163

18 July 46

DADME 12 B.L.U.
RMB 1,3,4,5,6 and 10 B.L.U.s

Reference this office Signal ME/31/45, dated 13 Apr 46.

Herewith, for information, copy of Ministry of War
letter 6c/2853/Q4/8 dated 10 July 46, addressed to G.I.P. Rome.

A. E. Mockridge, Capt.

A. E. MOCKRIDGE, Capt.
for Lt. Col.,

Assistant Director of Mechanical Engineering, MMIA.

2682

ARM/aw

87

C O P Y

TRANSLATION

From :- Ministry of War
 To :- C.I.P. Rome
 Info :- M.M.I.A.

N° 60/2853/Q4/S
 Dated 10 July 46

Arty and Mot G.D. (ref 33556/05185 of 13 June 46)

Subject :- Lubricants.

1. MMIA in agreement with Chemical Provincial Laboratory of Mantova, have pointed out, by the letters herewith attached, that the motor oils "CIP 3" issued to the dependent Units are of inferior quality and they seriously damage the efficiency of the engines of the vehicle employed.

This SMRE has often recalled your attention on this matter and now we ask you to arrange as soon as possible the issues of the types of oils under mentioned whose physico-chemical characteristics can ensure the perfect running of the engines.

2. Here under is the list of lubricants needed for the vehicles employed by the Italian Army:

Motor Oil

SAE 10

SAE 30=30 HD = OE 30 HD

SAE 50=50 HD = OE 50 HD

Gear Oil

G.600

SAE 90 spe. vv-4-761

or Hypoid

or Universal Lubricant

for gear G90=NY 2681

Grease

G.S. 1 - 4

Please keep us informed as to the actions taken on the matter.

sgd. Gen. LIUZZI

lr

118

Subject: - TRUCKS

Headquarters
4 B. L. U.
O I S B N C
Ref: 4/52/2-118

26 June 1945.

To: - O.C. 4 B. L. U.

Copy to: - ADM, H. H. H. L. A., HQS.

It is requested that a proposal be submitted to increase the A.M. of this B.L.U. to include a vehicle for the sole use of the M.S. as the present system of sharing does not allow adequate transport for the M.S. to carry out his duties successfully, especially as there is almost at all times one of the vehicles at present held, off the road either awaiting spares or repairs or is otherwise B.L.U.



Capt.
O.C. 4 B.L.U.

2680

1944

port for the 221 to carry out his duties successfully, especially as
there is almost at all times one of his vehicles at present held, off
the road either awaiting repairs or repairs or is otherwise D.L.F.

Robert

Capt.
S.C. ROBEY A. B.L.U.

2680

12/24

114

SUBJECT: P.O.L. - C.I.P. Issue

LENA SCORDE Sub Comm A.C.
(M.B.L.A.) R O L A
HR/31/123

19 June 46

D.A.D.M.B.: 12 BLU.
Miss 1934+5+6, and 10 BLU.

Further to this office signal HR/31/45 dated 13 April.

1. Samples of oils issued by C.I.P. in various territorial Commands have been analysed by 102 S.P.S.S.
2. From the report all C.I.P. No 2 oils issued are within specification limits of HD 30 oil, but in the case of D.I.P. No 3 oil it will be noted that issues made in FLORENCE, MILAN and NAPLES had low viscosity index and therefore should not be used as a substitute for HD 50 oil.
3. A sample of regenerated oil, which it is understood is widely used in the Italian Army, has also been analysed and addresses will note that this oil is not to be regarded as a suitable substitute for HD oils, and should not be used in engines or any vehicle component having highly stressed or heat generating bearing surfaces.
4. Action is being taken by this HQ with the industry of war to standardise the quality of C.I.P. oils within the specification limits of the HD lubricants for which they are issued as substitutes.

2673

should at any time the standard of C.I.P. lubricants

specification limits of HD 30 oil, but in the case of V.I.P. oil it will be noted that issues made in PICHENNE, ILAN and ZAFLE had low viscosity index and therefore should not be used as a substitute for HD 50 oil.

3. A sample of regenerated oil, which it is understood is widely used in the Italian Army, has also been analyzed and addressees will note that this oil is not to be regarded as a suitable substitute for ED oils, and should not be used in engines of any vehicle component having highly stressed or heat generating bearing surfaces.

4. Action is being taken by this HQ with the industry of our CO to standardize the quality of C.I.P. oils within the specification limits of the ED lubricants for which they are issued as substitutes.

5. Should at any time the standard of C.I.P. lubricants issued be questionable and facilities exist locally, it is requested that addressees arrange to have the lubricant analysed and forward a copy of the analysis report to this office.

6. A copy of the list of specification for certain ED lubricants is forwarded for information.

Dehookridge

Copy.
for Lt. Col. ADAM.

87

ALTERNATE SPECIFICATIONS

	ID 10	ID 30	ID 50	(Nature of oil 90% Mineral 10% Additives.)
Viscosity Kinematic at 130 °F Cgt at 210 °F Cst	18.2-25.2	39.8-55.0	19.5-21.6	15.6 - 18.0
Viscosity Index	85	55	75	85
Flash Point open Cup °F Min	360	390	400	-
Pour Pt. °F Max	-10	0	+15	-
Pour Pt. after dil., with 20% of Petrol Naptha °F Max	-10	-10	-	-
Corrosion Cu. Strip 3 hours at 212 °F	Poss	Poss	Poss	-
Corrosion Cu Strip 1 hour at 212 °F	-	-	-	Req
1 hour at 300 °F	-	-	-	Poss
Stability Test 96 hrs at 300 °F				2673
(1) Viscosity Increase % Max	-	-	-	200
(2) Insolbl Matter % Max	-	-	-	0.5
(3) Evaporation loss % Max	-	-	-	10.0

80a

REF: 4 2117
Ref. 4/22/2/30 L

15 April 1946.

To: CDR HQ Fifth Infantry Div.

Director of Repairs Bolzano Territorial Command.

Copy of message received from MIA is forwarded to you for information and necessary action.

Message.

10/30 u/c (...) Books 406, 402 and tank system instructions handbook in Italian are now with the Minister of War and should soon be available from computers. Please inform Italian units concerned.

A. White.

Capt.

2677

30 RECS 4 RIU.

77

CONFIDENTIAL
RMC 4 B.L.U.
Ref 4/15/2/77

8 April 1946

Subject: - Replacement of
Inefficient Officers

To: - O.C. 4 B.L.U.

Lt/Col SCOTTI

- 1.) The above named officer commanding the 4th Repair Sec W/S of the Territorial Command is considered quite unsuitable to fulfill this position successfully, as he lacks power of command, is a poor example as regards discipline (he is often unkempt and generally unshaven) and has little idea on W/S organisation.
- 2.) He also has a mania for attempting to keep the whole of his W/S under lock and key although guards are available.
- 3.) This mania is preventing the S/Shop becoming properly organised; this was pointed out to him but he stated he was responsible for any item lost although under a proper guard, and would therefore not trust guards.
- 4.) This statement was checked with Gen. MARSHALL and as expected was found to be untrue.
- 5.) It is considered that Col SCOTTI was aware that he was being untruthful.
- 6.) Further it is extremely difficult to work with this officer as he is evasive in his answers.
- 7.) It should, it is felt, be added that this officer was at one time the CMC of the Friuli Inf Bty but was posted on an adverse report by the British Army officer of the BAF attached (Capt Stocker) who found Col SCOTTI to be both untruthful and inefficient.
- 8.) In view of the above it is suggested that this officer should be replaced as soon as possible.

2676

(White)

- 3.) This mania is preventing the W/Shop becoming properly organized; this was pointed out to him but he stated he was responsible for any item lost although under a proper guard, and would therefore not trust guards.
- 4.) This statement was checked with Gen. NERSONI and as expected was found to be untrue.
- 5.) It is considered that Col SCOTTI was aware that he was being untruthful.
- 6.) Further, it is extremely difficult to work with this officer as he is evasive in his answers.
- 7.) It should, it is felt, be added that this officer was at one time the CMC of the Friuli Inf Div but was posted on an adverse report by the British RECON officer of the IAD attached (Capt Stecker) who found Col SCOTTI to be both untruthful and inefficient.
- 8.) In view of the above it is suggested that this officer should be replaced as soon as possible.

2676

White

Capt. SO RECON.

subject :- MEMO's etc.

76
Land Forces Sub Comm, A.C.
(M.M.I.A.) ROMA.

MB/13

2 April. 46.

MEMO's. 1, 3, 4, 6, 10, 12 BLU's.

It has been ruled that MEMO's, CIRCULARS, Modification Circulars, etc will NOT be issued or lent to the Italian Army through B L U channels though there is no objection to vehicle maintenance manuals, catalogues, and workshop manuals being made available to them.

MEMO's etc will be "screened" at this office and extracts passed to the Ministry of War (copy to MEMO's) for distribution to the Italian units concerned.

MEMO's will continue to be distributed to BLU's for the use of MEMO's there.

AB/can.

A. Blunt

Lt. Col.

A.D.M.S.

M.M.I.A.

2675

Subject. Repair of Allied Vehicles.

Headquarters
4 B.L.U.
Ref: 4/B/13 - 3
23 Dec 45

SO RME 4 BLU

Herewith copy of MIA letter EME/1545 of 15 Dec 45 for your information.

Pl. Sec.
Lt. Col.
G.S.

Copy

Subject. Repair of Allied Vehicles.

Land Forces Sub Commission A.C.
(M.M.I.A.) ROME
EME/1545.
15 Dec 45.

To: Dir Gen Artig
Motorizzazione
Ministry of War.

28685

With reference to your letter 024380 of 10 Dec 45, it is agreed that it is most important that the workshops at BOLOGNA should start to repair Allied vehicles from the Infantry Divisions as soon as possible.

It will be necessary to form an Inefficient Vehicles Park in that neighbourhood to which vehicles beyond 2nd echelon repair by the Divisional Workshops can be evacuated. It is understood that Budrio has been suggested as a site for this park, and it is strongly recommended that you urge the formation of this park with all speed, so that, in particular, the vehicles from the Folgore Division which are beyond their repair, may be evacuated there. The idea of leaving these vehicles at Trento when the Folgore Workshops move is strongly deprecated.

It is agreed that 6th Repair Unit is a suitable name for the unit which must carry out repair to vehicles of Italian manufacture in the Bologna Command, and it is suggested that the workshop for repair of Allied vehicles should be called "Italian Base Workshop".

(Signed) xxxxxxxxxxx

Lt. Col.
A.D.M.E.

Land Forces Sub Commission AC (MIA)

Copy to: 4 BLU
Internal: Q
G(SD)

2674

| 0 5 6 4 |