

785020

ACC

10000112014281

71

785020

10000112014281

71

Tpt British

1st Cover

Aug. 3, 1946 JAN 1, 1947

3299
3323

Q S A

Declassified E.O. 13065 Section 3-402/NHIC NO.

785020

PRO - FORMS.

LIST OF VEHICLES HELD BY BRITISH IN JAPAN.

No. Vehicle Type. Reg No. Engine No. Contract No. Chassis No. Efficient Local Repair. Beyond Local Repair.

1. Ford 1 ton truck. N.5665179. C.P. 79013. V. 9013.	No Record.	B.	--	--	--	--	--	--
2. Willys. 1 ton 4x4. 5636671. 630652.	30789.	B.	--	--	--	--	--	--
3. Dodge. 3 tons. 432. 5669315. T.110/1/50420.	9111813.	B.	--	--	--	--	--	--
4. 15.1 ton. L/H. 432. N.11090699. No Record.	3.1145.	Not B.	--	--	--	--	--	--
5. B.C. 1.500.00. C.1131573. 27200.	V.11.20. - 35227.	Not B.	--	--	--	--	--	--

Certify that the above vehicles are held on charge, that their condition is as stated, and that AM12, 2
and found correct.

1st January.

Signed



785020

P.D. - FORMS.

REPAIR OR REPAIRS, X. HEDD DZ 2 URGENT LINCOLN UNIT.

C.C.

C.C.

No.	Contract No.	Chassis No.	Sufficient Local Repair.	Beyond Local Repair.	Remarks.
AB13.	V. 9013.	No Record.	B.	--	--
	3.0769.		B.	--	--
AB42a.		9411843.	B.	--	--
	9.1445.	Not B.	--	--	--
					this Vehicle is very old, and needs thorough overhaul - may be good for a few hundred miles.
	V.1.20. - 35227.	Not B.	--	--	Rear wheel buckled slightly due to slide on wet road. No new wheel available here.

Vehicles are held on charge, that their condition is as stated, and that AB412, and AB 406 have been inspected

Signed



Major.

0546

Declassified E.O. 12065 Section 3-402/NNDC NO.

785020

ARMY FORM C2130 (Small)

MESSAGE FORM

Register No.
140045

Transmission Instructions

Call	Srl. No.	Pr		Date-Time of Origin	Office Date Stamp
				13110 A	<i>35</i>
ABOVE THIS LINE FOR SIGNALS USE ONLY					
FROM	Originator			Message Instructions	
HQ NAPLES AREA			<i>To be held at Q.M.H.Q. / To be held at Q.M.H.Q. / To be held at Q.M.H.Q.</i>		
For Action					
240 TOWN MAJOR					
9 B.L.U.					
TO	(W) For Information (INFO)			CU	
ORD					

Originator's No.

QC 506/12 (.) Authority is given for Car Lt UTY HILLMAN
 4x2 No. 5100734 and Car 4x2 SALOON-FORD No. 4767121 to be transferred
 from 240 Town Major to 9 BLU to be held within WS (.) Date of transfer
 to be arranged by 240 Town Major (.) Casualties will be published in
 Part X Orders

Wt. 225g/350g. Padi. 6-12, R-8, S-10, L-2-4

THIS MESSAGE MAY BE SENT AS WRITTEN
BY ANY MEANS { EXCEPT WIRELESSIF LIKELY TO BE INTERCEPTED OR TO
FALL INTO ENEMY HANDS, THIS MES-
SAGE MUST BE SENT IN CIPHERSIGNED *[Signature]*

SIGNED

ORIGINATOR'S INSTRUCTIONS
DEGREE OF PRIORITY*Very
complicated*

Time	System	Op.
THI or TOR		
Time cleared		

3322

0 5 4 1

Declassified E.O. 12065 Section 3-402/MNOC NO.

785020*File 6017**(32)*

SUBJECT :- Transport.

9 British Liaison Unit
DANL

Ref :- 71/32

8th Nov 1946

LAND FORCES SUB COMMISSION
A.G. (M.M.L.A.)

Ford 1½ x 2 Saloon No. 1767191

Hillman Utility No. 510072

1. Enclosed is a copy of a letter from O.C. Troops (Town Major) Peru to A.D.C.S. Naples Area re transfer of s/m vehicles to this unit.
Reference para 3 enclosure "C" to your Directive No. 3 of 21st Jan 46 it would be appreciated if you would give necessary authority for us to take over the vehicles and communicate with Naples Area to this effect.
2. This would not be in excess of our R.R. If the transfer of one 5 ton (ref your Q 234 of 25 Oct) and one P/U (ref your QT 9 of 25 Oct) could be arranged.
3. In this connection please note our own Hillman Utility (No. 1490699) is now in workshop w/s. damaged radiator which may or may not be repairable here. The car hit the back of an unlighted farmcart one evening. (Further details will be sent later.)
4. The Town Major's two vehicles are in good condition and are more suitable for work here than a 5 ton or a P/U. It would help us a great deal if you could arrange this.

P.J.(P.S.D.F.-IN) Major,
D.A.U. & Q.M.C.

Q 5 4 8

Declassified E.O. 12065 Section 1-402/NHDC NO.

785020

760
O.C. Troops, B.R.I.
W/100/114
8 Nov 46

Subject:- Transport.

To:- A.D.O.S., R.C. Naples Area

Lt. Utility Willys 4 str. 4x2 - W.D. No. 5100734 - Contract no. 1143 -
Chassis no. 1560734 - Classification 2.

Car 4 str 4x2 saloon - Ford W.D. No. 4767191 - Contract no. V. 4069 -
Chassis no. V.4069 - Classification 2.

The above quoted vehicles are held on charge to this H.Q.,
(2nd Town Major) surplus to War Establishment.

I have been approached by 9 B.L.U. stationed in Bari to
explore the possibility of having these vehicles transferred to them on
disbandment of this unit, to replace their deficiencies.

As my disbandment is unlikely to take place before HQ Naples
Area is disbanded, it is suggested that the easier course would be to have
these vehicles transferred to 9 B.L.U. before 30 Nov 46. I can make
arrangements with the Unit to continue to use the vehicles for the remainder
of the time I shall be in Bari although they will officially be on charge
to B.L.U.

It is understood that M.M.I.A. Rms are being requested by
B.L.U. to contact you on the same subject.

Cffemus

..... Lt.-Col., R.A.
O.C. Troops, B.R.I.

Copy to:- 9 B.L.U. (2)

3320

0549

Declassified E.O. 13065 Section 3-402/NHICG NO.

785020

WAGON MOVEMENT ORDER
INSTRUCTIONS

1. This form is the authority for M.C. to remove a loaded wagon and to despatch it to destination.

2. Make it out in duplicate and give one copy to R.T.O.

The following wagons are loaded and ready for despatch.

(Sd.) *R. T. O.* *Place* *Date*

Wagon Numbers A	Wagon Standing B	Weight of Contents		General Contents D	Consignee E
		Tons C	Cwts.		
230000 D			15 cwt.		To Bala Branch and Nappies
230001					
230002					
230003					
230004					
230005					
230006					
230007					
230008					
230009					
230010					
230011					
230012					
230013					
230014					
230015					
230016					
230017					
230018					
230019					
230020					
230021					
230022					
230023					
230024					
230025					
230026					
230027					
230028					
230029					
230030					
230031					
230032					
230033					
230034					
230035					
230036					
230037					
230038					
230039					
230040					
230041					
230042					
230043					
230044					
230045					
230046					
230047					
230048					
230049					
230050					
230051					
230052					
230053					
230054					
230055					
230056					
230057					
230058					
230059					
230060					
230061					
230062					
230063					
230064					
230065					
230066					
230067					
230068					
230069					
230070					
230071					
230072					
230073					
230074					
230075					
230076					
230077					
230078					
230079					
230080					
230081					
230082					
230083					
230084					
230085					
230086					
230087					
230088					
230089					
230090					
230091					
230092					
230093					
230094					
230095					
230096					
230097					
230098					
230099					
230100					
230101					
230102					
230103					
230104					
230105					
230106					
230107					
230108					
230109					
230110					
230111					
230112					
230113					
230114					
230115					
230116					
230117					
230118					
230119					
230120					
230121					
230122					
230123					
230124					
230125					
230126					
230127					
230128					
230129					
230130					
230131					
230132					
230133					
230134					
230135					
230136					
230137					
230138					
230139					
230140					
230141					
230142					
230143					
230144					
230145					
230146					
230147					
230148					
230149					
230150					
230151					
230152					
230153					
230154					
230155					
230156					
230157					
230158					
230159					
230160					
230161					
230162					
230163					
230164					
230165					
230166					
230167					
230168					
230169					
230170					
230171					
230172					
230173					
230174					
230175					
230176					
230177					
230178					
230179					
230180					
230181					
230182					
230183					
230184					
230185					
230186					
230187					
230188					
230189					
230190					
230191					
230192					
230193					
230194					
230195					
230196					

0556

785020

Army Form W-5158

WAGON MOVEMENT ORDER

INSTRUCTIONS

To it

R. co (date)

C

Place

Date

Time

(Officer authorising move)

B

Tons

Cwts.

C

D

E

F

G

H

I

J

K

L

M

N

O

P

Q

R

S

T

U

V

W

X

Y

Z

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

XX

YY

ZZ

AA

BB

CC

DD

EE

FF

GG

HH

II

JJ

KK

LL

MM

NN

OO

PP

QQ

RR

SS

TT

UU

VV

WW

0 5 5 1

Declassified E.O. 12065 Section 3-402/RNDC NO.

785020

41

6 Dec 46

(B7)

SUBJECT : - MP Spares

10 British Liaison Unit
POSILLIPO NAPLES
Tele : 12060
TIME 3

Director of Repairs
11 Territorial Comd. PAOKSO

6 Dec 46

Director of Repairs
10 Territorial Comd. NAPLES

Director of Repairs
9 Territorial Comd. BARI
11 British Liaison Unit
PAJUSMO

9 British Liaison Unit
BARI

1. A point raised on the recent visit by Capt RIMDL, MEM 10 BLU to workshops in 11 Territorial Command, SICILY, was the difficulty in obtaining spares for pre-war SPA Military vehicles, especially the L-39 type.

2. Information has since been obtained to the effect that SPA still manufacture these spares, or at least, that they still have a store of them.

3. It is therefore suggested that a representative be sent to the SPA works at Turin or that liaison be established with the Director of Repairs of No 1 Territorial Command with a view to obtaining the required spares.

OAF
WSR/ec

CIA
by PDR

TS
Office

O/S/P
PMT
Lt col,
GS
3318

785020

50. EXP - POLAR.

REVIEW OF BRITISH M.V. ISSUED BY 2 B DIVISIONAL LIAISON UNIT.

C.C.

C.C.

No.	Vehicle Type.	Reg. No.	Engine No.	Contract No.	Chassis No.	Sufficient Local Repair.	Beyond Local
1.	Ford. 1/4 ton. 4x2.	W.5663179	C.P.W.79013.	V. 9013.	No Record.	E.	--
2.	Willys. 1/4ton. 4x2.	5630671.	639632.		340769.	E.	--
3.	Dodge. 3 ton. 4x2.	5689315.	T.110/1/50420.		9111013.	E.	--
4.	Hillman. 1/4ton. 2.	W.4498699.	No Record.		S.1445.	Not E. Under Repair.	
5.	B.S.A. 500.cc.	G.1431673.	27200.		V.M.20.-35227.	E.	--

Certified that the above vehicles are held on charge, that their condition is as stated, and that all are
and found correct.

1st December.

Signed

JF

785020

170 - Form.

REPORT OF BRITISH M.V. HELD BY 2 BRITISH LIAISON UNIT.

Engine No.	Contract No.	Chassis No.	Equivalent Local Repair.	Beyond Local Repair.	Remarks.
P.W.79913.	V. 9013.	No Record.	E.	"	
638652.		340769.	E.	"	
110/LV/50420.		9111613.	E.	"	
Record.		3.1445.	Not E. Under Repair.		Value to ready use
200.		V.11.20.-55227.	E.	"	

I am held on charge, that their condition is as stated, and that all 412, and 106 have been inspected

Signed:

H.H.

Major.

055

785020

29 NOV 1945

KP

SUBJECT : - Transport domestic

TO: British Liaison Unit
POSTNET 0 14433
Re: 12060
W/T/1

27 Nov 45

Land Forces Sub-Commission U.S.
(USA) HQ

9 BLU

Reference your L 50 issued 21 Nov 45.

Car sent to 9 BLU is car 4 x 4, 5 cwt (Jeep) WD No 5636671
(previously 5436671 due to mistake).

Copy of 9 BLU receipt attached.

CAT
WSD/ma

B.R. M
J. Lt col,
G.S.

GTH ✓
D9 PH
3316

785020

SUMMARY :- Vehicles.

9 British Liaison Unit
PARIS

Ref :- 71/3

26 Nov 1946

10 BLU

Willys Gmc 5 cwt 4 x 4

Ref to U/D/1 of 26 Nov the WD No. on a/c vehicle is 5636671
and was so when taken over by this unit.

(P.M.D.Y. T.R.) Major,
D.A.A.C. W.C.

3315

033

Declassified E.O. 12065 Section 1-402/NNDC NO.

785020

H1. 11
SUBJECT : Vehicles

8 Nov 1946
W

10 British Liaison Unit
POSILLIPO NAPLES
Tele : 12060
H/T/1

26 Nov 46

9 British Liaison Unit
BARI

Herewith copy of STATCENTRE (CENSUS) GHQ MELF letter for action by you.

SD M
Lt col,
GS.

CMF
EC

Subject:- "B" Vehicle Census

STATCENTRE (CENSUS)
GHQ MELF
L/334/CS/CENSUS.

Camp Comdt.
HQ Naples Area
CMF

9 Nov 46

Reference your letter CO/6/1 dated 29 Oct 46.

Willys Car 5 cwt 4 x 4

3314

The correct WD number applicable to the above mentioned vehicle
is .5636671....and not 5436671.. as shown in your a/m letter.

Please ensure that the correct WD No.5636671... is painted clearly
on the vehicle and that all the relevant records are amended.

Delete all trace of the incorrect WD No.

On completion please notify this GHQ.

Ref yr H/T/1 of 26 Nov
the WD No on a few
vehicle is 5636671 was
so when taken over to this unit.

GT ✓
D.P.D.
SO I (STATS)

0 9 5

785020

SUBJECT :- Domestic Type

9 British Liaison Unit
RAF

Ref :- 71/46.

27 Nov 1946

LAW DECISION AND CO. I. T.O.F.

AC (R.A.F.)

10 BLU (for action)

FORWARD 15 cwt 2 5904210

Ref your signal 34 of 25 Nov reading :-

"Forward this the moment BLR certificate for forward
15 cwt 5904210".

Please be referred to your 1/1/46 of 30 Oct para 1 and 2
(copy to 10 BLU). It is presumed that 10 BLR officer is
obtaining BLR certificate and forwarding to you in accordance with
your instructions.

In this connection please note that vehicle in question may
NOT be BLR in Naples where a new back axle may be obtainable.

3313

P.S. Upde
(P.S. UPDE) Major,
RAA 5 Dec

0 5 5 8

Declassified E.O. 12065 Section 3-402/NNDC NO.

785020

36 NOV 1946

187th

44.

41.

MODELLO MF

§ 35 delle istruzioni sui collegamenti - Vol. V
(Cdot. 3798 - ediz. 1940)Indicazioni d' urgenza
e eventuali

O

(1) Mittente

(2) Da trasmettere alla stazione



N. 2919 del Catal.

Indice del collegamento

(1) Indicazione e bollo del comando mittente.

(2) Nominativo della stazione destinataria o indirizzo del comando destinatario.

(3) Indice della stazione mittente.

Le ore si contano sul meridiano medio dell'Europa Centrale e di seguito da una mezzanotte all'altra.

Rit sciolto il	25 - 11 - 1946	alle ore	18,46	Trasmesso il	19	alle ore	
della stazione (c)	Roma	Ricevente	Giordano	alla stazione (c)	Transittante		
Caratteri (cr) N.	1/25/m	11 25/11 ore 15,50 -					
Parole (p)	17	9° BLU	BARI				
Gruppi (gr)							

TESTO

a	b	c	d	e	f	g	i	l	m	n	o	p	q	r	s	t	u	v	x
1	251155	- Q	32 UNCLASSIFIED	= FORWARD THIS H.Q. SOONEST BLR															
2	CERTIFICATE FOR FORDSON 15 CKT Z 5504210																		
3																			
4																			
5																			
6																			
7																			
8																			
9																			
0																			

Q/T/9 M.M.I.A.

F.I.
P.G. P.M.

I.M.

Letter 37-Bis

Laff

3312

CHARTERED AIRLINES INC.

3 British Islands Ltd.
THE
PORT

DET - 785020.

22 MAY 1965

1965 REPORT OF INSPECTION

4.5. (1965)

1. 1965 REPORT OF INSPECTION OF 20 OCT 1965.

The a/c listed was examined by 10 AM on 17 Oct 65.

This is presented for inspection and comment on the technical condition of the aircraft. To prevent this unit from being used, the following conditions must be observed:

1. The aircraft must be grounded until further notice.

2. The aircraft must be grounded until further notice.

3. The aircraft must be grounded until further notice.

4. The aircraft must be grounded until further notice.

5. The aircraft must be grounded until further notice.

6. The aircraft must be grounded until further notice.

7. The aircraft must be grounded until further notice.

8. The aircraft must be grounded until further notice.

9. The aircraft must be grounded until further notice.

10. The aircraft must be grounded until further notice.

11. The aircraft must be grounded until further notice.

12. The aircraft must be grounded until further notice.

13. The aircraft must be grounded until further notice.

14. The aircraft must be grounded until further notice.

The a/c will be released to the operator on 19 Nov 65.

4. Date 12/24 or 25 Oct 45.

The USAFAC was in the process of reporting on the
functions of the vehicle. It was as far as the unit is able to
judge, the vehicle is primarily not req'd in combat operations in every
vege.

2221. 22 Nov. CLASS No. 3311

Date: 3 Dec 45. Serial No. 241032

2. Not true to 5 of 25 Oct 45.

USAFAF had been told we were going to the U/C vehicle 3311

at PAF.

The vehicle has been found to be at the (at vehicle point
of view) USAFAF (not broken). The vehicle is now reported to be in good
condition.

USAFAF has been given over from AF 121 and planned to
be sent back, no will not turn up again on the USAFAF's way back.

2222. 22 Nov. CLASS No. 3311

Date: 2 Dec 45. Serial No. 240700

2. Not true 1/2 to 25 Oct.

The vehicle has been turned in to the USAFAF for use by
the USAFAF.

2223. 22 Nov. CLASS No. 3311

Date: 2 Dec 45. Serial No. 240700

2. Not true 1/2 to 25 Oct.

RAD.

5. USAFAF
DA & QD

785020

SOURCE: See 91.

© Pristine Editions Ltd PART

Def. 2-74/46.

22 Nov 16

20 ~~10~~ MM

This confirms that D MU has now taken over the U/M vehicles
from you in accordance with FIA Letter Q 79 of 23 Oct 1946.

<u>Pink</u>	<u>D No.</u>	<u>Clinical No.</u>	<u>Trade No.</u>	<u>Contract No.</u>
T-1925 Greenback	5556671	340769	555532	2.0769

(PS 127PL) 15:05,
DAA 6: QF

(THE TRIPPLE) Major,
DAN de JES

0562

Declassified E.O. 12065 Section 3-402/NNDC NO.

785020

INSTRUCTIONS

1. This form is the authority for M.C. to remove a loaded wagon and to despatch it to destination.
2. Make it out in duplicate and give one copy to R.T.O.

WAGON MOVEMENT ORDER

To R.T.O. — Bari - Parco Nord

The following wagons are loaded and ready for despatch.

(Sd) 9 BLU BARI

J. Hulme, May

Place: Bari Parco Nord

Date 18 May

Wagon Numbers	Wagon Standing	Weight of Contents		General Contents	Consignee
		Tons	Cwts.		
A Z 5504210	B Prima merce	C 15		D FACSIMILE	E 10 British Liaison Unit - Naples

*R.T.O.
BARI PARCO NORD
J. Hulme, May
18/5/45*

Declassified E.O. 13065 Section 3-402/MNDC NO.

785020

WAGON MOVEMENT ORDER

INSTRUCTIONS

The inability for M.A. to receive a letter from him and to
duplicate and give one copy to K.T.O.

To R. Bari - Parco Nord

The following wagons are loaded and ready for despatch.
9 BLU B.R.I. *J. W. M. May*. (Officer authorising move)

Place Bari Parco Nord

Date 18 Nov 1946 time 15 hrs

0 5 6 4.

Declassified E.O. 12065 Section 3-402/NNDC NO.

785020



MODELLO MF

§ 35 Art. 11° provv. sui collegamenti - Vol. II
Roma 37/9 - ediz. G40)Indicazioni d'urgenza
e eventuali

O

DD

(1) Mittente

(2) Da trasmettere alla stazione



N. 2919 del Canal.

Indice del collegamento

- (1) Indicazione e nome del comando militare.
(2) Nome/indirizzo della stazione destinataria e inquadratura del comando destinatario.
(3) Indice della stazione mittente.

Le ore si contano sul meridiano medio dell'Europa Centrale e di seguito da una mettano alle altre.

Ri sciatto il 13/11/	19 46 alle ore 10,53	Trasmesso il	19 alle ore
della stazione (1) Napoli	Receiveante Giordano	alla stazione (1)	Trasmittente

Caratteri (ct) N. 2	11 13/11 ore 09,25
Parole (p) 27	AT 9 th BRITISH LIAISON UNIT
Gruppi (gr) 1	BARI

TESTO

a	b	c	d	e	f	g	i	l	m	n	o	p	q	r	s	t	u	v	x
1	Da 10 th British Liaison Unit Naples - nr. 5/0/1 punto one 3 tonner																		
2	arriving with itsalien driver punto eta evening 13 novembre punto																		
3	driver to stay overnight punto																		
4																			
5																			
6																			
7																			
8																			
9																			
10																			

Rv De Melvin Sjt

3308

785020

Telephone:
Tome 489001 Ext 270

LAND FORCES SUR CO, HQ (WIA) CAF

✓T/3

H.I.

8 Nov 1946

(34)

13 Nov 46

SAC (for 3).

Subject: Transport.

Ford 4x2 Saloon D 80476719
Hillman Utility D 5100734.

1. The two a/m vehicles are held on charge HQ 240 Tom Major NAFI surplus to AF and will shortly be available for transfer.

2. Subject to HQ NAFLES Area approval, authority is requested for the transfer of the two a/m vehicles to 9 RCU to replace their deficiencies.

Officer-in-Charge

*Major-General,
GOC, AFIA.*

Copy to: HQ NAFLES Area
9 RCU (ref your 71/32 —
dated 8 Nov).

SFM/ab

- U 3307
P.D. 1000, October
1946 Series - 52

T. J. M.

Telephone: Rome 489081 Ext 415

LAND FORCES SUP COM, AC (M.T.) ST

290/S Q

15 Nov 46

18 Nov 1946

9 S.I.U.

Subject : Repairs - M.T.

Ref your 71/18 dated 26 Oct 46 and this HQ Q. 204 dated 26 Aug 46.

1. You are requested to re-submit the voucher for repairs to HQ 14/0 1421575 on the English version of M.L.A. Form T/R further copies of which are enclosed. The charge is considered reasonable but it is pointed out that this version is filled with supporting documents and an Italian version will similarly not valid.

2. It is also necessary to obtain a R.E.D. office's signature on page 4 of the form T/R.

Repairs of this nature should not be so frequent as to make it impracticable to obtain countersignature by the R.E.D. officer of your affiliated A type B.M.

This could be done during his periodical visits or in the case of minor repairs through the post.

3. It will be recognised that large bills for repairs will not be incurred. For consideration has been given to obtaining a B.L.R. certificate Form B 25 red.

In such cases R.E.D. advice will be sought before formally asking assistance from the Italian Repair Unit concerned.

3366

RAC/ra

Copy to: List "E" (for info & necessary action).

785020

Ref your 71/18 dated 26 Oct 46 and this HQ Q.204 dated 26 Aug 46.

1. You are requested to re-submit the voucher for repairs to U/C 141575 on the English version of MTA Form T/R further copies of which are enclosed. The charge is considered reasonable but it is pointed out that this voucher is filled with supporting documents and an Italian version while similar is not valid.

2. It is also necessary to obtain a RME officer's signature on para 1 of the Form T/R.

Repairs of this nature should not be so frequent as to make it impracticable to obtain countersignature by the RME Officer of your affiliated Army Unit.

This could be done during his periodical visits or in the case of minor repairs through the post.

It will be recommended that large bills for repairs will not be submitted before consideration has been given to obtaining a 3 I R certificate (see U.C. Rep.)

In such cases MTA advice will be sought before formally asking assistance from the Italian Repair Unit concerned.

3366

Major General
J. C. G. L. H.
Colclough

RAC/ra

Copy to: List "B" (for info & necessary section).

T-2222D:R.B.M.E.
Q A/c.

*6 II. 2
N.B. AT,
D.P. 7/8*

Q 5 6 4

785020

41 1
14 NOV 1946 31

Subject:- Domestic Tpt.

Land Forces Sub Comm. A.C.
(M.M.I.A.)
R O M E
Q/T/9

30 Oct 46.

To :- 2 BLU BARI.

Ref your 71/17 dated 23 Oct 46.

1. Your vehicle 15 cwt Fordson WD No 5504210 will be backloaded to 10 BLU NAPLES who will obtain ELR certificate and dispose of the vehicle in question. ELR certificate will subsequently be forwarded to this HQ.

2. It is regretted that I.A.M.E. equivalents of ELR certificates cannot be accepted and procedure for ELR will be adopted in all cases as per para 1.

3. Your tpt difficulties will now be met as outlined in this HQ letters Q/T/9 of 23 Oct 46 and Q.204 dated 25 Oct. The 15 cwt to be backloaded will count as the vehicle to be returned by you.

an. Date, ?

W. F. BYATT

E.F. BYATT, Major,
for Major General,
M.M.I.A.

Copy to:- 10 BLU NAPLES.

ENB/ab

DP 3305
DD
T

0 5 6 9

785020

Subject:- Domestic Transport.

(8)

Land Forces Sub Comm. A.C.
(M.M.I.A.)
R C M E
Q.T.9

23 Oct 46.

To :- 9 BLU.

1. This HQ is transferring 1 P/V to you from 12 BFM (see our Q/T/10 dated 23 Oct 46) which will be taken on your strength.
2. This is being done in order that you may now be up to W/L and hold 1 vehicle in reserve as intended by this HQ.
3. This vehicle will be shown on your next monthly "B" vehicle census return to this HQ when in your possession.

*W. F. BYATT
Major*

E.F. BYATT, Major,
for Major General,
M.M.I.A.

EFB/ab

33 v 4

*A. P. G.
G. T. ~*

785020

Subject: Domestic Transport.

Lend Lease sub Comm. A.C.
 (S.A.)
 A.M.S.
 1/2/40

23 Oct 40.

To : - 10 . . .

1. The following notice has been dictated to you from this office by Mr. Johnson and C. 100-459864
Date and place of nomination will be transmitted to you when this vehicle is ready.
2. You will now bring you up to 1/2 plus 2 passenger vehicles. In order to bring you up to complete 1/2, the following adjustments will be made: *Done*
 - a) 1 passenger vehicle to be nominated by you will be transferred to G.E.L.U. Date and method of this transfer will be advised later.
 - b) You will notify this S.A. on receipt of the vehicle in par. 1, of one of the vehicles at present held by you which can be used and all details as to the technical condition of this vehicle will accompany your notification.
3. On receipt of the vehicle mentioned in para 1 you will make the necessary adjustment in your next monthly "B" Vehicle census return.

Copy to: 9 M.Y.

MDC MIA Super Garage
 File 1/1/9
 File 1/1/3

Abeyance
 J. P. BROWN, Major,
 for Major General, 33rd

10-1 To be used

SPD/nb

D.G.
 6/1/2
 T.A.P.

785020

Pro - Forma

RETURN OF BRITISH A.T. HELD BY 9 BRITISH LIAISON UNIT.

No	Vehicle Type.	Reg No.	Engine No.	Contract No.	Chassis No.	Efficient Local Repair.	Beyond Repair.
1.	Ford 1/4 ton 4x4.	M.5663179.	GFT.79013.	V.9013.	No Record.	E.	-
2.	B.S.A. 500cc M/C.	G.1431573.	27200.	No Record.	W20-35227.	S.	-
3.	Hillman L/U 4x2.	M.4498699.	No record.	" "	S1445.	E.	-
4.	Fordson 15cwt GS	Z.5504210.	" " "	"	7145779.	/	-
	4x2.					X	This Works & see

Certified that the above vehicles are held on charge, that their condition is as stated, and AB 406 have been inspected and found correct.

1st November.

Signed

(X)

GS

The differential ^{GS} is completely US - , crown wheel and pinion being in pieces. If a new diff. or even the entire back axle assembly could be obtained (Fordson 15 cwt Wat 11) the vehicle could be repaired here. In the meantime it is a non-runner and backloading will have to be by rear suspended tow or by rail.

785020

Pro - Forma

*Pls. sign.*RETURN OF BRITISH V.T. HELD BY 9 BRITISH LIAISON UNIT.

Engine No.	Contract No.	Chassis No.	Efficient Local Repair.	Beyond Local Repair.	Remarks.
GPW.79013. V.9013.	No Record.		E. -	-	
27200.	No Record.	W 20-35227.	E. -	-	
No record.	" "	S1445.	E. -	-	
" " "	" "	7145779.	/ -	X* This vehicle is now in 9 Reparto Workshop vide our 71/17 of 23 Oct. & see footnote.	

The vehicles are held on charge, that their condition is as stated, and that all 412
inspected and found correct.

Signed



~~CO~~
~~CO~~ Differential is completely US - , crown wheel and pinion being in
new diff. or even the entire back axle assembly could
be replaced (Fordson 15 cwt vat 11) the vehicle could be repaired here.
 meantime it is a non-runner and backloading will have to be by
pended tow or by rail.

785020

Subject : Repairs to vehicles.

9. Brit Liaison Unit
Bari.

To : M.M.I.A.
From : 9. B.L.U.

Ref : 71/18

B.S.A. M/C. G. 1431573.

1. It has now become necessary for this unit to make use of 9 Reparto (Italian) for repairs to vehicles.
2. Enclosed please find the first receipt in the form arranged by GHQ 2521/Q1 of 11 June '46. Pro forma attached to your Q.204 of 26 Aug. 46 refers.
3. In the case of this receipt for the a/m M/C. the DAA. & QMG of this BLU has signed in the place of REME BLU as there is now no REME here. In this case the cost of repairs at about £6 seems reasonable but it would be appreciated if you could give some ruling on this point for the future. It should be possible for this Unit to certify work as satisfactory in most cases but have we authority to certify costs as fair & reasonable ?
4. Pending your instructions on this point as we have NOT yet given 9 Reparto their copy of this receipt.

26 OCT 46.



Major.

3301

DAA. & QMG. 9. B.L.U.

Subject : Transport state (Domestic)

• M.M.I.A.
From : 2. B.L.U.

9. Brit. Liaison Unit.
DARL.

Ref. 71/17.

1. This unit's 15 cwt Fordson truck No. 5504210 is now in 9 Repair Shop (Italian) in a state Beyond Local Repair. The differential has been causing trouble for some time due to worn crown wheel & pinion. Enclosed is a letter from 9 Repair Shop which is the equivalent to a B.R.R. certificate. It would be appreciated if authority could be obtained for the unit to draw a new vehicle at an early date and disposal instructions for the old vehicle sent at the same time.

2. The transport state of this unit (apart from 1 w/o) is now as follows :-

(i) Hillman Utility. This vehicle is engaged almost permanently on the internal administration of the unit. Rations must be drawn daily from the Airport, 4 miles North of Darl, bread from the bakery, 3 miles South of Darl, meat & ice from a third place. These then have to be broken down and delivered to the O.R.S. billets, the married officer's villa and to the other officers. The vehicle is also used frequently for mail, signals, visits to hospital, AAIFI supplies and so on. It can be seen that, after allowing time for maintenance, the vehicle is seldom available for the normal work of the MUU.

(ii) Jeep. This is now the only BLU vehicle available for three officers to do the work of the unit. Even with good co-ordination this impairs efficiency. Visits to places as far apart as Reggia and Taranto are being regularly made. It should be added that the vehicle has done 35,000 miles and therefore needs a good deal of workshop attention. For example the petrol tank has been soldered once and welded twice in the past two weeks due to holes rusted through.

3. In consequence of the above state the unit has frequently to borrow vehicles from 9 Corp. Cond., It is not found satisfactory if this method of getting transport has to be used too often.

4. It is suggested that for the efficient working of the unit one vehicle for each officer is necessary and also one for admin. This would give the unit four vehicles in place of the existing two.

Old vehicle sent at the same time.

2. The transport state of this unit (apart from 1 m/o) is now as follows :-

(1) Hillman Utility. This vehicle is engaged almost permanently on the internal administration of the unit. Rations must be drawn daily from the Airport, 4 miles North of Bari, bread from the bakery, 3 miles South of Bari, meat & ice from a third place. These then have to be broken down and delivered to the O.R.s billets, the married officer's villa and to the other officers. The vehicle is also used frequently for mail, signals, visits to hospital, AAIFI supplies and so on. It can be seen that, after allowing time for maintenance, the vehicle is seldom available for the normal work of the BLU.

(2) Jeep. This is now the only BLU vehicle available for three officers to do the work of the unit. Even with good co-ordination this impairs efficiency. Visits to places as far apart as Foggia and Taranto are being regularly made. It should be added that the vehicle has done 35,000 miles and therefore needs a good deal of workshop attention. For example the petrol tank has been soldered once and welded twice in the past two weeks due to holes rusted through.

3. In consequence of the above state the unit has frequently to borrow vehicles from 9 Terr. Cond., It is not sound administrative if this method of getting transport has to be used too often.
4. It is suggested that for the efficient working of the unit one vehicle for each officer is necessary and also one for admin. This would give the unit four vehicles in place of the existing W.E. of three vehicles and 3 M.P./c. Furthermore it is felt that any vehicles allotted to this unit should be either new or in a very good initial state of repair as the present difficulties are likely to become aggravated when the unit becomes more isolated.

R.A.
Major.
DAA. & Q.M.C. 9. B.L.U.

23 Oct. 46

9° REPARTO RIPARAZIONI AUTOCARRI STRADALI

O C E A W D C

Prot. n. 1167 /2-1/2

Bari, 23 ottobre 1945

OOGNIE: Autocarro Ferguson targa 2.550421C.

DATA 2^ REITZSCH LIHNSCH UNIT (9^ U.S.A.)

B A L L

Dall'essere dell'autocarro Ferguson targa 2.550421C,
ricoverato nella riparante Cittadina il giorno 21 scorrente, ad
avendo riscontrato i danni subiti dall'autosero stesso è sta-
to accertato che per la rimessa in servizio è necessario la
costituzione del ponte posteriore completo di differenziale, esse-
ndo questo attualmente risultato completamente fuori uso.

Questo Comando non può pertanto procedere alla ripar-
azione dell'autosero stesso, essendo completamente surrivisto
dei rimandi di cui codice.

Si prega, pertanto, la curtesia di voler dire al Cittadino,
voler fornire i materiali di cui trattasi.

3299

IL COMANDANTE DEL REPARTO
(MSS. Francesco PIRELLI)

Francesco Pirelli

785020

785020

Subject:- M.T.

9 British Liaison Unit,
BARI.
Tel : 13859
Ref 71/190
17 Sept 46.

25

To:- Land Forces Sub Commission, AC,
(M.M.I.A.)

189

Further to my signal 71/186 dated 14 Sept 46.

During July 46 Dodge 4x4, 3/4ton No.M.5310905 was on loan
from 9 Territorial Command.

This fact was not known to DAA & QMG and it was included
in the vehicle return for July in error.

v

(J.Milmen) Major. GS.
Comd. 9 B.L.U.

JM/vm

3298

Q 573

Declassified E.O. 12065 Section 3-402/NNDC NO.

785020

MESSAGE FORM			Register No.
ARMY FORM C2136 (Small)			Transmission Instructions
Call	Srl. No.	Priority	
ABOVE THIS LINE FOR SIGNALS USE ONLY			
FROM (A)	Originator 9 D ZU	Date-Time of Origin 14 1200 D	OFFICE DATE STAMP
For Action			
TO	M M I A (W) For Information (INFO)		Message Instructions — GR —
Originator's No. 74/3 V. MOYAL () 100 1000 00 10 100 1000 10 100 1000 GIVEN BY SENDER TO REC'D () 100 1000 00 10 100 1000 10 100 1000 EXPLANATION			
3297			
THIS MESSAGE MAY BE SENT AS WRITTEN BY ANY MEANS EXCEPT <small>WIRELESS</small> SIGNED <i>P.S. Appleby</i>		IF LIKELY TO BE INTERCEPTED OR TO FALL INTO ENEMY HANDS, THIS MES- SAGE MUST BE SENT IN CIPHER SIGNED <i>Downey</i>	ORIGINATOR'S INSTRUCTIONS DEGREE OF PRIORITY <small>REG.</small> <i>SECRET</i> Time System Op THI or TOR Time cleared

3632/GHQ/P/12-43

785020

RAAC MESSAGE FORM

CALL	CIRCUIT No. NR	PRIORITY	TRANSMISSION INSTRUCTIONS
SPACES WITHIN DOUBLES LINES FOR SIGNALS USE ONLY			
			DATE-TIME OF ORIGIN
FROM (A)	M.M.I.A.		110 9/5 D
TO (FOR ACTION)	9 BLU BART		
TO (FOR INFORMATION)			<i>Message Instructions</i> GR
(REF. No.)	Q 1049	SECURITY CLASSIFICATION	UNCLASSIFIED

REF OUR SIGNAL Q 1048 DATED 10 SEPT '46 (.) TO WAD PRESENT
 LOCATION DODGE 15 CWT N 5310905

3296

LOCAL DISTRIBUTION Q/T/9	PRECEDENCE : ROUTINE	THI OR TOR	Op.
	ORIGINATING SECTION : "Q"		
	A. G. AUTHENTICATION:		
	ORIGINATOR'S AUTHENTICATION: A. A. BIGGS, Capt	TIME CLEARED	

0580

785020

RAAC MESSAGE FORM

C	L	CIRCUIT No. NR	PRIORITY	TRANSMISSION INSTRUCTIONS <i>SDS</i>
SPACES WITHIN DOUBLES LINES FOR SIGNALS USE ONLY				
			DATE-TIME OF ORIGIN 101730 B	
FROM (A)	M.M.I.A.			
TO (FOR ACTION)	9 BLU BARI			
TO (FOR INFORMATION)				<i>Message Instructions</i> GR <i>21</i>
(REF. No.)	Q 1048	(SECURITY CLASSIFICATION)	UNCLASSIFIED	

SIGNAL PRESENT LOCATION DOGE 15 CWT M 53109 (.) NOT REPEAT NOT
 DECLARED SEPT VEHICLE CENSUS RETURN

LOCAL DISTRIBUTION Q/T/9	PRECEDENCE : <i>ROUTINE</i>	THI OR TOR 101820
ORIGINATING SECTION :	A. G. AUTHENTICATION : R.A. BIGGS Capt	Op.
ORIGINATOR'S AUTHENTICATION : <i>R.A. BIGGS Capt</i>	TIME CLEARED	

0581

785020

SUBJECT:- Vehicles on charge.

(AO)

5 British Liaison Unit.
Tel.: 1762

8/20/86

9 July 46.

9 British Liaison Unit,
B A R I .

Ref your 71/163 of 4 Jul 46.

1. The Dodge 3/4 ton 4 x 4 taken to BARI by Major BORDA was never taken on charge by 52 B.L.U. nor is it on charge to 5 B.L.U.

J. H. Hunter
Capt. REME.

0582

Declassified E.O. 12063 Section 3-602/NNDC NO.

785020

Subject : Vehicle.

(P)

9 British Liaison Unit,
BARI.

71/163

4 July 46.

To : 5 British Liaison Unit.

There is a Dodge 3/4 ton 4x4 vehicle (peep) at
9 Terr. Reg. R.C. which was brought down to Bari by Major F. Borda R.M.A.
when he arrived from 52 B.L.U.

Please say whether this vehicle is on your charge.

H.F.
(H. Ferro) Major GS.
Comd. 9 B.L.U.

RE/ef

D 583

Declassified E.O. 12063 Section 3-602/RNHC NO.

785020

Pro - Forma

RETURN OF BRITISH M.T. HELD BY 9 BRITISH LIAISON U

No.	Vehicle Type.	Reg No	Engine No	Contract No	Chassis No	Efficient G S E
1.	Ford 1/4 ton 4x4	M.5563179	GPW 79013	V. 9013	No Record	E.
2.	B.S.A.500cc M/C	G.1431573	27200	No Record	WM20-35227	E.
3.	Hillman L/U 4x2	M.4498699	No Record	" "	S1445	E.
4.	Fordson 15cwt GS	Z.5504210 4x2.	" "	" "	7145779	E.

Certified that the above vehicles are held on charge, that their condition is as stated and AB406 have been inspected and found correct.

1st October.Signed J.

0584

Declassified E.O. 12065 Section 3-402/NNDC NO.

785020


Pro - Forma

RETURN OF BRITISH U.T. HELD BY 9 BRITISH LIAISON UNIT.

Engine No	Contract No	Chassis No	Efficient Local Repair		Beyond Local Repair	Remarks.
			2	3		
79 GPW 79013	V. 9013	No Record	E.	-	-	-
73 27200	No Record	WH20-35227	E.	--	-	
39 No Record	" "	S1445	E.	--	-	Spare inner tube 600x16 needed.
10 "	" "	7145779	E.	-	-	-

vehicles are held on charge, that their condition is as stated and that AB 412 and
d and found correct.

Signed



0 5 8 6

785020Subject:- CLASSIFICATION.C. I. TROOPS R.A.R.T.651 L of C W/Shops R.E.M.E.
Bari 13082
651/ME/5/C

4 September 46.

The undermentioned vehicles belonging to, 9 B.L.U.
are classified as under

<u>W.D. No</u>	<u>MAKE & TYPE</u>	<u>CHASSIS NO</u>	<u>REMARKS</u>
M 4498699	HILLMAN L/T UTY CAR	S 1443	CLASS III XXXXXXXXXXXXXX XXXXXXXXXXXXXX Class III
M 5663179	Car 5 cwt Jeep	-	

C.M.F.

R.J.Broad Capt.
(R.J.BROAD) Capt. R.E.M.E.
O.C. 651 L of C W/shops R.E.M.E.

0 5 8 6

785020

SUBJECT:- Domestic Transport

10 British Liaison Unit
TORRE DEL GRECO
Tele : 55802 NAPLES
H/T/1

✓
9 BLU
BARI

3 Aug 46

CHEVROLET 8 cwt H/U WD No Z 5906866

Further to this HQ letter H/T/1 dated 28 Jun 46.

1. The transport problems of this unit are at present critical as 2 vehicles have, during the past few weeks, been BLR'd.
2. It is considered probable that the BLR'd vehicle, for which the a/m CHEVROLET was loaned to you, has now been replaced and that the CHEVROLET can be returned to this HQ.
3. The CC LO of this unit will be visiting BARI within the next few days, and it is suggested that a driver (Italian) from the Increment attached to this HQ, accompany him in order to return with the vehicle.
4. Please confirm by signal if collection is possible.

✓
CLF
RVN/ec

WRC Log.
W Major, W
GS.

✓
S/6.

CHEVROLET 8 cwt H/U WD No Z 5906866

Further to this HQ letter H/T/1 dated 28 Jun 46.

1. The transport problems of this unit are at present critical as 2 vehicles have, during the past few weeks, been BLR'd.
2. It is considered probable that the BLR'd vehicle, for which the a/m CHEVROLET was loaned to you, has now been replaced and that the CHEVROLET can be returned to this HQ.
3. The OC LO of this unit will be visiting BARI within the next few days, and it is suggested that a driver (Italian) from the Increment attached to this HQ, accompany him in order to return with the vehicle.
4. Please confirm by signal if collection is possible.

WPC Log.
W Major, W
GS.

✓
SAC.

CMF
RVM/ec

3290

