

ACC/14610/1/PS

10000/143/1476

WA
FE

10000/143/1476

WARNING LIGHTS ON ROADS, ETC.
FEB.-AUG. 1944

0 2 3 4

Declassified E.O. 12356 Section 3.3(NN) No. 7

AC2/14610/1/25

WARNING LIGHTS ON ROADS ETC.

Folio Reference Date File Refered to Date File Referred to Date

0 2 3 5

Declassified E.O. 12356 Section 3.3(NN) No. 7

WARNING LIGHTS ON ROADS ETC.

Folio Reference Date Folio Refereed Date Folio Referred Date

10000 / 43 / 14/96
THIS FOLDER
CONTAINS PAPERS
FROM FILE
TO AUG
1944
CATALOGUE.

Holic State Ref. TOT 74m Substate T.

IA. 25 Feb. 25/26A from 40N 25W. Hazard lights at level crossing

MINUTE SHEET

62

O Lk 16A
HEADQUARTERS
ALLIED CONTROL COMMISSION
Public Safety Sub-Commission
APO 394

Tel: 473700

ACC/11630/1/PB

8 August, 1944.

SUBJECT : M.T. Accident involving Dodge,
No.R.A.F. 91011177 on 24 June 44.

TO : Air Officer, i/c Administration,
H.Q. Mediterranean Allied Air
Forces C.M.F.

16A
With reference to your MAP/1820/511/F.1. dated 31 July 1944,
addressed to Transportation Sub-Commission, A.C.C., I have to inform you
that action has been taken to bring the matter to the notice of the Italian
Authorities with a view to putting the recommendation in para 3 of your
letter into effect.

PAUL G. KIRK
Colonel Inf.
Director Public Safety
Sub-Commission.

cc/c.

62x7

HEADQUARTERS MEDITERRANEAN ALLIED AIR FORCE C.M.F.

TO : Headquarters, Allied Control Commission(Transportation
Sub-Commission (Roads)).

DATE : 31 July, 1944.

Ref : MAU/1820/511/P.1.

M.T. ACCIDENT INVOLVING DODGE, NO. R.A.F. 91011177
ON 24 June, 1944.

1. On the 24th June, 1944, at 20.20 hours, an accident happened on the NOVOLI-LINCOL Road.
2. The driver of the above-numbered vehicle was returning to Lecce when at a point approximately half a kilometre from Novoli, he noticed a wall projecting into the road. In trying to avoid the wall, the front right hand wheel of the vehicle came into contact with a concrete pillar at the end of the wall, which the driver had not seen. The vehicle then swung across to the right, over a crossing and collided with another wall on the other side.
3. An investigation into the accident was held, and, although the driver was found negligent, in so far that he was travelling too fast, the point where the accident happened, was considered to be very dangerous, and the following recommendation was put forward by the investigating officer :

" I recommend that suitable warning signs be displayed on the approach to the level crossing, and that reflectors be fitted to the projecting walls."
4. The recommendation is concurred in by this Headquarters, and it would be appreciated if steps could be taken to put it into effect.

H.F. Newman
Air Officer i/c Administration
Mediterranean Allied Air Forces.

1st T.M.

Tel: 478708

9 August, 1944.

from : H.Q. A.C.C. Public Safety
sub-Commission.

TO : R.P.S.O., Region II.

The above is forwarded for your information. Would you please bring it to the notice of the appropriate Italian Authorities with the view to having the recommendation ~~be~~ put into effect.


PAUL G. KIRK
Colonel Inf.

Director Public Safety S/C.

DR/G.

8100 Transportation S.C.

From:- Headquarters, Mediterranean Allied Air Forces., C.M.F.
 To :- Headquarters, Allied Control Commission (Transportation Sub-Commission (Roads)).
 Date:- 31st July, 1944.
 Ref :- MAAP/1020/511/1.1.

M.T. ACCIDENT INVOLVING LODGE NO. R.A.T. 9401177
ON 24TH JUNE, 1944.

1. On the 24th June, 1944, at 20.20 hours, an accident happened on the NOVELI-LECCO Road.
2. The driver of the above-numbered vehicle was returning to Lecco when at a point approximately half a kilometre from Novelli, he noticed a wall projecting into the road. In trying to avoid the wall, the front right-hand wheel of the vehicle came into contact with a concrete pillar at the end of the wall, which the driver had not seen. The vehicle then swung across to the right, over a crossing and collided with another wall on the other side.
3. An investigation into the accident was held, and, although the driver was found negligent, in so far that he was travelling too fast, the point where the accident happened, was considered to be very dangerous, and the following recommendation was put forward by the investigating Officer:

"I recommend that suitable warning signs be displayed on the approach to the level crossing, and that reflectors be fitted to the projecting walls."
4. The recommendation is concurred in by this Headquarters, and it would be appreciated if steps could be taken to put it into effect.

H. A. L. M. 624

(H.A. MANN)

Air Officer i/c Administration,
Mediterranean Allied Air Forces.

fwd

COPY

HEADQUARTERS
ALLIED CONTROL COMMISSION
Transportation Sub-Commission
ACO 394

14

TO : Public Safety Sub-Commission,
Reer H.Q., ACO.

SUBJECT : Level Crossings.

Our Reference: ACO Th/123/17
Date : 10 June 1944.

1. Reference is to your ACO/14610/PS of 29 May '44.
2. Gancello-Maddaloni crossing is under control of Director General of Military Railway Services.
3. The latter informs no matter has been taken up with Italian State Railways officials, and it is reported that the watchmen on duty has been reprimanded, and lanterns have been provided for use at night.

L.E. Vining,
Lieut-Colonel,
Director, Transportation Sub-Commission, ACO.

1st IMP

ACO/14610/1/PS.

11 June 1944.

From : H.Q., ACO., - Public Safety Sub-Commission.
To : HQ, No. 3 District.
Subject: Level Crossings.

84
With ref to your 353A dated 31 March 1944, the above is a copy of letter received by this Sub-Commission on the matter.

PAUL G. KIRK,
Colonel Inf.,
Chief, Public Safety
Sub-Commission.

6-27

Public Safety Sub-Commission
HEADQUARTERS
ALLIED CONTROL COMMISSION
Transportation Sub-Commission
AGC 394

Our Reference : AGC Mn/123/17
Date : 10 June 44

TO : Public Safety Sub-Commission,
Rear H.Q., AGC.

SUBJECT : Level Crossings.

1. Reference is to your AGC/14610/PB of 29 May '44.
 2. Cencello-Middleton crossing is under control of Director General of Military Railway Services.
 3. The letter informs no matter has been taken up with Iffelien State Railways officials, and it is reported that the watchmen on duty has been reprimanded, and lanterns have been provided for use at night.

*Acting Capt
for P.E. VINING,
Lieut-Colonel,
Director, Transportation Sub-Commission, AGC.*



REAR HEADQUARTERS
ALLIED CONTROL COMMISSION
Public Safety Sub-Commission

29 May 1944.

ACC/14610/RS

SUBJECT: Level Crossings.

TO : Transportation Sub-Commission.

Reference our letter ACC/14610/RS dated 3 April 44 enclosing a District letter complaining about level-crossing on the Cuncello-Maddalui road.

Are you yet in a position to state whether anything has been done to control this level-crossing during the hours of darkness.

A. E. Young
A. E. YOUNG, Colonel,
Deputy Chief, Public
Safety Sub-Commission.

6233

HEADQUARTERS
SECTION 3, ALLIED COMINT COMMISSION
AFG 394, U.S. ARMY

25 May 1944

BS/5.

SUBJECT: Railway accident.

TO : 2.2.3. 57 Area
HQ, (near) ACC, Public Safety Sub-Commission.

1175
Herewith, for your information, is translation of a letter received from the Governor of Naples relative to a collision between a motor vehicle and a railway train which occurred at Cassalnuovo, Province of Naples, on 21st May 1944.

Oppenel

C. T. FRANCIS
Lieut. Colonel, O.L.
Regional Public Safety Officer.

OTF/to.

623

TRANSLATION

1113

R. QUESTURA DI NAPOLI

Letter File n. 109912-Div. Gabinetto

Naples, 21 May 1944

SUBJECT: Railway incident.

TO : Regional Public Safety Office, R.Prefettura, Naples.

Today at about 12.15 hours, in Casalnuovo, a British truck, licence plate n. 328-948 coming from Naples, at a crossing in the Salice Road, collided with engine n. 212 of the Circumvesuviana train n. 344, which was derailed.

The driver of the British truck tried to cross the rails, notwithstanding that the level crossing keepers Jannotta Iuise di Domenico, born in Casalnuovo the 1 January 1913 and her father Jannotta Domenico di Salvatore, born in Casalnuovo 11 August 1898, both living in Via Purlici n. 1, had given the signal to stop because the train was coming.

It appears that a motor convey heading ~~from~~ Naples took notice of the signal to stop, while the above mentioned British car proceeding in the opposite direction continued its course following closely behind another car that managed to cross the rails.

The driver of the train, Izzo Giacomo fu Natale, of Pugliano was not able to be questioned, because he was wounded and taken away by an Allied Military truck.

The number of casualties, up to now, amounts to 30, who immediately after the accident were transported by Allied vehicles to the city hospitals. Three deaths are regretted, one of which was the driver of the British truck.

No responsibility is attributed to the train driver or the signalling agents at the level crossing. It is recalled, that the manager of the Circumvesuviana, Engineer Vanzai stated that, some time ago, ~~he~~ ^{had} received a request ^{from} made by Allied H.Q. that iron bars at some of the level crossing should not be lowered, at the passing of trains, to avoid any long halts of military vehicles.

Railway services were re-established after about an hour.

JMS/tp.

IL QUESTORE
(G. Lauricella)

HEADQUARTERS
ALLIED CONTROL COMMISSION
Public Safety Sub-Commission

folio (D) for [redacted] /information:

C.P.S.

D.C.P.S.

Police

Prisons

Fire & C.D.

Regn. & Licensing

Adm. Officer ... *PA*

Remarks:

P.A.

6/2/35

ALLIED CONTROL COMMISSION
REGION 2. HEADQUARTERS

Your ref ACC/14610/1/P.S. OFFICE OF THE REGIONAL POLICE OFFICER

My ref PS15 31 st March 1944

Subject warning Lights at Rly Level Crossings

TO : Chief, Public Safety Sub-Commission A.C.C.

The basic communication was forwarded to M
Col Vining, Provincial Commissioner Bari Province
on the 5th March 1944.

A reminder was forwarded this day and a reply
received that the matter has been taken up with
the appropriate Italian authorities requesting
attention to the points raised.

Brookhead
Captain.
Regional Police Officer.

6234

HEADQUARTERS
ALLIED COMINT COMMISSION
Public Safety Sub-Commission

Mr. GA

ACG/14610/ 25.

5 April 1944.

SUBJECT : Level crossings
TO : Internal Transportation Sub-Commission
ACG, Mr. Dr.
U.S.A. (Adv. Section) G.W.P.

qB / 5A

1. With reference to your letter ACG, Tr./125/5 dated 25th March 1944, the attached letter dated 31st March 1944 has been received from the Commanding Officer 3 District complaining that the level crossing on the Caneel-Bulletin road is still uncontrolled at night.
2. It is requested that a reply be sent to this Commission for transmission to 3 District.

W. W. Dugay 6257
Colonel Inf.,
3rd Public Safety
Sub-Commission.

Enclosure
Copy Mr. 3 Dist. Letter No. 253 A.

AFM/VL.

qB

COPY

SUBJECT : - Level crossings.

Rear HQ
ACO

3 District
Tel. Ext. 17
553A
31 March 1944.

- Ref your ACO/14610/1/PS dated 26 March 1944
1. It has been reported that OC 657 Gen Tpt Coy once again approached the level crossing on the Cencello- Maddaloni road at approx 0100 hrs and seeing no watchman, went to his hut to investigate and found him asleep. The watchman stated that he had no means of stopping traffic, other than by waving his arms, and that he is not in possession of a lantern or whistle.
 2. May this please be investigated.

Maj. Gen.
Comd.

623

SUBJECT:- Level crossings

*Public Safety SCA*3 District
Tel Ext 17
353A
14610/1
31 Mar 44Rear HQ
ACC*16A**JL*

Ref your ACC/14610/1/PS dated 26 Mar 44.
1. It has been reported that OC 657 Gen Tpt Coy once again approached the level crossing on the Cancelllo - Maddalona road at approx 0100 hrs and seeing no watchman, went to his hut to investigate and found him asleep. The watchman stated that he had no means of stopping traffic, other than by waving his arms, and that he is not in possession of a lantern or whistle.
2. May this please be investigated.

AMJ/EJP

H. M. W. S. 623
Maj Gen
Comd

File 7A

REAR HEADQUARTERS
ALLIED CONTROL COMMISSION
Public Safety Sub-Commission
APO 394

ACW/14610/1/PB

March 26th, 1944

SUBJECT: warning lights at railway level crossings

TO : RPSO, Region II

1. With reference to No. 2 District letter 25/1264 dated 25th Feb. 1944, forwarded to you from this HQs on 1st March 1944 asking that representations be made to the Italian authorities to place warning lights at the railway crossing between Cassano and San Nicandro, please report the result of your efforts.

M. W. K.
PAUL G. MCKEE *W.M.K.*
Colonel, Inf.
Chief, Public Safety
Sub-Commission

AFW/hgc

6230

Jul 64

REAR HEADQUARTERS
ALLIED CONTROL COMMISSION
Public Safety Sub-Commission
APO 394

ACC/1/610/RS

26th March 1944

SIR/MR: Level Crossing

TO : Commanding Officer, 3 District

HA.

1. Reference is made to your letter dated 7th March 1944, referring to an accident at a railway crossing near Maddaloni station on 31st Jan. 1944, and asking that steps be taken to control this and other railway crossings.
SB
2. This request was passed to the Allied Force Military Railway Service, whose reply dated 26th March 1944 is enclosed for your information.
3. It will be noted that the Allied Force Military Railway Service is prepared to consider providing guards for any crossings specifically brought to their attention.

FOR THE EXECUTIVE COMMISSIONER:

(Signature)

PAIL G. KIRK *Ways*
Colonel, Inf.
Chief, Public Safety
Sub-Commission

AFM/hgd

Platetg Road

Internal Transportation Sub-Commission, ACC., U
c/o Mov & Tn.,
H.Q., A.A.I. (Adm. Echelon),
C.M.F.

2087
5A

Our reference : ACC Tn/123/5

Date : 23 March 44.

TO : H.Q., A.C.C.,
Public Safety Sub-Commission.

14610/1

SUBJECT : Level Crossings.

4A

1. Reference your letter ACC/14610/1/PS.
2. Subject matter has been taken up with the Director General Military Railway Service for the necessary action.
3. Enclosed herewith reply received from the D.G.M.R.S.
4. Reference para 4 D.G.M.R.S. letter, if a list of crossings which it is considered are not properly safeguarded is submitted to this Sub-Commission, the matter will again be submitted to the D.G.M.R.S. for the necessary action.

W.H. Fitch

S.A. FITCH,
Colonel,

Director, Internal Transportation Sub-Commission, ACC.

623B

PA 813

5B

ALLIED FORCE
MILITARY RAILWAY SERVICE
OFFICE OF DIRECTOR GENERAL

A. P. O. 400
20 MARCH 1944

SUBJECT: PROTECTION AT GRADE CROSSINGS

TO: DIRECTOR, INTERNAL TRANSPORTATION SUB-COMMISSION,
ACC, SHOV & TN, HQ, ACMF (ADM ECH), C.U.P.,
APO 400

1. YOURS 18 MARCH, FILE ACC TN/123/5, REFERENCE
COMMUNICATION FROM COL. KIRK, DIRECTOR PUBLIC SAFETY SUB-
COMMISSION, ACC, AS TO HIGHWAY CROSSINGS OVER THE RAILROAD
AT GRADE.

2. AT THE PRESENT TIME GENERALLY, GRADE CROSSINGS
WITH OR WITHOUT GATES ARE GUARDED WITH NECESSARY CIVILIAN
I.S.R. WATCHMEN AND EFFORT IS BEING MADE TO PROVIDE SUCH
WATCHMEN WITH ADEQUATE SIGNALLING FOR BOTH DAY AND NIGHT.

3. THE MILITARY RAILWAY SERVICE HAS NO TROOPS AVAILABLE
FOR ADDITIONAL HIGHWAY CROSSING PROTECTION, BUT AT MOST CROSS-
INGS AT GRADE WHERE MILITARY TRAFFIC IS HEAVY IT DEVOLVES UPON
THE ARMIES TO PROVIDE THE NECESSARY MILITARY POLICE PATROL.

4. IF THERE ARE ANY PARTICULAR OR SPECIFIC CROSSINGS
IN MIND WHICH IN THE OPINION OF COLONEL KIRK DO NOT HAVE PROPER
SAFEGUARDS, WILL BE GLAD TO CONSIDER IF THEY ARE BROUGHT TO
OUR ATTENTION, THE SAME AS HAS ALREADY BEEN DONE WITH REFERENCE
TO THE CROSSING REFERRED TO ONE MILE SOUTHWEST OF MAGDALON STATION.

FOR THE DIRECTOR GENERAL:

CHARLES F. DOUGHERTY
COLONEL, T. C.
ASSISTANT GENERAL MANAGER
TRANSPORTATION DEPARTMENT

CC - CO, 701ST RY GR DIV, APO 400
CO, 703RD RY GR DIV, APO 400
AOTN 3, BUILDING

Ref.File
18610/1

The recent tragedy near
Vado di Potenza will
serve to emphasize the
necessity for much stricter
control of railway travel.

Adm. don ask for
minutes or recommendations.
The only one I can find is
that the matter is primarily
one for the Railway Police
administered by the Ministry
of RR & Civil Transport

Rudolf

LMS

In AMG territory exclusive
mil. control. I unoccupied
territory all concerned Italian
Mafiosi are meeting in
connection with some plot

HEADQUARTERS
ALLIED CONTROL COMMISSION
Public Safety Sub-Commission

Folio 3A for action/information

C.P.S.

D.C.P.S.

Police

Prisons

Fire & C.D.

Regn. & Licensing

Adm. Officer

Remarks:

.....
.....
.....
.....
.....
.....

Heg III

SUBJECT: Level Crossings

3 District
353 A.
Tel ext 17.

74A

7 Mar 44.

Main HQ A.C.C.

1. A number of fatal accidents have occurred due to the inadequate measures in existence for the control of level crossings in Italy area. In most cases it appears that an employee of the Italian State Railways is on duty at the crossings but is not provided with sufficient materials to be effective e.g. there are no barrier gates, flags or lamps for use at night.
2. Such an accident occurred at 1850 hrs on 31 Jan 44, when a WD truck collided with a train at the crossing one mile south west of MAGGIANO station. Although there were no military casualties, seventeen civilians were killed and another fourteen injured. At that time there was no watchman on duty. This has now been rectified but since he has no lamp or flag he is more or less useless.
3. It is requested that urgent steps are taken with the appropriate authority to provide suitable men and equipment to control these crossings, since their deficiency is causing an increasing number of totally unnecessary accidents.

Maj. Gen.
Comd.

62.3

1st IND

ACC/14610/1/RS

From : H.Q. ACC, Public Safety Sub-Commission

To : Internal Transportation Sub-Commission

Herewith a communication from No. 3 District which raises a matter presumably under your jurisdiction.

Paul C. Kirk
 PAUL C. KIRK
 Colonel, Inf.
 Chief, Public Safety
 Sub-Commission

PCX/hgd

SUBJECT:- Level Crossings.

U-1591 Public Safety S.C.

3 District.

353 A.

Tel Ext 17. 576.

7 Mar 44. 3A

Main HQ, A.C.C.

1. A number of fatal accidents have occurred due to the inadequate measures in existence for the control of level crossings in 57 Area. In most cases it appears that an employee of the Italian State Railways is on duty at the crossings but is not provided with sufficient materials to be effective e.g. there are no barrier gates, flags or lamps for use at night.

2. Such an accident occurred at 1850 hrs on 31 Jan 44, when a WD truck collided with a train at the crossing one mile south west of MADDALONI Station. Although there were no military casualties, seventeen civilians were killed and another fourteen injured. At that time there was no watchman on duty. This has now been rectified but since he has no lamp or flag he is more or less useless.

3. It is requested that urgent steps are taken with the appropriate authority to provide suitable men and equipment to control these crossings, since their deficiency is causing an increasing number of totally unnecessary accidents.

A. W. H. 625
Maj Gen Comd

file
2A

SUBJECT: Warning lights at level crossings

HQ No. 2 District, CGW
25/126 A
25 Feb. 44

Allied Control Commission:

1. Three traffic accidents have recently taken place, at the level crossing situated at kilometre 32125' Part - PAINTO railway line between OAS OIC and S. N. VIGANAO.
2. On 7 Jan 44, one G.C.C. was killed and another seriously injured.
3. No warning lights have been displayed since Oct. 1943, and as the approach to this level crossing is particularly dangerous it is requested that the appropriate representation be made to the civilian authorities to install these warning lights, and so avoid a repetition of these fatal accidents.

Major-General
HQ No. 2 District

Copy to: HQ Civil Commission
File D/1

Int. 217

To: GPO, Reg. II
From: HQ, CGC, Public Safety Sub-Commission

1 March 1944

It is requested that action be taken as in paragraph 3 of the basic communication.

Paul Caff
PAUL C. CAFF
Colonel, Inf.
Chief, Civil Safety
Sub-Commission

cc: P.M.C.

1318

28 FEB 1944

(IA)

File No 10101
"Warning lights on roads etc"

SUBJECT:- Warning Lights at Level Crossing

HQ No 2 District, GP

29/126 A

25 Feb 44

YR

Allied Control Commission

1. Three traffic accidents have recently taken place, at the level crossing situated at Kilometre 321258 VANI - PARANTO railway line between OSSIANO and SAN PIACAMBO.

2. On 7 Jan 44 one N.C.O. was killed and another seriously injured.

3. No warning lights have been displayed since Oct 1943, and as the approach to this level crossing is particularly dangerous it is requested that the strongest representations be made to the Italian authorities to restore these warning lights, and so avoid a repetition of these fatal accidents.

Miles G. S.
Capt
for Major-General
Comd No 2 District

Copy to:- No 4, Claims Commission
File 147 A

