

785020

ACC

10000/120/2700

ST/444

4

10000/120/2700

ST/444 N-14. Repair Unit. Sardinia
Ap 1945

48 1224

1	2	3	4	5	6	7	8
<u>149 MEMPHIS SEPARAZIONE</u>							
Autovetture	04576						
Motoricelli	41019						
	37504						
Autoservizi log. e							
pas.	131772						
	013648						
	026893						
	114079						
	137735						
	69281						
	64280						

1224

04578

41019

37504

131772

013648

024853

114079

137735

69281

64280

48

Y AED/mt

2

LIAISON OFFICER
LAND FORCES SUB COMMISSION
ALLIED COMMISSION (MMIA)
A.P.O. 394, U.S. Army

26 April 1945

SUBJECT: Windshield Labels

TO : Commanding General, Land Forces Sub Commission, A.C. (MMIA)

1. Reference your letter ST/1001 dated 7 April 1945 and our letter of 17 April 1945 subject as above.
2. On reviewing we find that the MMIA Certificate Numbers for the No. 14 Repairs Unit (Appendix "E" of our letter of 17 April) were incorrectly prepared. The MMIA Certificate Numbers should read from 281 through 290 instead of 181 through 190.
3. Our records and certificates have been amended accordingly.

"S & T. MMIA.

Recd

ST/

Lester R. Albert
LESTER R. ALBERT
Lt. Colonel, Infantry
Senior Liaison Officer

not

just

37

14° REPARTO RIPARAZIONI

-----●●-----

XPA 1224

T I P O	T A R G A	N° CERTIFICATO CIRCOLAZIONE
Spa L.39	RE. 131772	181 281
Fiat 614	" 013648	182 282
Fiat 634	" 024853	183 283
Lancia 3 RO	" 114079	184 284
Moto Gilera	" 41019	185 285
" Guzzi/Alice	" 37504	186 286
Spa L.39	" /2373 137735	187 287
Spa 38	" 69281	188 288
" "	" 64280	189 289
Fiat 1100	" 04578	190 290

V.D.N. 104.26/4-45-40 A.P.O. 394 U.S. ARMY



Spa L.39
Fiat 614
Fiat 634
Lancia 3 RO
Mete Gilera
" Guzzi/Alice
Spa L.39
Spa 38
" "
Fiat 1100

RE. 131772
" 013648
" 024853
" 114079
" 41019
" 37504
" /1373 137735
" 69281
" 64280
" 04578

181 281
182 282
183 283
184 284
185 285
186 286
187 287
188 288
189 289
190 290

INDEX 20/4-45 - LO 4.R.O 394 U.S.A.M.M

[Handwritten signature]

30

0592