

1320

Declassified E.O. 12356 Section 3.3/NND No. 785021

ACC

AC121/TN 4

10000/148/2215

WAGO
SEPT. 19

10000/148/2215

WAGONS - GENERAL

SEPT. 1944 - JUL. 1945

1922

Declassified E.O. 12356 Section 3.3/NND No. 785021

Invent.	Gen Order		Gen Order		Remarks
	Serviceable	Use	Location	Remarks	
BZ 20042	Yes	NAPLES - BARI			
" 20057	"	BARI			
" 20059	"	B.6 Ambulance			
" 20060	"	Flagstaff			
" 20064	"	B.3 Ambulance			
" 20070	"	B.7 Ambulance			
" 20089	"	NAPLES			
" 20106	"	ROME Pool			
" 20116	"	Car for Rome 13/4	NAPLES	Very heavy repairs	
" 20121	"	ROME	ROME	REPAIRED w/ 20% by local	
" 20133	"	BARI	ROME	REPAIRED w/ 14% Roof & Side damage	
" 20137	"	ROME	NAPLES	Interior Stripped	
" 20155	"	ROME Pool			
" 20156	"	B.5 Ambulance			
" 20164	"	ROME Pool			
" 20191	"	BARI			
" 20201	"	Leaves			
" 20202	"	B.6 Ambulance			
" 20210	"	ROME Pool			
" 20214	"	FLORENCE			
" 20227	"	ROME Pool			
" 20228	"	ROME Pool			
" 20250	"	BARI			
" 20269	"	Flagstaff			
" 20577	"	BARI			
" 21035	"	ROME Pool			
" 21054	"	B.1 Ambulance			
" 21060	"				
" 21072	"				

3908

Interior Stripped

1923

20004	"	B.3 Ambulance			
20070	"	B.7 Ambulance			
20089	"	NAPLES			
20106	"	ROME Pool			
20116	"	Sp. for June 18/4			
20121	"	ROME	ROME	Very heavy repairs	
20133	"	ROME	ROME	REPAIRED w/ 20%	
20137	"	ROME	ROME	REPAIRED w/ 14%	
20190	"	ROME	NAPLES	Roof & Side damage	
20195	"	ROME	NAPLES	Interior Stripped	
20196	"	ROME Pool			
20164	"	B.5 Ambulance			
20191	"	ROME Pool			
20201	"	ROME			
20202	"	Leave			
20210	"	B.6 Ambulance			
20214	"	ROME Pool			
20227	"	FLORISS			
20228	"	ROME Pool			
20250	"	ROME			
20269	"	Flagstaff			
20577	"	ROME			
21035	"	ROME Pool			
21054	"		Scrap		
21060	"	B.1 Ambulance			
21072	"		NAPLES	Interior Stripped	

3905

3/22 21079

1924

Prefix	Number	Good Order		Bad Order	
		Serviceable	Use	Location	Remarks
BZ	21079	Yes	B.2 Ambulance	FLORENCE	Waiting Repairs
"	21098	"	NAPLES		
	23379	"	NAPLES		
	24202	"	BARI		
	24232	"		NAPLES	Interior Stripped
	24235	"	Leave		
	24238	"	BARI		
	24252	"	B.4 Ambulance		
	24258	"	Leave		
	24261	"		NAPLES	Interior Stripped
	24278	"		ROME	Waiting Wagon Lits Hops
	24290	"	BARI	NAPLES	Interior Stripped
	24301	"			
	24321	"	ROME POOL		
	24328	"	B.3 Ambulance		
	24346	"		NAPLES	Scrap
	24401	"		SALERNO	Scrap
	24406	"		ROME	Parts Order
	24420	"	BARI		
	24432	"	BARI		
	24702	"		NAPLES	
	28003	"		ARSENAL	
	28009	"	BARI	ARSENAL	
	28030	"	SALERNO		
	28035	"		SALERNO	Scrap
	28064	"		NAPLES	Interior Stripped
	28067	"	BARI		
	28068	"	NAPLES		

3905

24235		NAPLES	Interior Stripped
24238	Leave		
24252	BARI		
24258	B.4 Ambulance		
24261	Leave		
24278		NAPLES	Interior Stripped
24290	BARI		
24301		NONE	Waiting Wagon Lite Shop
24321		NAPLES	Interior Stripped
24328	ROME Pool		
24346	B.3 Ambulance		
24401		NAPLES	Scrap
24406		SALERNO	Scrap
24420	BARI		
24432		ROME	Pair Order
24702	BARI		
28003		SACCA AREZZO	2905
28009	BARI		
28030	SALERNO		
28035		SALERNO	Scrap
28064		NAPLES	Interior Stripped
28067	BARI		
28068	NAPLES		

4/ 28070

Profile	Number	Good Order		Bad Order	
		Serviceable.	Use.	Location.	Remarks.
	28070	Yes	NAPLES		
	28073	"	NAPLES-BARI		
	28079	"	BARI		
	28082	"	NAPLES-BARI		
	28140	"	ROME Pool		
	28149			PLURANCE	Waiting Heavy Repairs
	28170	"	BARI		
	28502	"	ROME Pool		
ELS	28539			NAPLES	Interior Stripped & bogie damaged
"	28914	"	BARI		
"	28920	"		FORLI	Scrap
"	28966	"	B. Ambulance		
"	29113			NAPLES	Interior Stripped
"	29130	"	NAPLES-BARI		
"	29131	"	ROME Pool		
"	29159	"	BARI		
"	29161			NAPLES	Interior Stripped
"	29197	"	BARI		
"	29277	"	BARI		
"	29313			NAPLES	Interior damaged
"	29322	"	ROME	Line 257	Interior Stripped
"	29375	"	ROME	ROME	Repairs at Wagon Lits
"	29383	"	NAPLES-BARI		
"	29411			NAPLES	Interior Stripped
"	29422	"	NAPLES		
"	29432	"	B. Ambulance		
"	29447			NAPLES	Interior Stripped
"	29455	"	B. Ambulance		
"	29469			SACCHI	

1927

				Repairs
28149	"	BARI	INTERLUS	Interior Stripped & bogie damaged
28170	"	ROME Pool		
28502	"			
28539	"	BARI	FORLI	Scrap
28914	"	B. Ambulance		
28920	"	NAPLES-BARI		
28966	"	ROME Pool		
29113	"	BARI		
29130	"	BARI	NAPLES	Interior Stripped
29131	"	BARI		
29159	"	BARI		
29161	"	BARI		
29177	"	BARI		
29277	"	BARI		
29313	"	ROME	NAPLES	Interior damaged
29322	"		Line 257	Interior Stripped
29375	"		ROME	Repairs at Wagon bits
29383	"	NAPLES-BARI		
29411	"		NAPLES	Interior Stripped
29422	"	NAPLES		
29432	"	B. Ambulance		
29447	"		NAPLES	Interior Stripped
29455	"	B. Ambulance		
29469	"		SACCHI ALBERTO	390 1/2

5/312 29470

BIR	29470	Food Order		Location	Food Order	
		Serviceable	Use		Remarks	Remarks
"	29476			ROMA	Needs interior re-	maire.
"	29559	Yes	B.2 Ambulance	MAPLES	Interior Stripped	
On	30012			MAPLES	Interior Stripped	& sides down
"	30019	Yes	Leave			
"	30035	"	ROME Pool			
"	30032	"	ROME Pool			
"	30044	"	BARI			
"	30050	"	ROME Pool			
"	30052	"	Leave			
"	30075	"	ROME Pool			
"	30088	"	ROME Pool			
"	30100	"	MAPLES-BARI			
"	30109			MAPLES	Interior Stripped	& large hole in roof.
"	30113			CAMPORANCO Line	Interior Stripped	
"	30120	"	Leave			
"	30123	"	ROME Pool			
"	30133	"	BARI			
"	30139	"	ROME Pool			
"	30144	"	BARI			
"	30145	"	ROME Pool			
"	30149	"	ROME Pool			
"	30151	"	ROME Pool			
"	30156	"	BARI			
"	30157	"	MAPLES-BARI			
"	30159	"	ROME Pool			

30019	"	Leave		
30025	"	HOME Pool		
30032	"	HOME Pool		
30044	"	BARI		
30050	"	HOME Pool		
30052	"	Leave		
30075	"	HOME Pool		
30088	"	HOME Pool		
30100	"	WATER-BARI		
30109	"			
30113	"			
30120	"	Leave		
30123	"	HOME Pool		
30133	"	BARI		
30139	"	HOME Pool		
30144	"	BARI		
30145	"	HOME Pool		
30149	"	HOME Pool		
30151	"	HOME Pool		
30156	"	BARI		
30157	"	WATER-BARI		
30169	"	HOME Pool		
30181	"	Leave		

Interior Stripped
a Large hole in
roof.

Interior Stripped

RIPLES

CAMPOBANSO
Line

3903

6/02 30188

30428	"	HAPLES	ROME	REPAIRED w/1200000	Heavy Repairs
30506	"	"	FLORENCE		
30517	"	"	"		
30529	"	"	ROME Pool	CAMPORASSO	Requires medium repairs
30531	"	"	"	Line	
30543	"	"	BARI	ROME	Interior Stripped & one end damaged
30544	"	"	BARI		
30565	"	"	BARI		
30574	"	"	"		
30581	"	"	HAPLES-BARI	HAPLES	Interior Stripped & two large holes in roof.
30583	"	"	BARI		
30586	"	"	"		
30588	"	"	Flagstaff		
30600	"	"	ROME - Pool	CAMPORASSO	Medium repairs
30624	"	"	Leave	Line	
30638	"	"	BARI		
30639	"	"	ROME Pool		
30654	"	"	BARI		
30657	"	"	BARI		
30674	"	"	"		
30693	"	"	ROME Pool	ROME	Waiting repairs
31002	"	"	"		

3902

8/02 31015

Proj.	Number	Good Order		Bad Order	
		Serviceable	Use	Location	Remarks
GDAY	67497	Yes	NAPLES		
"	65022	"	NAPLES		
"	65043	"		ROME	Interior damaged
"	71164	"	BARI		
"	71453	"	BARI		
"	73606	"	BARI		
CI	73521	"	ROME	ROME	REPAIRED AT W/L 36 SEATS
DR. HCL	207239	"	ROME	ROME	REPAIRED AT W/L 60 SEATS
DR. HCL	12191	"	ROME	ROME	REPAIRED AT W/L 68 SEATS

1964

Declassified E.O. 12356 Section 3.3/NND No. 785021

Prefix.	Number.	Used Order.		Used Order.	
		Serviceable.	Use.	Location.	Remarks.
ABs	50665			ROME	Waiting Wagon Lits shops
"	50668	Yes	ROME Tool		
"	50683	"			
"	50685	"	ROME-BARI		
"	50693	"	Leave		
"	50702	"	B.2 Ambulance		
"	50709	"	BARI		
"	52000	"	BARI		
"	52013			ROME	Waiting Wagon Lits shops
"	52046			ROME	Scrap
"	52047	"	B.5 Ambulance		
"	52114			NAPLES	Interior Stripped
"	52134	"	B.7 Ambulance		
"	52329	"	BARI		
"	53825	"	NAPLES		
"	54315	"	NAPLES-BARI		
"	54347			Granilla shops	Undergoing repairs
"	54362			ROME	Waiting Wagon Lits shops
"	54413	"	NAPLES		
"	54418	"	BARI		
"	54456	"	Leave		
"	54479			BARI	Scrap
"	54485			BARI	3884
"	54533			ROME	Interior damaged
"	54614			ROME	Repair at W.L.
"	54615			NAPLES	Scrap
"	54616			NAPLES	Scrap

Prefix.	Number.	Good Order.		Bad Order.	
		Serviceable.	Use.	Location.	Remarks.
	54620	Yes	ROME Pool		
	54621	"	B.1 Ambulance		
	54628	"	BALTIMO		
	54630	"	ROME Pool		
	54646	"	BARI		
	55008	"	BARI		
	55020	"	BARI		
	56666	"	BARI		
	58462	"	ROME Pool		
	58474	"		NAPLES	Interior Stripped
	58476	"	BARI		
	58483	"	BARI		
	58496	"	BARI		
ABLY	58629	"	BARI		
"	58630	"	BARI		
"	58634	"		NAPLES	Interior damaged
"	58696	"	ROME Pool		
"	58827	"	NAPLES		
ABIS	59136	"		NAPLES	Interior damaged
"	59141	"	B.8 Ambulance		
"	59142	"		NAPLES	Interior stripped
"	59155	"		ROME	Interior Stripped
"	59193	"	BARI		
"	59195	"	NAPLES		
"	59196	"	NAPLES		
"	59231	"	NAPLES		
"	59241	"	NAPLES		

3883

54630	ROME Pool	"	ROME Pool	Interior Stripped
54646	BARI	"	BARI	
55008	BARI	"	BARI	
55020	BARI	"	BARI	
56666	BARI	"	BARI	
58462	ROME Pool	"	ROME Pool	
58474	BARI	"	BARI	
58476	BARI	"	BARI	
58483	BARI	"	BARI	
58496	BARI	"	BARI	
58629	BARI	"	BARI	
58630	BARI	"	BARI	
58634	ROME Pool	"	ROME Pool	
58696	NAPLES	"	NAPLES	
58827	NAPLES	"	NAPLES	
59136	B.6 Ambulance	"	B.6 Ambulance	
59141	NAPLES	"	NAPLES	
59142	NAPLES	"	NAPLES	
59155	NAPLES	"	NAPLES	
59193	NAPLES	"	NAPLES	
59195	NAPLES	"	NAPLES	
59196	NAPLES	"	NAPLES	
59231	NAPLES	"	NAPLES	
59941	NAPLES	"	NAPLES	
60078	BARI	"	BARI	

3883

23/ABCE 61005

1968

Declassified E.O. 12356 Section 3.3/NND No.

785021

each Nos.	Prefix	No of Axles	No of Seats	Date of Construction	Average Pass- enger.	Compartment or open type coach.	No of Lays.	Position of Lavatories.	
10000 - 10099	Am	4	42	1926	40.4	Compartment	2	End	
11000 - 11049	Am	4	48	1931	41.5	"	2	"	
13000 - 13001	Am	4	48	1939	38.5	"	2	"	Boi Lic sto
18650 - 19084	Ala	4	39 - 42	1926		"	1	End of Centre	
20000 - 20270	Ba	4	60	1920-1929	40.3-42.8	"	2	End	
21000 - 21114	Ba	4	72	1931	41.3	"	2	"	
23000 - 23003	Ba	4	64	1939	38.5	"	2	"	Boi Lic sto
27050 - 27092	By	3	44			"	1	Centre	
27400 - 27467	By	3	46			"	1	"	
28500 - 28609	Dlx	4	60	1914		"	1	"	
28820 - 28858	Bla	4	56 - 60	1900 -		"	1	End of Centre	
28980 - 29481	Bla	4	56 - 60	1907 -		"	1	" " "	
29500 - 29562	Bla	4	60	1910		"	1	Centre	
30000 - 30709	Ga	4	80	1924 - 1927	40.1	"	2	End	
31000 - 31142	Ga	4	98	1931	41.0	"	2	"	
32000 - 32794	Ga	4	80	1937 - 1938	39.6-42.0	"	2	"	
33000 - 33009	Ga	4	80		39.9	"	2	"	
34000 - 34014	Gly	3	48	1929	37.7	Open	1	"	
34400 - 34614	Gly	3	54	1929	32.4	"	1	"	
35000 - 35099	GT	2	87	1936	31.7	"	1	"	
35400 - 35409	GT	2	87	1938	31.7	"	1	"	
36000 - 37495	Ga	4	78	1927-1931	34.2	"	2	"	
38100 - 38195	GT	2	34			"	-	-	
38100 - 38399	GT	2	34			"	-	-	
38665 - 38699	GT	2	34			"	-	-	
38800 - 38884	GT	2	34			"	-	-	
39000 - 39010	Ga	4	80	1929	35.0	"	2	Centre	
41200 - 41769	Gla	4	80	1910		"	1	"	
41700 - 41711	Gla	4	80	1910		"	1	"	

785021

1969

No. of Axles.	No. of Seats.	Date of Constr.	Average Fare-Tenney.	Compartment or open type coach.	No. of Lays.	Position of Lavatories.	Remarks.
4	42	1926	40.4	Compartment	2	End	
4	48	1934	41.5	"	2	"	
4	48	1939	43.5	"	2	"	Built in stainless steel. Lightweight high-speed stock.
4	32 - 42	1906		"	1	End of Centre	
4	64	1926-1929	40.3-42.8	"	2	End	
4	72	1931	41.3	"	2	"	
4	64	1939	43.5	"	2	"	Stainless steel. High speed stock on S.A. and S.F.M.
3	44			"	1	Centre	" " " "
3	44			"	1	"	
4	60	1914		"	1	"	
4	56 - 60	1906 -		"	1	End of Centre	
4	56 - 60	1907 -		"	1	" " "	
4	60	1930		"	1	Centre	
4	30	1924 - 1927	40.2	"	2	End	
4	36	1931	41.0	"	2	"	
4	30	1937 - 1938	39.6-42.0	"	2	"	
4	30		39.9	"	2	"	Still under construction at June 1942.
3	48	1929	31.7	Open	1	"	
3	50	1929	32.4	"	1	"	
2	37	1936	31.7	"	1	"	
2	37	1938	31.7	"	1	"	
4	78	1923-1931	34.2	"	2	"	
2	34			"	-	-	on S.F.M.
2	34			"	-	-	" "
2	34			"	-	-	" "
2	34			"	-	-	" "
4	80	1929	35.0	"	2	Centre	
4	80	1930		"	1	"	
4	80	1935		"	1	"	

1970

Coach Nos.	Prefix.	No of Axles.	No of Seats.	Date of Contg.	Average Cars - Tonnes.	Compartment or open type coach	No of Lave.	Position of Lavatories.
41500 - 41999	CLs	4	80	1907 -		Open	(2 (1	End Centre
42050 - 42999	CLs	4	75	1907 -		"	2	End
44000 - 44259	CLs	4	70			"	1	Centre
44250 - 44399	CLs	4	73			"	1	"
46000 - 47009	CT	2	90	1933	20.2	"	1	"
50100 - 50369	ABs	4	18/36	1921-1924	40.0	Compartment	2	End
50500 - 50715	ABs	4	18/36	1929	42.5	"	2	"
52000 - 52149	ABs	4	18/33	1937	42.0	"	2	"
53000 - 53001	ABs	4	18/48		28.4	"	2	"
58616 - 58655	ABLy	3	9/24			"	1	"
58900 - 58917	ABLy	4	18/32	1914		"	1	Centre
59086 - 59451	ABLy	4	18/32	1906		"	2	End
59452 - 59599	ABLy	4	18/32	1910		"	(1 (2	Centre End
59655 - 59669	ADT	2	16/24			"	1	Centre
61000 - 61029	ABOs	4	12/16/32	1914	41.5	"	2	End
65000 - 65099	BCI	2	24/49	1936-1938	21.0	Open	1	Centre
65500 - 65509	BCDI	2	16/49	1936	21.7	"	1	"
66200 - 66209	BCDT	2	16/50	1933	20.5	"	1	"
66500 - 66551	BCs	4	40/23	1933-1934	35.8	Open 3/ Compartment	2	"
67000 - 67069	CDLy	3	40	1931	21.8	Open	1	"
67200 - 67249	CDLy	3	40	1931	22.1	"	1	"
67400 - 67449	CDLy	3	40	1931	21.7	"	1	"

03
08
00
14

1971

No. of Axles.	No. of Gears.	Date of Contr.	Average Horse - Power.	Compartment or open type coach	No. of lavs.	Position of lavatories.	Remarks.
4	80	1907 -		Open	(2)	End	
					(1)	Centre	
4	76	1907 -		"	2	End	
4	78			"	1	Centre	Y ex Austrian
4	78			"	1	"	" " "
2	50	1933	20.2	"	1	"	
4	18/36	1921-1924	40.0	Compartment	2	End	
4	18/36	1929	42.5	"	2	"	
4	18/33	1937	42.0	"	2	"	
4	18/48		28.4	"	2	"	Still under construction at June 1942.
3	9/24			"	1	"	
4	18/32	1934		"	1	Centre	
4	18/32	1906		"	2	End	
4	18/32	1930		"	(1)	Centre	
					(2)	End	
2	18/24			"	1	Centre	ex R.M.
4	12/18/32	1934	41.5	"	2	End	
2	24/48	1936-1938	21.0	Open	1	Centre	
2	16/48	1936	21.7	"	1	"	
2	16/50	1933	20.5	"	1	"	
4	18/23	1933-1934	35.8	Open 3/ Compartment	2	"	
3	40	1931	21.8	Open	1	"	
3	40	1931	22.1	"	1	"	
3	40	1931	21.7	"	1	"	

3881

Pescara 16 Feb. 1945

SITUATION OF ROLLING STOCK AT PESCARA CENTRAL STATION

n°	Series Number of car	Mat.	Type	Axles	Brake	Loaded or empty	Conditions	Remarks
1	Hall	G.	Box	2	none	empty	good	
2	F	F.	"	2	"	"	"	
3	Kuffs	G.	"	"	"	"	"	
4	Hall	"	"	"	"	"	"	
5	Kass	"	H.S.	"	Yes	"	"	
6	"	"	"	"	none	"	"	
7	P.	I.	Flat	2	Yes	"	"	
8	L.	"	H.S.	"	"	"	"	
9	L.	"	"	"	none	"	"	
10	Kass	G.	"	"	"	"	"	
11	"	"	"	"	"	"	"	
12	L.	I.	"	"	Yes	"	"	
13	Kuffs	G.	"	"	none	"	"	Milling machinery
14	L.	I.	Flat	"	"	machy	"	
15	Kuffs	G.	H.S.	"	"	empty	"	Chloride
16	Hall	"	"	"	"	loaded	"	
17	"	"	"	"	Yes	empty	"	One steel block
18	Essen	"	Box	"	none	loaded	"	Tube coils
19	Hall	"	Flat	"	"	"	"	"
20	Kass	"	H.S.	"	"	"	"	Steel blocks
21	"	"	"	"	"	"	"	machinery
22	Hall	"	"	"	"	"	"	"
23	Stett	"	"	"	Yes	"	"	empty iron barrels
24	L.	I.	"	"	none	"	"	"
25	L.	"	"	"	Yes	"	"	"
26	hall	G.	"	"	none	"	"	"
27	L.	I.	"	"	"	empty	"	3890
28	P.	I.	Flat	"	"	"	"	

Sheet no2

3879

no	Series Number of car	Nat.	Type	Axles	Brake	Loaded or empty		conditions	Remarks
						none	empty		
40	Essen	G.	Flat	2	none		empty	Good	
41	"	"	"	"	Yes		"	"	
42	L.	I.	H.S.	"	none		"	"	
43	Essen	G.	"	"	"		"	"	
44	"	"	"	"	"		"	"	
45	"	"	"	"	"		"	"	
46	Hall	"	"	"	"		"	"	
47	"	"	"	"	Yes		"	"	
48	Essen	"	"	"	none		"	"	
49	L.	I.	"	"	"		"	"	
50	Hg.	"	Refr.	"	Yes		"	heavy repairs	
51	E.	"	Box	"	"		"	"	
52	F.	"	"	"	"		"	"	
53	F.	"	"	"	"		"	"	
54	Hg.	"	Refr.	"	"		"	"	
55	Hall	G.	Box	"	none		"	"	
56	E.	I.	"	"	"		"	"	
57	Hg.	"	Refr.	"	Yes		"	"	
58	Hg.	"	"	"	"		"	"	
59	G.	I.	Box	"	none		"	"	
60	E.	"	"	"	"		"	"	
61	E.	"	"	"	Yes		"	"	
62	F.	"	"	"	none		"	"	
63	G								

1975

		G.	Flat	2	none	empty	Good	
40	Essen	939755	"	"	Yes	"	"	
41	"	938778	"	"	none	"	"	
42	L.	495516	H.S.	"	"	"	"	
43	Essen	86335	"	"	"	"	"	
44	"	83445	"	"	"	"	"	
45	"	939504	"	"	"	"	"	
46	Hall	62348	"	"	Yes	"	"	
47	"	91860	"	"	none	"	"	
48	Essen	939654	"	"	"	"	"	
49	L.	412776	Refr.	"	Yes	"	"	heavy repairs
50	Hg.	300504	Box	"	"	"	"	"
51	E.	1025034	"	"	"	"	"	"
52	F.	153256	"	"	"	"	"	"
53	F.	183895	"	"	"	"	"	"
54	Hg.	301485	Refr.	"	"	"	"	"
55	Hall	39316	Box	"	none	"	"	"
56	E.	1021924	"	"	"	"	"	"
57	Hg.	543223	Refr.	"	Yes	"	"	"
58	Hg.	304818	"	"	"	"	"	"
59	G.	7270168	Box	"	none	"	"	"
60	E.	1007701	"	"	"	"	"	"
61	E.	1019079	"	"	Yes	"	"	"
62	F.	7110793	"	"	none	"	"	"
63	Gc.	201491	"	"	Yes	"	"	"
64	F.	158572	"	"	none	"	"	"
65	E.	1023022	"	"	Yes	"	"	"
66	F.	7104452	"	"	"			

Sheet no3

n°	Series	Number of car	Nat. Type	Axles	Brake	Loaded conditions		Remarks
						or	empty	
91	L.	414048	I.	H.S.	2	Yes	empty	Heavy repairs
92	L.	485760	"	"	"	none	"	"
93	L.	484775	"	"	"	"	"	"
94	Essen	470593	G.	"	"	"	"	"
95	Hall	29600	"	"	"	"	"	"
96	L.	475018	I.	"	"	"	"	"
97	Hall	17251	G.	"	"	Yes	"	"
98	L.	493182	I.	"	"	none	"	"
99	Hall	16531	G.	"	"	"	"	"
100	L.	400279	I.	"	"	"	"	"
101	L.	412735	"	"	"	Yes	"	"
102	Cz.	32313	I.	Coadm	4	none	"	"
103	Cz.	36836	"	"	"	Yes	"	"
104	C.	35052	"	"	"	"	"	"
105	Cz.	32009	"	"	2	"	"	"
106	Cz.	32147	"	"	4	"	"	"
107	Cz.	36916	"	"	"	"	"	"
108	Dz.	88359	"	"	"	"	"	"
109	Dn.	99364	"	Luggage	"	"	"	"
110	E.	1020701	"	"	2	"	"	"
111	Hg.	307173	"	Box	"	none	"	Demolition
112	Ess	51583	"	Refr.	"	"	"	"
113	Hall	79545	D.	Box				

Sheet no 4

n°	Series Number of car	Nat.	Type	Axles	Brake	Loaded conditions or empty	demolition	transformers	Remarks
143	Stett	44772	G.	H.S.	2	none	loaded	transformers	
144	"	6811	"	"	"	"	empty	"	
145	Hall	68957	"	"	"	"	"	"	
146	Kuff	80442	"	Flat	"	"	"	"	
147	Hall	12717	"	H.S.	"	"	"	"	
148	34593	34593	"	"	"	"	"	"	
149	Bessen	28944	"	"	"	"	"	"	
150	"	19084	"	"	"	"	"	"	
151	"	18176	"	"	"	"	"	"	
152	"	7244	"	"	"	"	"	"	
153	"	628610	"	"	"	"	"	"	

There are further 16 vehicles (2 coaches, 2 tankers, 14 wagons) completely burnt out; all scraps.

Nat. means nationality : I. = Italy; G. = Germany; F. = France

Pescara, 16 February 1945

3897

