0002

Declassified E.O. 12356 Section 3.3/NND No. 785021

ACC AC/2321 T104 10000/148/2312 W AGO (Acc. 19 HAR.-A

Declassified E.O. 12356 Section 3.3/NND No. 785021

10000/148/2312 (U) AGONS- STATISTICS
(AUG. 1944)
MAR.-APR. 1945

Declassified E.O. 12356 Section 3.3/NND No. 785021

ITALIAN VEHICLE SITUATION - [illegible] DIVISION - 12 Aprile 1945

PRIGIONIERI DELLO STATO
SEZIONE MOVIMENTO
COMPARTIMENTO DI NAPOLI

Type of Equipment	In Service	In short repairable	Requires Major Overhaul	For Demolition
Az - 1st Class coach	1	4	-	5
Bz - 2nd " "	-	24	3	13
ABz - Mixed 1 & 2nd cl. coach	-	20	1	8
Cz - 3rd class coach	27	73	5	21
Ci - " " " 2 axle	14	13	-	5
Carrod.Ci - Van with seats	1	2	-	8
Dz - Brake van ½ axle	3	15	-	23
DUI/D " " 2 "	27	69	8	39
Chiusi - Box Wagons	1260	1270	257	956
Alto sponde - high sides	1924	749	149	573
Pianali - Flats	535	285	57	153
Poz - Tank transport	52	57	6	34
Refrigerante - Refrigerator	53	61	24	10
Tank Wagons				
Acqua - Cisterna	32	5	3	3
Vino - Vino	26	19	2	5
Olio Oil	22	16	6	8
Petrolio - Petrol	140	33	2	36
Grano	31	-	-	-
Copertoni - Carpaulin	26	2	317	-
Carbone - Coals	18	-	-	-

IL CAPO DELLA SEZIONE MOVIMENTO
1

0005

Declassified E.O. 12356 Section 3.3/NND No. 785021

SLB/ag 232 A/35

TRANSPORTATION SUB-COMMISSION, A.C.,
(RAIL DIVISION)
C/o Transportation Increment,
C.M.F.

Tel : 343403
Our ref: AC/232A/Tn.4.

14 April 1945

TO : MAJOR LONDON
M.R.S. Building

SUBJECT: Recovery of Equipment.

1. Herewith recovery of equipment return in respect of Reggio Division for period 16-31 March 45.

S.L.B.
S.L. BAXTER, Major
for Chief of Rail Division.

Situation of the rolli[illegible] stock on March 31st 1945

	COACHES	BAGGAGE	BOX	HIGH-SIDED	LOW-SIDED	FLATS	REFRIGERATORS	TANKS	OTHER	TOTALS
a) Number of vehicles under light repair or waiting for light repair	=	=	=	=	=	=	=	=	=	=
b) Number of vehicles under heavy repair or waiting for heavy repair.	21	28	288	168	122	50	12	14	=	703
c)Number of vehicles available for repair	12	5	98	7[illegible]	[illegible]	6	2	5	=	258

Declassified E.O. 12356 Section 3.3/NND No. 785021

0 0 0 7

Declassified E.O. 12356 Section 3.3/NND No. 785021

TRANSPORTATION SUB=COMMISSION A.C.

ALLIED CONTROL COMMISSION

PROVINCE OF REGGIO IN CALABRIA

SUBJECT: RECOVERY OF EQUIPMENT REF: 4 66
5 APR 45

TO: TN. S.C. A.C.
(Rail Div)
C/O TN. INC.
C.M.F.

1. Your AC/232 A/TN 4 of 24 Mar refer.

2. Heremith Report of Rolling Stock 16-31 Mar 45 called for in your AC/232 A/TN 4 of 16 Mar 45 para 3.

3. It will be noticed that no wagons or coaches have been recovered in the period as forecast in our Re 1/12/1/2 of 16 Mar 45, para 3.

B. W. Boddy

B. W. BODDY
CAPTAIN
DIVN. SUPT. TPTN. S.C.A.C.
REGGIO CAL.

Situation of the rolling-stock on March 31st 1945

Rapporto situazione materiale rotabile al 31 marzo 1945

	VETTURE	BAGAGLIAI	CHIUSI	ALTE SPONDE GON	BASSE SPONDE GON	PIANALI	FRIGO RIFERI	SERBATOI	ALTRI	TOTALE
a) Numero veicoli in corso o in attesa piccole riparazioni	=	=	=	=	=	=	=	=	=	=
b) Numero di veicoli in attesa o in corso grande riparazione	21	28	288	168	122	50	12	14	=	703
c) Numero veicoli disponibili che possono essere riparati	12	5	98	78	52	6	2	5	=	258

coaches baggage box high-sided low-sided floats refrigerators Tanks others Totals

a) Number of vehicles under light repair or waiting for light repair

b) Number of vehicles under heavy repair or waiting for heavy repair

c) Number of vehicles available for repair

Declassified E.O. 12356 Section 3.3/NND No. 785021

0 0 0 9 1

Declassified E.O. 12356 Section 3.3/NND No. 785021

RAILWAY VEHICLES UNDER REPAIR - VEICOLI IN RIPARAZIONE -

Situation at midnight, 5 aprile 1945

FERROVIE DELLO STATO
SEZIONE MOVIMENTO
COMPARTIMENTO DI NAPOLI

Type of Equipment	In Service	In shops for repairs	Awaiting Light repairs	For Demolition
Az - 1st Class coach		10		5
Bz - 2nd " "	1	29		16
ABz - Mixed 1 & 2nd cl. coach	2	18	2	7
Cz - 3rd class coach	15	62	3	64
Ci - " " " 2 mdo	21	26	6	4
Carrod.Ci - Lyon with seats		2	1	
Dz - Brake van 2 mdo	4	16		15
DUI/D " " 2 "	24	85	12	34
Chiusi - Box Wagons	1508	1335	284	928
Alto sponde - High sides	1473	1083	194	488
Pianali - Flats	644	408	85	134
Pos - Tank transports	85	61	10	21
Refrigerante - Refrigerator	266	66	32	11
Locomotives				
Acqua - Cisterna	17	10	1	4
Vino - Vino	50	18	14	5
Olio Oil	35	16		3
Petrolio - Petrol	103	24	3	23
Condizioni - Air conditi	11	4		
Carbone - Coaling	18		943	

IL CAPO DELLA SEZ[illegible]
Movimento

Declassified E.O. 12356 Section 3.3/NND No. 785021

...AIX VEHICLE DIAGRAM - ...ITAS CIVILE -

...ccl ordine s. ... 29 Marzo 1945

FERROVIE ...
SEZIONE MOVI...

Type of Equipment	In Service	In shops Ferrovieri	Required this week	For Demolition
Az - 1st Class coach		6	1	4
Bz - 2nd " "	8	24		13
ABz - Mixed 1 & 2nd cl. coach	2	21	4	17
Cz - 3rd class coach	31	64	14	65
Ci - " " " 2 cclo	10	20		4
Mixed Ci - Mixed with seats				
Dz - Brake van	7	16	4	17
DUI/D " " 2 "	28	73	2	23
Chiusi - Box wagons	892	1175	274	659
Alto sponde - high sides	885	874	159	372
Pianali - Flats	365	381	63	166
Poz - Speed transport	58	45	5	22
Refrigerante - Refrigerator	157	60	10	9

Miscellaneous				
Acqua - Cisterna	26	8	3	8
Vino - Wine	34	16	3	1
Olio Oil	7	24		8
Petrolio - Petrol	34	30	11	25
Benzina	17	1	1	
Coperture - Carpaulin	13	4		
Carbone - Coal	18		31	

IL CAPO DELL...
Movime...

0011

Declassified E.O. 12356 Section 3.3/NND No. 785021

RAILWAY VEHICLE STATISTICS - ROLLING STOCK -

Post ending 5 March ....10 March 45..

Type of Equipment	In Service	In shops For repairs	Required this week	For Demolition
Az - 1st Class coach	...2...	....8.....	.....-...	....8....
Bz - 2nd " "	...22..	....19....	.....1..	....16...
ABz - Mixed 1 & 2nd cl. coach	...1...	....26....	.....-...	....17...
Cz - 3rd class coach	..33..	....84....	.....7...	....51...
Ci - " " " 2 cable	...16..	....26....	.....-...	....12...
Mixed Ci - Mixed with seats	...-...	....-.....	.....-...	....-....
Dz - Brake van 2 cable	...9...	....24....	.... -...	....12...
DUI/D " " 2 "	..21..	....68....	.....2..	....34...
Chiusi - Box Wagons	..1403	....1044..	.....26.2	....1001..
Alto sponde - High sides	..1711	....912...	224	....471...
Pianali - Flats	..392.	....274....	.....92.	....142...
Pos - Special transport	..27...	....41....	.....14.	....19...
Refrigerante - Refrigerator	..145.	....56....	.....21.	....9....

3192

Tank Wagons

Acqua - Cisterna	..34..	....10....	.....1...	....4....
Vino - Wine	..52..	....15....	.....2..	....-....
Olio Oil	..61..	....9.....	.....2..	....3....
Petrolio - Petrol	..158.	....25....	.....12.	....21...
Coperture - Tarpaulin	..34...	....1.....	.....-...	....-....
Caboose - Guard's	..17...	....-.....	.....-...	....-....

SOUTHERN REGION TRANSPORTATION DIVISION (RAIL) NAPLES ALLIED COMMISSION

310

0012

Declassified E.O. 12356 Section 3.3/NND No. 785021

MAIN VEHICLE SITUATION - [illegible] DIVISION -
10 March 45
[illegible] Sardegna

Type of Equipment	In Service	In shops for repairs	Required this month	For Demolition
Aa - 1st Class coach	2	8	-	8
Ba - 2nd " "	22	19	1	16
ABa - Mixed 1 & 2nd cl. coach	1	26	-	17
Cz - 3rd class coach	33	84	7	51
Ci - " " " 2 axle	16	26	-	12
Arroda ti - Lavatories	-	-	-	-
Dz - Brake van 4 axle	9	24	-	12
DUI/D " " 2 "	21	68	2	34
Chiusi - Box wagons	1403	1044	26 2	1001
Alto sponde - high sides	1711	912	224	471
Pianali - Flats	392	274	92	142
Pos - Bogie transport	27	41	14	19
Refrigerante - Refrigerator	145	56	21	9
Serbatoi - Tanks				
Acqua - Cisterna	34	10	1	4
Vino - Wine	52	15	2	-
Olio Oil	61	9	2	3
Petrolio - Petrol	158	25	12	21
Coibenti - Insulated	34	1	-	-
Carbone - Grain's	17	-	-	-

SOUTHERN REGION
TRANSPORTATION
DIVISION (RAIL)
NAPLES
ALLIED COMMISSION

0013

Declassified E.O. 12356 Section 3.3/NND No. 785021

232A/31

SLB/av

TRANSPORTATION SUB-COMMISSION, AC.
(RAIL DIVISION)
C/o Transportation Increment
C.M.F.

Tel. 843403
Ref: AC/232A/Tn 4

24 March 1945

SUBJECT : Recovery of Equipment

TO : Capt. B.W.Boddy, Chief Transportation Officier
Reggio Calabria

1. Reference your REG 1/12/1/2 dated 16 March 1945.

2. Of the cars awaiting repair it appears reasonable to suppose some have not previously been in service since the allied invasion and will, therefore, after repair, be recovered cars.

3. The information given in the list attached to your letter referred to in 1 above is not what Major London of M.R.S. requires in this connection and the figures given under previous weeks repair in weekly progress report do not give exactly what is required ~~letters.~~ *Cltes*.

4. Please see my letter AC/232 A/Tn 4 dated 16 March 45 paras 2 and 3.

S.L. Baister

S.L. BAISTER, Major

For O.H. LINDBERG, Lt.Col.R.E.
Chief, Rail Division

328

TRANSPORTATION SUB-COMMISSION A.C.

ALLIED CONTROL COMMISSION

PROVINCE OF REGGIO IN CALABRIA

SUBJECT: Recovery of equipment

REF: PET.I/Is/I/2 .

TO: TFTN S.C.(RAIL SECTION) A.C.
C/O TN. INC. C.M.F.

16 MAR 45

1. Further to your AC/232A/TN 4 of 27 Jan. Attached (in duplicate) is list of cars in this division as at 1700 hrs 10 March.

2. As you will see there are 1125 cars awaiting repairs and 654 to be demolished (beyond repair).

3. Maj. Blair will no doubt discuss this question with you when passing through Rome. It seems to me this return gives Capt.London the information he needs as there are apparently no more rail cars in this Division available for recovery.

4. Please let me know if there is any more information you require.

B. W. Boddy

B. W. BODDY
CAPTAIN
DIV.SUPT.TN SUB-COMM. A.C.

307

Declassified E.O. 12356 Sec. 3.3/NND No. 785021

COPIA PER IL SIGNOR CAPITANO BODDY

SEZIONE MOVIMENTO DI REGGIO CALABRIA

Consistenza veicoli alle ore 17 del giorno 10 MARZO 1945

Qualifica dei veicoli		QUANTITA' VEICOLI						Annotazioni
		BUONI			RIPARANDI		Demolendi	
		Carichi	Vuoti occorrenti	Vuoti disponibili	Carichi	Vuoti		
Carrozze di classe superiore A - B	F. S.	3				3	7	
	Estere					1		
Carrozze di III Classe C	F. S.	11	1			18	5	
	Estere	2				7	1	
Carrozze Miste AB - BC - CD	F. S.	6				7	1	
	Estere			1				
Bagagliai a 2 assi	F. S.	9	7			32	10	
	Esteri						1	
Bagagliai a 4 assi	F. S.	1	3			6	4	
	Esteri	1						
Carri chiusi in genere (1)	F. S.	215	77	90		479	201	
	Esteri	52	13	29		88	38	
Carri equipaggio	F. S.			2		11		
	Esteri							
Carri refrigerandi ed isotermici	F. S.	10		5		34	16	
	Esteri					4	2	
Carri alze sponde	F. S.	329	65	263	2	219	179	
	Esteri	87	19	35		57	93	
Carri pianali	F. S.	55	37	151		70	55	
	Esteri	16	18	26	1	11	15	
Carri Poz (2)	F. S.		2	10		25	10	
	Esteri					6	1	
SERBATOI Acqua	F. S.	11	28			12	1	
	Esteri							
Vino	Privati	5	2	7		10	1	
Olio	F.S. e privati			2		3		
	Esteri							
Petrolio	F.S. e privati	1		5		20	7	
	Esteri					8	6	
Coperti ad	F. S.			26				

306

Declassified E.O. 12356 Section 3.3/NND No. 785021

Qualifica dei veicoli		Carichi	Vuoti occorrenti	Vuoti disponibili	Carichi	Vuoti	Detenuti	
Carrozze di classe superiore A - B	F. S.	3				3	7	
	Estere					1		
Carrozze di III Classe C	F. S.	11	1			18	5	
	Estere	2				7	1	
Carrozze Miste AB - BC - CD	F. S.	6				7	1	
	Estere			1				
Bagagliai a 2 assi	F. S.	9	7			32	10	
	Esteri						1	
Bagagliai a 4 assi	F. S.	1	3			6	4	
	Esteri	1						
Carri chiusi in genere (1)	F. S.	215	77	90		479	201	
	Esteri	52	13	29		88	38	
Carri equipaggio	F. S.			2		21		
	Esteri							
Carri refrigerandi ed isotermici	F. S.	10		5		34	16	
	Esteri					4	2	
Carri alze sponde	F. S.	329	65	263	2	219	179	
	Esteri	87	19	35		57	93	
Carri pianali	F. S.	55	37	151		70	55	
	Esteri	16	18	26	1	11	15	
Carri Poz (2)	F. S.		2	10		25	10	
	Esteri					6	1	
SERBATOI Acqua	F. S.	11	28			12	1	
	Esteri							
Vino	Privati	5	2	7		10	1	
Olio	F.S. e privati			2		3		
	Esteri							
Petrolio	F.S. e privati	1		5		20	7	
	Esteri					8	6	
Copertoni	F. S.			26				
	Esteri							
Catene	F. S.			1		1		
	Esteri							
Totale		814	272	653	3	1122	654	

306

(1) Esclusi i carri equipaggio refrigerandi ed isotermici.

(1) Comprendere anche i carri: Pr. - Prz - Pvz - Pvvz ecc.

Nei veicoli esteri si debbono comprendere anche quelli privati e di altre Amministrazioni.

Questo prospetto dovrà compilarsi nei giorni 10 - 20 ed ultimo giorno del mese.

Declassified E.O. 12356 Section 3.3/NND No. 785021

COPIA PER IL SIGNOR CAPITANO BODDY

SEZIONE MOVIMENTO DI REGGIO CALABRIA

Consistenza veicoli alle ore 17 del giorno 10 MARZO 1945

Qualifica dei veicoli		QUANTITA' VEICOLI						Annotazioni
		BUONI			RIPARANDI		Demolendi	
		Carichi	Vuoti		Carichi	Vuoti		
			occorrenti	disponibili				
Carrozze di classe superiore A - B	F. S.	3				3	7	
	Estere					1		
Carrozze di III Classe C	F. S.	11	1			18	5	
	Estere	2				7	1	
Carrozze Miste AB - BC - CD	F. S.	6				7	1	
	Estere			1				
Bagagliai a 2 assi	F. S.	9	7			32	10	
	Esteri						1	
Bagagliai a 4 assi	F. S.	1	3			6	4	
	Esteri	1						
Carri chiusi in genere (1)	F. S.	215	77	90		479	201	
	Esteri	52	13	29		88	38	
Carri equipaggio	F. S.			2		1		
	Esteri							
Carri refrigerandi ed isotermici	F. S.	10		5		34	16	
	Esteri					4	2	
Carri alze sponde	F. S.	329	65	263	2	219	179	
	Esteri	87	19	35		57	93	
Carri pianali	F. S.	55	37	151		70	55	
	Esteri	16	18	26	1	11	15	
Carri Poz (2)	F. S.		2	10		25	10	
	Esteri					6	1	
SERBATOI Acqua	F. S.	11	28			12	1	
	Esteri							
Vino	Privati	5	2	7		10	1	
Olio	F.S. e privati			2		3		
	Esteri							
Petrolio	F.S. e privati	1		5		20	7	
	Esteri					8	6	
Coperti	F. S.			26				

305

Declassified E.O. 12356 Section 3.3/NND No. 785021

Qualifica dei veicoli		Vuoti in sosta: Carichi	Vuoti: Vuoti occorrenti	Vuoti: Vuoti disponibili	Vuoti in arrivo: Carichi	Vuoti: Vuoti	Demolendi	Annotazioni
Carrozze di classe superiore A - B	F. S.	3				3	7	
	Estere					1		
Carrozze di III Classe C	F. S.	11	1			18	5	
	Estere	2				7	1	
Carrozze Miste AB - BC - CD	F. S.	6				7	1	
	Estere			1				
Bagagliai a 2 assi	F. S.	9	7			32	10	
	Esteri						1	
Bagagliai a 4 assi	F. S.	1	3			6	4	
	Esteri	1						
Carri chiusi in genere (1)	F. S.	215	77	90		479	201	
	Esteri	52	13	29		88	38	
Carri equipaggio	F. S.			2		1		
	Esteri							
Carri refrigerandi ed isotermici	F. S.	10		5		34	16	
	Esteri					4	2	
Carri alze sponde	F. S.	329	65	263	2	219	179	
	Esteri	87	19	35		57	93	
Carri pianali	F. S.	55	37	151		70	55	
	Esteri	16	18	26	1	11	15	
Carri Poz (2)	F. S.		2	10		25	10	
	Esteri					6	1	
SERBATOI Acqua	F. S.	11	28			12	1	
	Esteri							
SERBATOI Vino	Privati	5	2	7		10	1	
SERBATOI Olio	F.S. e privati			2		3		
	Esteri							
SERBATOI Petrolio	F.S. e privati	1		5		20	7	
	Esteri					8	6	
Copertoni	F. S.			26				
	Esteri							
Catene	F. S.			1		1		
	Esteri							
Totale		814	272	653	3	1122	654	

(1) Esclusi i carri equipaggio ~~refrigeranti ed isotermici~~.

(1) Comprendere anche i carri: Pr. - Prz - Pvz - Pvvz ecc.

Nei veicoli esteri si debbono comprendere anche quelli privati e di altre Amministrazioni.

Questo prospetto dovrà compilarsi nei giorni 10 - 20 ed ultimo giorno del mese.

305

Declassified E.O. 12356 Section 3.3/NND No. 785021

0019

Declassified E.O. 12356 Section 3.3/NND No. 785021

232A/29

SLB/ic

TRANSPORTATION SUB-COMMISSION, AC
(RAIL DIVISION)
c/o Transportation Increment
C.M.F.

Tel. 843403
Ref. AC/232A/Tn 4

17 March 1945

TO : Capt.Irvine Lynch R.E. Sicilia Region.

SUBJECT : Recovery of Equipment.

1. Reference my letter AC/232A/Tn 4 dated 27 January 45 and attachment thereto.

2. Will you please render this return of recovered rail cars for March 1945 in respect of the latter half of month only (16th to 31st). This in order that continuity may be maintained from date of wagon census on 15 March.

S.L.Baister
S.L.BAISTER Major
for O.H.Lindberg Lieut.Col. R.E.
Chief of Rail Division.

0020

Declassified E.O. 12356 Section 3.3/NND No. 785021

232A/28

SLB/ic

TRANSPORTATION SUB-COMMISSION, AC
(RAIL DIVISION)
c/o Transportation Increment
C.M.F.

Tel. 843403
Ref. AC/232A/Tn 4

16 March 1945

TO : Capt.B.W.Boddy, c/o Movements Reggio

SUBJECT : Recovery of Equipment.

1. Reference my letter AC/232A/Tn 4 dated 27 January 45 and weekly progress reports.

2. The attachment to the letter referred to in 1 above calls for a monthly return of cars in process of recovery, and should not include any cars under repair which have been withdrawn from service for repair(see para 2 of MRS.letter 453 T of 18 January 45).

3. It is very important that this information should be received each month, but in respect of March 1945 please render return from 16th to 31st only so that continuity may be maintained from date of wagon census on 15 March.

4.(a) The figures given in your weekly progress report for locomotives and cars repaired are not understood here. For example return dated 26 february 45, referring to week 22 January ~~and~~ to 28 January shows under para 9 that during the previous week no less than 15 locomotives which had not previously been in service were repaired. This means that 15 locos were recovered during that week, which is not credible.

(b) Similarly under para 12, the number of cars recovered during the previous week is given as 289 + 751, but a foot-note states that these need heavy repairs. It is not intended that cars waiting repairs should be shown in the columns for previous weeks repairs but only cars actually repaired and returned to service, the last column, "not previuously in service" thereby indicating the numbers recovered from war damaged stock etc. during the week in question.

303

5. The latest weekly progress report to hand from you is dated 6 March but refers to week 29 January to 4 February. Can these returns be expedited please?

S.L.Baister

S.L.BAISTER Major
for O.H.LINDBERG Lieut Col. R.E.
Chief, Rail Division.

0021

Declassified E.O. 12356 Section 3.3/NND No. 785021

RECEIVED
TRANSPORTATION (RAIL)
JAPLEC
COMMISSION

M.T. VEHICLE STRENGTH - [illegible] DIVISION -

Week ending Saturday...3 March 45....

Type of Equipment	In Service	In short Tons Required	Required this week	For Demolition
Az - 1st Class coach	-	8	-	10
Bz - 2nd " "	-	19	1	6
ABz - Mixed 1 & 2nd cl. coach	-	17	-	8
Cz - 3rd class coach	11	67	-	33
Ci - " " " 2 axle	12	29	1	8
Mixed Ci - Lorry with seats	-	-	-	-
Dz - Brake van 4 axle	7	16	1	6
DUI/D " " 2 "	9	22	3	21
Chiusi - Box Wagons	1084	1057	295	746
Alto sponde - high sides	962	817	176	317
Pianali - Flats	265	268	80	84
Poz - Tank transport	31	49	2	27
Refrigerante - Refrigerator	169	57	21	10
Tank Wagons				
Acqua - Cisterna	32	20	-	3
Vino - Wine	32	16	-	3
Olio Oil	94	8	-	1
Petrolio - Petrol	154	34	-	10
Carboni - Carbolia	49	-	-	-
Catrame - Chalk	17	-	-	-

3 0 3

0022

Declassified E.O. 12356 Section 3.3/NND No. 785021

SOUTHERN LINE REGION TRANSPORTATION DIVISION (RAIL) NAPLES ALLIED COMMISSION

RAILWAY VEHICLE SITUATION - ITALIAN DIVISION -

Stock ending 8 a.m. of ...24 February 45

Type of Equipment	In Service	In shops for repairs	Required this week	For Demolition
Az - 1st Class coach	....5....	....4....	....-....	....5....
Bz - 2nd " "	....-....	....32....	....1....	....3....
ABz - Mixed 1 & 2nd cl. coach	....-....	....23....	....4....	....4....
Cz - 3rd class coach	37	....59....	....5....	....51....
Ci - " " " 2 axle	12	....21....	....-....	....4....
Mixed Ci - Saloon with seats	-	....1....	....-....	....-....
Dz - Brake van 4 axle	3	....15....	....-....	....9....
DUI/D " " 2 "	41	....67....	....4....	....33....
Carri - Box wagons	1216	....1187....	....248....	....737....
Alte sponde - high sides	909	....933....	....193....	....400....
Pianali - Flats	292	....290....	....75....	....139....
Roz - Bank wagons	44	....50....	....9....	....26....
Refrigerante - Refrigerator	274	....39....	....21....	....19....
Tank wagons				
Acqua - Cisterne	32	....13....	....-....	....4....
Vino - Vino	69	....12....	....-....	....3....
Olio Oil	60	....10....	....1....	....1....
Petrolio - Petrol	...148.	...25....	...12...	...26....
Coibentati - Lagged	...68...	....-....	....-....	....-....
Catrame - Tarring	...17...	....-....	....-....	....-....

Declassified E.O. 12356 Section 3.3/NND No. 785021

In increment

ROLLING STOCK - ITALIAN DIVISION -

Last updated 10 Feb 45

Type of Equipment	In Service	In short Term Repairs	Required Major Repairs	For Demolition
Az - 1st Class coach	5	4	1	2
Bz - 2nd " "	1	17	7	15
Bz - Mixed 1 & 2nd cl. coach	2	20	7	7
Cz - 3rd class coach	32	58	7	25
Ci - " " " 2 cl.	27	11	2	14
Mixed Ti - Mixed with seats	7	7	7	7
Dz - Brake van	7	15	1	6
DUI/D " " "	17	36	1	21
Chiusi - Box Wagons	1451	670	234	797
Alto sponde - high sides	1496	593	144	335
Pianali - Flats	296	226	44	81
Poz - Tank transports	73	33	3	22
Refrigerante - Refrigerator	217	33	20	5
Tank Wagons				
Acqua - Cisterna	24	6	1	10
Vino - Wine	36	14	1	3
Olio Oil	13	9	9	1
Petrolio - Petrol	92	18	9	25
Copertoni - Carpoulin	28	4	7	7
Cotone - Cotton	17	7	3	7

SOUTHERN REGION TRANSPORTATION DIVISION (RAIL) NAPLES ALLIED COMMISSION

0 0 2 4

Declassified E.O. 12356 Section 3.3/NND No. 785021

In Sub Commission
A.C./ (Rail)
Care Transportation Increment
C.M.F

ITALIAN VEHICLE HOLDING - ALLIED DIVISION -

Week ending Saturday....3 February 45

Type of Equipment	In Service	In short for repairs	Required this week	For Demolition
Az - 1st Class coach	.5.....	.....6...	....5....	.....4...
Bz - 2nd " "	.5.....	.....24...	....5....	.....15..
ABz - Mixed 1 & 2nd cl. coach	.1.....	.....22...	....5....	.....7...
Cz - 3rd class coach	.25....	.....65...	....9....	.....57..
Ci - " " " 2 axle	.12....	.....19...	....1....	.....11..
Carrodelli - Saloon with seats	.5.....	.....5....	....5....	.....5...
Dz - Brake van 4 axle	.5.....	.....19...	....2....	.....2...
DUI/D " " 2 "	.14....	.....54...	....5....	.....11..
Chiusi - Box Wagons	.1328..	.....1188.	....227..	.....802.
Alto sponde - high sides	.944...	.....991..	....171..	.....463.
Pianali - Flats	.391...	.....314...	....35...	.....103.
Poz - Tank Wagons	.53....	.....26...	....1....	.....27..
Refrigerante - Refrigerator	.92....	.....33...	....26...	.....8...
Tank Wagons				
Acqua - Cisterna	.27....	.....11..	....1....	.....7...
Vino - Wine	.30....	.....12..	....2....	.....4...
Olio Oil	.66....	.....12..	....3....	.....1...
Petrolio - Petrol	.148...	.....21..	....3....	.....21..
Coperture - Carpaulin	.38....	.....2...	....5....	.....5...
Catene - Chains	.17....	.....5...	....5....	.....5...

SOUTHERN REGION
TRANSPORTATION
DIVISION (RAIL)
NAPLES
ALLIED COMMISSION

Declassified E.O. 12356 Section 3.3/NND No. 785021

ITALY VEHICLE STATISTICS - [illegible] DIVISION -

Week ending Saturday 27 Gennaio 45

Type of Equipment	In Service	In short Term Repairs	Required this week	For Demolition
Az - 1st Class coach	----	....3....	....-....	....2....
Bz - 2nd " "	..2...	.....16...	....-....	....4....
ABz - Mixed 1 & 2nd cl. coach	-----	.....19...	....-....	....6....
Cz - 3rd class coach	2.....	.....32...	....4....	....34....
Ci - " " " 2 class	-----	.....10...	....1....	....24....
Mixed Ci - Mixed with seats	-----	.....-....	....-....	....-....
Dz - Brake van 3rd cl.	..10...	.....8....	....-....	....7....
DUI/D " " 2 "	-----	.....51...	....1....	....24....
Chiusi - Box wagons	..1469.	.....1007..	....199..	....669...
Alto sponde - high sides	..859..	.....826...	....141..	....289...
Pianali - Flats	..348..	.....334...	....36...	....169...
Poz - Tank for transport	..53...	.....27...	....5....	....26....
Refrigerante - Refrigerator	..212..	.....34...	....12...	....11....
Liquid Tanks				
Acqua - Cisterna	..20...	.....24...	....-....	....7....
Vino - Wine	..20...	.....5....	....3....	....-....
Olio Oil	..25...	.....17...	....2....	....1....
Petrolio - Petrol	..87...	.....16...	....8....	....15....
Combustibili - Combustible	..23...	.....-....	....-....	....-....
Catrame - Chain's	..17...	.....-....	....-....	....-....

298

TRANSPORTATION NAPLES DIVISION SUB COMM.N A.C.

Driving Serand, 1st Lt. CAC

0026

Declassified E.O. 12356 Section 3.3/NND No. 785021

2324/22

Sheet N°1

L.T. R.C. BOWIE R.A. TRANSPORTATION SUB COMMISSION

(RAILS) - ALLIED COMMISSION - MINISTRY OF TRANSPORTS - R O M A -

n° 102/II P E S C A R A C E N T R A L S T A T I O N

Pescara 16 Feb. 1945

STTUATION OF ROLLING STOCK AT PESCARA CENTRAL STATION

n°	Series	Number of car	Nat.	Type	Axles	Brake	Loaded or empty	Conditions	Remarks
1	Hall	75031	G.	Box	2	none	empty	good	
2	"	96002	F.	"	2	"	"	"	
3	Kuffs	56820	G.	"	"	"	"	"	
4	HMII	2365	"	"	"	"	"	"	
5	Kass	1050	"	H.S.	"	Yes	"	"	
6	"	3669	"	"	"	none	"	"	
7	F.	653628	I.	Flat	2	Yes	"	"	
8	L.	414008	"	H.S.	"	"	"	"	
9	L.	7400084	"	"	"	"	"	"	
10	Kass	55695	G.	"	"	none	"	"	
11	"	26389	"	"	"	"	"	"	
12	L.	413519	I.	"	"	"	"	"	
13	Kuffs	11200	G.	"	"	Yes	"	"	
14	L.	477946	I.	"	"	none	"	"	
15	Kuffs	177035	G.	Flat	"	"	mucky	"	Milling machinery
16	Hall	74396	"	H.S.	"	"	empty	"	
17	"	31383	"	"	"	"	loaded	"	Chloride
18	Essen	920808	"	Box	"	Yes	empty	"	
19	Hall	157499	"	Flat	"	none	loaded	"	One steel block
20	Kass	96613	"	H.S.	"	"	"	"	Tube coils
21	"	32810	"	"	"	"	"	"	" "
22	Hall	61526	"	"	"	"	"	"	Steel blocks
23	Stett	44343	"	"	"	"	"	"	machinery
24	L.	402678	I.	"	"	Yes	"	"	"
25	L.	418314	"	"	"	none	"	"	empty iron barrels
26	Hall	19806	G.	"	"	Yes	"	"	" " "
27	L.	408195	I.	"	"	none	"	"	" " "
28	F.	604591	I.	Flat	"	"	empty	"	
29	L.	7401451	"	H.S.	"	Yes	"	"	
30	Stett	18632	G.	"	"	"	"	"	
31	L.	480951	I.	"	"	none	"	"	
32	Hall	63405	G.	"	"	"	"	"	
33	"	72317	"	Flat	"	Yes	"	"	
34	"	5624	"	"	"	none	loaded	"	IBH Rails, Short
35	"	2205	"	"	"	"	"	"	" " "
36	Stett	7253	"	"	"	"	empty	"	
37	"	48977	"	"	"	"	"	"	
38	Kass	62990	"	"	"	"	"	"	
39	"	62533	"	"	"	"	"	"	
40									

297

n°	Series	Number of car	Nat.	Type	Axles	Brake	Loaded or empty	conditions	Remarks
40	Wasem	939755	G.	Flat	2	none	empty	Good	
41	"	938778	"	"	"	Yes	"	"	
42	L.	499516	I.	H.S.	"	none	"	"	
43	Wasem	86335	G.	"	"	"	"	"	
44	"	83445	"	"	"	"	"	"	
45	"	939504	"	"	"	"	"	"	
46	Hall	62348	"	"	"	"	"	"	
47	"	91860	"	"	"	Yes	"	"	
48	Wasem	939654	"	"	"	none	"	"	
49	L.	412776	I.	"	"	"	"	"	
50	Hg.	300604	"	Refr.	"	Yes	"	heavy repairs	
51	E.	1025034	"	Box	"	"	"	"	"
52	F.	153256	"	"	"	"	"	"	"
53	F.	183895	"	"	"	"	"	"	"
54	Hg.	301485	"	Refr.	"	"	"	"	"
55	Hall	39316	G.	Box	"	none	"	"	"
56	E.	1021924	I.	"	"	"	"	"	"
57	Hg.	543223	"	Refr.	"	Yes	"	"	"
58	Hg.	304818	"	"	"	"	"	"	"
59	G.	7270168	I.	Box	"	none	"	"	"
60	E.	1007701	"	"	"	"	"	"	"
61	E.	1019079	"	"	"	Yes	"	"	"
62	F.	7110793	"	"	"	none	"	"	"
63	Gc.	201491	"	"	"	Yes	"	"	"
64	E.	158572	"	"	"	none	"	"	"
65	E.	1023022	"	"	"	Yes	"	"	"
66	F.	7104452	"	"	"	"	"	"	"
67	Hall	43163	G.	H.S.	"	"	"	"	"
68	Stett	24023	"	"	"	none	"	"	"
69	"	39884	"	"	"	"	"	"	"
70	Cassel	45285	"	"	"	"	"	"	"
71	L.	469009	P.	"	"	Yes	"	"	"
72	Wasen	31756	G.	"	"	none	"	"	"
73	L.	415267	I.	"	"	Yes	"	"	"
74	Wasen	66180	G.	"	"	none	"	"	"
75	L.	450317	I.	"	"	"	"	"	"
76	L.	414457	"	"	"	Yes	"	"	"
77	Wasen	444482	G.	"	"	"	"	"	"
78	Hall	78781	"	"	"	none	"	"	"
79	"	33957	"	"	"	"	"	"	"
80	L.	491558	I.	"	"	"	"	"	"
81	K.	507161	P.	tank	"	Yes	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

41	"	938776	"	"	"	"	Yes	"	"		
42	L.	495516	I.	H.S.	"	"	none	"	"		
43	Essen	86335	G.	"	"	"	"	"	"		
44	"	83445	"	"	"	"	"	"	"		
45	"	939504	"	"	"	"	"	"	"		
46	Hall	62348	"	"	"	"	Yes	"	"		
47	"	91860	"	"	"	"	none	"	"		
48	Essen	939654	"	"	"	"	"	"	"		
49	L.	412776	I.	"	"	"	Yes	"	heavy repairs		
50	Hg.	300604	"	Refr.	"	"	"	"	"		
51	K.	1025034	"	Box	"	"	"	"	"		
52	F.	153256	"	"	"	"	"	"	"		
53	F.	183895	"	"	"	"	"	"	"		
54	Hg.	301485	"	Refr.	"	"	none	"	"		
55	Hall	39316	G.	Box	"	"	"	"	"		
56	K.	1021924	I.	"	"	"	Yes	"	"		
57	Hg.	543223	"	Refr.	"	"	"	"	"		
58	Hg.	304818	"	"	"	"	none	"	"		
59	G.	7270168	I.	Box	"	"	"	"	"		
60	E.	1007791	"	"	"	"	Yes	"	"		
61	B.	1019079	"	"	"	"	none	"	"		
62	F.	7110793	"	"	"	"	Yes	"	"		
63	Ge.	201491	"	"	"	"	none	"	"		
64	K.	155572	"	"	"	"	Yes	"	"		
65	K.	1023028	"	"	"	"	"	"	"		
66	F.	7104452	"	"	"	"	"	"	"		
67	Hall	43163	G.	H.S.	"	"	none	"	"		
68	Stett	24023	"	"	"	"	"	"	"		
69	"	39084	"	"	"	"	"	"	"		
70	Cassel	45285	"	"	"	"	Yes	"	"		
71	L.	469009	P.	"	"	"	none	"	"		
72	Essen	31756	G.	"	"	"	Yes	"	"		
73	L.	415257	I.	"	"	"	none	"	"		
74	Essen	66180	G.	"	"	"	"	"	"		
75	L.	450317	I.	"	"	"	Yes	"	"		
76	L.	414497	"	"	"	"	"	"	"		
77	Essen	444482	G.	"	"	"	none	"	"		
78	Hall	78781	"	"	"	"	"	"	"		
79	"	33857	"	"	"	"	"	"	"		
80	L.	491558	I.	"	"	"	Yes	"	"		
81	M.	507061	"	tank	"	"	"	"	"		
82	Essen	924859	G.	"	"	"	"	loaded	"	"	Tube coils
83	Hall	62777	"	H.S.	"	"	"	empty	"	"	
84	Q.	7700137	I.	Flat	"	"	none	"	"	"	empty gun barrels
85	L.	466072	"	H.S.	"	"	Yes	loaded	"	"	
86	L.	413953	"	"	"	"	none	empty	"	"	
87	L.	478229	"	"	"	"	Yes	"	"	"	
88	Essen	94875	G.	Flat	"	"	none	"	"	"	
89	L.	485359	I.	H.S.	"	"	"	"	"	"	
90	K.F.	65281	F.	"	"	"	"	"	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

n°	Series	Number of car	Nat.	Type	Axles	Brake	Loaded or empty	conditions	Remarks
01	L.	414048	I.	H.S.	2	Yes	empty	Heavy repairs	
02	L.	485760	"	"	"	none	"	"	"
03	L.	484775	"	"	"	"	"	"	"
04	Essen	470593	G.	"	"	"	"	"	"
05	Hall	29600	"	"	"	"	"	"	"
06	L.	475018	I.	"	"	Yes	"	"	"
07	Hall	17251	G.	"	"	none	"	"	"
08	L.	493182	I.	"	"	"	"	"	"
09	Hall	16531	G.	"	"	"	"	"	"
00	L.	400279	I.	"	"	Yes	"	"	"
01	L.	412735	"	"	"	none	"	"	"
02	Cz.	32313	I.	Coach	4	Yes	"	"	"
103	Cz.	36836	"	"	"	"	"	"	"
04	C.	35052	"	"	2	"	"	"	"
05	Cz.	32009	"	"	4	"	"	"	"
06	Cz.	32147	"	"	"	"	"	"	"
07	Cz.	36916	"	"	"	"	"	"	"
08	Dz.	88359	"	Luggage	"	"	"	"	"
09	Dm.	99364	"	"	2	"	"	"	"
10	R.	1020701	"	Box	"	none	"	Demolition	
11	Hg.	307173	"	Refr.	"	"	"	"	
12	Esse	51583	D.	Box	"	"	"	"	
13	Hall	79545	"	"	"	"	"	"	
14	D.	251364	I.	"	"	"	"	"	
15	F.	184065	"	"	"	Yes	"	"	
16	F.	161392	"	"	"	none	"	"	
17	E.	1027150	"	"	"	"	"	"	
18	Hg.	308718	"	Refr.	"	"	"	"	
19	E.	1003541	"	Box	"	"	"	"	
20	F.	133633	"	"	"	Yes	"	"	
21	E.	1030290	"	"	"	"	"	"	
22	Hg.	343027	"	Refr.	"	"	"	"	
23	E.	1I15071	"	Box	"	"	"	"	
24	F.	7110306	"	"	"	none	"	"	
25	F.	184483	"	"	"	Yes	"	"	
26	E.	1131597	"	"	"	none	"	"	
27	L.	410364	"	H.S.	"	"	"	"	
28	L.	411276	"	"	"	Yes	"	"	
29	F.	123.132	"	Box	"	none	"	"	
30	L.	550.876	"	"	"	Yes	"	"	
31	L.	476054	"	H.S.	"	"	"	"	
32	L.	7470236	"	"	"	"	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

11	L.	414648	I.	H.S.	2	Yes	empty	Heavy repairs		
12	L.	485760	"	"	"	none	"	"	"	
13	L.	484775	"	"	"	"	"	"	"	
14	Bacon	470593	G.	"	"	"	"	"	"	
15	Hall	29600	"	"	"	"	"	"	"	
16	L.	475018	I.	"	"	Yes	"	"	"	
17	Hall	17251	G.	"	"	none	"	"	"	
18	L.	493182	I.	"	"	"	"	"	"	
19	Hall	16531	G.	"	"	"	"	"	"	
00	L.	400279	I.	"	"	Yes	"	"	"	
01	L.	412735	"	"	"	none	"	"	"	
02	Cz.	32313	I.	Coach	4	Yes	"	"	"	
103	Cz.	36836	"	"	"	"	"	"	"	
04	C.	35052	"	"	2	"	"	"	"	
05	Cz.	32009	"	"	4	"	"	"	"	
06	Cz.	32147	"	"	"	"	"	"	"	
07	Cz.	36916	"	"	"	"	"	"	"	
08	Dz.	88359	"	Luggage	"	"	"	"	"	
09	Dm.	99364	"	"	2	"	"	"	"	
10	E.	1020701	"	Box	"	none	"	Demolition		
11	Hg.	307173	"	Refr.	"	"	"	"		
12	Bacon	51583	D.	Box	"	"	"	"		
13	Hall	79545	"	"	"	"	"	"		
14	D.	251364	I.	"	"	"	"	"		
15	F.	184065	"	"	"	Yes	"	"		
16	F.	161392	"	"	"	none	"	"		
17	E.	1027150	"	"	"	"	"	"		
18	Hg.	308718	"	Refr.	"	"	"	"		
19	E.	1003541	"	Box	"	"	"	"		
20	F.	133633	"	"	"	Yes	"	"		
21	E.	1030290	"	"	"	"	"	"		
22	Hg.	343027	"	Refr.	"	"	"	"		
23	E.	1I15071	"	Box	"	"	"	"		
24	F.	7110306	"	"	"	none	"	"		
25	F.	184483	"	"	"	Yes	"	"		
26	E.	1131597	"	"	"	none	"	"		
27	L.	410364	"	H.S.	"	"	"	"		
28	L.	411276	"	"	"	Yes	"	"		
29	F.	123.132	"	Box	"	none	"	"		
30	L.	850.876	"	"	"	Yes	"	"		
31	L.	476054	"	H.S.	"	"	"	"		
32	L.	7470236	"	"	"	"	"	"		
33	L.	476928	"	"	"	none	"	"		
34	L.	479382	"	"	"	"	"	"		
35	L.	415497	"	"	"	Yes	"	"		
36	L.	419820	"	"	"	"	"	"		
37	L.	042737	"	"	"	none	"	"		
38	L.	488825	"	"	"	Yes	"	"		
39	L.	402257	"	"	"	"	"	"		
40	Bacon	64290	G.	Box	"	"	"	"		
41	Hall	92001	"	H.S.	"	none	"	"		
42	Bacon	96872	"	"	"	"	"	"		

293

Declassified E.O. 12356 Section 3.3/NND No. 785021

n°	Series	Number of car	Nat.	Type	Axles	Brake	Loaded or empty	conditions	Remarks
143	Stett	44772	G.	H.S.	2	none	loaded	demolition	transformers
144	"	6811	"	"	"	"	empty	"	
145	Hall	68957	"	"	"	"	"	"	
146	Kuff	80442	"	Flat	"	"	"	"	
147	Hall	12717	"	H.S.	"	"	"	"	
148	~~34593~~	34593	"	"	"	"	"	"	
149	Henon	28944	"	"	"	"	"	"	
150	"	19084	"	"	"	"	"	"	
151	"	18176	"	"	"	"	"	"	
152	"	7244	"	"	"	"	"	"	
153	"	628610	"	"	"	"	"	"	

There are further 18 vehicles (2 coaches, 2 tankers, 14 wagons) completely burnt out; all scraps.

Nat. means nationality : I. = Italy; G. = Germany; F. = France

Pescara, 16 February 1945

Declassified E.O. 12356 Section 3.3/NND No. 785021

WEEKLY CAR SHOP PROGRESS REPORT

LOCATION Reggio Cal. WEEK ENDING 13/1.45

CAR NO.	TYPE	REPAIRS HEAVY	REPAIRS LIGHT	DATE IN SHOP	DATE DUE OUT	ACTUAL DATE OUT	REMARKS
4230	P	1		2.1.45	13.1.45		Revisione assi riostruzione sponde e ribaltini
704559	F		1	8.1.45	" " "		Ricordino ferramenta e Cassa
101207	E		1	8.1.45	" " "		" " " "
30365	P	1		2.1.45	" " "		Revisione assi riostruzione sponde
99655	Pm	1		2.1.45	" " "		" " riordino Cassa
646762	L		1	8.1.45	" " "		" " " "
491950	L		1	8.1.45	" " "		Riordino ferramenta e Cassa
308704	Hg		1	8.1.45	" " "		" " " "
481959	L		1	8.1.45	" " "		Revisione assi riordino Cassa
14184	Pm	1		8.1.45	" " "		" " " "
463722	L		1	8.1.45	" " "		Riordino ferramenta e Cassa
560818	M		1	8.1.45	" " "		Revisione assi riordino Cassa
23454	F	1		8.1.45	" " "		" " " "
84610	P		1	26.12.44	" " "		Lastrine e Bulloni montabi riordino Cassa
170265	F		1	26.12.45	" " "		Riordino ferramenta e Cassa
928391	F		1	18.12.45	" " "		Revisione assi riordino Cassa
203415	H3	1		18.12.45	" " "		" " " "
8242	HM		1	8.1.45	" " "		Riordino ferramenta e Cassa
14907	C		1	8.1.45	" " "		" " " "
8725	C		1	2.1.45	" " "		" " " "
64994	C		1	18.12.44	" " "		Revisione assi riordino Cassa
7106251	F		1	18.12.44	" " "		Riordino ferramenta e Cassa
3242H	Cz		1	8.1.45	" " "		" " " "
720168	C		1	8.1.45	" " "		" " " "
6088	Om		1	4.12.44	" " "		" " " "
100480	F		1	8.1.45	" " "		Revisione assi riordino Cassa
493909	L		1	8.1.45	" " "		Riordino ferramenta e Cassa
7749671	L		1	8.1.45	" " "		Revisione assi riordino Cassa

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR NO.	TYPE	HEAVY REPAIRS	LIGHT REPAIRS	DATE				
H230	P	1		2.1.45	13.1.45			Revisione assi ricostruzione sfondi e ricostruzione
7104559	F		1	8.1.45	"	"	"	Riordino ferramenta e Dassa
1011207	E		1	8.1.45	"	"	"	" " " "
30365	P	1		2.1.45	"	"	"	Revisione assi ricostruzione sfondi
99655	Dm	1		2.1.45	"	"	"	riordino Cassa
646762	L		1	8.1.45	"	"	"	" " " "
491950	L		1	8-1-45	"	"	"	Riordino ferramenta e Cassa
308704	Hg		1	8.1.45	"	"	"	" " " "
481959	L		1	8.1.45	"	"	"	Revisione assi riordino Cassa
1H184	Dm	1		8.1.45	"	"	"	" " " "
463722	L		1	8.1.45	"	"	"	Riordino ferramenta e Cassa
560818	M		1	8.1.45	"	"	"	Revisione assi riordino Cassa
2345H	F	1		8.1.45	"	"	"	" " " "
8H610	D		1	26.12.44	"	"	"	Sostituz 2 sede mobile riordino Cassa
170265	F		1	26.12.45	"	"	"	Riordino ferramenta e Cassa
928391	F		1	18.12.45	"	"	"	Revisione assi riordino Cassa
203H15	Hg	1		18.12.45	"	"	"	" " " "
82H2	WM		1	8.1.45	"	"	"	Riordino ferramenta e Cassa
14907	C		1	8.1.45	"	"	"	" " " "
8725	Ty		1	2.1.45	"	"	"	" " " "
6H994	Ty		1	18.12.44	"	"	"	Revisione assi riordino Cassa
7106251	F		1	18.12.44	"	"	"	Riordino ferramenta e Cassa
3242H	Cz		1	8.1.45	"	"	"	" " " "
720568	Ty		1	8.1.45	"	"	"	" " " "
6068	Om		1	4.12.44	"	"	"	" " " "
100480	F		1	8.1.45	"	"	"	Revisione assi riordino Cassa
493909	L		1	8.1.45	"	"	"	Riordino ferramenta e Cassa
7749657	L		1	8.1.45	"	"	"	Revisione assi riordino Cassa
410532	L		1	8.1.45	"	"	"	Riordino ferramenta e Cassa

	HEAVY REPAIRS	LIGHT REPAIRS	GRAND TOTAL
TOTAL NO. OF CARS TURNED OUT OF SHOP	6	23	29
TOTAL NO. OF CARS TURNED OUT OF SHOP PREVIOUS WEEK	8	21	29

IL CAPO TECNICO

Declassified E.O. 12356 Section 3.3/NND No. 785021

0034

Declassified E.O. 12356 Section 3.3/NND No. 785021

INCOMING MESSAGE

HEADQUARTERS ALLIED COMMISSION

TN 5-2

Originator's Reference: CITE MTC 185

Date/Time of Origin: FEB 28

Message Centre No: P/3749

Date Time Rec'd: MAR 010700

Precedence: ROUTINE

FROM: ALCOM SICILIA REGION (LYNCH)

TO : HQ ALCOM CITE ACTPT FOR BALSTER

RESTRICTED

RESTRICTED.

Para 1. Reference your letter 21 February AC/232/1/TN4.

Para 2. I3R assure report recovered rail equipment will be submitted 8 March covering February.

Para 3. No report will be submitted for January on account of impossibility obtaining date for January.

HEADQUARTERS
MAR 1945

DIST

ACTION TN SC -
INFO A/PRESIDENT
CHIEF COMMISSIONER
ECON SEC
FILE (2)
FLOAT

ACTION

RESTRICTED

292

0035

Declassified E.O. 12356 Section 3.3/NND No. 785021

232 A/19

0 G /ES\

TRANSPORTATION SUB-COMMISSION, AC.
(RAIL DIVISION)
C/o Transportation Increment
C.M.F.

Tel. 548402
Ref. AC/232/A/Tn 4

21 February 45

TO : REGIONAL COMMISSIONER
Sicilia Region, AC.

SUBJECT: Recovery of Equipment.

1. Reference signal dated 20 February 45 Cite REG 403.

2. Attached is further copy of letter AC/232/A/Tn 4 dated 27 January 45.

O.H. LINDBERG
Lt.Col. R.E.

For MERRITT H.TAYLOR
Director Tn.Sub-Commission

Copy to: Capt. A.F.H. Irvine Lynch

0036

Declassified E.O. 12356 Section 3.3/NND No. 785021

Allied Forces
MILITARY RAILWAY SERVICE
Office of Director - Italy

453 T

A.P.O. 512
18 January 1945

SUBJECT: Recovery of Equipment

TO : DAD Tn 3 (M), Building
ADD - Equipment, 774 RW Grand Divn, Building
Rail Division, AC Transp Sub-Comm, Building

1. In order to prepare essential reports at the close of each month regarding the status of recovered rail equipment the following data is required for both freight and passenger cars.

	Coach	Bag	Box	Hi Gon	Low Gon	Flat	Refr	Tank	Others	Total
(a) Number cars on hand receiving and awaiting light repairs.										
(b) Number cars on hand receiving and awaiting heavy repairs										
(c) Number cars available for recovery which can be repaired										

2. Items (a) and (b) will include only such cars as are in the process of recovery, and not those which have been previously in service and are temporarily laid up for repairs.

3. Inventory should be made as of the last day of each calender month, commencing with January, and first report reach this headquarters not later than 5 February, and so on for each succeeding month.

4. As much importance attaches to the recovery of rail stock, it is requested that supervisors and others who will be directed to assemble the data in the various areas be impressed that accuracy in reporting is most desirable.

290

0037

Declassified E.O. 12356 Section 3.3/NND No. 785021

5. It is assumed that Rail Divn, AC Tn.Sub-Comm., in conjunction with ISR can furnish a report for Calabria and Sicily; that Tn 3 (M) can submit for British supervised territory, and ADD-Equipment, 774th RGD, can submit for USA supervised territory. The three reports will then be consolidated in this office and copies issued to all interested departments.

For the Director:

S.E. LONDON
Captain, TC
Superintendent Transportation

0038

Declassified E.O. 12356 Section 3.3/NND No. 785021

MINISTERO DEI TRASPORTI
FERROVIE DELLO STATO
SEZIONE MATERIALE E TRAZIONE
REGGIO CALABRIA

REGGIO C
N

ALLIED CONT

Rapporto situazione materiale rotabile al 31 Gennaio 1945

	VETTURE	BAGAGLIAI	CHIUSI	ALTE SPONDE GON	BASSE SPONDE GON	PIANALI	FRIGORIFERI	SERBATOI	A
a) Numero di veicoli in corso o in attesa di piccole riparazioni	=	3	82	52	29	6	2	5	
b) Numero di veicoli in attesa o in corso di grande riparazioni	21	28	235	122	105	50	12	14	
c) Numero di veicoli disponibili che possono essere riparati	21	31	317	174	134	56	14	19	

Card provided by courtesy of R
287

IL CAPO DELLA S
MATERIALE E TRA

0039

Declassified E.O. 12356 Section 3.3/NND No. 785021

REGGIO CALABRIA 14 FEB.1945
M.172.I.GV.

AI

RAZIONE

ALLIED CONTROL COMMISSION
REGGIO CALABRIA

to situazione materiale rotabile al 31 Gennaio 1945

ETTURE	CARROZZE	CARRI CHIUSI	CARRI ALTE SPONDE GON	CARRI BASSE SPONDE GON	PIANALI	FRIGORIFERI	SERBATOI	ALTRI	=	TOTALE
=	3	32	52	29	6	2	5	=		179
21	28	235	122	105	50	12	14	=		587
21	31	317	174	134	56	14	19	=		766

IL CAPO DELLA SEZIONE
MATERIALE E TRAZIONE

Carck forwarded for correct [illegible]

287

Declassified E.O. 12356 Section 3.3/NND No. 785021

TN SUB=COMM A.C.

ALLIED CONTROL COMMISSION

PROVINCE OF REGGIO IN CALABRIA

SUBJECT: Recovery of equipment

TO: Tn Sub=Comm A.C.
(Rail Section)
c/o Tn Increment
C.M.F.

REF: Reg. 2/6/10
Reggio Calabria
16 Feb. 45

Attached is copy of report asked for in your letter AC/232 A/TN 4 of 27 Jan. 45

W. F. Blair. Major

W.F. BLAIR, MAJOR
DIV. SUPT. TN. SUB=COMM

? Para 2. of MRS letter.

0041

Declassified E.O. 12356 Section 3.3/NND No. 785021

I.C
e Lv Increment.

...RAIN VEHICLE STATISTIC - ...PLIED DIVLIA -

232 A/14

...ic ending Saturday...17. Feb.45.

Type of Equipment	In Service	In shops For repairs	Required this week	For Demolition
		7	1	2
Az = 1st Class coach	-	7	1	2
Bz - 2nd " "	1	33	6	12
ABz - Mixed 1 & 2nd cl. coach	2	23	3	19
Cz - 3rd class coach	35	63	8	62
Ci - " " " 2 scale	20	22	4	2
Merci Ti - Wagon with sides	-	-	-	-
Dz - Brake van 4 scale	10	17	1	9
DUI/D " " 2 "	27	65	3	32
Chiusi - Box Wagons	1846	1368	282	805
Alto sponde - High sides	1652	1109	174	559
Piani li - Flats	552	312	43	105
Poz - Brake or ...port	93	38	9	25
Refrigerante - Refrigerator	203	62	9	19
Tank Wagons				
Acqua - Cistern	31	15	2	9
Vino - Wine	42	13	1	-
Olio Oil	39	12	2	2
Petrolio - Petrol	107	23	9	29
Coperture - Carpaulin	47	-	-	-
Catene - Chain's	17	-	-	-

SOUTHERN REGION
TRANSPORTATION
DIVISION (RAIL)
NAPLES
ALLIED COMMISSION

TRANSPORTATION SUB-COMM A.C.

RAIL SECTION

TRANSPORTATION ENCLOSURE

C.M.F.

Reggio, Cal 10 Feb 1943

To: CHIEF RAIL SECTION TRANS.SUB.COMM.A.C.

FROM: MAJOR P.G. MATSON T.C.

SUBJECT: WAGON INVENTORY.

1. Attached is another wagon inventory which was made on Feb 10 th.

2. You will note the box wagon situation on that date was worse than it was on previous report.

3. This report is interesting because it shows just what the various wagons are doing. Ordinarily we just look at the total, but when this total is broken down as shown in the report we are not so well off as it appears, for example note the box wagon situation which is our present headache, 219 were loaded 98 were loading and 15 were available for loading or moving in trains. So we just about have nothing As far as closed wagons are concerned.

4. Distribution here is slow and clumsy due to the Petrace Bridge being out of service. The lines running up the west coast aneast coast are connected by the low capacity line catanzaro-Rufemia which further complicates matters and slows up movement.

5. Wish to call your attention to the inventory which wastaken on 10 Feb. the condition to-day is much better and from latest information available further im provement is in sight.

P. G. MATSON
MAJOR T.C.
P.G.MATSON
MAJOR T.C.

285

Declassified E.O. 12356 Section 3.3/NND No. 785021

0043

Declassified E.O. 12356 Section 3.3/NND No. 785021

C A R I N V E N T O R Y C A L A B R I A

DIVISION AS OF 10 FEB 45

C L A S S	Loaded includes cars in trains moving	Empties placed to load or loading	Empties moving in trains or available for placing	TOTAL
PASSENGER COACHES	15	9	9	33
BAGE CARS	6	11	2	21
BOX "	219	98	15	330
REFERS	15	-	1	16
GONDOLAS	341	37	51	429
FLATS	95	122	102	319
FOZ FLATS	5	=	11	16
TANKS WATER	5	44	=	49
" WINE	12	6	=	18
" EDIBLE OIL	=	=	3	3
" PETRO				
" PRODUCTS	1	=	12	13
	716	325	206	1247

Grano total 1247

0044

Declassified E.O. 12356 Section 3.3/NND No. 785021

C A R I N V E N T O R Y C A L A B R I A

DIVISION AS OF 10 FEB 45

Loaded includes cars in trains moving	Empties placed to load or loading	Empties Moving in trains or available for placing	TOTAL
15	9	9	33
0	11	2	21
219	96	15	330
15	-	1	16
341	37	51	429
95	122	102	319
5	=	11	16
5	44	=	49
12	6	=	18
=	=	3	3
1	=	12	13
716	325	206	1247

P. G. MATSON
MAJOR T.C.
Feb 16- 1945

247

0045

Declassified E.O. 12356 Section 3.3/NND No. 785021

2324/12

(1) ALCOM SOUTHERN REGION (2) ALCOM SICILIA REGION

1844 15 FEB 45 ROUTINE

CONFIDENTIAL FD

PARA ONE FD REFERENCE LETTER ABLE CHARLIE SLANT TWO THREE TWO ABLE SLANT TH FOUR OF TWO SEVEN JANUARY FD

PAREN TO ALCOM SOUTHERN REGION FOR REGIONAL COMMISSIONER TO ALCOM SICILIA REGION FOR REGIONAL COMMISSIONER FROM ALCOM CITE ACCEPT PAREN

PARA TWO FD RETURNS FOR JANUARY NOT REPEAT NOT TO HAND FD

EXPEDITE FD

for Sig I Green

.283.

Transportation etc

399

NICHOLAS PLUMERO,
C.W.O., USA
ASST. ADJUTANT

FD

0046

Declassified E.O. 12356 Section 3.3/NND No. 785021

Memorandum. Tn.A.3(O)/26/42-12A.

To:- Supt. Transportation. 13 Feb.'45

Reference your 5057 dated 24 Jan.

As British Operating Groups do not check asr numbers it is not possible to verify the passage of these cars over British territory through our channels.

If you can furnish details of handing over at Tibertina matter can be taken up with Movements through their channels.

Capt. R.D.
DFD Tn.3(O)

JK.

Declassified E.O. 12356 Section 3.3/NND No. 785021

Allied Force
MILITARY RAILWAY SERVICE
Headquarters 715th Railway Operating Battalion
Office of Commanding Officer.

A P O 512
27 January 1945.

Subject : Rail Traffic Delays.

To : DMRI, APO 512, US Army.

1. Reference is made to your letter 24 January, above subject.

2. Following are records of cars listed in communication mentioned above :

479944 and 14060: Arrived Caserta Extra 626436, 15 December, departed Extra 3393, Line 90, dame date, arrived Roma-Tiburtina same train 16 December . Transferred to Smistamento 16 December.

7407789: arrived Caserta Extra 626306, 14 December, departed Extra 3384, same date, Line 90, arrived Rome-Tiburtina same train, 15 Dec. transferred to Smistamento Extra 1737, same date.

1003100: Arrived Caserta Extra 626436, 14 December, departed Extra 3389, same date, Line 90. Arrived Roma-Tiburtina 14 December and transferred to Smistamento same date, Extra 3423.

3. 111581 and 480592 did not move over 715th territory, therefore no record available.

4. Passing records on cars handled above indicate no delay in handling at either Caserta or Rome areas.

T.F. CRYMES,
Lt.Col., T.C.
Superintendent.

281

0048

Declassified E.O. 12356 Section 3.3/NND No. 785021

FILE SEL:CD

Allied Force
MILITARY RAILWAY SERVICE
Office of Director - Italy

505 T

A.P.O. 512
24 January 1945

SUBJECT : Rail Traffic Delays:

TO : Commanding Officer, 701 Ry Grand Divn, APO 512
Commanding Officer, 715 Ry Operating Bn, APO 512
DAD Tn 3 (O), Building

1. Below is a list of cars which were excessively delayed in transit from Naples Area and Terni to 8th Army railheads:

Number	Consignor	Consignee	Dispatched	Arrived	Days in Transit
(a) RIMINI					
479944	557 BOD	Pack 14	28 Nov	22 Dec	24
14060	557 BOD	Pack 12	27 Nov	22 Dec	25
111581	557 BOD	Pack 14	4 Dec	23 Dec	19
490592	Terni Gas Plant	Pack 12	26 Nov	23 Dec	27
7407789	557 BOD	Pack 27	30 Nov	1 Jan	32
(b) CESENA					
1003100	557 BOD	Pack 7	12 Dec	8 Jan	27

2. During the period in question, some operating difficulties, due to line interruptions, occurred on Lines 87 and 86, but even so the delays were too excessive to be attributed to that cause alone. Please have prompt investigation made and advise this headquarters record of the movement over your respective territory and the reason for the slow transit time of each car listed. Prompt handling requested.

For the Director:

S.N.LONDON
Captain, TC
Superintendent Transportation

230

0049

Declassified E.O. 12356 Section 3.3/NND No. 785021

G-4 Mov & Tn,
Allied Force Headquarters,
Tel.No.Freedom 878.

Mov 3/3 B.

Subject : Rail Traffic Delays.

To : D.M.R.S. ITALY.

1. Attached is list of wagons which were excessively delayed in transit from NAPLES Area and TERNI to Eigth Army Railheads.

2. It is appreciated that during this period Line 87 was closed until 4 December, and Operating difficulties were experienced over Line 86 during the middle of the month. Considering these factors, journey times from Base to Railheads should not have exceeded 14 days in extreme cases.

3. In view of the seriousness of these delays, it is requested that they be investigated and steps taken please to avoid similar occurences.

4. Movement Area Headquarters are instructed to assist Operating personnel by bringing to their notice immediately all cases of apparent delay to traffic in transit.

(G.ARMITAGE PLEWS), Major,
for Brigadier,
D.Q.M.G.(Mov & Tn).

20 January 1945.

Copy to :-
DMRS Rep, A.F.H.Q.
Tn(B)
HQ Movements, Central Italy.
HQ Movements, East Italy.
HQ Movements, West Italy.
HQ Movements, Rome.
HQ Movements, 8 Army.

279

00501

Declassified E.O. 12356 Section 3.3/NND No. 785021

Truck No.	Consignor	Consignee	Despatched	Arrived	Days in Transit.
(a) RIMINI					
479944	557 BOD	Pack 14	28 Nov	22 Dec	24
14060	557 BOD	Pack 12	27 Nov	22 Dec	25
111581	557 BOD	Pack 14	4 Dec	23 Dec	19
480592	Terni Gas Plant	Pack 12	26 Nov	23 Dec	27
474342	557 BOD	Pack 12	27 Nov	24 Dec	27
	557 BOD	Pack 12	4 Dec	28 Dec	24
7407789	557 BOD	Pack 27	30 Nov	1 Jan	32
(b) CESENA					
1003100	557 BOD	Pack 7	12 Dec	8 Jan	27

0051

Declassified E.O. 12356 Section 3.3/NND No. 785021

Allied Force
MILITARY RAILWAY SERVICE
Office of Director - Italy

453 T

A.P.O. 512
18 January 1945

SUBJECT: Recovery of Equipment

TO : DAD Tn 3 (M), Building
ADD - Equipment, 774 Ry Grand Divn, Building
Rail Division, AC Transp Sub-Comm, Building

1. In order to prepare essential reports at the close of each month regarding the status of recovered rail equipment, the following data is required for both freight and passenger cars.

	Coach	Bag	Box	Hi Gon	Low Gon	Flat	Refr	Tank	Others	Total
(a) Number cars on hand receiving and awaiting light repairs.										
(b) Number cars on hand receiving and awaiting heavy repairs										
(c) Number cars available for recovery which can be repaired										

2. Items (a) and (b) will include only such cars as are in the process of recovery, and not thos which have been previously in service and are temporarily laid up for repairs.

3. Inventory should be made as of the last day of each calendar month, commencing with January, and first report reach this headquarters not later than 5 February, and so on for each succeeding month.

4. As much importance attaches to the recovery of rail stock, it is requested that supervisors and others who will be directed to assemble the data in the various areas be impressed that accuracy in reporting is most desirable.

0052

Declassified E.O. 12356 Section 3.3/NND No. 785021

5. It is assumed that Rail Divn, AC Tn. Sub-Comm., in conjunction with ISR can furnish a report for Calabria and Sicily; that Tn 3 (M) can submit for British supervised territory, and ADD-Equipment, 774th RGD, can submit for USA supervised territory. The three reports will then be consolidated in this office and copies issued to all interested departments.

For the Director:

S. E. LONDON
Captain, TC
Superintendent Transportation

232 A/7

ACP/ic

TRANSPORTATION SUB-COMMISSION, AC.
(RAIL SECTION)
C/o Transportation Increment
C/M.F.

Tel: 843238
Our Reference: AC/232A/Tn

16 January 1945

TO : Rail (Moves)
Tn. Sub-Commission
HQ. AC.

SUBJECT : Return of wagons, loaded and unloaded.

Set out hereunder are details of wagons of civil traffic in the Rome compartimento Area, for the week-ending 31 Dec.44 and 7 January 1945 :

25-31 December 1944

STATION	LOADED	UNLOADED
Rome Tuscolana	8	236
Rome Trastevere	34	291
Rome Prenestina	==	19
Rome S.Lorenzo	==	36
Rome Ostiense	19	383
Grosseto	20	===
Chiusi B. di Ch.	7	1
Tarquinia	1	===
S.Severa	6	===
Littoria	==	50
Civitavecchia	138	6
Ciampino	==	1
Priverno Fossanova	==	2
TOTAL	233	1025

1-7 January 1945.

STATION	LOADED	UNLOADED
Rome Ostiense	15	27 ~~29~~ 8
Rome Trastevere	21	~~19~~ 8
Rome Prenestina	===	40
Rome Tuscolana	2	113

Declassified E.O. 12356 Section 3.3/NND No. 785021

TO : Rail (Moves)
Tn. Sub-Commission
HQ. AC.

SUBJECT : Return of wagons, loaded and unloaded.

Set out hereunder are details of wagons of civil traffic in the Rome compartimento Area, for the week-ending 31 Dec.44 and 7 January 1945 :

25-31 December 1944

STATION	LOADED	UNLOADED
Rome Tuscolana	8	236
Rome Trastevere	34	291
Rome Prenestina	==	19
Rome S.Lorenzo	==	36
Rome Ostiense	19	383
Grosseto	20	===
Chiusi B. di Ch.	7	1
Tarquinia	1	===
S.Severa	6	===
Littoria	==	50
Civitavecchia	138	6
Ciampino	==	1
Priverno Fossanova	==	2
TOTAL	233	1025

1-7 January 1945.

STATION	LOADED	UNLOADED
Rome Ostiense	15	278
Rome Trastevere	21	198
Rome Prenestina	===	40
Rome Tuscolana	2	113
Rome S.Lorenzo	3	14
Attigliano	5	===
Civitavecchia	62	14
Grosseto	21	5
Chiusi	14	3
S. Severa	4	===
Total	147	665

O.H.LINDBERG
Lt.Col. R.E.,
Chief, Rail Section

Declassified E.O. 12356 Section 3.3/NND No. 785021

0055

Declassified E.O. 12356 Section 3.3/NND No. 785021

SECRET 2378/5

Allied Force
MILITARY RAILWAY SERVICE
Office of Director - Italy

SEL/cwd

A.P.O. 512
9 February 1945

453 T

SUBJECT: Recovery of Railway Rolling Stock.

TO : DMRI
DDMRI
ADDMRI
DD-Operations
DAD Tn 3 (O)
DAD Tn 3 (M)
ADD-Equipment
CO; 701 RGD
CO; 715 ROB
CO, 719 ROB
AC Tn Sub/Comm, Rail Divn
Director General, ISR

1. Following is statement showing total number of cars by types restored to service during month of January 1945:

AREA	BOX	HSG	LSG	FLAT	REFS	TNKS	PSGR CARS	OTHERS	TOTAL
ROME	169	80	10	20	2	9	19	1	310
NAPLES	133	57	23	8	4	6	7	19	257
C.ITALY	82	121	39	0	3	9	15	0	269
E.ITALY	*10	0	0	0	0	0	0	0	10
TOTAL	394	258	72	28	9	24	41	20	846

1 January 1945 - Total cars on hand 28;242
1 February 1945- Total cars on hand 29,088

* The 10 USA cars added to East Italy arrived at Bari from North Africa 25 January. No other report received from East Italy as to cars restored to service in that area.

2. Number of cars restored in Calabria and Sicily Compartimenti not available at this time, but will be included in February report.

For the Director:

S. E. LONDON
Captain, TC
Superintendent Transportation

0056

Declassified E.O. 12356 Section 3.3/NND No. 785021

Lieut-Col Lindsay.

Subject : Line recovery : Line 257.

Major Barker

Military Railway Service,
C.M.F.
Telephone : Firebox 52.
Outside Line BA3867.
Tn.3(1)/54.
6 Feb. 45.

To : D.D. Ops. (Rly.)

Copy to : D.A.D.O.S. (Rly.)

Tn.3(Ops) (Rly.)

D.D. Tn. (Constn.) (Rly.)

Director General, L.M. (Rly.)

1. I attach you statement showing the wagons available for recovery on Line 257 (ACHS - VITERBO).

2. Those up to and including CARSOLICA can be obtained and brought to ROME by merely sending an engine to cut them out.

3. As regards those beyond CARSOLICA, they cannot be brought direct to ROME as the line is cut. They can, however, be worked round through VITERBO to the CAVE Ford Rly. by the two steam engines available in VITERBO. To avoid the subsequent lengthy process of removing all these by tractor at ACQUE ACETOSA, D.D. Tn.(Constn.) has promised to examine the possibility of replacing the connection between the L&N and the CAVE Ford Rly. at FABRICA DI CAVE.

273

D.D. Tn.(1),
for Brigadier,
Director Military Railway Service.

0057

Declassified E.O. 12356 Section 3.3/NND No. 785021

(560)

WAGON RECONNAISSANCE.

LINE 257.

(a) JOIE - CAPRICA (Inclusive).

	Fleta.	Box.	L.S.	L.D.	Tanks.	Fig.	Others.	Total.
O.K.	4	6	13	-	1	2	-	26
Require Light Repa.	1	13	7	-	-	2	2	25
" Med. "	2	16	6	-	5	2	8	39
" Heavy "	7	71	16	3	6	-	2	105
Burnt out and Scrap	4	74	27	-	8	-	2	115

(b) After VIGO MATERIC.

	Fleta.	Box.	L.S.	L.D.	Tanks.	Fig.	Others.	Total.
O.K.	1	12	27	-	-	1	2	43
Require Light Repairs	-	3	11	-	-	-	2	16
" Med. "	-	5	10	-	-	-	-	15
" Heavy "	-	8	12	-	-	-	1	21
Burnt out and Scrap	-	7	6	-	-	-	-	13

(a) Above includes 10 passenger type vehicles requiring Light and Medium repairs.

0058

Declassified E.O. 12356 Section 3.3/NND No. 785021

MINISTERO DELLE COMUNICAZIONI Tipo 5
FERROVIE DELLO STATO

COMPARTIMENTO DI B A R I

232 A/3

N. 122-502-6

al N. ..... del .....

Bari 1 Settembre 1944 - A.

OGGETTO: Inventario veicoli.

IN OUT
HQ AMG
14 SEP 1944
REG IV

All'Ufficio del Direttore Generale
Militare delle Forze Alleate in

R O M A

Trasmetto la situazione veicoli accertata alle ore 24 di giovedì ~~XXXXX~~ 24 andante dalle stazioni di questo Compartimento.-

E AND S DIV.
REGION IV
RECD SEP 16 1944
TO
REPLIED
FILE

IL CAPO COMPARTIMENTO

271

CENSIMENTO MATERIALE ROTABILE CIRCOLANTE SULLE LINEE DELLA RETE

AI SENSI DEL DECRETO 24 AGOSTO 1946

NT 969/33
15-9-44

STAZIONE	Serie del veicolo (se F.S. Numero o di altra Amministrazione)	Numero del veicolo	Tipo del veicolo (vettura, bagagl., carro chiuso, alte sponde, basse sponde, pianali e serbatoi	Carico o Vuoti	Buono ripassando o demolendo	Destinazione dei veicoli
Bari S.S.	F.S.E.	1928	F.chiuso	Carico	Buono	Bari Sud-Est.
"	"	1903	" "	"	S	" "
"	"	1822	" "	"	"	" "
"	"	2204	" "	"	"	" "
"	"	1114	" "	"	"	" "
"	"	1122	" "	Vuoto	Ripassando	" "
"	"	1882	" "	"	"	" "
"	"	1930	" chiuso	Carico	Buono	" "
"	"	1832	" "	"	"	" "
"	"	1416	" "	"	"	" "
"	"	1403	" "	"	"	" "
"	"	1112	" "	"	"	" "
"	"	3003	" "	"	"	" "
"	"	1824	" "	"	"	" "
"	"	2202	" "	"	"	" "
"	"	1116	" "	"	"	" "
"	"	1906	" "	"	"	" "
"	"	2101	" "	"	"	" "
"	"	1130	" "	"	"	" "
"	"	1904	" "	"	"	" "
"	"	1499	" "	"	"	" "
"	"	1405	" "	"	"	" "
"	"	8200	" "	Vuoto	Bagno	" "
"	"	5001	Cisterna	"	Ripassando	" "
"	"	11024	N serbatoio	"	"	" "
"	"	11013	" "	"	"	" "
"	"	11038	" "	Vuoto	Buono	" "
"	"	11021	" "	"	"	" "
"	"	11104	" "	"	"	" "
"	"	11021	" "	"	"	" "
"	"	11107	" "	"	"	" "
"	"	4000	L alte sponde	Carico	Ripassando	Bari
"	"	4402	" "	Vuoto	"	" "
"	"	11	Ac vettura	"	"	" "
"	"	503	Pc Portaglio	"	"	" "

276

Declassified E.O. 12356 Section 3.3/NND No. 785021

CONSIGNATO NATURALMENTE ESCLUSIVAMENTE SULLE LINEE DELLA VIA

AD ORD 18 DEL 24 AGOSTO 1944

NF 969/22
15-9-44

STAZIONE	Serie del veicolo(ne F.S.Estero o di altra Amministrazione	Numero del veicolo	Tipo del veicolo(vettura, bagagl.,carro chiuso, alto sponde,basso sponde, pianali e serbatoi	Carico o Vuoti	Buono riparando o demolendo	Destinazione dei veicoli
Bari S.F.	F.S.F.	1928	F.chiuso	Carico	Buono	Bari Sud-Est.
"	"	1903	" "	"	S	" "
"	"	1822	" "	"	"	" "
"	"	2204	" "	"	"	" "
"	"	1114	" "	"	"	" "
"	"	1122	" "	Vuoto	Riparando	" "
"	"	1382	" "	"	"	" "
"	"	1930	" chiuso	Carico	Buono	" "
"	"	1832	" "	"	"	" "
"	"	1418	" "	"	"	" "
"	"	1402	" "	"	"	" "
"	"	1112	" "	"	"	" "
"	"	3003	" "	"	"	" "
"	"	1824	" "	"	"	" "
"	"	2202	" "	"	"	" "
"	"	1124	" "	"	"	" "
"	"	1906	" "	"	"	" "
"	"	8101	" "	"	"	" "
"	"	1130	" "	"	"	" "
"	"	1904	" "	"	"	" "
"	"	1409	" "	"	"	" "
"	"	1405	" "	"	"	" "
"	"	8200	" "	"	"	" "
"	"	5001	Cisterne	Vuote	Buono	" "
"	"	11024	K serbatoio	"	Riparando	" "
"	"	11013	" "	"	"	" "
"	"	11038	" "	"	"	" "
"	"	11011	" "	Vuoto	Buono	" "
"	"	11104	" "	"	"	" "
"	"	11021	" "	"	"	" "
"	"	11007	" "	"	"	" "
"	"	4000	L alte sponde	"	"	Bari
"	"	4402	" "	Carico	Riparando	" "
"	"	11	Ac vetture	Vuoto	"	" "
"	"	501	D Bagagliaio	"	"	" "
"	"	502	" "	"	Buono	" "

27d

Declassified E.O. 12356 Section 3.3/NND No. 785021

	di altre Amministrazioni	Veicoli	chiuso, aperto, spondo, bianco spondo, pianali e carrelli	Vuoto		Veicoli
Ferr S.F.	F.S.S.	1928	F.chiuso	Carico	Buono	Ferr Sud-Est.
"	"	1903	" "	"	8	" "
"	"	1822	" "	"	"	" "
"	"	2204	" "	"	"	" "
"	"	1114	" "	"	"	" "
"	"	1122	" "	Vuoto	Riparando	" "
"	"	1802	" "	"	"	" "
"	"	1930	8 chiuso	Carico	Buono	" "
"	"	1832	8 "	"	"	" "
"	"	1418	" "	"	"	" "
"	"	1402	" "	"	"	" "
"	"	1112	" "	"	"	" "
"	"	3003	" "	"	"	" "
"	"	1824	" "	"	"	" "
"	"	2202	" "	"	"	" "
"	"	1116	" "	"	"	" "
"	"	1906	" "	"	"	" "
"	"	2101	" "	"	"	" "
"	"	1130	" "	"	"	" "
"	"	1904	" "	"	"	" "
"	"	1409	" "	"	"	" "
"	"	1405	" "	"	"	" "
"	"	8200	" "	Vuote	Rimo	
"	"	5001	Cisterna	"	Riparando	
"	"	11034	1 serbatoio	"	"	
"	"	11013	" "	"	"	
"	"	11038	" "	Vuoto	Buono	
"	"	11012	" "	"	"	
"	"	11104	" "	"	"	
"	"	11001	" "	"	"	
"	"	11307	" "	"	"	
"	"	4005	1 alto sponde	"	"	Ferr
"	"	4402	" "	Carico	Riparando	" "
"	"	11	4c vetture	Vuoto		" "
"	"	501	1 Bagagliaio	"	"	" "
"	"	502	" "	"	Buono	" "
"	"	415	3 vetture	"	"	" "
"	"	[illegible]	"	"	"	" "
"	"	504	1 Bagagliaio	"	"	" "
"	"	404	3 vetture	Vuoto		" "
"	"	211	4c "	"	"	" "
"	"	15	4c "	"	"	" "
"	"	203	" "	"	"	" "
"	"	412	6 "	"	"	" "
"	"	402	40 "	"	"	Antiquato
						Carro 7

Declassified E.O. 12356 Section 3.3/NND No. 785021

Bari S.E.	F.S.F.	14	AC vettura	Vuoto	Buono	Putignano
"	"	202	" "	"	"	"
"	"	19	" "	"	"	Martina
"	"	851	DI Semplicio	"	"	Treno 107
"	"	603	Ce vettura	"	"	"
"	"	606	" "	"	"	Bari S.E.
"	"	609	" "	"	Demolendo	"
"	Saterno	753	Cz "	Vuoto	Buono	"
"	"	758	" "	Carico	"	"
"	"	196788	L alte sponde	"		"
"	"	11567	P basse spond.	Vuoto	Ripiegando	"
"	"	61496	Alte sponde	Carico	Buono	"
"	"	92009	Chiuso	"	"	"
"	"	14207	Alte sponde	"	"	"
"	"	3905	" "	"	"	"
"	"	14777	" "	Vuoto	"	"
"	"	14388	" "	Carico	"	"
"	F.S.	1023245	Fe chiuso	"	"	"
"	"	1025401	" "	"	"	"
"	"	1024445	" "	"	"	"
"	"	77196005	F "	"	"	"
"	"	1024439	Fe "	"	"	"
"	"	1026380	" "	"	"	"
"	"	182083	F "	Vuoto	Ripiegando	Napoli
"	"	7270173	" "	Carico	Buono	Bari S.E.
"	"	7270146	" "	"	"	"
"	"	209493	" "	"	"	"
"	"	7104988	G "	"	"	"
"	"	1021132	F "	"	"	Centrale
"	"	1016131	Fe "	"	"	Foggia
"	"	77492022	F "	"	"	Napoli
"	"	144483	" "	"	"	Venafro
"	"	11315?9	" "	"	"	"
"	"	1011072	" "	"	"	Bari Centrale
"	"	181034	" "	"	"	Barletta
"	"149216	"	" "	"	"	Bari Centrale
"	"	1135594	" "	"	"	Casamassima
"	"	1030232	" "	"	"	Barletta
"	"	1020391	" "	"	"	"
"	"	572018	Nr serbatoi	"	"	"
"	"	568126	" "	"	"	"
"	"	568129	" "	"	"	Bari N.E.
"	"	568123	" "	"	"	"
"	"	582001	" "	Vuoto	Riparando	"
"	"	760605	F chiuso	"	Buono	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	606	" "	"	"	"
"	"	609	" "	"	"	"
"	"	793	Co "	"	"	"
"	"	758	" "	"	"	"
"	Matera	196788	L alto spende	Vuoto	Demolendo	Bari C.M.
"	"	11597	P basso spond.	Carico	Buono	" "
"	"	62406	Alto spende	"	"	" "
"	"	28089	Chiuso	Vuoto	Riparando	" "
"	"	24207	Alto spende	Carico	Buono	" "
"	"	3965	" "	"	"	" "
"	"	14777	" "	"	"	" "
"	"	14388	" "	"	"	" "
"	P.S.	1023245	Fo chiuso	Vuoto	"	" Centrale
"	"	1029404	" "	Carico	"	" S.S.
"	"	1024445	" "	"	"	Noicattaro
"	"	77196005	P "	"	"	Bari S.S.
"	"	1024439	Fo "	"	"	" "
"	"	1006380	" "	"	"	" "
"	"	182083	" "	"	"	" "
"	"	7270173	P "	"	"	" "
"	"	7270146	" "	Vuoto	Riparando	" "
"	"	200499	C "	Carico	Buono	Napoli
"	"	7204988	P "	"	"	Bari S.S.
"	"	1021132	Fo "	"	"	" "
"	"	1010131	" "	"	"	" "
"	"	77452002	P "	"	"	" "
"	"	144483	" "	"	"	" Centrale
"	"	1131509	" "	"	"	Bari
"	"	1021072	" "	"	"	Napoli
"	"	181034	" "	"	"	Massagno
"	"149216	"	" "	"	"	"
"	"	1135594	" "	"	"	Bari Centrale
"	"	1030232	" "	"	"	Barletta
"	"	1020391	" "	Vuoto	"	Bari Centrale
"	"	972018	Mv serbatoi	Carico	"	Canosa sa
"	"	568526	" "	"	"	Barletta
"	"	568229	" "	"	"	"
"	"	568183	" "	"	"	"
"	"	582801	" "	Vuoto	"	"
"	"	760905	P chiuso	"	Riparando	Bari S.S.
"	"	571696	Cisterne	"	Buono	" "
"	"	571698	" "	"	"	" "
"	"	571812	" "	"	"	" "
"	"	572652	M cisterne	Vuoto	"	" "
"	"	571864	" "	"	"	" "
"	"	471468	L alto spon.	Carico	"	" "
"	"	479993	" "	"	"	Valenzano
"	"	473596	" "	"	"	Bari S.S.
"	"	426342	" "	"	"	" "
"	"	756169	" "	"	"	Valenzano

269

Declassified E.O. 12356 Section 3.3/NND No. 785021

Officina	F.S.E.	607	C vettura	Vuoto	Ripurando	Officina S.E.
"	"	17	" "	"	"	" "
"	"	403	" "	"	"	" "
"	"	204	" "	"	"	" "
"	"	861	DOT Bagagl.	"	"	" "
"	F.S.	101945	F chiuso	"	Buono	" "
"	"	1026595	F "	"	"	" "
"	"	1023522	" "	"	"	" "
"	"	1025127	" "	"	"	" "
"	"	113713	F "	"	Ripurando	" "
"	"	154906	" "	"	"	" "
"	"	1134386	" "	"	"	" "
Bari S.E.	"	7303053	DT chiuso	Vuoto	"	" "
officina	"	271029	C "	"	"	" "
"	"	656326	F bassa spon.	Carico	Buono	" "
"	"	7406926	L alta spon.	Vuoto	Ripurando	" "
"	Estero	82474	Bassa sponde	"	"	" "
"	F.S.	96670	DU bagagl.	"	"	" "
"	Estero	70273	C vettura	"	"	" "
Barletta	F.S.	448693	L alta spon.	Carico	"	Barletta Città
"	"	704695	" "	"	"	" "
"	"	694765	F Bassa Spon.	"	"	Coglie Ferrov.
"	Estero	62555	Alte sponde	"	"	Averen
"	F.S.	698071	VDT pianali	"	"	" "
"	"	692262	" "	"	"	" "
"	Estero	4345	Pianali	"	"	" "
"	"	353439	" "	"	"	" "
"	"	353501	" "	"	"	" "
"	"	353513	" "	"	"	" "
"	"	894	" "	"	"	" "
"	F.S.	693698	" "	"	"	" "
"	"	698603	" "	"	"	" "
"	"	698036	" "	"	"	" "
"	"	604262	" "	"	"	" "
—	—	—	—	—	—	—
Vegl ie	—	—	—	—	—	—
Carbonara	Estero	257739	L alta spon.	Carico	Buono	Valenzano
Valenzano	"	47167	F bassa spon.	"	"	" "
"	"	1009772	Fo chiuso	Vuoto	"	Putignano
"	"	128953	F "	"	"	" "
"	"	646517	F bassa spon.	Carico	"	Valenzano
"	"	661643	" "	"	"	" "
Adelfia	F.S.	202821	C chiuso	Vuoto	"	Putignano
"	"	1021675	F "	"	"	"
"	Estero	8600	Alte sponde	"	"	Bari Sud-Est
"	"	3845	Chiuso	"	"	S.Pietro

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	F.S.	1026595	U "	"	"	"	"
"	"	1023582	" "	"	"	"	"
"	"	1025117	" "	"	"	"	"
"	"	115713	P "	"	"	"	"
"	"	154906	" "	"	"	"	"
"	"	1134386	" "	"	"	"	"
Bari S.E.	"	7303953	III chiuso	"	Riparando	"	"
Officina	"	271029	C "	"	"	"	"
"	"	656316	P basse spon.	"	"	"	"
"	"	7408926	L alte spon.	Vuoto	"	"	"
"	Ratero	82474	Basse sponde	"	"	"	"
"	F.S.	96570	DU bacyl.	"	"	"	"
"	Ratero	70273	C vetturn	"	"	"	"
Bungivecca	F.S.	448693	L alte spon.	Carico	Buono	"	"
"	"	704695	" "	"	"	"	"
"	"	694765	P Basse Spon.	"	"	"	"
"	Ratero	62555	Alte sponde	"	"	"	"
"	F.S.	698071	POO pisnali	"	"	"	"
"	"	692962	" "	"	"	"	"
"	Ratero	4345	Pianali	"	"	"	"
"	"	353439	" "	"	"	"	"
"	"	353501	" "	"	"	"	"
"	"	353513	" "	"	"	"	"
"	"	394	" "	"	"	"	"
"	F.S.	693696	" "	"	"	"	"
"	"	698643	" "	"	"	"	"
"	"	698094	" "	"	"	"	"
"	"	604252	" "	"	"	"	"
Bari	—	—	—	—	—	—	—
Carbonara	—	—	—	—	—	—	—
Valenzano	Ratero	257739	L alte spon.	Carico	Buono	Valenzano	
"	"	67187	P basse spon.	"	"	"	"
"	"	1009772	Pe chiuso	Vuoto	"	Putignano	
"	"	122953	P "	"	"	"	"
"	"	648517	L basse spon.	Carico	"	Valenzano	
"	"	661643	" "	"	"	"	"
"	F.S.	202821	C chiuso	Vuoto	"	Putignano	
Adolfia	"	1011675	P "	"	"	"	
"	Ratero	8600	Alte sponde	"	"	Bari Sud-Est	
"	"	3825	Chiuso	"	"	S.Michele	
Bungivecca	—	—	—	—	—	—	—
S.Michele	F.S.	1000038	Pe chiuso	Arredato	"		
"	"	100959	P "	"	"		
"	F.S.E.	1111	" "	"	"		
"	"	1105	" "	"	"		
"	"	2013	" "	"	"		
"	"	127354	" "	"	"		
"	"	1031523	" "	"	"		

treno 22 Mar
Bari Sud-Est

Declassified E.O. 12356 Section 3.3/NND No. 785021

Bari S...	F.S.	456510	L alte sponde	Carico	Buono	Valenzano
"	"	461851	" "	"	"	Triggiano
"	"	4411190	" "	"	"	Bari S.E.
"	"	454418	" "	"	"	" "
"	"	475913	" "	"	"	" "
"	"	412937	" "	"	"	" "
"	"	469142	" "	"	"	" "
"	"	447762	" "	"	"	" "
"	"	457952	" "	"	"	" "
"	"	093994	" "	"	"	" "
"	"	469146	" "	"	"	" "
"	"	004806	" "	"	"	" "
"	"	418059	" "	Vuoto	"	Centrale
"	"	479108	" "	"	"	"
"	"	470585	" "	"	"	"
"	"	472317	" "	"	"	"
"	"	7401469	" "	"	"	"
"	"	416155	" "	"	"	"
"	"	474878	" "	"	"	"
"	"	413651	" "	"	"	"
"	"	446046	" "	"	"	"
"	"	7470045	" "	Carico	"	Ortona
"	"	622377	P basso spon.	"	"	"
"	"	660061	" "	"	"	Bari S.E.
"	"	660220	" "	"	"	"
"	"	651015	" "	"	"	"
"	"	654327	P basse sponde	"	"	"
"	"	654732	" "	"	"	"
"	"	652465	" "	"	"	Centrale
"	"	651544	" "	"	"	"
"	"	41402	C vettura	Vuoto	Riparandi	S.E.
"	"	44751	" "	"	"	"
"	"	42616	" "	"	"	"
"	"	468352	L alte spon.	"	"	"
"	"	87268	P basse"sponde	"	"	"
"	F.S.E	1405	P chiuso	Carico	Buono	Officina F.S.
Officina	"	1706	" "	"	"	"
"	"	1812	" "	"	"	"
"	"	1424	" "	Vuoto "	Riparando	"
"	"	1494	" "	"	"	"
"	"	1888	" "	"	"	"
"	"	1228	" "	"	"	"
"	"	1401	" "	"	"	"
"	"	1420	" "	"	"	"
"	"	1124	" "	"	"	"
"	"	3005	H "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	447762	"	"	"	"
"	"	457952	"	"	"	"
"	"	093994	"	"	"	"
"	"	489146	"	"	"	"
"	"	BO4808	"	"	Vuoto	Centrale
"	"	418059	"	"		"
"	"	479108	"	"		"
"	"	470589	"	"		"
"	"	478317	"	"		"
"	"	7401469	"	"		"
"	"	414155	"	"		"
"	"	474878	"	"		"
"	"	413051	"	"		"
"	"	446046	"	"	Carico	Ortona
"	"	7470045	"	"		"
"	"	622377	P basse spon.	"		Bari S.E.
"	"	660061	" "	"		"
"	"	660220	" "	"		"
"	"	651815	" "	"		"
"	"	654327	P basse spende	"		"
"	"	654732	" "	"		"
"	"	652465	" "	"		"
"	"	651544	" "	"		Centrale
"	"	41402	C vetture	"	Vuoto	"
"	"	44751	" "	"		"
"	"	42616	" "	"		"
"	"	468352	L alte spon.	"		"
"	"	67268	M basse"spende	"		"
"	F.S.E	1405	F chiuso	"	Carico	Officina F.S.
"	"	1706	" "	"		"
"	"	1812	" "	"		"
"	"	1424	" "	"	Vuoto	"
"	"	1404	" "	"		"
"	"	1808	" "	"		"
"	"	1229	" "	"		"
"	"	1401	" "	"		"
"	"	1420	" "	"		"
"	"	1124	" "	"		"
"	"	3005	H "	"		"
"	"	2117	G "	"	Carico	Buono
"	"	2213	" "	"	Vuoto	Riparando
"	"	1913	F "	"	Carico	Buono
"	"	4265	L alte spende	"	Vuoto	Riparando
"	"	4262	" "	"		"
"	"	4251	" "	"		"
"	"	11007	Le serbatoio	"		Demolendo
"	"	5202	M serbatoio acq.	"		"
"	"	5258	" "	"		"

Declassified E.O. 12356 Section 3.3/NND No. 785021

S.Michele	F.S.E.	1006488	F chiuso	Arredato	Buono	S.Michele
"	"	122926	" "	"	"	"
Turi	F.S.	534032	4 serbatoi	Vuoto	"	Turi
Triggiano	"	447787	2 alte sponde	"	"	Bari Sud-Est
"	"	442937	" "	"	"	" "
"	"	489152	" "	"	"	" "
"	"	485538	" "	"	"	" "
Capurso	"	436741	" "	"	"	Capurso
"	"	1135322	Fc chiuso	"	"	" "
"	"	1020752	F "	"	"	"
"	F.S.E	1716	Fc "	Arredati	"	"
"	"	1007	" "	"	"	"
"	"	1407	" "	"	"	"
"	F.S.	1135763	Fc "	"	"	"
"	"	164347	F "	"	"	"
Noicattaro	"	1009090	Fc chiuso	Carico	"	Noicattaro
"	"	131623	F "	Vuoto	"	"
Rutigliano		1113585	2 altesp.	Caric	"	Sarà
Conversano	F.S.	50801	4v serbatoio	Vuoto	Riparando	Turi
"	"	114517	F chiuso	carico	Buono	Rutigliano
"	"	1008366	Fc "	"	"	Bari S.E.
"	"	114103	" "	"	"	"
"	"	1118761	" "	"	"	"
"	"	1122588	" "	"	"	"
"	"	1001603	" "	"	"	"
"	F.S.E.	1213	" "	"	"	"
"	"	1203	" "	"	"	"
"	"	1211	" "	"	"	"
"	"	1210	" "	"	"	"
"	"	2000	" "	"	"	"
"	"	2006	" "	"	"	"

Arrivo 12 ore
Bari S.E.

201 vuoto ex

Abiti e trasporti vinggiatori
per Bari S.E. treno 112 e 113

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

"	"	442937	" "	"	"	" "
"	"	489152	" "	"	"	" "
"	"	485538	" "	"	"	" "
Capurso	"	436741	" "	"	"	Capurso
"	"	1135382	Fc chiuso	"	"	" "
"	"	1020752	E "	"	"	" "
"	F.S.E	1726	Fc "	Arredati	"	" "
"	"	1097	" "	"	"	" "
"	"	1407	" "	"	"	" "
"	F.S.	1135763	Fc "	"	"	" "
"	"	164347	F "	"	"	" "
Noicattaro	"	1009090	Fc chiuso	Carico	"	Noicattaro
"	"	131623	F "	Vuoto	"	"
Putignano		1115585	E altec;pn.	Carico	"	Turdò
Conversano	F.S.	150801	Mv serbatoio	Vuoto	Riparando	Turi
"	"	114517	F chiuso	carico	Buono	Sarno
"	"	1008366	Fc "	"	"	Bari S.E.
"	"	114103	" "	"	"	" "
"	"	1110761	" "	"	"	" "
"	"	1122588	" "	"	"	" "
"	"	1001603	" "	"	"	" "
"	F.S.E.	1213	" "	"	"	" "
"	"	1205	" "	"	"	" "
"	"	1211	" "	"	"	" "
"	"	1210	" "	"	"	" "
"	"	2000	" "	"	"	" "
"	"	2006	" "	"	"	" "
Castellana	F.S.	497854	L alte sponde	Vuoto	Buono	Alberobello
"	Entero	35359	" "	Carico	"	Adelfia
"	F.S.	445061	" "	Vuoto	"	Alberobello
Putignano	F.S.E	422	E vettura	Vuota	Buono	Bari S.E.
"	"	16	" "	"	"	" "
"	"	418	" "	"	"	" "

Adibiti a trasporti viaggiatori
Per Bari S.E. treno 112 o 113
20.1 quarto asse

266

Declassified E.O. 12356 Section 3.3/NND No. 785021

Putignano	F.S.E.	409	9 vettura	Vuoto	Buono	Bari S.S.
"	"	18	" "	"	"	" "
"	"	755	CE "	"	"	" "
"	"	751	" "	"	"	" "
"	"	1425	F chiuso	Carico	"	Putignano
"	"	1411	" "	"	"	Adibiti a deposito
"	"	1923	" "	"	"	merci e mate-
"	"	1410	" "	"	"	riali di ar-
"	"	2112	" "	"	"	mamento
"	"	1113	" "	"	"	F.S.E.
"	F.S.	186649	F.chiuso	Vuoto	Riparando	Novoli
"	"	400453	L alte spon.	Carico	Buono	Bari
"	"	418491	" "	"	"	Taranto
"	"	487766	" "	"	"	"
"	Estero	18664	" "	"	"	"
Noci	F.S.	108561	" "	"	"	Noci
"	"	481652	" "	Vuoto	"	Alberobello
"	"	418460	" "	"	"	"
"	"	77492013	" "	"	"	"
Alberobello	"	041167	" "	"	"	Cotrona
Locorotondo	"	494954	" "	"	"	Bari
"	"	419815	" "	"	"	"
"	"	457280	" "	"	"	"
"	Estero	8218	" "	Carico	"	Barletta
"	F.S.E.	11128	Mv serb.	Vuoto	"	Bari
"	F.S.	111301	F chiuso	"	Riparando	Rossirotondo
"	F.S.E.	2208	"	"	"	"
"	"	6107	Basse sponde	Vuoto	Buono	Martina
Martina	F.S.	524651	Mv serb.	"	"	"
"	F.S.E.	11102	" "	"	"	"
"	"	11036	" "	"	"	"
"	F.S.	546613	" "	Carico	"	Bari S.E.
"	F.S.E	1805	F chiuso	Vuoto	"	"
"	"	1718	" "	Carico	"	Lecce
"	F.S.	118383	" "	"	"	Taranto
"	"	1000426	" "	"	"	Alberobello
"	"	1122922	" "	"	"	"
"	"	112719	" "	"	"	Bari
"	"	430945	L alte Spon.	"	"	"
"	"	469534	" "	Vuoto	"	"
"	Estero	97713	" "	"	"	"
"	F.S.	2023658	F chiuso	"	"	"
"	"	110994	" "	"	"	"
"	"	478385	L alte spon.	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	1973	" "	"	"	"
"	"	1110	" "	"	"	"
"	"	2112	" "	"	"	"
"	"	1113	" "	"	"	"
"	F.S.	186649	F.chiuso	Vuoto	Riparando	Novoli
"	"	400633	L alte spon.	Carico	Buono	Bari
"	"	418491	" "	"	"	Taranto
"	"	487766	" "	"	"	"
"	Estero	18664	" "	"	"	"
Nuoci	F.S.	108561	" "	"	"	Nuoci
"	"	481652	" "	"	"	Alberobello
"	"	418469	" "	"	"	"
"	"	77492015	" "	"	"	Ortona
"	"	041167	" "	"	"	Bari
Alberobello	"	494954	" "	"	"	"
Locorotondo	"	419815	" "	"	"	"
"	"	457280	" "	"	"	Barletta
"	Estero	8210	Mv serb.	Carico	Riparando	Bari
"	F.S.E.	11128	F chiuso	Vuoto	"	Locorotondo
"	F.S.	111361	"	"	Buono	"
"	F.C.B.	2206	Buone sponde	"	"	Martina
"	"	6107	Mv serb.	Vuoto	"	"
Martina	F.S.	524651	" "	"	"	"
"	F.S.E.	11102	" "	"	"	Bari S.E.
"	"	11036	" "	"	"	"
"	F.S.	546613	F chiuso	Carico	"	Lecce
"	F.S.E	1805	" "	Vuoto	"	Taranto
"	"	1718	" "	Carico	"	Alberobello
"	F.S.	118383	" "	"	"	"
"	"	1000426	" "	"	"	Bari
"	"	1122922	" "	"	"	"
"	"	112719	L alte Spon.	Vuoto	"	"
"	"	490945	" "	"	"	"
"	Estero	469534	" "	"	"	"
"	F.S.	97713	F chiuso	"	"	"
"	"	2028658	" "	"	"	"
"	"	110994	L alte spon.	Carico	"	Martina
"	"	478385	Fe chiuso	"	"	Adibiti a
"	"	1002882	" "	"	"	dormitorio
"	F.S.E.	1002094	" "	"	"	Martina
"	"	2110	" "	"	"	"
"	"	1117	Spartineve	Vuoto	"	Cocorente per
"	F.S.	1111	P basso sponde	Vuota	"	treno 102
"	F.S.E	4204	Cs vettura	"	"	"
"	"	648504	" "	"	"	
"	"	760	C "	"	"	
"		961				
"		503				

Declassified E.O. 12356 Section 3.3/NND No. 785021

Martina	F.S.E.	404	C vetture	Vuoto	Buono
"	"	405	" "	"	"
"	"	406	" "	"	"
"	"	414	" "	"	"
"	"	401	" "	"	"
"	F.S.	1927747	Fc chiuso	"	"
"	"	1016175	" "	"	"
"	"	131834	" "	"	"
"	F.S.E.	1604	" "	"	"
Statte	F.S.	400298	L alte spon.	"	"
"	F.S.E.	415073	" "	"	"
"	"	4406	" "	"	"
"	Metero	84950	" "	"	"
"	"	18225	" "	"	"
Crispiano	—	—	—	—	—
Taranto	F.S.E.	5000	M serbatoio	Vuoto	Buono
"	"	1708	F chiuso	Carico	"
"	"	1207	" "	Arredato	"
"	"	1200	" "	"	"
"	"	1601	" "	"	"
"	F.S.	1122541	" "	"	"
"	"	1131582	" "	"	"
"	"	1090698	" "	"	"
"	F.S.E	423	C vetture	Carico	"
"	"	420	" "	"	"
"	"	407	" "	"	"
"	"	505	MM bagagliaio	"	"
"	F.S.	135801	F chiuso	Carico	"
Pisternino	"	497782	L alte spon.	Vuoto	Buono
"	Metero	91691	" "	"	"
"	F.S.	489581	" "	"	"
"	"	466318	" "	"	"
Beglie Mes.	"	192371	MM chiuso	Vuoto	Buono
"	"	1010515	E "	Carico	"
"	"	660696	F basse spon.	Vuoto	"
"	F.S.E	5004	Mv serbat. acc.	"	"
Nave	—	—	—	—	—
Manduria	—	—	—	—	—
Erchie	F.S.	465273	L alte spon.	Vuoto	Buono
"	"	470531	" "	"	"
S. Pancrazio	"	77643003	F basse sponde	Carico	"
"	"	647187	" "	"	"
"	"	660161	" "	"	"
"	"	655341	" "	"	"
"	"	645076	" "	"	"
"	"	77600000	" "	"	"

Per treno 108

Martina	
Taranto	Celsse
"	"
"	"
"	"
"	"
Taranto	Celsse
"	"
Martina	
"	"
"	"
"	"
"	"
"	"
"	"
"	"
"	"
Taranto	Celsse
Francavilla	
"	"
"	"
"	"
"	"
"	"
Pescarose	
"	"
—	—
—	—
Erchie	
"	
S.Pancrazio	
"	
"	
"	
"	
"	
"	

264

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	131834	" "	"	"	" "
"	F.S.F.	1604	" "	"	"	" "
Biette	F.S.	400398	L alte spon.	"	"	Taranto Celsee
"	F.S.S.	415973	" "	"	"	" "
"	"	4406	" "	"	"	" "
"	Intero	44959	" "	"	"	" "
"	"	18225	" "	"	"	" "
Crispiano	—	—	—	—	—	—
Taranto	F.S.T.	5003	M serbatoio	Vuoto	Buono	Taranto Celese
"	"	1708	F chiuso	Carico	"	" "
"	"	1207	" "	Arredato	"	Martina
"	"	1202	" "	"	"	"
"	"	1601	" "	"	"	"
"	F.S.	1128541	" "	"	"	"
"	"	1111582	" "	"	"	"
"	"	1090698	" "	"	"	"
"	F.S.E	423	C vettura	Carico	"	"
"	"	410	" "	"	"	"
"	"	407	" "	"	"	"
"	"	505	" "	"	"	"
"	F.S.	195901	M bagagliaio	Carico	"	"
Cisternino	"	497782	F chiuso	Vuoto	Buono	Taranto Celese
"	Intero	03691	L alte spón.	"	"	Francavilla
"	F.S.	489581	" "	"	"	" "
"	"	466118	" "	"	"	" "
Foglie Nos.	"	192172	MB chiuso	Vuoto	Buono	" "
"	"	1010515	E "	Carico	"	" "
"	"	660696	F basse spon.	Vuoto	"	Francavilla
"	F.S.F	5004	MF serbat. acc.	"	"	" "
Cava	—	—	—	—	—	—
Manduria	—	—	—	—	—	—
Erchie	F.S.	495473	L alte spon.	Vuoto	Buono	Erchie
"	"	490532	" "	"	"	"
S. Pancrazio	"	77643000	F basse sponde	Carico	"	S.Pancrazio
"	"	647287	" "	"	"	"
"	"	660161	" "	"	"	"
"	"	655341	" "	"	"	"
"	"	645676	" "	"	"	"
"	"	77600000	" "	"	"	"
"	"	660537	" "	"	"	"
"	"	648297	" "	"	"	"
"	"	454251	L alte sponde	"	"	"
"	"	479093	" "	"	"	"
"	"	433189	" "	"	"	"
"	"	471321	" "	"	"	"
"	"	474887	" "	"	"	"
"	"	408582	" "	"	"	"
"	"	445341	" "	"	"	"
"	"	77492017	" "	"	"	"

Per treno 108

264

Declassified E.O. 12356 Section 3.3/NND No. 785021

S.Giorgio	F.S.	7407705	L alte sponde	Carico	Buono	S.Severino
"	"	475744	" "	"	"	"
"	"	470730	" "	"	"	Cotarano Sole
"	Estero	18156	" "	"	"	S. Severino
"	"	27844	" "	"	"	"
"	F.S.	513286	Mv scrittoi vino	"	"	Napoli S.C.N.
"	"	397460	" "	"	"	Sale Cancilina
Guagnano	F.S.S.	850	DLT bagagliaio	"	"	Martina
"	"	304	C vetture	"	"	
"	"	853	" "	"	"	
"	"	309	" "	"	"	
"	"	310	" "	"	"	
"	"	854	" "	"	"	
"	"	2511761	C chiuso	"	"	Martina Franca 205
"	"	2705	F chiuso	Vuoto	Ripetendo	Martina
"	"	1125	" "	"	"	Guagnano
"	"	2129	" "	"	"	" "
"	"	2914	" "	"	"	"
"	"	2907	" "	"	"	"
"	"	2838	" "	"	"	"
"	"	1923	" "	"	"	"
"	"	4436	L alte sponde	"	"	"
"	F.S	1135982	F e chiuso	Merico	"	Salice
Campi	"	542512	Mv scrittoio	Vuoto	Ripetendo	Campi
"	"	508227	" "	Carico	Buono	Napoli S.C.N.
"	"	511870	" "	"	"	Valle S.Cebbaro
"	"	100332	F chiuso	"	"	Campi
"	"	197787	" "	"	"	"
"	"	1015447	" "	"	"	"
"	"	1022410	" "	Vuoto	"	"
"	"	1127752	" "	"	"	"
"	"	185842	" "	"	"	"
"	"	141561	" "	"	"	"
"	Estero	73042	" "	Carico	"	"
Novoli	F/S.	1029506	Fc chiuso	"	"	S. Giovanni Rotondo
"	"	1007454	" "	"	"	" "
"	"	130035	" "	"	"	Foglio Sampalco "
"	"	1033950	" "	"	"	" "
"	"	1020410	" "	"	"	Francavilla
"	"	1122783	" "	"	"	"
"	"	189126	" "	"	"	"
"	"	1024397	" "	"	"	"
"	"	1029804	" "	"	"	"
"	"	1009476	" "	"	"	Verdè Città
"	"	1044762	" "	"	"	Calatina
"	"	203437	" "	"	"	Barletta
"	"	1001036	" "	"	"	"
"	"	210870	" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Bisaccia	F.S.B	855	Mt Deserglinio	"	"	ertine
"	"	391	C vetture	"	"	
"	"	852	" "	"	"	
"	"	395	" "	"	"	
"	"	110	" "	"	"	
"	"	454	" "	"	"	
"	"	2533783	C chiuso	"	"	ertine
"	"	2705	F chiuso	Tucto	Riparando	Bisaccia
"	"	2195	" "	"	"	" "
"	"	2109	" "	"	"	"
"	"	1973	" "	"	"	"
"	"	2907	" "	"	"	"
"	"	2808	" "	"	"	"
"	"	1903	" "	"	"	"
"	"	4408	I alto sponde	"	"	"
"	F.S	1135908	F e chiuso	Carico	"	Calitri
Bengpi	"	941518	Av corbitoio	Tucto	Riparando	Bengpi
"	"	908227	" "	Carico	Buono	Napoli S.O.D.
"	"	911470	" "	"	"	Melfa S.Gebbaro
"	"	100332	F chiuso	"	"	Bengpi
"	"	198787	" "	"	"	"
"	"	1019417	" "	"	"	"
"	"	1024401	" "	Tucto	"	"
"	"	1227752	" "	"	"	"
"	"	189542	" "	"	"	"
"	"	141581	" "	"	"	"
"	Eatoro	73062	" "	Carico	"	"
Napoli	F/S.	1029506	Fe chiuso	"	"	S. Giovanni Bertra
"	"	1007464	" "	"	"	" "
"	"	230946	" "	"	"	Foglie Mesagnico "
"	"	1033050	" "	"	"	" "
"	"	1002010	" "	"	"	Francavilla
"	"	1122783	" "	"	"	"
"	"	189018	" "	"	"	"
"	"	1024357	" "	"	"	"
"	"	1029084	" "	"	"	"
"	"	1009476	" "	"	"	Napoli Città
"	"	1004762	" "	"	"	Celestina
"	"	205417	" "	"	"	Ferrobia
"	"	1001036	" "	"	"	" 263
"	"	7108975	" "	"	"	"
"	Eatero	7881	" "	"	"	"
"	F.S.	130509	" "	"	"	Molisano
"	"	1004610	" "	"	"	"
"		89108	" "	"	"	Frosicone
"	"	212056	" "	"	"	Ivrea
"	Eatero	13183	" "	"	"	"
"	F.S.	1113210	" "	"	"	"
"	Eatero	71344	" "	"	"	"
"	"	312134	" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Novoli	Estero	360118	F. chiuso	Carico	Buono	Averza
"	F.S.	407046	L alte sponde	"	"	Taranto
"	"	417783	" "	"	"	"
"	"	466254	" "	"	"	"
"	"	444836	" "	"	"	Oria
"	"	477584	" "	"	"	Bari Marittima
"	Estero	81433	Basse sponde	"	"	Manduria
"	F.S.	657344	" "	"	"	Lecce
"	F.S.E.	6501	Le serbatoi	Vuoto	Buono	Novoli
"	"	3004	F chiuso	"	"	"
"	"	3137	" "	"	"	Francavilla
"	"	3006	" "	"	"	"
"	"	4003	L alte sponde	Vuoto	"	Novoli
"	"	4221	" "	"	"	"
"	"	4252	" "	"	"	"
"	F.S.	425946	" "	Carico	"	"
"	"	484566	" "	"	"	"
"	"	660851	P.basse sponde	"	"	"
"	"	644708	" "	"	"	"
"	"	653173	" "	"	"	"
"	"	688167	" "	"	"	"
"	"	652307	" "	"	"	"
"	"	645225	" "	"	"	"
"	"	646076	" "	"	"	"
"	F.S.E.	4264	" "	Vuoto	"	"
"	"	4266	" "	"	"	"
"	"	6111	" "	Carico	"	"
"	F.S.	524726	Le serbatoi	Vuoto	"	"
"	"	538013	" "	"	"	"
"	"	514076	" "	"	"	"
"	"	514092	" "	"	"	"
"	"	508920	" "	Carico	"	Napoli
"	"	524307	" "	"	"	"
"	"	1011251	F chiuso	Vuoto	Riparando	Caserta
"	"	1029703	" "	"	"	Novoli
"	"	1022160	" "	"	"	"
"	"	1010421	" "	"	"	"
"	"	117732	" "	"	"	"
"	"	186483	F chiuso	"	"	"
"	"	186286	" "	"	"	"
"	Estero	40428	" "	"	"	"
"	"	19671	" "	"	"	"
"	F.S.	416250	L alto sponde	"	"	"
"	"	459393	" "	"	"	"
"	"	7448948	" "	"	"	"
"	"	481236	" "	"	"	"
"	"	455448	" "	"	"	"
"	"	476397	" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Premo offerto n o m 21.

"	F.S.	657344	" "	"	"	Lecce
"	F.S.K.	6501	Le serbatoi	Vuoto	Buono	Novoli
"	"	3004	F chiuso	"	"	"
"	"	2127	" "	"	"	Francavilla
"	"	3006	" "	"	"	"
"	"	4003	L alte sponde	Vuoto	"	Novoli
"	"	4221	" "	"	"	"
"	"	4252	" "	"	"	"
"	F.S.	416946	" "	Carico	"	"
"	"	404566	" "	"	"	"
"	"	660852	P basse sponde	"	"	"
"	"	644708	" "	"	"	"
"	"	653173	" "	"	"	"
"	"	658107	" "	"	"	"
"	"	652307	" "	"	"	"
"	"	645225	" "	"	"	"
"	"	646076	" "	"	"	"
"	F.S.E.	4264	" "	Vuoto	"	"
"	"	4266	" "	"	"	"
"	"	6111	" "	Carico	"	"
"	F.S.	524726	[illegible]	Vuoto	"	"
"	"	538013	" "	"	"	"
"	"	514076	" "	"	"	"
"	"	514092	" "	"	"	Napoli
"	"	508020	" "	Carico	"	"
"	"	524347	" "	"	"	Caserta
"	"	1011251	F chiuso	Vuoto	Riparando	Novoli
"	"	1029703	" "	"	"	"
"	"	1022160	" "	"	"	"
"	"	1016421	" "	"	"	"
"	"	117732	" "	"	"	"
"	"	186483	F chiuso	"	"	"
"	"	186286	" "	"	"	"
"	Estero	49428	" "	"	"	"
"	"	19671	" "	"	"	"
"	F.S.	416250	L alte sponde	"	"	"
"	"	459393	" "	"	"	"
"	"	7448942	" "	"	"	"
"	"	481236	" "	"	"	"
"	"	455448	" "	"	"	"
"	"	479397	" "	"	"	"
"	"	468736	" "	"	"	"
"	"	419407	" "	"	"	"
"	Estero	1152	" "	"	"	"
"	F.S.	472078	" "	"	"	"
"	"	7401398	" "	"	"	"
Carniano						
Montoroni	F.S.	468394	L alte sponde	Carico	Buono	S.Pancrazio
Copertino	Estero	34451	" "	Vuoto	"	Lecce
"	F.S.	140832	F chiuso	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

0.0.711

prego ortolone Monfalcone 26

Copertino	Estero	1005920	Fc chiuso	Vuoto	Buono	Lecce
"	"	2004788	" "	"	"	"
"	"	1003063	" "	"	"	"
"	"	7106279	" "	"	"	"
"	"	1007093	" "	"	"	"
"	Estero	38531	" "	"	"	"
"	F.S.	475464	F "	"	"	"
"	"	144994	" "	"	"	"
"	"	487780	L alte sponde	"	"	"
"	"	415760	" "	"	"	"
"	"	484756	" "	"	"	"
"	"	479387	" "	"	"	"
"	"	455016	" "	"	"	"
"	"	445649	" "	"	"	"
"	"	490529	" "	"	"	"
"	"	451244	" "	"	"	"
"	"	481166	" "	"	"	"
"	"	632914	P basse sponde	"	"	"
"	"	646048	" "	"	"	"
"	"	623906	" "	"	"	"
"	"	651819	" "	"	"	"
"	"	646462	" "	"	"	"
"	"	508344	Mv serbatoio	"	Copertino	Copertino
"	"	508104	" "	"	"	"
Nardò Città	"	419837	L alte sponde	Carico	"	Nardo Città
"	"	7448761	" "	"	"	"
Galatone	"	1010425	Fc chiuso	Vuoto	"	Galatone Città
"	"	170497	F chiuso	"	"	"
"	Estero	40020	" "	"	"	"
Gallipoli	—	—	—	—	—	—
Tuglie	F.S.	508312	Mv serbatoi	Carico	Buono	Barletta
"	F.S.E	11029	" "	"	"	Termoli
"	"	1118300	Fc chiuso	Vuoto	"	Lecce
"	Estero	8499	Alte sponde	"	"	"
"	F.S.E	906	Due Pagagliai	Carico	"	"
"	"	307	C vettura	"	"	"
"	"	151	" "	"	"	"
"	"	361	" "	"	"	"
"	"	303	" "	"	"	"
"	"	356	" "	"	"	"
"	"	106	" "	"	"	"
"	"	100	" "	"	"	"
Parabita	F.S.	1002557	E chiuso	Vuoto	"	Parabita
"	Estero	84062	" "	"	"	"
"	F.S.	472786	L alte sponde	"	"	"
"	447779	"	" "	"	"	"

tronco 305 per Gagliano

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	F.S.	173454	" "	"	"	"	"
"	"	144094	" "	"	"	"	"
"	"	487780	L alte sponde	"	"	"	"
"	"	435760	" "	"	"	"	"
"	"	484756	" "	"	"	"	"
"	"	479387	" "	"	"	"	"
"	"	455016	" "	"	"	"	"
"	"	445849	" "	"	"	"	"
"	"	490529	" "	"	"	"	"
"	"	451244	" "	"	"	"	"
"	"	481166	" "	"	"	"	"
"	"	652914	P basso sponde	"	"	"	"
"	"	646048	" "	"	"	"	"
"	"	623906	" "	"	"	"	"
"	"	651819	" "	"	"	"	"
"	"	646452	" "	"	"	"	"
"	"	508344	My serbatoio	"	"	"	"
"	"	508104	" "	"	"	"	"
Verdà Città	"	419837	L alte sponde	"	"	Copertino	Copertino
"	"	7448761	" "	"	"	"	"
Galatone	"	1010425	Fe chiuso	"	"	"	Nardo Città
"	"	170497	F chiuso	"	"	"	"
"	Estero	40020	" "	"	"	"	Galatone Città
Nardò	—	—	—	—	—	—	"
Tuglie	F.S.	508312	My serbatoi	Carico	Buono	Marletta	—
"	F.S.E	11029	" "	"	"	Tornoli	Marletta
"	"	1138300	Fe chiuso	Vuoto	"	Lecce	Tornoli
"	Estero	8499	Alte sponde	"	"	"	Lecce
"	F.S.E	906	Dut Bagagliai	Carico	"	"	"
"	"	307	C vettura	"	"	"	"
"	"	151	" "	"	"	"	"
"	"	301	" "	"	"	"	"
"	"	303	" "	"	"	"	"
"	"	356	" "	"	"	"	"
"	"	106	" "	"	"	"	"
"	"	100	" "	"	"	"	"
Parabita	F.S.	1002557	E chiuso	Vuoto	"	"	"
"	Estero	8402	" "	"	"	"	"
"	F.S.	472786	L alte sponde	"	"	"	"
"	447779	"	" "	"	"	"	"
"	Estero	4448	" "	Carico	"	"	"
"	"	77493007	" "	"	"	"	"
Matino	F.S.	1133118	Fe chiuso	Vuoto	"	"	"
"	"	1130972	" "	"	"	"	"
"	"	418873	L alte sponde	"	"	"	"
"	"	77186319	F chiuso	"	"	"	"
Casarano	F.S.E.	6101	P basse sponde	Carico	"	"	Parabita
"	"	5003	Fe cisterne	Vuoto	"	"	"
"	"	8205	C chiuso	Carico	"	"	"
"	"	~~196~~	" "	"	"	"	"
							2 C.1
							Parabita
							Lecce
							"
							"
							Magliano
							Casarano
							Gallipoli
							"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Cesarano	F.S.E.	2108	S. chiuso	Carico	Buono	Pozzo 404 per Cell... poli
"	"	12	Ct vettura	"	"	
"	"	210	" "	"	"	
"	"	413	C "	"	"	
"	"	420	" "	"	"	
"	"	421	" "	"	"	
"	"	852	Dut Bagagliaio	"	"	
Ugento	"---	---	---	---	---	
Presicce	F.S.	1022411	Fe chiuso	Vuoto	Buono	Presicce
"	"	1003917	" "	Serbatoio	"	Meglie
Salve	"---	---	---	---	---	
Morciano	F.S.	82493	D bagagliaio	Vuoti	Demolendo	Morciano
"	Estero	50698	C vettura	"	"	"
Gagliano T.	Tedesco	36151	C vettura	"	Riparando	Gagliano
"	F.S.	86383	D bagagliaio	"	"	"
"	"	94056	DST "	"	"	"
"	"	94254	" "	"	"	"
"	F.S.E.	6394	Serbatoio	"	Buono	"
"	Tedesco	29519	Alte sponde	"	"	Morciano
"	F.S.	468911	L alte sponde	"	"	"
"	"	156811	F chiuso	Carico	"	Novoli
"	"	468899	L alte sponde	"	"	Spongano
"	"	1016633	F e chiuso	"	"	"
Alessano	"	490473	L alte sponde	Vuoto	"	Alessano
"	"	476440	" "	"	"	"
Tricase	119	429927	" "	"	"	Lecce
"	"	416067	" "	"	"	"
Miggiano	F.S.E.	6192	P basse sponde	"	"	Miggiano
Andrano	---	---	---	---	---	---
Spongano	---	---	---	---	---	---
Muro Leccese	---	---	---	---	---	---
Meglie	Estero	51119	L Alte sponde	Carico	Buono	Meglie
"	F.S.	1025940	F Chiuso	"	"	Rollino
"	"	481733	L alte sponde	"	"	Meglie
"	"	410238	" "	"	"	"
"	"	466744	" "	"	"	"
"	"	473737	" "	"	"	"
"	"	486653	" "	Vuoto	"	Lecce
"	"	466069	" "	"	"	Lecce
"	"	1016850	Fe chiuso	Vuoto	"	"
"	"	185256	" "	Carico	"	Lecce
"	Estero	9231	Alte sponde	"	"	Meglie
"	F.S.	480252	L "	"	"	"
"	Estero	35270	" "	"	"	"
"	F.S/E	4205	" "	"	"	"
"	F.S.	77496646	" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	221	" "	"	"	
"	"	852	Dut Bagagliaio			
Ugento	"					
Presicce	F.S.	1027411	Fe chiuso	Vuoto	Buono	Presicce
"	"	1003917	" "	Carico	"	Meglie
Salve	T2					
Morciano	F.S.	62493	D bagagliaio	Vuoti	Demolendo	Morciano
"	Estero	50688	C vettura	"	"	"
Gagliano T.	Tedesco	36151	C vettura	"	Riparando	Gagliano
"	F.S.	86263	D bagagliaio	"	"	"
"	"	94956	DGT "	"	"	"
"	"	94254	" "	"	"	"
"	F.S.E.	6594	Serbatoio	"	Buono	"
"	Tedesco	20319	Alte sponde	"	"	Morciano
"	F.S.	462511	L alte sponde	"	"	"
"	"	155811	F chiuso	"	"	Novoli
"	"	468239	L alte sponde	"	"	Spongano
"	"	1026633	F e chiuso	"	"	"
"	"	490273	L alte sponde	"	"	Alessano
Alessano	"	476440	" "	"	"	"
"	#19	429027	" "	"	"	Lecce
Trieste	"	438087	" "	"	"	"
"	F.S.E.	6198	F bagag sponde	"	"	Miggiano
Miggiano						
Andrano						
Spongano						
Muro Leccese			L Alte s onde	Carico	Buono	Meglie
Meglie	Estero	5119	F Chiuso	"	"	Zollino
"	F.S.	1025949	L al e sponde	"	"	Meglie
"	"	491733	" "	"	"	"
"	"	410238	" "	"	"	"
"	"	468744	" "	"	"	Lecce
"	"	473737	" "	"	"	Lecce
"	"	480651	" "	"	"	"
"	"	466069	Fe chiuso	Vuoto	"	Lecce
"	"	1016250	" "	"	"	"
"	"	185255	Alte sponde	Vuoto	"	Meglie
"	Estero	9031	L "	Carico	"	"
"	F.S.	420352	" "	"	"	"
"	Estero	35270	" "	"	"	"
"	F.S/E	4205	" "	"	"	"
"	F.S.	77496046	" "	"	"	"
"	"	402073	" "	"	"	"
"	"	460987	" "	"	"	"
"	"	477417	" "	"	"	"
"	"	414693	" "	"	"	"
"	"	423248	" "	"	"	"
"	F.S.E.	352	B. vettura	vuoto	"	Alessano
"	"	107	" "	"	"	Trieste
"	"	854	Du bagagliaio	"	"	Otranto
"	"	314	C vettura	"	"	
"	"	306	" "	"	"	

Treno 705
Fem
Otranto

Declassified E.O. 12356 Section 3.3/NND No. 785021

0081

Maglie	F.S.M.	210	Di Lagnasco	Carico	Carico	Cagliano
"	"	353	Cavallero	"	"	Treno 605 per Cagliano
"	"	300	" "	"	"	
"	"	1011	" "	"	"	
"	"	1144	" "	"	"	
"	"	1206	" "	"	"	
"	"	1006	" "	"	"	
"	"	452	" "	"	"	
"	"	402	" "	"	"	
"	"	707	Ca "	"	"	
"	"	1505	N. sufficio	"	"	Otranto
Otranto	"					
Bagnoli		4407	L alle spunde	Carico	Buoio	Sandaria
Corigliano	F.S.E.	16335	" "	"	"	Corigliano
Otranto	Ritorno	457924	" "	"	"	Francavilla
"	F.S.	456697	" "	"	"	"
"	"	468729	" "	"	"	Martina
"	"	470858	" "	"	"	"
"	"	469854	" "	"	"	Torciano
"	"	474164	" "	"	"	Corigliano
S.Cesario	"					
Dollino	F.S.	1234132	F chiuso	Vuoto	Domicando	Mollino
"	"	180476	" "	"	"	"
"	"	171548	" "	"	"	"
"	"	110047	" "	"	"	"
"	"	180433	" "	"	"	"
"	"	100825	" "	"	"	"
"	Ritorno	11565	" "	"	"	"
"	"	58085	" "	"	"	"
"	"	1196	" "	"	"	"
"	"	135883	Alte sponde	"	"	"
"	"	75547	" "	"	"	"
"	F.S.	479992	" "	"	"	"
"	"	470413	" "	"	"	"
"	"	479343	" "	"	"	"
"	"	479150	" "	"	"	"
"	"	693253	Fos pilmale	"	"	"
"	"	669364	F basso sponde	"	"	"
"		1023941	Fe chiuso	"	"	"
"	Ritorno	5099	" "	"	Ripasando	"
"	Ritorno	36150	" "	"	"	"
"	"	1135	Alte sponde	"	"	"
Dollino	Ritorno	2301	Alte sponde	"	"	Zollino
"	"	767200	" "	"	"	"
"	"	32460	" "	"	"	"
"	"	95240	" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	488	" "	"	"	
"	"	706	2 "	"	"	Otranto
"	"	2515	Mezzatolo			
Otranto	"					Soleria
Bagnolo						Corigliano
Corigliano	P.S.	4407	L alte sponde	Carico	Buono	Tranoville
Otranto	Ratero	16335	" "	"	"	"
"	P.S.	457	" "	"	"	Martina
"	"	456	" "	"	"	"
"	"	468	" "	"	"	Mercisno
"	"	470	" "	"	"	Corigliano
"	"	469	" "	"	"	
"	"	471	" "	"	"	
S.Cesario	"					Sollino
Zollino	P.S.	123	F chiuso	Vuoto	Demolendo	"
"	"	180	" "	"	"	"
"	"	171	" "	"	"	"
"	"	120	" "	"	"	"
"	"	150	" "	"	"	"
"	"	100	" "	"	"	"
"	Ratero	12	" "	"	"	"
"	"	28	" "	"	"	"
"	"	1196	" "	"	"	"
"	"	155	Alte sponde	"	"	"
"	"	75547	" "	"	"	"
"	P.S.	479	" "	"	"	"
"	"	470	" "	"	"	"
"	"	479	" "	"	"	"
"	"	470	" "	"	"	"
"	"	693	Dos pidmale	"	"	"
"	"	669	F basse sponde	"	"	"
"		107	Fe chiuso	"	"	"
"	Ratero	5099	" "	"	"	"
"	Ratero	38150	" "	"	"	"
"	"	1915	Alto sponde	"	"	"
Zollino	Ratero	2321	Alte sponde	"	"	Zollino
"	"	767	" "	"	"	"
"	"	2146	" "	"	"	"
"	"	95640	" "	"	"	"
"	P.S.	740581	" "	"	"	"
"	"	749	" "	"	"	"
"	"	411	" "	"	"	"
"	"	407	" "	"	"	"
"	"	479	" "	"	"	"
"	Ratero	10423	" basse sponde	"	"	"
"	"	43375	" "	"	"	"
"	"	38490	" "	"	"	"
"	"	12326	" "	"	"	"
"	P.S.	410597	L alte sponde	Vuote	Buono	Lecce

259

Declassified E.O. 12356 Section 3.3/NND No. 785021

Zollino	F.S.	7477030	1 alto sponde	Tunto	Buono	Lecce
"	"	474712	" "	"	"	"
"	"	474897	" "	"	"	"
"	"	496779	" "	"	"	"
"	"	497134	" "	"	"	"
"	"	413793	" "	"	"	"
"	"	498176	" "	"	"	"
"	"	491126	" "	"	"	"
"	"	417917	" "	"	"	"
"	"	416586	" "	"	"	"
"	"	498141	" "	"	"	"
"	"	4 87721	" "	"	"	"
"	"	491980	" "	"	"	"
"	Estero	19212	" "	"	"	Zollino
"	"	13934	" "	"	"	"
"	F.S.	86601	DI bagagliaio	"	Demolendo	"
"	"	99746	" "	"	"	"
"	"	9985	" "	"	"	"
"	"	486456	1 alto sponde	Tunto	"	Lecce
"	"	10241936	Fo chiuso	Verico	Buono	Galatina
"	"	246441	G "	Tunto	"	Lecce
"	F.S.E.	2009	F "	"	"	"
"	F.S.	499577	1 alto sponde	"	"	"
"	"	487021	" "	"	"	"
"	Estero	58769	" "	"	"	"
"	"	340085	Bagno sponde	"	"	"
"	F.S.	645309	" "	"	"	"
"	"	752714	" "	"	"	"
"	F.S.	5069	R sambatoio	"	"	"
"	"	731	Cn Vetture	"	"	"
"	F.S.	458575	1 alto sponde	"	"	Galatone
"	"	475729	" "	"	"	"
"	"	205439	G chiuso	"	"	Nardò Centrale
"	F.S.	1000300	Fo chiuso	carico	"	"
"	"	942134	1 alto sponde	"	"	Lecce
"	Estero	203105	" "	"	"	"
"	F.S.E.	1001	F chiuso	Tunto	"	"
"	"	1105	" "	"	"	"
"	"	1712	" "	"	"	"
"	1830	1830	R sambatoi	"	"	"
"	"	6503	" "	"	"	"
"	"	5007	" "	"	"	Zollino
"	"	79016611	DI bagagliaio	"	"	"
"	F.S.E.	903	Ct vetture	"	"	Lecce
"	"	350	" "	"	"	"
"	"	410	Ct vetture	"	"	"
Nardò C.le	"	459	" "	"	"	"
"	"	333				
Salento						
Sempi						
"						
Nardò						
Centrale						
"						
"						
"

0 0 8 5 1

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	427037	" "	"	"	"
"	"	419546	" "	"	"	"
"	"	439141	" "	"	"	"
"	"	4 8721	" "	"	"	"
"	"	433986	" "	"	"	"
"	Estero	12732	" "	"	"	"
"	"	13914	" "	"	"	"
"	F.S.	86401	" "	"	"	"
"	"	99746	" "	"	"	"
"	"	9986/	" "	"	"	"
"	"	486454	" "	"	"	"
Soleto	"	1024936	" "	"	"	"
Galatina	"	244441	" "	"	"	"
"	"	2009	" "	"	"	"
"	F.S.E.	499970	" "	"	"	"
"	F.S.	467061	" "	"	"	"
"	"	98769	" "	"	"	"
"	Estero	3 9025	" "	"	"	"
"	"	649329	" "	"	"	"
"	F.S.	7.2714	" "	"	"	"
"	"	5008	" "	"	"	"
"	F.S.	733	" "	"	"	"
"	"	456570	" "	"	"	"
"	F.S.	475709	" "	"	"	"
"	"	205439	" "	"	"	"
Galatone	F.S.	1000802	" "	"	"	"
Nardò	"	042134	" "	"	"	"
Centrale	Estero	203105	" "	"	"	"
"	F.S.E.	1001	" "	"	"	"
"	"	1106	" "	"	"	"
"	"	1712	" "	"	"	"
"	"	1830	1830	"	"	"
"	"	650	" "	"	"	"
"	"	5007	" "	"	"	"
"	"	79016611	" "	"	"	"
"	F.S.E.	905	" "	"	"	"
"	"	359	" "	"	"	"
"	"	446	" "	"	"	"
Nardò C.le	"	459	" "	"	"	"
"	"	313	" "	"	"	"
"	"	353	" "	"	"	"
"	"	195	" "	"	"	"
Carmiola	F.S.	202085	" "	"	"	"
Alessio	"	1129726	" "	"	"	"
"	"	5311893	" "	"	"	"
"	"	524943	" "	"	"	"
Gallipoli	"	7471969	" "	"	"	"
"	"	477102	" "	"	"	"

"	"	"	"	"	"	"
"	"	"	"	"	"	"
"	"	"	"	"	"	"

Gallipoli	P.S.	416534	I alte sponde	Vuote	Buono	Lecce
"	"	418264	" "	"	"	"
"	"	402718	" "	"	"	"
"	Metero	17962	" "	"	"	"
"	P.S.	407974	" "	"	"	"
"	"	408816	" "	"	"	"
"	"	489355	" "	"	"	"
"	Metero	12768	" "	"	"	"
"	P.S.	451353	" "	"	"	"
"	Metero	56542	" "	"	"	"
"	P.S.	414923	" "	"	"	"
"	"	442919	" "	"	"	"
"	"	496866	" "	"	"	"
"	"	495729	" "	"	"	"
"	"	468976	" "	"	"	"
"	"	1011765	" "	"	"	"
"	Metero	23571	Fo chiuso	Barico	"	Gallipoli
"	P.S.	1028362	" "	"	"	"
"	"	483500	I. alto sponde	"	"	Lecce
Gallipoli	Metero	98220	F chiuso	Vuoto	"	"
"	P.S.E.	1214	Du bagagliaio	"	"	
"						
"			F chiuso	"	Buono	
Taviano	P.S.	199023	" "	"	"	Lecce
Racale	"	172660	I alte sponde	"	"	"
"	"	492332	Fo chiuso	"	"	"
"	P.S.	1027915	" "	"	"	"
Veliceano	"	1118325	I alte sponde	"	"	Lecce
"	P.S.	469006	F chiuso	"	"	"
Lecce	"	172991	Du bagagliaio	"	"	"
Nardiche	"	87093	F chiuso	"	"	"
"	"	304858	" "	"	"	"
"	"	184608	F "	"	"	"
"	"	1020417	Chiuso	"	"	"
"	"	133254	" "	"	"	"
"	"	7108524	" "	"	"	"
"	"	661849	I alte sponde	"	"	"
"	Metero	13674	" "	"	"	"
"	P.S.	23678	Du bagagliaio	"	"	"
"	"	935	Os vettura	"	"	"
"	"	756	" "	"	"	"
"	"	601	" "	"	"	"
"	"	602	Dus bagaglino	"	"	"
"	"	606	C vettura	"	"	"
"	"	902	" "	"	"	"
"	"	103	" "	"	"	"
"	"	305		"	"	"
"	"	453		"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Treno 202 Per Martina

Treno 201 Per Lecce

"	"	"	"	"	"	"	"
"	F.S.	191353	" "	"	"	"	"
"	Estero	56542	" "	"	"	"	"
"	F.S.	424225	" "	"	"	"	"
"	"	448919	" "	"	"	"	"
"	"	486860	" "	"	"	"	"
"	"	495729	" "	"	"	"	"
"	"	468576	" "	"	"	"	"
"	"	1011765	Fc chiuso	"	"	"	Gallipoli
"	Estero	23571	" "	"	"	"	"
Gallipoli	F.S.	1028361	" "	"	"	"	"
"	"	483500	L alte sponde	"	"	"	Lecce
"	Estero	24220	F chiuso	"	"	"	"
"	F.S.E.	1214	Du bagagliaio	"	"	"	"
Tavirno	—	—	—	—	—	—	—
Racale	F.S.	199023	F chiuso	Vuoto	Buono	"	Lecce
"	"	172650	" "	"	"	"	"
"	"	492332	L alte sponde	"	"	"	"
Melissano	F.S.	1027913	Fc chiuso	"	"	"	"
"	"	1118325	" "	"	"	"	"
Lecce	F.S.	469005	L alte sponde	"	"	"	Lecce
Stazione	"	172891	F chiuso	"	"	"	"
"	"	87093	DF bagagliaio	"	"	"	"
"	"	304268	R chiuso	"	"	"	"
"	"	104608	F "	"	"	"	"
"	"	1020417	Fabbriso	"	"	"	"
"	"	133254	" "	"	"	"	"
"	"	7105524	" "	"	"	"	"
"	"	661849	L a te sponde	"	"	"	"
"	Estero	13674	" "	"	"	"	"
"	"	51678	" "	"	"	"	"
"	F.S.E.	935	DuF bagagliaio	"	"	"	"
"	"	756	Cx vettura	"	"	"	"
"	"	601	" "	"	"	"	"
"	"	602	" "	"	"	"	"
"	"	606	" "	"	"	"	"
"	"	902	Dut bagagliaio	"	"	"	"
"	"	103	c vettura	"	"	"	"
"	"	305	" "	"	"	"	"
"	"	453	" "	"	"	"	"
"	"	458	F chiuso	"	"	"	"
"	"	1209	" "	"	"	"	"
"	"	1414	Du bagagliaio	"	"	"	"
"	"	1812	" "	"	"	"	"
"	"	2012	D4 "	"	"	"	"
"	"	862	" "	"	"	"	"
"	"	850	" "	"	"	"	"
"	"	907	Du bagagliaio	"	"	"	"
"	"	2007	DUT "	"	"	"	"
Lecce	"	906	" "	"	"	"	"
Stazione	"	"	" "	"	"	"	"
"	"	"	" "	"	"	"	"
"	"	"	" "	"	"	"	"
"

Stazione	F.S.E.	709	2a vettura	Vuote	Buona	Lecce
"	"	703	" "	"	"	"
"	"	712	" "	"	"	"
"	"	707	" "	"	"	"
"	"	452	" "	"	"	"
"	"	905	DUT bagagliaio	"	"	"
"	"	253	C vettura	"	"	"
"	"	251	" "	"	"	"
"	"	457	" "	"	"	"
"	"	308	" "	"	"	"
"	"	2010	F chiuso	Arredati	"	"
"	"	2004	" "	"	"	"
"	"	1205	" "	"	"	"
"	F.S.	646671	F basse sponde	Carico	Buono	Lecce
Lecce	Estero	269284	Chiuso	Vuoto	Riparando	Offic. Rialto
Officine	"	7296	" "	"	"	"
"	"	20588	" "	"	"	"
"	"	2862	Bagagliaio	"	"	"
"	"	77373	" "	"	"	"
"	"	75830	" "	"	"	"
"	"	45355	" "	"	"	"
"	"	40512	Alte sponde	"	"	"
"	Estero	32091	" "	"	"	"
Lecce	Esteri	3116	" "	"	"	"
Officina	Esteri	28084	Bagagliaio	"	"	"
"	F.S.	162176	F chiuso	"	"	"
"	"	173169	" "	"	"	"
"	"	7108969	" "	"	"	"
"	"	102193	E "	"	"	"
"	"	188804	F "	"	"	"
"	F.S.	475073	L alte sponde	"	"	"
"	"	7404320	" "	"	"	"
"	"	443346	" "	"	"	"
"	"	422372	" "	"	"	"
"	F.S.E.	646671	" "	Carico	Buono	"
"	"	4212	" "	"	"	"
"	"	2212	" "	Vuoto	Riparando	"
"	"	3908	E "	"	"	"
"	"	312	GT vettura	"	"	"
"	"	311	" "	"	"	"
"	"	452	" "	"	"	"
"	"	257	" "	"	"	"
"	"	710	MCs "	"	"	"
"	"	704	" "	"	"	"
"	"	909	MU bagagliaio	"	"	"
"	"	1902	Fc chiuso	Carico	Buono	"
"	"	6112	F basse sponde	"	"	"
"	Estero	21468	L alte sponde	Vuoto	Riparando	Officine Collina
"	"		" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

235

"	"	251	" "	"	"	"
"	"	497	" "	"	"	"
"	"	308	" "	"	"	"
"	"	2810	F chiuso	Arrendati	"	"
"	"	2004	" "	"	"	"
"	"	1205	" "	"	"	"
"	F.S.	646671	F basso sponde	Carico	Buono	Lecce
Lecce	Estero	269284	Chiuso	Vuoto	Riparend.	Offic. Rialto
Officina	"	7236	" "	"	"	"
"	"	20588	" "	"	"	"
"	"	2862	Bagagliaio	"	"	"
"	"	77373	" "	"	"	"
"	"	75830	" "	"	"	"
"	"	45355	" "	"	"	"
"	"	40512	Alte sponde	"	"	"
"	Estero	32091	" "	"	"	"
Lecce	Esteri	3116	" "	"	"	"
Officina	Esteri	28084	Bagagliaio	"	"	"
"	F.S.	162176	F chiuso	"	"	"
"	"	173169	" "	"	"	"
"	"	7108969	" "	"	"	"
"	"	102193	R "	"	"	"
"	"	188804	F "	"	"	"
"	"	475073	L alte sponde	"	"	"
"	F.S.	7404326	" "	"	"	"
"	"	443346	" "	"	"	"
"	"	422372	" "	"	"	"
"	"	646671	" "	"	"	"
"	F.S.E.	4212	" "	Carico	Buono	"
"	"	2212	R. "	"	"	"
"	"	3908	F "	Vuoto	Riparando	"
"	"	312	CT vettura	"	"	"
"	"	311	" "	"	"	"
"	"	451	" "	"	"	"
"	"	257	" "	"	"	"
"	"	710	MCs "	"	"	"
"	"	704	" "	"	"	"
"	"	909	FU bagagliaio	"	"	"
"	"	1902	Fo chiuso	Carico	Buono	"
"	"	6112	F basso sponde	"	"	"
"	Estero	91468	L alte sponde	Vuoto	Riparando	Officine Collina
"	F.S.	474669	" "	"	"	"
"	Estero	767280	" "	"	"	"
"	F.S.	479607	" "	"	"	"
"	Estero	43385	Basso sponde	"	"	"
"	"	10483	chiuso "	"	"	"
Lecce	"	12326	Basso sponde	Vuoto	Riparando	"
Officina	F.S.	7400167	L alte sponde	"	"	"
"	"	411248	" "	"	"	"
"	"	417784	" "	"	"	"
"	Estero	38849	" "	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Officio	F.S.	1025948	E chiuso	Vuoto	Riparando	Off. Molfino
"	Metero	38150	" "	"	"	" "
"	"	2321	Alte sponde	"	"	" "
"	F.S.	7405317	L alte sponde	"	"	" "
"	Metero	1515	" "	"	"	" "
"	"	40428	" "	"	"	" Novelli
"	F.S.	1022160	E chiuso	"	"	" "
"	"	196811	F "	"	"	" "
"	"	455448	L alte sponde	"	"	" "
"	F.S.	841236	" "	"	"	" "
"	"	7448894	Chiuso	"	"	" "
"	"	416250	L alte sponde	"	"	" "
"	"	1011251	E chiuso	"	"	" "
"	"	459393	L Alte sponde	"	"	" "
"	"	1029703	E chiuso	"	"	" "
"	"	186286	F "	"	"	" "
"	"	468736	L alte sponde	"	"	" "
"	"	1016421	E chiuso	"	"	" "
"	Metero	1152	Alte sponde	"	"	" "
"	F.S.	117732	Fe chiuso	"	"	" "
"	"	186485	F "	"	"	" "
"	"	419407	L alte sponde	"	"	" "
"	"	746397	Chiuso	"	"	" "
Lecce	F.S.E.	0000	"	Carico	Buono	Lecce
"	"	1896	"	carro verific.	"	"
"	"	1104	"	adibito dormit.	"	"
"	"	4404	Alte sponde	carico	"	"
"	"	4268	"	"	"	"
"	"	1208	D bagagliaio	Vuoto	Riparando	Squadra Lecce
"	"	1301	F chiuso	"	"	"
"	"	6L01	Basse sponde	"	"	"
"	"	853	Dut bagagliaio	"	"	"
"	"	1128	F chiuso	"	"	"
"	"	1939	"	"	"	"
"	"	1815	"	"	"	"
"	"	1818	"	"	"	"
"	"	355	CT vettura	"	"	"
"	F.S.	490972	L alte sponde	"	"	"
"	"	472972	"	"	"	"
"	"	463381	"	"	"	"
"	"	413149	"	"	"	"
"	Entero	92561	Chiuso	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	40428	"	"	"	"	Novoli
"	F.S.	1022160	E chiuso	"	"	"	"
"	"	196811	F "	"	"	"	"
"	"	455448	L alte sponde	"	"	"	"
"	F.S.	881236	" "	"	"	"	"
"	"	7448834	Chiuso	"	"	"	"
"	"	416250	L alte sponde	"	"	"	"
"	"	1011251	E chiuso	"	"	"	"
"	"	459393	L Alte sponde	"	"	"	"
"	"	1029703	E chiuso	"	"	"	"
"	"	186286	F "	"	"	"	"
"	"	408736	L alte sponde	"	"	"	"
"	"	1016421	E chiuso	"	"	"	"
"	Entero	1152	Alte sponde	"	"	"	"
"	F.S.	117732	Fe chiuso	"	"	"	"
"	"	186485	F "	"	"	"	"
"	"	419407	L alte sponde	"	"	"	"
"	"	746357	Chiuso	"	"	"	"
Lecce	F.S.E.	8000	"	Carico	Buono	Lecce	
"	"	1806	"	carro verific.	"	"	
"	"	1104	"	adibito dormit.	"	"	
"	"	4494	Alte sponde	carico	"	"	
"	"	4268	"	"	"	"	
"	"	1208	D bagagliaio	Vuoto	Riparando	Squadra Lecce	
"	"	1301	F chiuso	"	"	"	
"	"	6101	Basse sponde	"	"	"	
"	"	853	Dut bagagliaio	"	"	"	
"	"	1198	F chiuso	"	"	"	
"	"	1939	"	"	"	"	
"	"	1815	"	"	"	"	
"	"	1818	"	"	"	"	
"	"	355	GT vettura	"	"	"	
"	F.S.	490978	L alte sponde	"	"	"	
"	"	472972	"	"	"	"	
"	"	463881	"	"	"	"	
"	"	413149	"	"	"	"	
"	Entero	92561	Chiuso	"	"	"	

255

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 **Agosto** *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Elenco delle vetture e Bagagliai.					
BARI S. SPIRITO	F.S. estero	99733 I2I2I22	Dm Bag	Ricovero voto	Inglesi
POTENZA INF.	F.S.	99404	Bag.Dm	buono	
SPINAZZOLA	"	4488	Cz	"	
	"	4I847	"	"	
	"	8269I	Bag.	"	
	"	82256	"	"	
METAPONTO	"	2065 9	Abz	riparando	
	"	36098	Cz	"	
	"	326I3	"	"	
	"	86295	Di	"	
	"	5243	Um	"	
	"	966I0	Dui	"	
	"	324I6	Cz	"	
CERVARO	"	96739	Dui	buono	
S. VITO LANCIANO	"	4272I	Cz	ospedale	
ORTONA	"	98963	Dm	vuoto	
SQUINZANO	"	I004	Az	riparando	
	"	50666	Abz	"	
	"	544I8	"	"	
	"	5092I	"	"	
	"	50204	"	"	
	"	58629	"	"	
	"	5I092	Bz	"	
	"	29I59	"	"	
	"	24290	"	"	
	"	20228	"	"	
	"	30639	Cz	"	
	"	32748	"	"	
	"	42058	"	"	
	"	4I760	"	"	
	"	36340	"	"	
	"	3I052	"	"	
	"	36555	"	"	
	"	370I8	"	"	
	"	44596	"	"	
	"	4I699	"	"	
	"	44076	"	"	

Declassified E.O. 12356 Sec Section 3.3/NND No. 785021

Elenco delle vetture e Bagagliai.

BARI S. SPIRITO	F.S.	99733	Dm	Ricovero	Inglesi
	estero	I2I2I22	Bag	voto	
POTENZA INF.	F.S.	99404	Bag.Dm	buono	
SPINAZZOLA	"	4488	Cz	"	
	"	4I847	"	"	
	"	8269I	Bag.	"	
	"	82256	"	"	
METAPONTO	"	20659	Abz	riparando	
	"	36098	Cz	"	
	"	326I3	"	"	
	"	86295	Di	"	
	"	5243	Um	"	
	"	966I0	Dui	"	
	"	324I6	Cz	"	
CERVARO	"	96739	Dui	buono	
S. VITO LANCIANO	"	4272I	Cz	ospedale	
ORTONA	"	98963	Dm	vuoto	
SQUINZANO	"	I004	Az	riparando	
	"	50666	Bbz	"	
	"	544I8	"	"	
	"	5092I	"	"	
	"	50204	"	"	
	"	58629	"	"	
	"	5I092	Bz	"	
	"	29I59	"	"	
	"	24290	"	"	
	"	20228	"	"	
	"	30639	Cz	"	
	"	32748	"	"	
	"	42058	"	"	
	"	4I760	"	"	
	"	36340	"	"	
	"	3I052	"	"	
	"	36555	"	"	
	"	370I8	"	"	
	"	44596	"	"	
	"	4I699	"	"	
	"	44076	Bz	"	
	estero	020557	ABCZ	"	
	"	7306	Bz	"	
	"	48782	Cz	"	
	"	9I82	Bz	"	
	"	52329	Cz	"	
FOGGIA	"	[illegible]			
	"	30I74	Cz	riparando	
	"	8826I	Dz	"	
	"	99809	Dm	"	

254

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Sigle del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	F.S.	99546	Dm	buono	
	"	99919	"	"	
	"	86278	Dp	"	
	"	73528	C	riparando	
	"	32517	Cz	"	
	"	84250	D i	"	
	"	20106	Bz	"	
	"	32555	"	"	
	"	30176	Cz	"	
	"	92047	Di	"	
	"	10094	Az	"	
	"	24346	Bz	"	
	"	36164	Cz	"	
	"	36537	"	"	
	"	36483	"	"	
	"	50688	Abz	"	
	"	20064	Bz	"	
	"	32230	Cz	"	
	"	900011	Di	"	
	"	31110	Cz	"	
	"	82207	Di	buono	
	"	87238	"	riparando	
	"	304499	Cz	carico	Comando Inglese
	"	30435	"	"	" "
	"	31126	"	"	
	"	96510	Dmi	"	
	estero	67132	D.R.	"	
	F.S.	99898	Dm	"	
	"	99948	"	"	
BRINDISI SMISTAM.	"	6902	"	vuoto	
BRINDISI	"	99303	D	buono	
	"	42661	Cz	"	
	"	39190	"	"	
	"	32699	"	"	
	"	87426	D	vuoto	
	"	2434	Uiy	"	
	"	1067	Uz	"	
	"	32617	Cz	"	
	"	44209	"	"	
	"	30583	"	"	
	"	30496	"	"	
	"	41462	"	"	
	"	71483	C	"	
	"	87627	D	"	
	"	66241	Cd	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	325I7	Cz	"		
	"	84250	D i	"		
	"	20I06	Bz	"		
	"	32555	"	"		
	"	30I76	Cz	"		
	"	92047	Di	"		
	"	I0094	Az	"		
	"	24346	Bz	"		
	"	36I64	Cz	"		
	"	36537	"	"		
	"	36483	"	"		
	"	50688	Abz	"		
	"	20064	Bz	"		
	"	32230	Cz	"		
	"	9000II	Di	"		
	"	3IIIO	Cz	"		
	"	82207	Di	buono		
	"	87238	"	riparando		
	"	304499	Cz	carico	Comando Inglese	
	"	30435	"	"	"	"
	"	3II26	"	"		
	"	965I0	Dii	"		
	estero	67I32	D.R.	"		
	F.S.	99898	Dm	"		
	"	99948	"	"		
BRINDISI SMISTAM.	"	6902	"	vuoto		
BRINDISI	"	99303	D	buono		
	"	4266I	Cz	"		
	"	39I90	"	"		
	"	32699	"	"		
	"	87426	D	vuoto		
	"	2434	Uiy	"		
	"	I067	Uż	"		
	"	326I7	Cz	"		
	"	44209	"	"		
	"	30583	"	"		
	"	30496	"	"		
	"	4I462	"	"	"	
	"	7I483	C	"		
	"	87627	D	"		
	"	6624I	Cd	"		
	"	32504	Cz	"		
	"	453II	"	"		
	"	4I539	"	"		
	"	30456	"	"		
	"	42484	"	"		
	"	30454	"	"		
	"	87620	D	"		
	"	44223	Cz	"		
	"	4I898	"	"		
	"	2009	"	"		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BRINDISI	F.S.	28009	Dz	vuoto	
	"	4I284v	Cz	"	
	"	52099	Abz	"	
	"	70I35	Cz	"	
TRINITAPOLI	"	90I70	Gi	riparando	
	"	98II4	Dá	"	
	"	99600	"	"	
	"	4I320	Cz	"	
Lecce	"	8605I	bag.	riparando	
	"	99407	"	"	
	"	87407	"	"	
	"	8I809	"	"	
	estere	7861 8	"	"	
	FS	98892	"	"	
	"	96392	"	"	
	"	96747	"	"	
	"	874II	"	"	
	"	98849	"	"	
	"	29I66	vett.	"	
	"	243I0	"	"	
	estero	66695	"	"	
	FS	37I42	"	"	
	"	44732	"	"	
	"	44589	"	"	
	"	30088	"	"	
	"	28852	"	"	
	"	4I650	"	"	
	"	I058	postale	"	
	"	2035	"	"	
	"	2052	"	"	
NASISI	"	99987	Dm	buono	
Termoli	"	8895I	Diz	carico	
TRA479 BARI Cle	"	8354	postale	buono	
	"	87283	bag.	"	
	"	30654	vett.	"	
	"	30633	"	"	
	"	30I00	"	"	
	"	30350	"	"	
	"	32583	"	"	
	"	42090	"	"	

253

Declassified E.O. 12356 Section 3.3/NND No. 785021

BRINDISI	F.S.	28009	Dz	vuoto
	"	4I284v	Cz	"
	"	52099	Abz	"
	"	70I35	Cz	"
TRINITAPOLI	"	90I70	Gi	riparando
	"	98II4	Dm	"
	"	99600	"	"
	"	4I320	Cz	"
Lecce	"	86051	bag.	riparando
	"	99407	"	"
	"	87407	"	"
	"	8I809	"	"
	estere	78618	"	"
	FS	98892	"	"
	"	96392	"	"
	"	96747	"	"
	"	874II	"	"
	"	98849	"	"
	"	29I66	vett.	"
	"	243I0	"	"
	estero	66695	"	"
	FS	37I42	"	"
	"	44732	"	"
	"	44589	"	"
	"	30088	"	"
	"	28852	"	"
	"	4I650	"	"
	"	I058	postale	"
	"	2035	"	"
	"	2052	"	"
	"	99987	Dm	buono
NASISI	"	8895I	Diz	carico
Termoli	"	8354	postale	buono
TR 4795 BARI Cle	"	87283	bag.	"
	"	30654	vett.	"
	"	30633	"	"
	"	30I00	"	"
	"	30350	"	"
	"	32583	"	"
	"	42090	"	"
	"	4I940	"	"
	"	303I3	"	"
	"	30056	"	"
	"	3024I	"	"
	"	3058I	"	"
	"	24420	"	"
TR. 4889	"	8720I	bag	"
	"	4242	vett.	"
	"	42588	"	"
	"	44929	"	"

253

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Cr 4889-Bari C.	FS	24326	vett?	buona	
	"	4I272	"	"	
	"	65083	"	"	
	"	28079	"	"	
Tr. I79I -Bari Cle	"	44002	"	"	
	"	44536	"	"	
	"	4I506	"	"	
	"	30044	"	"	
	"	50I27	"	"	
	"	58482	"	"	
Tr. 4885 Bari C-	"	87633	bag.	"	
	"	44447	vet.	"	
	"	42540	"	"	
	"	73600	"	"	
	"	626I7	"	"	
	"	58470	"	"	
	"	44766	"	"	
	"	4I54I	"	"	
Tr. 3535 Bari C	"	82495	bag	"	
	"	I7037	vett.	"	
	"	3I037	"	"	
	"	32063	"	"	
	"	370I5	"	"	
	"	32308	"	"	
	"	3I088	"	"	
	"	36344	"	"	
TARANTO	"	2033	postale	"	
	"	44443	Voh	"	
	"	92II7	bag.	"	
	"	996I2	"	"	
	"	83202	"	"	
	"	95078	"	"	
	"	96040	"	"	
	estero	73600	vett.	riparando	
	"	I2I9I	"	buona	
	FS	302I5	"	"	
	"	42625	"	"	
	"	32053	"	"	
	"	440II	"	"	
	"	4I447	"	"	
	"	35279	"	"	
	"	427I4	"	"	
	"	92068	bag.	"	
	"	84I3	postale	"	
	"	36274	vett?	"	
	"	32096	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Tr. 1791 Bari C.	"	44536	"	"
	"	41506	"	"
	"	30044	"	"
	"	50127	"	"
	"	58482	"	"
Tr. 4885 Bari C-	"	87633	bag.	"
	"	44447	vet.	"
	"	42540	"	"
	"	73600	"	"
	"	62617	"	"
	"	58470	"	"
	"	44766	"	"
	"	41541	"	"
Tr. 3535 Bari C	"	82495	bag	"
	"	17037	vett.	"
	"	31037	"	"
	"	32063	"	"
	"	37015	"	"
	"	32308	"	"
	"	31088	"	"
	"	36344	"	"
TARANTO	"	2033	postale	"
	"	44443	Veh	"
	"	92117	bag.	"
	"	99612	"	"
	"	83202	"	"
	"	95078	"	"
	"	96040	"	"
	estero	73600	vett.	riparando
	"	12191	"	buona
	FS	30215	"	"
	"	42625	"	"
	"	32053	"	"
	"	44011	"	"
	"	41447	"	"
	"	35279	"	"
	"	42714	"	"
	"	92088	bag.	"
	"	8413	postale	"
	"	36274	vett?	"
	"	32096	"	"
	"	52000	"	"
	"	44600	"	"
	"	60061	"	"
	"	44051	"	"
	"	44814	"	"
	"	44811	"	"
	"	37133	"	"
	"	36140	"	"
	"	36330	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Taranto	FS	44265	vett.	buona	
	"	28073	"	"	
	"	87465	bag.	"	
	"	84285	"	"	
BARI Cle	"	98873	Fa	"	
	"	29476	vett.	riparando	
	"	84280	bag.	"	
	"	6 57	postale	buona	
	"	8401	"	"	
	"	431 I	cellulare	"	
	"	30052	vett.	riparando	
	"	44474	"	"	
	"	I8477	"	"	
	"	28914	"	"	
	"	30492	"	"	
Taranto	FS	II096			
	"	24252	vett.	riparando	
	"	24247	"	"	
	"	44078	"	"	
	"	32014	"	"	
	"	30329	"	"	
	"	44707	"	"	
	"	44544	"	"	
	"	32686	"	"	
	"	42315	"	"	
	"	42127	"	"	
	"	44110	"	riparando	
	"	99860	bag	"	
Treno I790 -	"	67854	"	buono	
	"	42727	vett.	"	
	"	30533	"	"	
	"	II024	"	"	
	"	41860	"	"	
	"	41373	"	"	
	"	30120	"	"	
	"	30646	"	"	
	"	30327	"	"	
	"	44790	"	"	
	"	529008	"	"	

252

Declassified E.O. 12356 Section 3.3/NND No. 785021

Taranto	FS	44265	vett.	"
	"	28073	"	"
	"	87463	bag.	"
	"	84255	"	"
BARI Cle	"	98873	Fu	"
	"	29476	vett.	riparando
	"	84283	bag.	"
	"	6 57	postale	buono
	"	8401	"	"
	"	48[illegible]	cellulare	"
	"	50052	vett.	riparando
	"	44474	"	"
	"	18477	"	"
	"	28914	"	"
	"	30402	"	"
Ferrovi	FFSS	RI090	"	"
	"	24052	vett.	riparando
	"	24247	"	"
	"	44078	"	"
	"	52014	"	"
	"	30329	"	"
	"	44707	"	"
	"	44544	"	"
	"	32686	"	"
	"	42315	"	"
	"	42127	"	riparando
	"	44110	"	"
	"	99360	bag	buono
	"	67854	"	"
Treno 1790 -	"	42727	vett.	"
	"	30533	"	"
	"	II024	"	"
	"	41860	"	"
	"	41373	"	"
	"	30120	"	"
	"	30646	"	"
	"	30027	"	"
	"	44790	"	"
	"	535080	"	"
	"	37021	bag.	"
	"	73717	Ci	"
Treno 3913	estero	46734	"	"
	FS	44181	"	"
	"	41510	Cz	ripiegando
Grassano	"	24989	Bz	riparando
	"	44498	Cz	buono
treno T.V. 56	"	37235	"	"
	"	52303	"	S
	"	50709	ABz	"
	"	44280	Cz	"

252

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
T reno TV 56	FS	365II	Cz	buono	
	"	58475	Abz	"	
	"	41331	"	"	
	"	4470I	Cz	"	
	"	95020	Bnz	"	
	"	2025	Uerg	"	
Treno 3538	"	30138	vet.	"	
	"	30338	"	"	
	"	30544	"	"	
	"	30299	"	"	
	"	36592	"	"	
	"	66540	Bcz	"	
	"	32227	Cz	"	
	"	96337	Dui	"	
Treno TM 7160	"	99407	Dm	bar.	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Cerignola Campag.	estero	84615	I	carico	Candelaro
	FS	503354	I	"	"
	"	7403535	"	"	"
	"	483980	"	"	"
	estero	87290	"	"	"
	FS	476449	"	"	"
	"	493172	"	vuoto	Bari
	"	502825	"	"	"
	"	412768	"	"	"
	"	492369	"	"	"
	"	431662	"	"	"
	"	654702	P	"	"
	estero	3290693	I	carico	
	"	196037	"	vuoto	Bari
	FS	486142	"	"	"
	"	406732	"	"	"
	"	646514	P	"	"
	"	560856	"	"	"
	"	457101	"	"	"
	"	60.[illegible]09	I	vuoto	
	estero	76878	"	carico	
	FS	664510	"	"	
	"	473390	"	vuoto	Bari
	"	441332	"	"	"
	"	459795	"	"	"
	"	416855	"	"	"
	estero	3750	"	carico	Candelaro
	FS	94959	"	"	"
	"	407774	"	"	"
	estero	21705	"	"	"
	"	6714	"	"	"
	FS	7470719	"	"	"
	"	7471708	"	"	"
	"	533097	"	"	"
	"	560371	"	"	"
	"	523997	"	"	"
	estero	7401	"	"	"
	FS	7468452	"	"	"
	"	471755	"	"	"
	"	446156	"	"	"

254

Declassified E.O. 12356 Section 3.3/NND No. 785021

0104

Declassified E.O. 12356 Section 3.3/NND No. 785021

Cardenas Campos, esteva
Castro
Castro
Castro

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Cerignola Campo.	FS	647161	E	Carico	Cmandolaro
	"	647547	"	"	"
	"	654935	"	"	"
	"	77646025	"	"	"
	estero	92864	"	"	"
	"	060	"	"	"
	U.S.A.	928897	E	Vuoto	Ripartenza Ponteangano
	FS	644750	T	Carico	
	"	697025	"	"	
	"	648572	"	"	
	"	661204	"	"	
	"	558049	"	"	
	estero	80372	"	"	
	FS	77696015	"	"	
	"	77696014	"	"	
	"	77645521	"	"	
	"	622163	"	"	
	"	655927	"	"	
	"	652590	"	"	
	"	1008675	E	"	
	"	108340	"	"	
	"	428229	E	"	
	estero	88058	"	"	
	FS	601466	"	"	
	"	776280	"	"	
	"	651166	"	"	
	FSE	1905	"	"	
	FS	77195507	E	"	
	"	653558	T	"	
	"	651934	E	"	
	"	475623	L	"	
	"	694365	"	"	
	"	498174	"	"	
	"	546762	E	"	
	"	655596	"	"	
	"	654956	"	"	
	"	685161	"	"	
	"	623968	"	"	
	estero	79318	"	"	
	FS	[illegible]			
	"	488796	L	Vuoto	
	"	647063	E	Carico	
	"	655728	"	Vuoto	
	"	77643021	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

ester	32864	"	"	"
"	960	"	"	"
U.S.	2288897	F	Ingarrubi	Pontecagnano
PS	644750	P	Carlo	
"	657929	"	"	
"	648972	"	"	
"	661204	"	"	
"	651849	"	"	
estero	2697I	"	"	
PS	7759[illegible]6025	"	"	
"	7762[illegible]6025	"	"	
"	7764552[illegible]	"	"	
"	6[illegible]2163	"	"	
"	655927	"	"	
"	652590	"	"	
"	I[illegible]8675	"	"	
"	I[illegible]3340	"	"	
"	183829	"	"	
estero	98[illegible]58	"	"	
PS	1[illegible]1466	"	"	
"	476180	"	"	
"	163166	"	"	
PS2	2307	"	"	
PS	7719550[illegible]	"	"	
"	653558	"	"	
"	651934	"	"	
"	475623	"	"	
"	084305	"	"	
"	499174	"	"	
"	646762	"	"	
"	655596	"	"	
"	654056	"	"	
"	685161	"	"	
"	623968	"	"	
estero	79338	"	"	
PS	[illegible]			
"	419795	I	vasto	
"	647052	P	carico	
"	655728	"	vasto	
"	77643021	"	"	
"	652019	"	carico	
"	77493043	"	"	
"	77493043	"	"	
"	640853	"	"	
"	I75933	P	"	
"	I56177	"	"	
"	747[illegible]362	"	"	
"	404921	"	"	
"	419765	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
CANOSA DI PUGLIA	F.S.	409730	Lc	carico	
	"	81030	Om	"	
	"	III4931	Fc	"	
	"	654116	P	"	
	"	646079	"	"	
	"	408395	Lc	"	
	"	448317	"	"	
	"	116783	P	"	
	"	044771	L	"	
	"	451700	"	"	
	"	455802	"	"	
	"	1855	"	"	
	"	169246	P	"	
	"	7170047	"	"	
	"	645952	P	"	
	"	82270	Rr	"	
	"	194100	Rs	"	
	"	657184	P	"	
	"	657588	"	"	
	"	646972	"	"	
	"	645592	"	"	
	"	96142	Rs	"	
	"	317	chiuso	"	
	"	268645	"	"	
	"	7107603	F	"	
	"	1028864	Sc	"	
	"	201649	"	"	
	"	104415	"	"	
RESTINCO	F.	1009705	F	carico	
	estero	3627	"	"	
	F.S.	101358	"	"	
	"	7170198	"	"	
	estero	124655	"	vuoto	
	"	44500	"	"	
	F.S.	104223	P	"	
	"	182243	"	carico	
	"	102949	M	"	
	estero	20242	U.S.A.	"	

250

Declassified E.O. 12356 Section 3.3/NND No. 785021

CANOSA DI PUGLIA	F.S.	409790	Lc	carico	
	"	81090	Om	"	
	"	III4[illegible]5I	Fo	"	
	"	654116	F	"	
	"	646579	"	"	
	"	406[illegible]93	Lo	"	
	"	448317	"	"	
	"	116733	F	"	
	"	043771	L	"	
	"	451710	"	"	
	"	455302	"	"	
	"	1055	"	"	
	"	169426	P	"	
	"	7I70047	"	"	
	"	645952	F	"	
	"	81270	Rx	"	
	"	I94100	IE	"	
	"	657156	P	"	
	"	657[illegible]	"	"	
	"	646972	"	"	
	"	645592	"	"	
	"	96141	"	"	
	"	317	Rs	"	
	"	25,[illegible]65	chiuso	"	
	"	7I07603	"	"	
	"	I[illegible]804	F	"	
	"	28I[illegible]96	Ec	"	
	"	I8[illegible]19	"	"	
	"	I06[illegible]5	"	"	
RESTINCO	F. S.	36[illegible]	F	carico	
	estero	I01350	"	"	
	F.S.	7I7[illegible]34	"	"	
	"	I[illegible]633	"	vuoto	
	estero	44590	"	"	
	"	I04223	"	"	
	F.S.	I02243	F	carico	
	"	I02[illegible]69	"	"	
	"	20242	"	"	
	estero	30[illegible]172	U.S.A.	"	
	F.S.	20727	E	"	
	estero	48748	G	"	
	"	I5835	G	"	
	"	II[illegible]305	F	"	
	F.S.	II9905	"	"	
	"	I02[illegible]69	"	"	
	"	I004194	"	vuoto	
	"	I020738	E	"	
	"	I025[illegible]0	L	"	
	"	3915[illegible]	Eg	"	
	"	771950II	F	"	

250

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
[illegible] F.S.		1024745	[illegible]	carico	
	estero	128740	"	"	
	"	II743	"	"	
	F.S.	261559	"	"	
	estero	26251	"	"	
	F.S.	1029187	"	"	
	"	200617	"	"	
	"	II3[illegible]8	"	"	
	"	13[illegible]8	"	"	
	"	251[illegible]	"	"	
	"	201[illegible]3	"	"	
	"	1000[illegible]	"	"	
	"	47[illegible]	"	vuoto	
[illegible] BARI S.SPIRITO	"	1007[illegible]	"	carico	
	estero	51307	"	vuoto	
	F.S.	1014[illegible]	"	carico	
	"	1[illegible]557	"	"	
	"	1[illegible]	"	"	
	"	1[illegible]	"	"	
	"	1[illegible]	"	"	
	"	1016[illegible]36	"	vuoto	
	estero	23141	"	"	
	F.S.	1005[illegible]	"	"	
	"	28[illegible]	"	"	
	"	2[illegible]5	"	"	
	"	1133[illegible]5	"	carico	
	"	[illegible]	"	vuoto	
	"	25II[illegible]	"	"	
	"	1[illegible]	"	"	
	"	710[illegible]	"	"	
	"	1[illegible]	"	"	
	"	1[illegible]	"	"	
	"	10275	"	"	
	"	7[illegible]	"	"	
	estero	12567	"	carico	
	F.S.	1[illegible]174	"	"	
	estero	2[illegible]	"	"	
	F.S.	1[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

	estero	26231	P	vuoto
	P.S.	I020 87	R	"
	"	20617	C	"
	"	II3 78	P	"
	"	I35 73	"	"
	"	2514	C	"
	"	201 13	E	"
	"	100	"	"
	"	41	T	vuoto
R X N E X X X O				
BARI S.SPIRITO	"	1007	F	carico
	estero	2137	"	vuoto
	P.S.	1851	P	carico
	"	I2IB	"	"
	"	I	"	"
	"	1033	"	"
	"	I 07	"	"
	"	IOI6	"	vuoto
	estero	2514	"	"
	P.S.	I	"	"
	"	20	"	"
	"	205	"	carico
	"	II3	"	vuoto
	"	20	"	"
	"	26II	"	"
	"	I02	"	"
	"	710	"	"
	"	I0 67	"	"
	"	I02	"	"
	"	I0	"	"
	estero	I25	"	carico
	P.S.	I6	"	"
	estero	206	"	"
	F.S.	I56	"	"
	"	J0I	"	"
	"	20	"	"
	"	7	"	"
	"	I	"	"
	"	I2I	"	"
	P.S.	40	"	vuoto
	"	44	"	"
	"	943	"	"
	"	51	"	"
	"	18	"	"
	"	53	"	"
	estero	27	"	"
	F.S.	40	"	"
	"	40	"	"
	"	405	"	"

ALTAMURA

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 20 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Gorlgnola Sanp.	estero	[illegible]	[illegible]	[illegible]	
	"	[illegible]	"	"	
	PS	[illegible]	F	"	
	estero	5737	L	Turco	Bari
	"	[illegible]	"	"	"
	PS	[illegible]	"	"	"
	"	[illegible]	"	Carico	
	estero	[illegible]	"	"	
	PS	[illegible]	F	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	estero	[illegible]	"	"	
	PS	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	estero	[illegible]	"	"	
	PS	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"

Gorizzola Comp.	Estero	[illegible]	[illegible]	[illegible]	
	"	[illegible]	"	"	
	PS	[illegible]	Pa	Tonnage	Dual
	Estero	57[illegible]	"	"	"
	"	[illegible]	"	"	"
	PS	46,[illegible]	"	"	
	"	47,[illegible]	"	Commercial	
	Estero	[illegible]	"	"	
	PS	66[illegible]	"	"	
	"	62,[illegible]	"	"	
	"	62,[illegible]	"	"	
	"	697576	"	"	
	"	66[illegible]	"	"	
	"	5,[illegible]	"	"	
	"	646[illegible]	"	"	
	"	[illegible]	"	"	
	Estero	[illegible]	"	"	
	"	[illegible]	"	"	
	"	61705	"	"	
	PS	[illegible]	"	"	
	"	65,[illegible]	"	"	
	"	65,[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	Estero	646[illegible]	"	"	
	PS	[illegible]	L	"	Bari
	"	[illegible]	Ro	"	"
	PSW	[illegible]	Lo	"	Lugliano
	PSE	[illegible]	"	"	"
	"	[illegible]	L	"	Bari
	PS	[illegible]	"	"	"
	"	[illegible]	"	"	"
	"	[illegible]	"	"	"
	"

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Treno 3930	[illegible]	[illegible]	[illegible]	[illegible]	Bari
	"	[illegible]	"	"	"
	"	[illegible]	"	"	"
	"	[illegible]	"	"	"
Treno [illegible] 7160	[illegible]	[illegible]	[illegible]	vuoto	Monopoli
	"	[illegible]	"	"	
	ecboro	[illegible]	[illegible]	vuoto	Brindisi
	[illegible]	[illegible]	[illegible]	[illegible]eco	Oria
	"	[illegible]	[illegible]	vuoto	Brindisi
	"	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	"	7169906	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	ecboro	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	[illegible]	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	"	[illegible]	[illegible]	"	"
	"

0114

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
treno 3913	F.S.	32653	Do	carico	G I O I A
	ester.	13617	Gl	"	"
	F.S.	14731	GZ	"	"
	"	44781	"	"	"
	"	I66827	F	"	"
	"	204002	G	"	"
	"	5670167	Ms	"	ALTAMURA
	"	555863	M	"	"
	"	201694	G	vuoto	FASANO
treno I890	"	TICI19	F	viaggiatori	"
	"	T2TII91	E	"	"
	"	140673	Fic	"	"
	"	141663	"	"	"
	"	7[illegible]		"	"
	"	77106507	E Bo	"	"
	"	I014030	F	"	"
	"	198788	"	"	"
	"	185044	"	"	"
	"	182476	"	"	"
	"	I008187	"	"	"
	"	I024026	"	"	"
	servizio	2637	"	"	"
	F.S.	I41035	"	"	"
	"	3P4443	"	"	"
	"	I00695	"	"	"
	"	196686	"	"	"
	"	3[illegible]599	"	"	"
	"	617764	"	"	"
	"	[illegible]	"	"	"
	"	418205	"	scorta	LUCERA
	"	451964	"	carico	"
	"	472834	"	"	"
	"	471300	"	vuoto	"
	"	417296	"	"	"
	"	493552	"	"	"
	"	428845	"	"	"
	"	7493545	"	"	"
	"	419422	"	"	"
	"	[illegible]	"	"	"
treno T.M.3959					
CANDELARO					

248

Declassified E.O. 12356 Section 3.3/NND No. 785021

treno 3913	F.S.	20553	Dc	carico	G I O I A
	estero	17617	Gi	"	"
	F.S.	14731	G2	"	"
	"	14171	"	"	"
	"	256027	F	"	"
	"	204092	G	"	"
	"	6771167	Ma	"	"
	"	550055	M	"	"
	"	201564	G	vuoto	ALTAMURA
	"	7777299	F	viaggiatori	FASANO
	"	2497II91	S	"	"
	"	140673	Fio	"	"
	"	511663	"	"	"
	"	9[illegible]20		"	"
	"	7719[illegible]07	F	"	"
	"	1018[illegible]30	Bo	"	"
	"	175798	F	"	"
	"	186744	"	"	"
	"	1024T6	"	"	"
	"	1[illegible]02[illegible]87	"	"	"
	"	1[illegible]24026	"	"	"
	"	[illegible]37	G	"	"
	estero	5[illegible]1035	Pio	"	"
	F.S.	1[illegible]5463	F	"	"
	"	1[illegible]0995	G	"	"
	"	1[illegible]28[illegible]5	"	"	"
	"	1[illegible]5[illegible]99	"	scorta	LUCERA
	"	642364	"	carico	"
	"	[illegible]0780	"	"	"
	FS	498205	L	vuoto	"
	"	461964	"	"	"
	"	472834	"	"	"
	"	471320	"	"	"
	"	427295	"	"	"
	"	495552	"	"	"
	"	438345	"	"	"
	"	7403545	"	"	"
	"	419422	"	"	"
	"	46[illegible]6 I00	"	"	"
	"	410678	"	"	"
	"	4[illegible]462	"	"	"
	estero	948[illegible]	I	carico	Taranto
	"	I9040	"	vuoto	Foggia
	"	I[illegible]874	"	"	"
	"	67734	"	"	Taranto
	"	I5265	"	carico	Foggia
	FS	455261	E	vuoto	"
	"	I020202	"	"	"
	"	I028I37	"	"	"
	"	I004306	"	"	"
treno I890					
treno T.M.3959					

CANDELARO

248

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
XEXXEV					
C A N D E L A R O	FS	I028376	E	vuoto	Foggia
	"	I007196	"	"	"
	"	I58340	Fe	"	"
	"	TI3393	"	"	"
	"	I025912	E	"	"
	"	II0338	Fc	"	"
	"	II20781	"	"	"
	"	T2583I	"	"	"
	"	I80CTO	"	"	"
	estero	52093	E	"	"
	"	409I0	F	"	"
	"	I4027	"	"	"
	"	598I	"	"	"
	"	II7 50	F	"	"
	FSE	I9?I	"	"	"
T.8I40	estero	2I608	"	"	Potenza
	FS	I0I0404	"	carico	Napoli.
	"	584404	MV	"	Potenza
	"	524074	"	"	Avellino
	"	5I4442	"	"	Frattamaggiore
	"	I00I96	F	"	Nola
	"	I9I2I3	"	"	Napoli
	"	I22I90	"	"	Roma
	"	205239	"	"	"
	"	I0I2813	"	"	"
	"	I005916	"	"	"
	"	56?I84	MV	"	Portici
	FSE	II103	"	"	Portici
	Fs	9I4405	"	"	Napoli
	"	5I4I40	"	"	"
	"	I0028?5	E	"	Pagani
	"	I0CI823	"	"	Angri
	FSE	504I9	F	"	Pagani
	"	I22IA	"	"	Cava dei; Tirreni
	FS	I56200	"	"	Napoli
	estero	94595	"	"	"
	XXXXXX	415?8?			
	FS	508008	MV	"	Angri
	"	508357	"	"	"
	"	5I444I	"	"	"
	"	I82440	F	"	Potenza
T.M. 8I35	estero	I0736	E	"	Nocagne
	FS	298879	G	"	Gallipoli
	"	I75359	F	"	Nocagne
	estero	41936	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

		"	I02593?	E	"	"
		"	II6I3?	To	"	"
		"	II2038I	"	"	"
		"	I256?I	"	"	"
		"	I88?I0	"	"	"
		estero	52098	"	"	"
		"	4091O	"	"	"
		"	I4027	"	"	"
		"	598I	"	"	"
		"	II7 50	P	"	"
		FSE	I9?I	"	"	"
T.8I40		estero	2I608	"	"	Potenza
		FS	I0I9494	"	carico	Napoli .
		"	584404	MV	"	Potenza
		"	524074	"	"	Avellino
		"	5I4482	"	"	Frattamaggiore
		"	I03I96	P	"	Nola
		"	I9I3I3	"	"	Napoli
		"	I23I90	"	"	Roma
		"	285239	"	"	"
		"	I0I28I8	"	"	"
		"	I0059I6	"	"	"
		"	568I84	MV	"	Portici
		FSE	II103	"	"	Portici
		FS	5I4483	"	"	Napoli
		"	5I4I40	"	"	"
		"	I003845	"	"	Pagani
		"	I00I883	"	"	Angri
		FSE	5O4I9	"	"	Pagani
		"	I22I?	"	"	Cava dei; Tirreni
		FS	I96280	"	"	Napoli
		estero	94535	"	"	"
		XXXXXX	XXXXXX			
		FS	508008	MV	"	Angri
		"	508357	"	"	"
		"	5I444I	"	"	"
		"	I82440	F	"	Potenza
T.M. 8I35		estero	I0735	L	"	Nocagne
		FS	2988?9	G	"	Gallipoli
		"	I75959	F	"	Nocagne
		estero	42936	"	"	"
		FS	I024394	"	"	Bari
		estero	77495570	"	"	Lecce
		FS	5I5449	H	"	Manduria
		"	I88246	F	vuoto	Brindisi
		"	I4I049	"	"	"
		"	490637	R	"	"
		"	447516	"	"	"
		"	49II52	"	"	"
		"	23852	F	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STAT
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
T r e n o 8I35	FS	410596	L	vuoto	Brindisi
	"	414013	"	"	"
	estero	63402	"	"	"
	"	63402	"	"	"
	"	99922	"	"	"
	"	8596	"	"	"
	FS	419529	"	"	"
	"	414766	"	"	"
	"	433171	"	"	"
	estero	3890	"	"	"
	FS	486634	"	"	"
	estero	I7036	"	"	"
	"	35411	"	"	"
	FS	434593	"	"	"
	"	7403506	E	"	"
	"	406169	"	"	"
	"	400092	"	"	"
Treno TM3942	estero	695264	Poz	carico	Modugno
	USA	20798	chiuso	"	"
	"	20II7	"	"	Bari
	FS	222642	G	"	"
	"	652467	P	"	"
	"	647112	"	"	"
	"	486849	L	"	"
	"	I334123	F	"	Bitetto
	"	402748	L	"	Bari
	estero	3II05	"	"	"
	FS	4III53	"	"	Molfetta
	"	II29350	E	"	Giovinazzo
	"	I002I04	"	"	"
	"	7749603	"	"	"
Treno 3942	"	945755	Mp	vuoto	Monopoli
	"	631391	"	"	
	estero	9II822	"	"	
	"	0500841	"	"	
	FS	I0II863	E	carico	Bari
	"	66632	Mp	"	S.Severo
	"	511367	"	"	Foggia

Declassified E.O. 12356 Sec. 3.3/NND No. 785021

T r e n o 8I35	FS	410596	L	vuoto	Brindisi
	"	414013	"	"	"
	e d'ter	63402	"	"	"
	"	63402	"	"	"
	"	99002	"	"	"
	"	8296	"	"	"
	FS	419529	"	"	"
	"	414766	"	"	"
	"	433I7I	"	"	"
	estero	2890	"	"	"
	FS	486634	"	"	"
	estero	27936	"	"	"
	"	35411	"	"	"
	FS	434593	"	"	"
	"	7403506	E	"	"
	"	406I69	"	"	"
	"	400092	"	"	"
Treno TM3942	estero	695264	Poz	carico	Modugno
	USA	20798	chiuso	"	"
	"	20II7	"	"	Bari
	FS	222642	G	"	"
	"	652467	P	"	"
	"	647112	"	"	"
	"	486849	L	"	"
	"	I334123	F	"	Bitetto
	"	482748	L	"	Bari
	estero	2I05	"	"	"
	FS	4III53	"	"	Molfetta
	"	II29350	E	"	Giovinazzo
	"	I002I04	"	"	"
	"	7749603	"	"	"
Treno 3942	"	945755	Mp	vuoto	Monopoli
	"	631391	"	"	
	estero	9II822	"	"	
	"	0500841	"	"	
	FS	I0II860	E	carico	Bari
	"	68632	Mp	"	S.Severo
	"	511367	"	"	Foggia
	estero	2096	F	"	Ortona
	FS	II67I9	"	"	"
	"	458641	"	"	"
	estero	9806	"	"	Montenegro

257

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
ORTONA	F.S.	487476	L	carico	
	"	4III35	"	"	
	"	77495547	"	"	
	"	474519	"	"	
	"	I98390	"	"	
	"	II7383	Fc	"	
	"	480205	L	"	
	"	446I8I	"	"	
	"	I0I4665	Ec	"	
	"	525603	Mv	"	
	"	5082II	"	"	
	"	524476	"	"	
	"	309I55	Hg	vuoto	
	estero	I9857	L	"	
	F.S.	458867	"	"	
	estero	I0296	"	"	
	F.S.	476782	"	"	
	"	46062I	"	"	
	"	252522	G	"	
	estero	94409	L	"	
	F.S.	I004786	E	carico	
	"	042008	L	vuoto	
	"	I23553	Fc	"	
	"	053431	"	"	
	"	I024345	E	"	
	"	7470217	L	carico	
	"	II26I822	Fc	"	
	"	I025387	E	"	
	"	440509	"	"	
	"	479605	E	"	
	"	7I0I795	E	"	
	"	483960	L	"	
	"	470807	"	"	
	"	646III	P	"	
	"	655I54	"	"	
	"	649567	"	"	
	"	4132II	"	"	
	"	I836 4	F	"	
	estero	8I394	"	"	

256

Declassified E.O. 12356 Section 3.3/NND No. 785021

ORTONA	F.S.	487476	L	carico
	"	4III35	"	"
	"	77495547	"	"
	"	474519	"	"
	"	I98390	"	"
	"	II7383	Fc	"
	"	480205	L	"
	"	446I8I	"	"
	"	IOI4665	Ec	"
	"	525603	Gv	"
	"	5082II	"	"
	"	524476	"	"
	"	309I55	Hg	vuoto
	estero	I9857	L	"
	F.S.	458867	"	"
	estero	I0296	"	"
	F.S.	476782	"	"
	"	46062I	"	"
	"	252522	G	"
	estero	94409	L	"
	F.S.	I004786	E	carico
	"	042008	L	vuoto
	"	I2[illegible]553	Fc	"
	"	053431	"	"
	"	I024345	E	"
	"	7470217	L	carico
	"	II26I822	Fc	"
	"	I025387	E	"
	"	440509	"	"
	"	479605	E	"
	"	7101795	L	"
	"	483960	"	"
	"	470807	P	"
	"	646III	"	"
	"	655154	F	"
	"	649567	"	"
	"	4132II	E	"
	"	I836 4	"	"
	estero	81394	"	"
	F.S.	I011736	"	"
	"	I005793	"	"
	"	I004682	"	"
	"	I22I99	Ec	"
	"	I09026I	G	"
	"	250443	Ec	"
	"	I0I44I0	Gc	"
	"	202881	Fc	"
	"	II35938,	"	"
	"	II0613		

2 cf

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
ORTONA	F.S.	[illegible]CI4041	Ec	carico	
	"	II35722	Fc	"	
	estero	46II,	F	"	
	F.S.	II4940	Fc	"	
	"	II33344	"	"	
	estero	33732	F	"	
	F.S.	II3I940	Fc	"	
	"	I026339	E	"	
	"	309446	Hs	"	
	"	II273I4	Fc	"	
	"	I000406	Ec	"	
	"	I60974	F	"	
	"	I2I769	Fc	"	
	U.S.A.	222716	F	"	
	estero	252I	"	"	
	F.S.	I024798	E	"	
	"	442946	L	"	
	estero	I19189	E	"	
	"	523009	Ec	"	
	F.S.	645947	F	vuoto	
	"	644513	"	"	
	"	653984	"	"	
	"	661536	"	"	
	"	615760	"	"	
	"	I00I619	E	"	
	estero	70II7	F	"	
	F.S.	426603	L	"	
	"	412749	"	"	
	"	I025747	E	carico	
	"	I926	Fc	"	
	"	II3I598	"	"	
	"	I000065	Ec	"	
	"	I002693	"	"	
	estero	2007	F	"	
	U.S.A.	222625	"	"	
	F.S.	I44645	"	"	
	estero	2828	"	"	
	F.S.	II35II8	"	"	
	"	I00I856	Ec	" "	
	"	422587	L	"	
	"	652591	P	"	
	"	495769	L	"	
	"	443994	"	"	
	"	7471254	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0124

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
ORTONA	F.S.	261315	Gc	carico	
	estero	61447	Fi	"	
	F.S.	I022419	Ec	"	
S. VITO LANCIANO	"	814001	Vocf	carro Attrezzi	
	"	568349	Nv	carico	
	"	42721			
	"	550267	Nm	carico	
ISTONIO	estero	52902	G	vuoto	
	"	25546	Gh	"	
	"	I0575	"	"	
	"	I5225	G	"	
	"	I218	Gh	"	
	"	279165	KKvw	"	
	F.S.	I0042I7	Ec	"	
	"	I009179	E	"	
	"	I85294	F	" "	
	"	I000602	Ec	" "	
	"	201695	Gc	" "	
	"	I024504	E	" "	
	"	I88655	F	" "	
	"	I87207			
FOSSACESIA	estero	3448I	O	carico	
	F.S.	108799	L	"	
	"	464217	"	"	
BITONTO	"	419273	"	"	
	"	445501	"	"	
	"	I027314	E	carico	
	F.S.E.	I125	"	"	
	estero	I1082	"	"	
	"	41536	"	"	
	F.S.	001167	"	"	
	"	261122	"	"	
	"	III4522	F	"	
	"	77193039	"	"	
	"	I0II42	"	"	
	"	III7764	"	"	
RACCORDO S.SPIRITO	estero	II556	G	"	
	"	96502	coperto	"	
	F.S.	965022X			
	"	I80847	Fc	vuoto	

255

Declassified E.O. 12356 Section 3.3/NND No. 785021

[illegible]	estero	61447	Fl		"
	F.S.	I022419	Ec		
S. VITO LANCIANO	"	814001	Vocf	carro	Attrezzi
	"	568549	Mv		carico
	"	[illegible]			
	"	550267	Mm		carico
	estero	52902	G		vuoto
ISTONIO	"	25546	Gh		"
	"	I0575	"		"
	"	I5225	G		"
	"	I2I8	Gh		"
	"	279165	KZvw		"
	F.S.	I0042I7	Ec		"
	"	I009I79	E		"
	"	I85294	F		" "
	"	I000602	Ec		"
	"	201695	Gc		"
	"	I024504	E		"
	"	I08655	F		"
	"	I872[illegible]7			
FOSSACESIA	estero	34481	Om		carico
	F.S.	408799	L		"
	"	464217	" "		"
	"	419273	"		"
BITONTO	"	445501	"		"
	"	I027314	E		carico
	F.S.E.	I125	"		"
	estero	I1082	G		"
	"	41536	"		"
	F.S.	003I67	"		"
	"	26II22	"		"
	"	III4522	F		"
	"	77193039	"		"
	"	I0II42	"		"
	"	III7764	"		"
	estero	I1556	G		"
RACCORDO S.SPIRITO	"	96502	coperto		
	F.S.	965[illegible]			
	"	I80847	Fc		vuoto
	"	I00003	"		"
	"	260792	Gc		"
	"	I01488	F		"
	estero	I945	coperto		"
	F.S.	I59415	fc		"
	"	I009731	E		"
	estero	20587	U.S.A.		"
	F.S.	77496050	L		carico
GIOIA DEL COLLE	"	419362	"		"
	"	436754	"		"

25 cm

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
GIOIA DEL COLLE	F.S.	478525	L	carico	
	"	488297	"	"	
	"	486390	"	"	
	"	001455	"	"	
	"	409492	"	"	
	"	402472	"	"	
	"	482122			
	"	480581	"	"	
	"	460167	"	"	
	estero	6413	"	vuoto	
	"	35540	"	"	
	F.S.	77299060	"	"	
	"	921108	M	in deposito	
	"	7900039	Ma	"	
	"	950623	"	"	
	"	579651	Mo	"	
	"	93 063		"	
	"	802202	Vci	"	
CERIGNOLA	"	470531,	L	"	
	"	251398	G	"	
	"	452816	L	buono	
	"	I30605	Fc	"	
	estero	2537I	E	"	
	F.S.	499599	L	"	
	"	4410748	"	"	
	"	4I4I40	"	"	
	"	445768	"	"	
	"	454605	"	"	
	estero	I98948	"	"	
	"	I6840	"	"	
	F.S.	474575	"	"	
	"	85306	"	"	
	"	478873	Lc	"	
	"	7470305	L	"	
	estero	I8690	"	"	
	"	24657	Li	"	
CANDELARO	F.S.	434150	L	carico	
	"	40I84I	"	"	
	"	474306	"	"	
	"	4I660I	"	"	
	"	I022066	"	"	
	"	406267	"	"	
	"	496707	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	004455	"	"
	"	409492	"	"
	"	402472	"	"
	"	402122		
	"	480581	"	"
	"	460167	"	"
	estero	6413	"	vuoto
	"	38540	"	"
	F.S.	7749060	"	"
	"	981108	M	in deposito
	"	7900039	Ma	"
	"	950683	"	"
	"	579651	Mo	"
	"	938063		"
	"	802282	Voi	"
CERIGNOLA	"	470581,	L	"
	"	251398	G	"
	"	452876	L	buono
	"	1306059	Fo	"
	estero	25371	E	"
	F.S.	499509	L	"
	"	4616748	"	"
	"	414140	"	"
	"	445768	"	"
	"	454605	"	"
	estero	198949	"	"
	"	16848	"	"
	F.S.	474575	"	"
	"	85306	"	"
	"	478873	Lc	"
	"	7470383	L	"
	estero	18699	"	"
	"	24697	Li	"
CANDELARO	F.S.	434150	S	carico
	"	401841	"	"
	"	474306	"	"
	"	416661	"	"
	"	1022066	"	"
	"	406267	"	"
	"	496707	"	"
	"	417126	"	"
	"	466134	"	"
	"	479104	"	"
	"	7403902	"	"
	"	400078	"	"
	"	4873 8.	"	"
	"	480526	"	vuoto
	"	461124	"	"
	"	446707	"	"
	"	481056	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARLETTA	FS	I0IC106	E	carico	
	"	I02I320	"	"	
	"	I007793	"	"	
	"	I50824	F	"	
	estero	20875	"	"	
	"	I2858	"	"	
	"FS	II9058	"	"	
	"	II2959I	"	"	
	F	I83329	"	"	
	"	7I07I80	"	"	
	estero	3I5025	Hg	"	
	estero	I5099	"	vuoto	
	FS	48390I	L	"	
	"	7405I68	"	"	
	"	478687	"	"	
	"	7I07603	"	carico	
	"	263645	G	"	
	estero	3I7	"	"	
	"	8239I	"	"	
	FS	047I37	"	"	
	estero	86IK44	P	"	
	FS	645I42	P	"	
	"	646772	"	"	
	"	657578	"	"	
	"	657I84	"	"	
	estero	94I00	"	"	
	"	8I270	"	"	
	F.FS.	645952	"	"	
	"	462880	L	"	
	estero	3I420	"	"	
	FS	668274	P	"	
	"	652871	"	"	
	"	655I88	"	"	
	"	6573I2	"	"	
	"	77643022	"	"	
	"	660383	"	"	
	"	495969	E	"	
	estero	34655	L	"	

244

Declassified E.O. 12356 Section 3.3/NND No. 785021

B A R L E T T A	FS	I0I0I06	E	carico
	"	I02I320	"	"
	"	I007793	"	"
	"	I50824	F	"
	estero	20875	"	"
	"	I2858	"	"
	"FS	II9058	"	"
	"	II2959I	"	"
	F	I83329	"	"
	"	7I07I80	"	"
	[illegible]	3I5025	Hg	"
	estero	I3099	"	vuoto
	FS	48390I	L	"
	"	7405I68	"	"
	"	478687	"	"
	"	7I07603	"	carico
	"	265645	G	"
	estero	3I7	"	"
	"	82391	"	"
	FS	047I37	"	"
	estero	86IX44	F	"
	FS	645I42	P	"
	"	646772	"	"
	"	657578	"	"
	"	657I84	"	"
	estero	94I00	"	"
	"	8I270	"	"
	F.SS.	645952	"	"
	"	462880	L	"
	estero	3I420	"	"
	FS	668274	P	"
	"	65287I	"	"
	"	655I88	"	"
	"	6573I2	"	"
	"	77643022	"	"
	"	660383	"	"
	"	495969	E	"
	estero	34655	L	"
	FS	472600	L	"
	"	I02777I	E	"
	"	476638	L	"
	"	48I252	"	"
	"	479826	"	"
	"	4008I2	"	"
	"	466585	"	"
	"	446953	"	"
	"	I0I00300	"	"
	"	465436	"	"
	"	4I8869	L	"
	"	473945	"	"

244

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARLETTA	FS	473945	L	vuoto	
	"	418552	"	"	
	"	448157	"	"	
	"	404320	"	"	
	"	463055	"	"	
	estero	43970	"	ripärando	
	"	2442	"	"	
	FS	470899	"	"	
	"	435368	"	"	
	"	1401	"	"	
	"	648411	P	"	
	estero	51873	L	"	
	FS	601477	P	carico rip.	
	"	541011	M	vuoto rip.	
	"	509026	"	"	
	"	508091	"	carico	
	"	572006	"	"	
	"	11027	"	"	
	"	572006	"	vuoto	
	"	11027	"	"	
	"	9581244	"	"	
	"	9581375	"	"	
	"	510653	"	"	
	"	510656	"	"	
	"	503510	"	"	
	"	503012	"	"	
	"	510557	"	"	
	"	379652	"	"	
	"	531411	"	"	
	"	531419	"	"	
	"	531406	"	"	
	"	567012	"	"	
	"	510654	"	"	
	"	192104	"	"	Uso Inglese
	estero	38903	"	"	" "
	FS	1134398	F	"	" "
	"	1007168	E	"	" "
	estero	87252	Dip	"	" "
	"	96739	Dui		
	"	9670473	Mtey	acqua	
	FS	100147	F	vuoto	
	"	1135253	Fc	"	
	"	261528	Gc	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	403055	"	"	ripärando	
estero	43970	"	"	"	
"	2442	"	"	"	
FS	476899	"	"	"	
"	485368	"	"	"	
"	I40I	"	"	"	
"	6484II	P	L	"	
estero	5I873	P		carico rip.	
FS	66I477	P	M	vuoto rip.	
"	54I0II	"	"	"	
"	509026	"	"	carico	
"	50809I	"	"	"	
"	572006	"	"	"	
"	II027	"	"	vuoto	
"	572006	"	"	"	
"	II027	"	"	"	
"	958I244	"	"	"	
"	958I375	"	"	"	
"	5I0653	"	"	"	
"	5I0656	"	"	"	
"	503510	"	"	"	
"	503012	"	"	"	
"	5I0657	"	"	"	
"	379632	"	"	"	
"	53I4II	"	"	"	
"	53I4I9	"	"	"	
"	53I406	"	"	"	
"	557012	"	"	"	
"	5I0654	"	"	"	
"	I92I04	"	"	"	Uso Inglese
estero	38903	"	"	"	"
FS	II34398	"	"	"	"
"	I0C7I68	"	"	"	"
estero	87252	Dip	"	"	"
"	96739	Dui	"	"	"
"	9670473	Mtoy	"	acqua	
FS	I00I47	F	"	vuoto	
"	II35253	Fc	"	"	
"	26I528	Gc	"	"	
"	II22585	F	"	"	
"	7470580	L	"	carico	
"	6I4494	"	"	"	
"	480836	"	"	"	
"	416650	"	"	"	
"	406558	"	"	"	
"	446461	"	"	"	
Estero	I4I5628	Gu	"	"	
SNCF	I37954	K	"	"	
FS	66I477	P	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Cerbaro	Estero	I47933	Kkw	carico	
	FS	I022255	Fc	vuoto	
	estero	77450	G	carico	
	"	34911	"	"	
	U.S.A.	222257	"	"	
	"	51216	"	"	
	FS	449131	L	"	
	estero	7900	ssk	"	
	F.S.E.	II2	K	carico	
	estero	7609	SS	"	
	F.S.	401256	L	"	
	"	466626	"	"	
	"	7A05190	"	"	
	"	7A70741	"	"	
	"	261313	Gh	"	
	"	307758	Bgc	"	
	"	481649	L	"	
	"	303242	Hgc	"	
	"	305823	"	"	
	"	391360	Hgbv	"	
	"	300513	Hg	"	
	"	315865	Hgc	"	
	"	311625	"	"	
	"	7739605C	"	"	
	"	3 I559	"	"	
	"	300437	"	"	
	"	306827	"	"	
	"	390412	"	"	
	"	304641	Hgc	"	
	"	305065	"	"	
	"	I010103	E	"	
	"	I08I420	"	"	
	"	I007693	Ec	"	
	"	I50824	Fc	"	
	estero	20875	O PP	"	
	"	I2358	Gsmk	"	
	"	I2058	Gu	"	
	"	3877T	G	"	
	F.S.	I07263	K	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Cervaro	Estero	I47963	Kkw	carico	
	FS	I022255	Fc	vuoto	
	estero	77450	G	carico	
	"	348II	"	"	
	U.S.A.	222257	"	"	
	"	5I2I6	"	"	
	FS	449I3I	L	"	
	estero	7900	sst	"	
	F.S.E.	II2	M	carico	
	estero	7609	SS	"	
	F.S.	40I256	L	"	
	"	466626	"	"	
	"	7403I90	"	"	
	"	747074I	"	"	
	"	261313	Gh	"	
	"	307758	Hgc	"	
	"	482649	L	"	
	"	305242	Hgc	"	
	"	303023	"	"	
	"	301360	Hgbv	"	
	"	300513	Hg	"	
	"	315865	Hgc	"	
	"	301525	"	"	
	"	77196050	"	"	
	"	5 1359	"	"	
	"	300437	"	"	
	"	305927	"	"	
	"	3004I2	"	"	
	"	304641	Hgc	"	
	"	302065	"	"	
	"	I5I0I06	E	"	
	"	I021420	"	"	
	"	I007693	Ec	"	
	"	I50824	Fc	"	
	estero	20875	0 PP	"	
	"	I2558	GmmK	"	
	"	I9058	Gu	"	
	"	3077I	G	"	
	F.S.	II9553	W	"	
	"	475263	L	"	
	"	472I65	"	"	
	"	490165	"	"	
	estero	32072	OH	"	
	F.S.	9434	GMR	"	
POLIGNANO A MARE	F.S.	6548[illegible]4	P	"	
	"	661087	"	"	
	estero	85962	"	"	
	"	I8717	L	riparando	
	FS	I024572	F	"	

243

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
[redacted]	F.	117716	F	carico	
	F.S.F.	[illegible]	G	"	
	F. "	[illegible]	F	"	
	"	[illegible]	GV	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	carro	[illegible]	F	"	
	F. C.F.	[illegible]	GV	"	
	F.	[illegible]	LC	vuoto	
	carro	[illegible]	L	"	
	F.C.	[illegible]	"	"	
	"	[illegible]	"	"	
	carro	[illegible]	"	"	
	F.	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"

0136

Declassified E.O. 12356 Section 3.3/NND No. 785021

PALAZZO S. GIACOMO
PALAZZO S. GIACOMO
PALAZZO S. GIACOMO

Declassified E.O. 12356 Section 3.3/NND No. 785021

BEST COPY POSSIBLE

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
CANDELARO	P.S.	499952	L	carico	
	"	468267	"	"	
	"	49555	"	"	
	"	466279	"	"	
	"	457884	"	"	
	"	499163	"	"	
	"	040091	"	"	
	"	412864	"	vuoto	
	"	044781	"	"	
	"	414455	"	carico	
	"	419413	"	"	
	"	481443	"	"	
	"	413626	"	"	
	"	480630	"	"	
	"	7403122	"	"	
	"	47094I	"	"	
	"	493906	"	"	
	"	419006	"	"	
	"	411370	"	"	
	"	489I6	"	"	
	"	446708	"	"	
	"	495I34	"	"	
	"	497968	"	"	
	"	477673	"	"	
	"	412943	"	"	
	estero	20628	"	"	
	"	490373	"	"	
	F.S.	486417	"	"	
	estero	25710	"	"	
	F.S.	I00605I	"	"	
	estero	2540	G	"	
	F.S.	I73270	F	"	
BITETTO	estero	22866	L	buono	
	"	259	"	"	
	"	22739	"	"	
	"	30809	"	"	
	"	29631	"	"	
	F.S.	48762I	"	"	
	"	486773	"	"	

242

Declassified E.O. 12356 Sec. 3.3/NND No. 785021

CANDELARO	F.S.	439952	E		"	
	"	468267	"		"	
	"	49565	"		"	
	"	466279	"		"	
	"	457884	"		"	
	"	499163	"		"	
	"	040091	"		"	
	"	4I2564	"		vuoto	
	"	044781	"		"	
	"	4I4455	"		carico	
	"	4I84I3	"		"	
	"	48I143	"		"	
	"	413626	"		"	
	"	482630	"		"	
	"	7403I22	"		"	
	"	47094I	"		"	
	"	493906	"		"	
	"	4I3006	"		"	
	"	4II370	"		"	
	"	4*89I6	"		"	
	"	446708	"		"	
	"	495I34	"		"	
	"	497968	"		"	
	"	477673	"		"	
	"	4I2943	"		"	
	estero	20628	"		"	
	"	490373	"		"	
	F.S.	486417	"		"	
	estero	257I0	"		"	
	F.S.	I00605I	"		"	
	estero	2540	G		"	
	F.S.	173270	F		"	
BITETTO	estero	22866	L		buono	
	"	259	"		"	
	"	22739	"		"	
	"	30809	"		"	
	"	2983I	"		"	
	F.S.	48762I	"		"	
	"	486773	"		"	
	"	477276	"		"	
	"	4I29I5	"		"	
	"	4I7649,	"		"	
	estero	66I66	P		"	
	"	7898	G		"	"
	"	30369	"		"	
	"	32798	"		"	
	"	I9896	"		"	
	F.S.	771980I0	"		"	
	"	I011517	E		"	
	"	I020949	E		"	

242

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B I T E T T O	F.S.	II335 6	F	vuoto	
	"	I6085I	"	"	
	"	I02I26	"	"	
	"	III973I	"	"	
M O D U G N O	"	472931	L	carico	
	"	040046	"	"	
	"	419605	"	"	
	"	I0001?6	"	"	
	"	695000	F.C.Z.	"	
	"	282955	G	"	
	"	I096913	E	"	
	"	II33158	F	"	
	"	I58257	"	"	
	"	230394	G	"	
	"	748774	L	"	
	"	A1	"	"	
	"	476919	"	"	
	"	455827	"	"	
	"	464636	"	"	
	"	447304	"	"	
	"	4	"	"	
	"	698639	F.C.Z.	vuoto	
	"	77	L	"	
	"	46873	"	"	
	"	486046	"	"	
	estero	I413	"	"	
	"	I9785	"	"	
	"	73352	"	"	
	F.S.	I8	"	"	
	"	I	E	"	
	"	I4 I-I4	"	"	
	"	955180	"	"	
	"	95	"	"	
P O T E N Z A	F.S.	476292	L	carico	
	"	468896	"	"	
	"	491939	"	"	
	"	476728	"	"	
	"	436099	"	"	
	"	467088	"	"	
	"	415873	"	"	
	"	475639	"	"	
	"	412319	"	"	
	estero	I4934	F	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0144

Declassified E.O. 12356 Section 3.3/NND No. 785021

| MODELO | PROCEDENCIA | | |

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
CERVARO	FS	452944	P	carico	
	"	454631	"	"	
	"	485118	"	"	
	estero	78478	"	"	
	FS	1012421	"	"	
	"	1002601	"	"	
	"	424757	L	"	
	estero	1523	Kbin	"	
	"	2553I	Om	"	
	"	26786	Vil	"	
	FS	1016621	E	"	
	estero	27875	G	"	
	FS	27497540	J	"	
	estero	13657	J	"	
	"	35902	"	"	
	"	41956	G	"	
	"	98894	G	"	
	FS	172024	F	"	
	"	462852	L	"	
	"	477241	"	"	
	estero	13528	Ll	"	
	"	43264	R	"	
	FS	6106I5	P	vuoto	
	"	616523	"	"	
	"	654263	"	"	
	"	644142	"	"	
	estero	91582	Xxo	"	
	FS	845645	P	carico	
	"	1699687	Bc	"	
	"	169441	E	"	
	estero	28902	G	"	
	FS	1133710	Fc	"	
	"	207084	G	"	
	"	7789593I	"	"	
	"	1022782	"	"	
	"	1096494	Bc	"	
	estero	27241	G	"	
	"	1842150	E	"	
	"	1004246	"	"	

241

Declassified E.O. 12356 Section 3.3/NND No. 785021

C E R V A R O	FS	152944	P	carico
	"	154631	"	"
	"	148518	"	"
	estero	78475	"	"
	FS	1012421	"	"
	"	1002601	"	"
	"	94737	L	"
	estero	1523	Kbin	"
	"	8535I	Om	"
	"	76786	Vil	"
	FS	4015621	E	"
	estero	87875	O	"
	FS	77497540	I	"
	estero	13657	I	"
	"	35902	"	"
	"	41956	G	"
	"	85934	C	"
	FS	172024	F	"
	"	462832	L	"
	"	47124I	"	"
	estero	10528	Ll	"
	"	43264	R	"
	FS	0104I6	P	vuoto
	"	019623	"	"
	"	05a263	"	"
	"	044142	"	"
	estero	91522	Xxo	"
	FS	045645	P	carico
	"	1008057	Be	"
	"	16843I	T	"
	estero	12902	O	"
	FS	1151719	Fe	"
	"	207084	G	"
	"	771965?I	"	"
	"	1024782	"	"
	"	1006454	Be	"
	estero	27241	G	"
	"	1022150	E	"
	"	1004246	"	"
	"	4002005	"	"
	"	187622	"	"
	estero	87412	"	"
	FS	771955505	"	"
	"	1028198	"	"
	"	205886	O	"
	"	1021792	E	"
	"	1005109	"	"
	"	1000780	"	"
	"	04371I	L	"
	"	434592	E	"

241

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
CERVARO	FS	4I8I5I	L	carico	
	"	4I57I2	"	"	
	"	445335	"	"	
	"	485545	"	"	
	estero	I5364	"	"	
	FS	4I5380	"	"	
	"	487765	"	"	
	"	474043	"	"	
	estero	5I658	"	"	
	FS	486357	"	"	
	"	7403I4I	"	"	
	estero	5070	"	"	
	FS	646988	"	"	
	"	62I726	P	"	
	"	4I3732	L	"	
	"	7404952	"	"	
	"	4I5707	"	"	
	"	450383	"	"	
	"	5I2763	"	"	
	"	II26I39	"	"	
	"	478981	L	"	
	"	494992	"	"	
	"	447394	"	"	
	"	463941	"	"	
	estero	I2858	"	"	
	"	60083	"	"	
	FS	40I93I	L	"	
	"	459996	"	"	
	"	460012	"	"	
	"	482758	"	"	
	"	7402703	"	"	
	"	480010	"	"	
	estero	60272	"	"	
	"	2533	"	"	
	FS	AI4I6I	L	"	
	estero	60249	"	"	
	"	I2850	"	"	
	FS	I62482	"	"	
	estero	II5564	"	"	
	"	I4269	"	"	
	FS	I92I00	"	"	
	"	3I5I3I4	"	Oxm	
	estero	2163	"	To	
	FS	I2II49	"	L.	
	"	7440I76	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	437769	"	"	"
"	474043	"	"	"
estero	5I658	"	"	"
PS	423357	"	"	"
"	7403I4I	"	"	"
estero	5079	"	"	"
PS	046988	"	"	"
"	60I726	P	"	"
"	4I3732	L	"	"
"	7404952	"	"	"
"	4I5707	"	"	"
"	450383	"	"	"
"	5I2763	"	"	"
"	II65I39	T	"	"
"	47298I	L	"	"
"	494992	"	"	"
"	417394	"	"	"
"	463041	"	"	"
estero	I2958	"	"	"
"	83033	"	"	"
PS	49I92I	I	"	"
"	459806	"	"	"
"	460012	"	"	"
"	482758	"	"	"
"	7402703	"	"	"
"	48[illegible]0I0	"	"	"
estero	6[illegible]272	"	"	"
"	2933	"	"	"
PS	4I486I	L	"	"
estero	80249	"	"	"
"	I2850	"	"	"
PS	I024821	"	"	"
[illegible]	II5964	"	"	"
estero	I4269	"	"	"
PS	I92I00	E	"	"
"	7[illegible]5I3I4	Hs	"	"
estero	2253	Cerro	"	"
PS	I2II49	To	"	"
[illegible]	[illegible]48I76	L	"	"
"	T000045	E	"	"
"	49599I	L	"	"
"	77I96539	"	"	"
"	494596	L	"	"
"	II33728	F	"	"
estero	3599I	"	"	"
PS	99900	"	"	"
"	472763	L	"	"
"	I006866	EC	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
[illegible]	F.S.	[illegible]	[illegible]	[illegible]	
	"		"	"	
	"		"	"	
	"		"	vuoto	
	"		[illegible]	"	
	"		"	"	
	F.S.A.		"	"	
	"		L	"	
	"		"	"	
	"		"	"	
	"		"	"	
	"		"	"	
	"		"	"	
	"		"	carico	
	"		"	"	
	"		"	"	
	"		"	"	
	"		"	"	
	"		"	"

0 1 4 7

Declassified E.O. 12356 Section 3.3/NND No. 785021

[illegible]	F.B.	[illegible]7	Dv	cuprico	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	vitreo	
	"	[illegible]7	Tp	"	
	"	[illegible]	"	"	
	F.B.M.	[illegible]	"	"	
	"	[illegible]	L	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	cuprico	
	"	[illegible]7	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	[illegible]	[illegible]	E	"	
	FB	371922	"	"	
	"	[illegible]	F	"	Toxico a Rana
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	L	"	
	"	[illegible]	"	"	
	"	[illegible]	MV	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	P	Migratorio	
	"	[illegible]	"	"	
	"	[illegible]	Pc	cuprico	
	"	[illegible]	P	"	Pentecostense 240
	"	[illegible]	"	"	
	Extenso	[illegible]	"	"	
	FB	497927	"	"	
	"	418766	"	"	
	"	[illegible]	HP	"	
	"	[illegible]	P	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	Extenso-[illegible]		"	"	
	FB	748765	"	"	
	"	457592	"	"	
	Extenso-79572		"	"	
	"	54072	"	"	
	FB	776952	P	"	

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
ROTNEZA	PS	769704	B	carico	
	"	665039	"	"	
	"	218284	F	"	
	entero	65570	"	"	
	"	0230	"	"	
	"	6358	"	"	
	"	87895010	"	"	
	"	747760	"	"	
	"	1408909	D	"	
	PS	647360	P	"	
	entero	143	"	"	
	"	12000	"	"	
	"	15466	"	"	
	PS	459724	B	"	
	"	646634	"	"	
	"	472570	"	"	
	entero	4265	"	"	
	PS	681306	"	"	
	"	67244	"	"	
	"	7696010	"	"	
	"	7799015	"	"	
	"	467555	"	"	
	entero	1578	"	"	
	"	10980	"	"	
	PS	4767211	"	"	
QUINOSA	PS	470154	"	"	
	"	613352	"	"	
	"	1007216	"	"	
Stinnesol	entero	472403	"	riparando	
	PS	118787	"	vuoto	
	"	10015	"	"	
	"	1100853	"	"	
	"	1006625	"	"	
	"	200921	"	"	
	"	1281103	"	carico	
	"	1230264	"	"	
	"	61512	"	"	
	"	450566	"	"	
	"	480634	"	"	
	"	483749	"	vuoto	
	"	7489307	"	"	
	"	61322	"	"	
	"	607022	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0149

Declassified E.O. 12356 Section 3.3/NND No. 785021

Stinson Beach
Bolinas
Olema
Point Reyes Station
Inverness
Petaluma
Sausalito
San Rafael
Novato
Petaluma
Sebastopol
Santa Rosa
Windsor
Healdsburg
Cloverdale
Geyserville
Asti
Cotati
Rohnert Park
Cotati
Penngrove
Kenwood
Glen Ellen
Sonoma
Boyes Hot Springs
Fetters Hot Springs
Agua Caliente
Sonoma
Glen Ellen
Kenwood
Santa Rosa
Sebastopol
Graton
Forestville
Guerneville
Monte Rio
Duncans Mills
Jenner
Cazadero
Occidental
Freestone
Bodega
Bodega Bay
Valley Ford
Tomales
Dillon Beach
Petaluma
Sonoma
Napa
Yountville
Oakville
Rutherford
St. Helena
Calistoga
Angwin
Pope Valley
Lower Lake
Middletown
Hidden Valley Lake
Kelseyville
Clearlake Oaks
Clearlake Park
Clearlake
Lakeport
Upper Lake
Nice
Lucerne
Clearlake Highlands
Glenhaven
Kelseyville
Soda Bay

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 14 agosto 1944 *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Spinazzola	FS	443156	L	vuoto	
	ostav8	27487	"	"	
	FS	109905	"	"	
	"	573478	"	"	
	"	437897	L	"	
	"	46967	L	"	
	"	455762	"	"	
	"	470339	"	"	
	"	473014	"	"	
	"	538124	"	carico	
	"	0500846	"	"	
	"	946295	"	"	
	"	931093	"	"	
	"	552061	"	"	
	"	1009502	"	"	
	"	539674	"	"	
	"	88756	"	"	
	"	3005938	"	"	
	"	2005656	"	"	
	"	33.873	"	"	
	"	2003095	"	"	
	"	1034200	"	"	
Bisceglie	FS	617296	P	carico	
	"	635005	"	"	
	"	615026	"	"	
	"	639737	"	"	
	"	630907	"	"	
	"	667836	"	vuoto	
	"	7764000	"	"	
	"	694942	"	"	
	"	668833	"	"	
	ostav	83.7	"	"	
		2688	"	"	
	FS	526842	"	"	
	ostav	6029	"	"	
	FS	540715	"	"	
	"	554926	"	"	
	"	561779	"	"	

239

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

OFSI

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Riccadio	PS	646300	P	Vuoto	
	"	654600	"	"	
	"	651652	"	"	
	"	651574	"	"	
	"	650234	"	"	
	"	685120	"	"	
	"	660395	"	"	
	ottavo	17804	"	"	
	28	660658	"	"	
	"	646074	"	"	
	"	644023	"	"	
	"	654361	"	"	
	"	653940	"	"	
	"	656073	"	"	
	"	649479	"	"	
	"	645432	"	"	
	"	657167	"	"	
	"	652736	"	"	
	"	654322	"	"	
	"	6453[illegible]6	"	"	
	"	6[illegible]0132	"	"	
	"	7[illegible]2142	"	"	
	ottavo	13425	"	"	
	PS	649059	"	"	
	ottavo	87786	"	"	
	P	47572	"	"	
	PS	658589	"	"	
	"	6[illegible]4327	"	"	
	"	65[illegible]36	"	"	
	"	66[illegible]415	"	"	
	"	653426	Pom	"	
	"	6[illegible]8280	"	"	
	ottavo	153473	"	"	
	"	155590	"	"	
	"	75[illegible]05	L	carico	Ofantino
	P3	6[illegible]8812	"	"	"
	"	652994	"	"	"
	ottavo	53417	"	"	
	28	647[illegible]60	"	Vuoto	
	ottavo	24[illegible]12	B	"	
	P3	643456	Fo	carico	Aurelia

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

0153

Declassified E.O. 12356 Section 3.3/NND No. 785021

		"	"	"	
		"	"	"	
		"	"	"	

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 [illegible] *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	FS	465449	L	carico	
	"	410831	"	"	
	"	499346	"	"	
	"	415490	"	"	
	"	401474	"	"	
	"	450928	"	"	
	"	444787	"	"	
	"	448709	"	"	
	"	472183	"	"	
	"	410317	"	"	
	"	419367	"	"	
	"	407148	"	"	
	"	461813	"	"	
	estero	353498	Hg	"	
	FS	301297	"	ripar.	
	"	204486	G	carico	
	"	1024291	D	"	
	"	150812	E	"	
	"	1016676	E	"	
	"	419615	L	vuoto	
	"	7300217	Ma	"	
	"	469244	L	ripar.	
	"	150088	Fc	"	
	"	121031	"	"	
	estero	14272	F	"	
	FS	661252	"	"	
	"	1020159	E	"	
	"	1001362	"	"	
	"	1000854	"	"	
	"	155604	F	"	
	"	159657	"	"	
	"	1016658	E	"	
	"	1003176	"	"	
	"	1001319	"	"	
	"	1015060	"	"	
	"	433500	L	"	
	"	419257	"	"	
	estero	66852	K	"	
	"	98402	Cs	"	

228

Declassified E.O. 12356 Section 3.3/NND No. 785021

FOGGIA	FS	465449	L	carico
	"	410831	"	"
	"	490346	"	"
	"	415490	"	"
	"	421474	"	"
	"	459928	"	"
	"	444787	"	"
	"	418709	"	"
	"	472183	"	"
	"	410317	"	"
	"	419367	"	"
	"	407118	"	"
	"	461813	"	"
	estero	353498	Hg	"
	FS	301297	"	ripar.
	"	604486	G	carico
	"	1014291	"	"
	"	190812	F	"
	"	1016676	E	"
	"	410615	L	vuoto
	"	7300217	Ma	"
	"	465244	L	ripar.
	"	160088	Fe	"
	"	121031	"	"
	estero	14272	F	"
	FS	661252	F	"
	"	1020159	E	"
	"	1001362	"	"
	"	1006854	"	"
	"	155604	F	"
	"	153697	"	"
	"	1016658	E	"
	"	1003176	"	"
	"	1001319	"	"
	"	1015068	"	"
	"	433500	L	"
	"	418257	"	"
	estero	66892	K	"
	"	88402	Cm	"
	"	41103	L	"
	"	222693	P	carico
	Fs	100486	"	ripar.
	"	201602	Ge	"
	"	545061	P	"
	"	448520	L	"
	"	416240	"	carico
	"	414343	"	"
	"	417912	"	"
	"	416863	"	"
	estero	18120	L	ripar.

228

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
F O G G I A	F.S.	692436	P.O.Z.	riparando	
	Est Fo	5305	L	"	
	F.S.	747925	G	"	
	"	7I05143	F	"	
	Estero	4[illegible]	L	"	
	"	23183	Kann	"	
	F.S.	187602	Fc	"	
	"	1025073	"	"	
	Estero	28144	G	"	
	"	138657	F	"	
	"	269134	G	"	
	F.S.	046134	L	"	
		I50732	F	"	
	"	459022	L	"	
	"	656168	F	"	
	"	237308	G	"	
	Estero	15400	F	"	
	"	34671	F	"	
	"	251024	G	"	
	F.S.	1060195	F	"	
	"	747270	L	"	
	Estero	27683	G	"	
	"	3909	L	"	
	F.S.	418232	L	"	
	"	1075[illegible]	L	"	
	"	034481	L	"	
	"	462261	L	"	
	"	7406166	L	"	
	"	4103[illegible]	L	"	
	Estero	15951	F	"	
	"	29172	G	"	
	F.S.	747067	L	"	
	"	7403241	L	"	
	Estero	9171	A.M.	"	
	F.S.	621960	P	"	
	"	615970	P	"	
	"	7 00556	L	"	
	"	648014	L	"	
	Estero	354006	L	"	
	"	69457	L	"	
	F.S.	7448016	L	"	
	"	7303743	HHE	"	
	"	1901518	Bo	"	
	"	7406218	P	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

F.S.	15 682	Fe	"	
"	1 [illegible]5	"	"	
Estero	28 44	G	"	
"	13863	F	"	
"	6 5134	G	"	
F.S.	645134	L	"	
	I5 73	F	"	
"	45	L	"	
"	656168	F	"	
"	23	G	"	
Estero	154	F	"	
"	34 671	F	"	
"	891024	G	"	
F.S.	1	F	"	
"	7	L	"	
Estero	27623	G	"	
"	390	L	"	
F.S.	418232	L	"	
"	1 7555	F	"	
"	044	I	"	
"	46	"	"	
"	7	"	"	
"	61	"	"	
Estero	15	F	"	
"	5 17	G	"	
F.S.	7 706 7	L	"	
"	74	"	"	
Estero	3172	A.F.	"	
F.S.	621969	F	"	
"	643	"	"	
"	7 0855	"	"	
"	648	"	"	
Estero	154	"	"	
"	69457	"	"	
F.S.	7	L	"	
"	7	IHH	"	
"	1	Bc	"	
"	1	E	"	
"	2	G	"	
"	6	F	"	
"	1	BBc	"	
Estero	7	B	"	
"	1	F	"	
F.S.	77	F	"	
"	1	F	"	
"	042	L	"	
"	163	F	"	
"	7	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Marittima	FS	I45020	Fi	buono	
	"	I00908	F	"	
	estero	76317	chiuso	"	
	FS	261328	G	"	
	estero	92871	chiuso	"	
	FS	7I08794	F	"	
	"	II2975	"	"	
	"	230369	G	"	
	"	250811	"	"	
	estero	6I5I	L	vuoto	
	"	807	P6Z	"	
	FS	650871	P	"	
	estero	45062	"	"	
	FS	497965	E	"	
	"	487977	L	"	
	"	469898	"	"	
	estero	9I82	P.O.Z.	"	
	FS	695479	"	"	
	"	469074	L	in scaric.	
	estero	67402	P	"	
	"	705093	"	"	
	FS	65002I	P	"	
	"	697340	L	vuoto	
	"	30409I	Hg	in partenza	
	"	300039	"	"	
	"	261325	G	"	
	"	7I09I27	F	vuoto	
	"	4I2447	L	"	
	"	474591	"	"	
	"	470864	"	"	
	"	485710	"	"	
	"	470964	"	"	
	"	I61905	F	"	
	"	I4I836	Fi	"	
	"	7I00690	"	"	
	"	I72772	"	"	
	"	I020I83	E	"	
	"	I45057	Fi	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Bari Marittima	FS	I45020	Fi	buono
	"	I00908	F	"
	estero	76817	chiuso	"
	FS	26I328	G	"
	estero	92871	chiuso	"
	FS	7I08794	F	"
	"	I72975	"	"
	"	230369	G	"
	"	250811	"	"
	estero	6I5I	L	vuoto
	"	807	POZ	"
	FS	650871	F	"
	estero	45062	"	"
	FS	497965	B	"
	"	487977	L	"
	"	469898	"	"
	estero	9182	P.O.Z.	"
	FS	695479	"	"
	"	469074	L	da Bari c.
	estero	67402	P	"
	"	705093	"	"
	FS	65002I	F	"
	"	697340	L	vuoto
	"	30409I	Hg	in partenza
	"	300039	"	"
	"	261325	G	"
	"	7I09I87	F	vuoto
	"	4I2447	L	"
	"	474891	"	"
	"	470864	"	"
	"	488710	"	"
	"	470964	"	"
	"	I61905	F	"
	"	I4I836	Fi	"
	"	7I00690	"	"
	"	I72772	"	"
	"	I020I83	E	"
	"	I45257	Fi	"
	"	I81800	F	"
	"	I21953	"	"
	estero	45244	chiuso	"
	FS	I005796	E	"
	estero	8718	chiuso	"
	"	I34820	F	"
	FSE	I8I3	"	"
	estero	I7730	chiuso	"
	FS	I84225	F	"
	"	I506I6	"	"
	"	7II78I	"	"
	"	508363	Hg	"

237

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Marittima	FS	936460	M	partenza	
	"	390251	Hg	"	
	"	308759	"	"	
	"	315279	"	"	
	"	306516	"	"	
	"	315068	"	"	
	"	300349	"	"	
	"	40594	L	"	
	"	694614	P.O.Z.	"	
	"	692060	"	"	
	"	182620	F	"	
	"	187848	"	"	
	"	183627	"	"	
	"	418826	L	"	
	"	645453	P	"	
	"	650615	"	"	
	"	654623	"	"	
	"	406738	"	"	
	"	494102	"	"	
	"	405346	"	"	
	"	460463	"	"	
	"	465421	"	"	
	"	414341	"	"	
	"	409559	"	"	
	"	412136	"	"	
	"	472772	"	"	
	"	478095	"	"	
	"	7405136	"	"	
	"	476253	"	"	
	"	478929	"	"	
	"	740I338	"	"	
	"	479679	"	"	
	"	458659	"	"	
	"	412774	"	"	
	"	419051	"	"	
	"	622954	P	"	
	"	647607	"	"	
	"	648281	"	"	
	"	77645509	"	"	
	"	466871	L	"	
	"	646553	P	"	
	"	6[illegible]3203	"	"	
	"	650590	"	"	
	"	7670008	"	"	
	"	654504	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	3I5068	"	"	
"	"	300349	"	"	
"	"	40594	L	"	
"	"	6946I4	P.O.Z.	"	
"	"	692060	"	"	
"	"	I82620	F	"	
"	"	I87848	"	"	
"	"	I83627	"	"	
"	"	4I8826	L	"	
"	"	645453	P	"	
"	"	6506I5	"	"	
"	"	654623	"	"	
"	"	406738	"	"	
"	"	494I02	"	"	
"	"	405346	"	"	
"	"	460463	"	"	
"	"	46542I	"	"	
"	"	4I434I	"	"	
"	"	409559	"	"	
"	"	4I2I36	"	"	
"	"	472772	"	"	
"	"	478095	"	"	
"	"	7405I36	"	"	
"	"	476253	"	"	
"	"	478929	"	"	
"	"	740I338	"	"	
"	"	479679	"	"	
"	"	458659	"	"	
"	"	4I2774	"	"	
"	"	4I905I	"	"	
"	"	622954	P	"	
"	"	647607	"	"	
"	"	648281	"	"	
"	"	77645509	"	"	
"	"	46487I	L	"	
"	"	646563	P	"	
"	"	6M23203	"	"	
"	"	660590	"	"	
"	"	7670008	"	"	
"	"	654504	"	"	
"	"	648727	P	"	
"	"	654950	"	"	
"	"	644020	"	"	
estero		38II5	L	"	
"	"	3I0353	H5	"	
"	"	II249	P	"	
"	"	I22982	"	"	
"	"	82424	"	"	
"	"	8I398	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi Smis/to	FSE	III3I	F	carico	Bari
	FS	507I07	Mv	"	
	"	524436	"	"	
	"	508I67	"	"	
	"	548459	"	"	
	"	5II273	"	"	
	"	583423	"	"	
	"	I0007726	E	"	
	"	508095	Mv	"	
	"	5II282	"	"	
	"	565204	"	"	
	"	574395	"	"	
	estero	26578	G	"	
	FS	5I4253	Mv	"	
	"	I2I374	F	"	
	"	I73078	"	"	
	"	666790	P	"	
	"	658544	"	"	
	estero	49620	"	"	
	"	90I00	R	vuoto	
	FS	640522	P	carico	
	"	645857	"	"	
	"	I0005?I	E	vuoto	
	"	509I2I	Mv	carico	
	"	203839	G	"	
	"	574700	Mv	"	
	"	5I3653	"	"	
	"	4I7730	L	"	
	estero	4587	L	"	
	FS	4773II	"	"	
	"	I0I3276	Ec	"	
	estero	52939	L	"	
	"	94803	"	"	
	FS	4I3752	L	"	
	"	040524	"	"	
	"	400019	"	"	
	"	4I0296	"	"	
	"	472230	"	"	
	"	657751	P	"	

226

Declassified E.O. 12356 Section 3.3/NND No. 785021

FS	507I07	Mv	"	
"	524356	"	"	
"	508I07	"	"	
"	548459	"	"	
"	5II273	"	"	
"	583423	"	"	
"	I00077 26	E	"	
"	508095	Mv	"	
"	5II282	"	"	
"	565204	"	"	
"	574395	"	"	
estero	28678	G	"	
FS	5I4253	Mv	"	
"	I2I374	F	"	
"	I73078	"	"	
"	666790	P	"	
"	652544	"	"	
estero	49620	"	"	
"	90I30	R	vuotō	
FS	640582	P	carico	
"	645857	"	"	
"	I00092I	E	vuoto	
"	509I2I	Mv	carico	
"	203839	G	"	
"	574700	Mv	"	
"	5I3633	"	"	
"	4I7730	L	"	
estero	4587	L	"	
FS	4773II	"	"	
"	IOI3276	Ec	"	
estero	52939	L	"	
"	94803	"	"	
FS	4I3752	L	"	
"	040584	"	"	
"	400CI9	"	"	
"	4I0296	"	"	
"	472230	"	"	
"	65775I	P	"	
"	65I624	"	"	
"	646379	"	"	
"	645726	"	"	
"	I00884	"	"	
"	2575I3	E	"	
"	I55535	"	"	
"	7I07378	"	"	
"	I03I532	"	"	
"	472955	"	"	
"	043953	"	"	
"	I024843	E	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi Smista/to	FS	I54899	Fc	carico	
	estero	678	H	"	
	FS	I2I77	Fc	"	
	"	I59264	" G	"	
	"	830406	G	"	
	"	720I388	G	"	
	"	492975	L	"	
	"	I006967	E	"	
	"	4I0083	L	"	
	"	II4984	F	"	
	"	475349	L	"	
	"	7769667I	"	"	
	"	604775	" P	"	
	"	65I845	L	"	
	"	49I895	D	"	
	"	II6786	P	"	
	"	648391	"	"	
	"	66D047	"	"	
	"	622938	" Q	"	
	"	752757	"	"	
	"	697481	" F	"	
	"	I84406	E	"	
	"	I003705	F	"	
	estero	96272	F	"	
	FS	I0I356	F	"	
	"	7I70I96	F	vuoto	
	estero	I46633	E	carico	
	FS	I0II2I5	P	"	
	estero	I3509	"	"	
	FS	752763	"	"	
	"	7770I97	"	"	
	estero	5036I	F	"	
	FS	I87676	C	"	
	estero	64I67	P	vuoto	
	FS	646421	"	"	
	"	655915	E	"	
	"	I0I0397	"	buono	
Bari Marittima	"	I029I35	F	"	
	"	I7329I	E	"	
	"	I024442	"	"	
	"	I00I250	"	"	
	"	I029781	chiuso	"	
	estero	I55540	F	"	
	FS	II33359	G	"	
	"	202880		"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	830406	G	"	
"	7201388	G	"	
"	492975	I	"	
"	I006967	E	"	
"	410083	L	"	
"	II4984	F	"	
"	475349	L	"	
"	7769667I	"	"	
"	604775		"	
"	85I845	P	"	
"	49I895	L	"	
"	II6766	E	"	
"	648391	P	"	"
"	86E047	"	"	
"	622938	"	"	
"	752757	Q	"	
"	597481	"	"	
"	I84406	F	"	
"	I003705	E	"	
Estero	96272	E	"	
FS	I0I356	F	"	
"	7I70I96	"	"	
estero	I46633	F	vuoto	
FS	I0II2I5	E	carico	
estero	I3509	P	"	
FS	752763	"	"	
"	7770I97	"	"	
estero	5036I	"	"	
FS	I87676	F	"	
estero	64I67	G	"	
FS	646421	P	vuoto	
"	6559I5	"	"	
"	I9I0397	E	"	
"	I029I35	"	buono	
"	I7329I	F	"	
"	I024442	E	"	
"	I00I250	"	"	
"	I029781	"	"	
estero	I55540	chiuso	"	
FS	II33359	F	"	
"	902880	G	"	
"	I43634	F	"	
estero	2789I	chiuso	"	
"	I7I649	"	"	
FS	III7553	F	"	
"	I80487	"	"	
"	I86654	"	"	
"	II35939	"	"	
"	7I6I260	"	"	

Bari Marittima

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	Estero	28661	Om	riparando	
	F.S.	7408997	L	"	
	"	1003182	E	"	
	"	490019	L	"	
	"	645181	P	"	
	Estero	8198	stuttengrd	"	
	F.S.	040533	L	"	
	"	464901	"	"	
	"	411109	"	carico	
	"	542505	"	vuoto	
	"	468395	"	carico	
	"	468772	"	" "	
	"	77495023	"	vuoto	
	"	653856	P	"	
	"	130812	Fc	"	
	"	4707227	L	"	
	"	460330	"	"	
	"	047222	"	"	
	"	7403854	"	"	
	"	656935	P	"	
	"	7402694	L	carico	
	"	5098[illegible]4	Mv	vuoto	
	"	625038	P	rip rando	
	"	330148	Hg	"	
	"	116163	F	"	
	"	1008750	E	"	
	"	473391	L	"	
	"	486397	"	"	
	"	452236	"	"	
	"	416445	"	"	
	"	187831	P	"	
	"	7104066	F	"	
	"	161611	Fc	"	
	"	807168	Gru	"	
	Estero	7738	Halle	"	
	"	21547	O.M.	"	
	F.E.	35718	"	"	
	F.S.	455377	L	"	
	"	480971	"	carico	

235

Declassified E.O. 12356 Sec Section 3.3/NND No. 785021

FOGGIA

Estero	28654	Om	Riparando
F.S.	7408997	L	"
"	I003I82	E	"
"	490019	L	"
"	645181	P	"
Estero	8198	stuttengrd	"
F.S.	04 533	L	"
"	464901	"	"
"	4III09	"	carico
"	542505	"	vuoto
"	468395	"	carico
"	468772	"	" "
"	77495023	"	vuoto
"	653856	P	"
"	I308II	Fc	"
"	4707227	L	"
"	460330	"	"
"	047222	"	"
"	7402854	"	"
"	656935	P	"
"	7402694	L	carico
"	5098[illegible]4	Mv	vuoto
"	6[illegible]9038	P	rip rando
"	300148	Hg	"
"	II6I63	F	"
"	I008750	E	"
"	473391	L	"
"	486397	"	"
"	458236	"	"
"	416445	"	"
"	I87831	F	"
"	7I04066	F	"
"	I616II	Fc	"
"	807168	Gru	"
Estero	7738	Halle	"
"	2154-7	O.M.	"
F.E.	35718	"	"
F.S.	455377	L	"
"	48[illegible]271	"	carico
"	4614I4	"	"
"	478110	"	"
"	040962	"	"
"	466578	"	"
"	9581008	Mp	"
"	931019	"	"
"	508504	"	"
"	553214	"	"
"	505407	"	"
"	599834	"	"
"	9530616	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	F.S.	[illegible]	Mp	carico	
	Estero	926722	Vienna	"	
	F.S.	553438	Mp	"	
	"	982016	Mo	"	
	"	[illegible]	Mp	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	Estero	97854	R	"	
	T.E.	[illegible]	L	"	
	F.S.	[illegible]	Go	"	
	"	[illegible]	Mp	"	
	"	[illegible]	Fo	"	
	"	[illegible]	L	"	
	"	[illegible]	P	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	Estero	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	F.S.	[illegible]	L	"	
	Estero	[illegible]	L	"	
	"	[illegible]	"	"	
	T.E.	[illegible]	"	"	
	"	[illegible]	"	"	
	F.S.	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0169

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Marittima	FS	81398	L	partenza	
	"	36247	"	"	
	"	72763	"	"	
	"	93635	"	"	
	"	40647	"	"	
	"	53978	"	"	
	"	980077	"	"	
	"	32675	"	"	
	"	52801	P	"	
	"	81330	"	"	
	"	71670	"	"	
	"	95236	B	"	
	"	239890	"	"	
	"	61106	P	"	
	"	632916	"	"	
	"	9761	"	"	
	"	8521	"	"	
	"	28597	chiuso	"	
	"	45680	L	"	
	FS	251675	C	"	
	"	47378	L	"	
	"	40575I	"	"	
	"	47020	"	"	
	"	48498I	"	"	
	"	475275	"	"	
	"	493970	"	"	
	"	47716	"	"	
	"	049599	"	"	
	"	64414I	"	"	
	FS	480249	"	da scarico.	
	etsero	62258	Fm	"	
	FS	315059	Hg	"	
	"	1007497	E	vuoto	
	"	1022911	"	"	
	"	100955	"	"	
	"	1007377	"	"	
	"	204845	G	"	
	"	7170053	"	"	

224

Declassified E.O. 12356 Section 3.3/NND No. 785021

Bari Marittima	FS	8I398	L	partenza
	"	36247	"	"
	"	72763	"	"
	"	93635	"	"
	"	40647	"	"
	"	53978	"	"
	"	980077	"	"
	"	32675	"	"
	"	5280I	P	"
	"	8I330	"	"
	"	7I670	"	"
	"	95236	E	"
	"	239890	"	"
	"	6II06	P	"
	"	632916	"	"
	"	976I	"	"
	"	852I	"	"
	"	28597	chiuso	"
	"	45680	L	"
	FS	25I675	G	"
	"	473I78	L	"
	"	40575I	"	"
	"	470I20	"	"
	"	484981	"	"
	"	475275	"	"
	"	493970	"	"
	"	477316	"	"
	"	049599	"	"
	"	64II4I	"	"
	FS	480249	"	da scaric.
	estero	62258	"	"
	FS	3I5059	Hg	"
	"	I007497	E	vuoto
	"	I0229II	"	"
	"	I00955	"	"
	"	I007377	"	"
	"	204845	"	"
	"	7I70058	"	"
	"	I67830	P	"
	"	I68565	"	"
	"	469305	L	partenza
	"	4I9420	"	"
	estero	I25320	"	"
	FS	4I9I7I	L	da scaric.
	"	482559	"	"
	"	494922	"	vuoto
	estero	85729	P	da scaric.
	FS	7769501 6	"	"
	"	657330	"	"
	"	644345	"	partenza

.234

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Marittima	FS	40730I	L	vuoto	
	"	II2793	F	"	
	"	7I70I6I	F	"	
	"	623926	P	"	
	"	307796	Hg	"	
	"	30403I	"	"	
	"	456442	B	"	
	"	692236	Poz	da scaricare	
	"	04II34	L	"	
	"	458946	"	"	
	"	492II8	"	"	
	"	480II2	"	"	
	"	477I22	"	"	
	estero	658I	"	"	
	FS	473258	"	"	
	"	486659	"	"	
	estero	I2639	"	"	
	FS	479779	"	"	
	"	48632I	"	"	
	"	343008	Hg	vuoto	
	"	343039	"	"	
	"	5096II	MD	"	
	"	5096I5	"	"	
	"	493493	L	"	
	"	693493	P	"	
	"	694072	"	"	
	"	698074	"	"	
	estero	2069	"	"	
	"	I2I09	"	da scaricare	
	FS	488435	"	"	
	"	30658I	"	"	
	"	475470	L	"	
	"	482086	"	"	
	"	462930	"	"	
	estero	I7C4048	"	"	
	FS	74758I	L	vuoto	
	"	4I22I8	"	"	
	"	459906	"	"	
	estero	50823	"	"	
	"	I607	"	"	
	FSK	434369	L	"	
	FS	460311	"	"	
	FSE	4409	"	"	
	FS	4I8195	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	[illegible]	"	"
"	456442	E	da "scaricare
"	692236	Poz	"
"	04II34	L	"
"	458946	"	"
"	492II8	"	"
"	480II2	"	"
"	477I22	"	"
estero	658I	"	"
FS	473258	"	"
"	486659	"	"
estero	I2639	"	"
FS	479779	"	"
"	486321	"	"
"	343008	Hg	vuoto
"	343039	"	"
"	5096II	MQ	"
"	5096I5	"	"
"	493493	L	"
"	693493	P	"
"	694072	"	"
"	698074	"	"
estero	2069	"	da "scaricare
"	I2I09	"	"
FS	488435	"	"
"	30658I	"	"
"	475470	L	"
"	482086	"	"
"	462930	"	"
estero	I704049	L	vuoto
FS	74758I	"	"
"	4I22I8	"	"
"	459906	"	"
estero	50823	"	"
"	I607	"	"
FS	434369	L	"
FS	4603II	"	"
FSE	4409	"	"
FS	4I8I95	"	"
"	494525	L	da "scaricare
"	467818	"	"
"	4755I0	"	"
"	4I930I	"	"
"	40I473	"	"
"	469350	"	"
"	480590	"	"
"	4I9488	"	"
estero	I055I	P	"
"	6I270	"	"
FS	I0I463I	E	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALE

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Marittima	FS	I0023604	E	da sca[illegible]icare	
	"	479180	L	"	
	"	412930	"	"	
	"	I97I37	E	"	
	estero	I7I4I	L	"	
	"	I2753	"	"	
	"	23289	"	"	
	"	4734I	chiuso	"	
	FS	4I4863	L	"	
	"	496714	"	"	
	"	I84480	E	"	
	estero	17930	chiuso	"	
Brindisi Marittima-	FS	I005204	Ec	vuoto	
	"	I0I2489	"	carico	
	"	I0I4473	"	"	
	"	I007423	"	"	
	"	I0I3326	"	"	
	"	I006405	"	"	
	"	I4I897	Fl	"	
	"	I4I928	"	"	
	"	I5758I	Fc	"	
	"	II637I	"	vuoto	
	"	III8346	"	"	
	"	III7782	"	carico	
	"	III57I2	"	"	
	"	I33258	"	"	
	"	II4969	"	"	
	"	III5356	"	"	
	"	I021490	E	vuoto	
	"	I84583	F	carico	
	"	77I93044	"	"	
	"	I7249I	"	"	
	"	I020001	B	"	
	"	I66668	F	"	
	"	I027976	E	"	
	"	200480	Cc	"	
	"	727QI28	"	"	
	"	251939	"	"	

223

Declassified E.O. 12356 Sec Section 3.3/NND No. 785021

Bari Marittima	FS	I0029604	E	da scaricare
	"	479190	L	E "
	"	4I2930	"	"
	"	I92737	EE	"
	estero	I7I4I	L	"
	"	I2733	"	"
	"	03289	"	"
	"	4734I	chiuso	"
	FS	4I4863	L	"
	"	496714	"	"
	"	I84480	E	"
	estero	17930	chiuso	"
Brindisi Marittima	FS	I005204	Ec	vuoto
	"	I0I2489	"	carico
	"	I0I4473	"	"
	"	I007423	"	"
	"	I0I33276	"	"
	"	I006405	"	"
	"	I4I897	Fi	"
	"	I4I023	"	"
	"	I57681	Fo	"
	"	II8371	"	vuoto
	"	III8346	"	"
	"	III7782	"	carico
	"	III57I2	"	"
	"	I33268	"	"
	"	II4969	"	"
	"	III5356	"	"
	"	I021490	E	vuoto
	"	I84883	F	carico
	"	77I93044	"	"
	"	I7249I	"	"
	"	I020001	"	"
	"	I66668	"	"
	"	I027976	"	"
	"	200480	Go	"
	"	7270I28	"	"
	"	25I939	"	"
	"	202400	"	vuoto
	"	466648	L	carico
	"	482770	"	"
	"	40I6I8	"	"
	"	459II0	"	vuoto
	"	4I7[illegible]5I8	"	"
	"	4I4623	"	"
	"	467276	"	"
	"	7470266	"	"
	"	435906	"	"
	"	476427	"	"
	"	47348I	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi Marittima	PS	4I0I33	L	carico	
	"	748I085	"	"	
	"	477I7	"	"	
	"	472036	"	"	
	"	472230	"	"	
	"	4I0286	"	"	
	"	400019	"	"	
	"	040584	"	"	
	"	413752	"	"	
	"	427305	"	"	
	"	4II22I	"	"	
	"	461897	"	"	
	"	494330	"	"	
	"	485748	"	"	
	"	485II6	"	"	
	"	740I402	"	"	
	"	497775	"	"	
	"	472512	"	"	
	"	469493	"	"	
	"	487579	"	"	
	"	447390	"	"	
	"	447705	"	"	
	"	4I4052	"	"	
	"	740791I	"	"	
	"	479351	"	"	
	"	481624	"	"	
	"	476237	"	"	
	"	494329	"	"	
	"	463925	"	"	
	"	454653	"	"	
	"	4I5909	"	"	
	"	481992	"	"	
	"	7769551I3	P.O.Z.	"	
	"	695062	P	"	
	"	065036	"	"	
	"	695031	"	"	
	"	648581	"	"	
	"	647I35	"	vuoto	
	"	657I25	"	"	
	"	656968	"	"	
	"	66I865	"	"	
	"	648853	"	carico	
	"	643736	"	"	
	"	646379	"	"	

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

"	406019	"	"	
"	040584	"	"	
"	413752	"	"	
"	427305	"	"	
"	411221	"	"	
"	461897	"	"	
"	494330	"	"	
"	485748	"	"	
"	485116	"	"	
"	740I402	"	"	
"	497775	"	"	
"	472512	"	"	
"	469493	"	"	
"	487679	"	"	
"	447590	"	"	
"	447705	"	"	
"	414052	"	"	
"	7407911	"	"	
"	479351	"	"	
"	481624	"	"	
"	476237	"	"	
"	404329	"	"	
"	463925	"	"	
"	454653	"	"	
"	419909	"	"	
"	481992	"	"	
"	77695513	P.O.Z.	"	
"	695092	P	"	
"	061036	"	"	
"	695031	"	"	
"	648581	"	"	
"	647135	"	vuoto	
"	657125	"	"	
"	656968	"	"	
"	661865	"	"	
"	647853	"	cerico	
"	645726	"	"	
"	646379	"	"	
"	651524	"	"	
"	657751	"	"	
PSE"	4140	"	"	
estero	811114	chiuso	"	
"	811119	"	"	
"	414249	"	"	
"	197II	"	"	
"	88X	"	"	
"	58939	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	Estero	20[illegible]3	U.S.A.	rip. rando	
	"	25601	L	"	
	"	1592	"	"	
	"	22933	"	"	
	F.S.	163261	"	"	
	"	250779	"	"	
	"	482904	"	"	
	"	655331	"	"	
	"	660098	"	"	
	"	467644	"	"	
	"	488763	"	"	
	"	041940	"	"	
	"	I41029	"	"	
	"	I45483	F	"	
	"	4084	L	"	
	"	7I60084	F	"	
	"	598706	Fp	"	
	"	I726I0	F	"	
	Estero	96957	L	"	
	F.S.	I88083	F	carico	
	"	77I92024	"	"	
	"	321521	Hg	"	
	"	695I08	P	"	
	"	007I73	"	"	
	"	767OI20	"	"	
	"	650974	"	"	
	"	776455II	"	"	
	Estero	2292	I	"	
	"	12150	"	"	
	"	45980	"	"	
	"	45537	"	"	
	"	5315	"	"	
	"	26335	"	"	
	"	30394	"	"	
	F.S.	77696500	"	"	
	"	77695502	"	"	
	estero	32406	Hg	"	
	F.S.	3159I0		"	

232

Declassified E.O. 12356 Section 3.3/NND No. 785021

F O G G I A	Estero	20163	U.S.A.	rip rendo	
	"	2560I	L	"	
	"	1592	"	"	
	"	22933	"	"	
	F.S.	163261	"	"	
	"	250779	"	"	
	"	482901	"	"	
	"	655331	"	"	
	""	66[illegible]98	"	"	
	"	467644	"	"	
	"	488763	"	"	
	"	04I949	"	"	
	"	I4I929	"	"	
	"	I45483	F	"	
	"	4084	L	"	
	"	71600[illegible]84	F	"	
	"	5987[illegible]6	Mp	"	
	"	I726I0	F	""	
	Estero	96957	L	"	
	F.S.	I88083	F	carico	
	"	77I92024	"	"	
	"	381521	Hg	"	
	""	695I08	P	""	
	"	007I73	"	""	
	"	7670I20	"	"	
	"	650974	"	"	
	"	776455II	"	"	
	Estreo	22923	L	"	
	"	12150	"	""""	
	"	45980	"	"	
	"	45537	"	"	
	"	5313	"	"	
	"	26335	F	"	
	""	30394	"	"	
	F.S.	77696500	"	"	
	"	77695502	"	"	
	estero	32406	"	"	
	F.S.	3159I0	Hg	"	
	estero	33240	P	"	
	F.S.	7700II5	"	"	
	estero	I45 7	"	"	
	"	IIOI	"	"	
	"	47329	"	"	
	"	36779	"	"	
	F.S.	I72I46	"	"	
	"	IOII425	Ec	"	
	"	IOI4440	"	"	
	estero	35232	MW	"	
	F.S.	569023	Mv	"	

232

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
F O G G I A	F.S.	3994191	Hc	Carico	
	"	652784	P	"	
	"	62[illegible]686	"	"	
	"	645519	"	"	
	"	644716	"	"	
	"	7200140	F	"	
	"	66[illegible]	"	"	
	"	656386	"	"	
	"	7740183	P	"	
	"	[illegible]	"	"	
	estero	958	"	"	
	"	39165	"	Vuoto	
	F.S.	648106	"	"	
	"	457166	L	"	
	estero	[illegible]669	"	"	
	"	27448	"	"	
	"	138650	"	"	
	F.S.	1001278	Hc	"	
	"	260146	G	"	
	"	485080	L	"	
	"	477581	"	"	
	"	490304	"	"	
	"	1021154	"	"	
	"	1015092	"	"	
	"	1005207	E	"	
	"	1041475	E	"	
	"	7448032	L	"	
	"	1101110	F	"	
	"	130690	Fc	Carico	
	"	340314	L	vuoto	
	"	2005277	E	"	
	"	1005956	E	"	
	Estero	71517	L	"	
	F.S.	1007034	Lc	"	
	estero	13435	L	"	
	F.S.	340658	Hc	"	
	estero	23115	L	"	
	"	2004159	Fusa	"	
	F.S.	[illegible]			
	"	111157	F	"	
	"	46[illegible]	L	"	
	"	1119132	Fc	"	
	"	1008-50	L	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	646716	"	"	
"	7790148	F	"	
"	66 4[illegible]	"	"	
"	696986	"	"	
"	77 0185	"	"	
"	[illegible]	"	"	
estero	[illegible]	"	"	
"	35165	"	VV 60	
F.S.	648106	"	"	
"	457168	L	"	
estero	[illegible]	"	"	
"	27448	"	"	
"	133650	"	"	
F.S.	1901275	Fe	"	
"	26136	G	"	
"	885980	L	"	
"	327581	"	"	
"	493104	"	"	
"	1981156	"	"	
"	1015809	"	"	
"	1005207	E	"	
"	1031475	E	"	
"	7448034	L	"	
"	111110	F	"	
"	330696	Fe	esercito	
"	040374	L	vuoto	
"	1005277	E	"	
"	1025906	E	"	
Estero	71517	L	"	
F.S.	1007034	Fe	"	
estero	10439	L	"	
F.S.	346658	[illegible]	"	
estero	20315	L	"	
"	220259	Fase	"	
F.	[illegible]	F	"	
"	111157	L	"	
"	466536	Fe	"	
"	1018132	E	"	
"	1008459	Mc	"	
"	951242	F	"	
"	651944	"	"	
"	655168	"	"	
"	619513	"	"	
"	8 06864	VVer	"	
"	808221	Ver	"	
"	828053	"	"	
"	5670128	Mety	"	
"	6 8454	Ver	"	
"	808235	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
F O G G I A	F.S.	411660	L	rip.rando	
	Estero	111[illegible]8	E	"	
	"	49617	"	"	
	F.S.	184073	F	vuoto	
	estero	[illegible]05	G	rip rando	
	"	I 19138	"	"	
	F.S.	101021	Fc	"	
	estero	97094	"	"	
	F.S.	65468	F	"	
	"	808842	Vrz	"	
	estero	401108	"	"	
	F.S.	7810017	"	"	
	"	[illegible]601I	L	carico	
	estero	31127	"	"	
	F.S.	[illegible]			
	"	308697	Vz	"	
	"	[illegible]3489	Fc	"	
	"	[illegible]1944	"	"	
	"	[illegible]10017	Voz	"	
	"	[illegible]948			
	"	1003662	E	"	
	"	[illegible]45590	Fc	"	
	"	[illegible]29 972	"	"	
	"	[illegible]18378	"	"	
	"	645192	F	"	
	"	489389	L	"	
	"	463505	"	vuoto	
	"	042777	"	"	
	"	401616	"	"	
	"	456511	"	"	
	"	413689	"	"	
	estero	58174	"	"	
	F.S.	434720	"	"	
	"	[illegible]8348	"	carico	
	"	408939	"	"	
	"	[illegible]	Fc		
	"	[illegible]	[illegible]	[illegible]	
	"	[illegible]	xFx	"	
	[illegible]	[illegible]	[illegible]		
	estero	238222	L	vuoto	

221

Declassified E.O. 12356 Section 3.3/NND No. 785021

F O G G I A	F.S.	41[illegible]660	L	Ripe rando	
	Estero	1[illegible]18	E	"	
	"	4[illegible]617	"	"	
	F.S.	184[illegible]73	I	vuoto	
	estero	1[illegible]05	G	Ripe rando	
	"	I 19[illegible]3	"	"	
	F.S.	IC[illegible]1021	Bc	"	
	estero	97094	"	"	
	F.S.	6516 8	F	"	
	"	8[illegible]8842	Vrz	"	
	estero	401[illegible]08	"	"	
	F.S.	78IC[illegible]17	"	"	
	"	[illegible]6011	L	carico	
	estero	[illegible]127	"	"	
	F.S.	[illegible]			
	"	[illegible]6897	Vs	"	
	"	[illegible]13489	Fc	"	
	"	[illegible]944	"	"	
	"	[illegible]17	Vcz	"	
	"	[illegible]945			
	"	[illegible]1052	E	"	
	"	[illegible]5590	Fc	"	
	"	[illegible]9 972	"	"	
	"	[illegible]8378	"	"	
	"	[illegible]6192	F	"	
	"	[illegible]9389	L	"	
	"	[illegible]3505	"	vuoto	
	"	[illegible]777	"	"	
	"	[illegible]516	"	"	
	"	[illegible]	"	"	
	"	[illegible]689	"	"	
	estero	[illegible]74	"	"	
	F. .	[illegible]720	"	"	
	"	[illegible]348	"	carico	
	"	[illegible]939	"	"	
	"	[illegible]	Bc		
	"	[illegible]	[illegible]	[illegible]	
	"	[illegible]	[illegible]	"	
	[illegible]	[illegible]	[illegible]		
	estero	[illegible]8222	L	vuoto	
	F.S.	[illegible]5082	"	"	
	"	[illegible]4826	"	"	
	"	[illegible]02607	"	"	
	"	[illegible]2675	"	"	
	"	[illegible]738	"	"	
	estero	[illegible]4072	"	"	
	F. .	[illegible]0313	"	"	
	"	[illegible]4334	"	"	
	estero	[illegible]361	"	"	
	"	[illegible]0592	B	"	

221

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Foggia	P.C.	455 13	L	Grano	
	"	2[illegible]910	"	Vuoto	
	"	2[illegible]066	"	Grano	
	"	[illegible]427	"	"	
	"	7[illegible]473	"	"	
	"	7[illegible]075	"	"	
	"	2[illegible]743	"	"	
	"	[illegible]2814	"	"	
	"	[illegible]3	"	"	Candelaro
	"	[illegible]4 23	L	"	"
	"	[illegible]46	"	"	"
	"	[illegible]000	"	"	"
	"	[illegible]7491	"	"	"
	"	[illegible]3376	"	"	"
	"	[illegible]1936	"	"	"
	"	[illegible]3793	"	"	"
	"	[illegible]7[illegible]3	"	"	"
	"	[illegible]7[illegible]99	"	"	"
	"	[illegible]7[illegible]66	"	"	"
	"	[illegible]7[illegible]47	"	"	"
	"	[illegible]7[illegible]69	"	"	"
	"	[illegible]7[illegible]74	"	"	"
	Ferro	[illegible]7[illegible]74	"	"	"
	P.L.	[illegible]9[illegible]14	Ge	"	"
	"	[illegible]0[illegible]8	"	"	Lucera
	"	[illegible]1[illegible]793	"	"	Cicia Faro
	"	[illegible]0[illegible]876	"	"	"
	"	[illegible]0[illegible]98	"	"	"
	"	[illegible]0[illegible]934	"	"	"
	"	[illegible]0[illegible]46	"	"	"
	"	[illegible]2[illegible]779	"	"	"
	"	[illegible]7[illegible]700	"	"	Bari Dalo
	"	[illegible]7[illegible]977	"	"	Termoli
	"	[illegible]0[illegible]980	"	"	"
	"	[illegible]0[illegible]937	"	"	"
	"	[illegible]0[illegible]765	"	"	Adelfia
	"	[illegible]7[illegible]00	"	"	"
	"	[illegible]7[illegible]567	Fe	"	"
	"	[illegible]7[illegible]575	L	"	Molfetta
	"	[illegible]2[illegible]705	Ge	"	Incoronata
	"	[illegible]7[illegible]746	L	"	Barletta
	"	[illegible]4[illegible]470	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

0185

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi Marittima	estero	95465	aperto	carico	
	"	3473	"	Carico	carico
	"	200037	"	"	
	"	94883	"	vuoto	
	"	I5I67	"	vuoto	vuoto
	"	94880	"	carico	
	"	6948	"	"	
	"	5269I	"	"	
	"	I29380	"	"	
	"	67287	"	"	
Margherita di Savoia-FS		459311	L	vuoto	
	estero	23690	aperto	buono vuoto	"
Manfredonia	FSI	I676I5	F	"	
	"	I0I6743	"	carico	
	"	7779502I	"	"	
	estero	5843	L	"	
	FS	442927	"	"	
	"	458204	"	"	
	estero	4826	chiuso	"	
	"	75972	"	"	
	FS	400035	"	"	
	"	488299	"	"	
	"	496995	"	"	
	estero	5I534	L	vuoto	
	FS	455319	"	carico	
Incoronata	"	I004620	E	vuoto ripar.	
	"	408754	L	riparando	
	estero	94800	"	"	
	"	2144	"	"	
	FS	942I64	"	carico	
	"	747II00	"	"	
	"	48I7II	L	"	
	"	7448774	F	"	
	"	II32730	"	"	
	"	III5	"	"	
	"	II27799	"	"	
	"	I028504	"	"	
	"	I423	"	"	

239

Declassified E.O. 12356 Section 3.3/NND No. 785021

Brindisi Marittima	estero	93445	aperto	carico
	"	3423	"	Cerchio carico
	"	800037	"	vuoto
	"	94885	"	vuoto
	"	15167	"	carico
	"	94630	"	"
	"	6948	"	"
	"	67591	"	"
	"	129380	"	"
	"	67287	"	vuoto
Margherita di Savoia-FS		459311	L	buono vuoto
	estero	23690	aperto	" "
Manfredonia	FSI	167815	F	carico
	"	1016743	"	"
	"	7775509I	"	"
	estero	5643	L	"
	FS	442927	"	"
	"	458204	"	"
	estero	4826	chiuso	"
	"	75972	"	"
	FS	400035	"	"
	"	483299	"	"
	"	496995	"	"
	estero	51534	L	vuoto
	FS	455319	"	carico
Incoronata	"	1004620	E	vuoto ripar.
	"	408754	L	riparando
	estero	94800	"	"
	"	2144	"	"
	FS	042164	"	carico
	"	747I100	"	"
	"	48I711	L	"
	"	7443771	"	"
	"	II32730	"	"
	"	III5	"	"
	"	II27799	"	"
	"	1008504	"	"
	"	I423	"	"
	"	34992	"	"
	"	46I353	L	"
	"	I003573	"E	"
	"	I7089I	F	"
	"	484304	L	"
	"	49531?	"	"
RIO NERO	FS	I36108	Fc	vuoto
	estero	55570	aperto	"
	FS	482567	L	carico
	estero	I8667	"	"

239

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
RIONERO	FS	459654	L	carico	
	"	472408	"	"	
	"	408375	"	"	
	"	489190	"	"	
Acquaviva delle F.	"	14976	F	vuoto	
Potenza Superiore	"	I15977	F	"	
	"	I027527	E	riparando	
	"	[illegible]	Fec		
Palagiano M.	"	[illegible]	L	vuoto	
	"	[illegible]	"	"	
	"	7400523	L	riparando	
	"	476577	"	"	
	estero	25469	"	"	
Rocchetta S. Antonio-FS	"	I22323	F	carico	
	"	260528	G	"	
	"	II28I76	F	"	
	"	476526	L	"	
	"	465558	"	"	
	"	486232	"	"	
	"	458060	"	"	
	"	77493012	"	"	
	"	437355	"	"	
	"	14I045	Fi	"	
	"	III6995	E	"	
Giovinazzo	"	47III0	L	carico	
	"	497126	"	"	
	"	415895	"	"	
	"	485332	"	"	
	"	4I9715	"	"	
	"	251923	"	"	
	"	468547	"	"	
	"	I5I248	F	"	
	"	480160	L	"	
	estero	7697I	L	"	
	"	40992	"	"	
	"	243			
	"	183060	F	"	
	"	180830	"	"	
	"	1135764	"	"	
	"	III523	"	"	
	"	7107333	"	"	

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

	"	439199	"	"	
	"	I4976	F	vuoto	
Acquaviva delle F.	"	I15977	F	"	
Potenza Superiore	"	I027527	E	riparando	
	"	[illegible]	Fec		
	"	[illegible]	L	vuoto	
Palagiano M.	"	[illegible]	"	"	
	"	7400525	I	riparando	
	"	476577	"	"	
	estero	25469	"	"	
Rocchetta S. Antonio-FS	"	I22523	F	carico	
	"	260528	G	"	
	"	II28176	F	"	
	"	475526	L	"	
	"	465558	"	"	
	"	486232	"	"	
	"	452060	"	"	
	"	774930I2	"	"	
	"	437355	"	"	
	"	141045	Fi	"	
	"	III6993	E	"	
Giovinazzo	"	47III0	L	carico	
	"	497I26	"	"	
	"	415895	"	"	
	"	485332	"	"	
	"	4I97I5	"	"	
	"	251923	"	"	
	"	468347	"	"	
	"	I3I248	F	"	
	"	490I60	E	"	
	estero	7657I	L	"	
	"	4D982	"	"	
	"	243	"	"	
	"	I83060	F	"	
	"	I80030	"	"	
	"	1135764	"	"	
	"	III523	"	"	
	"	7107955	"	"	
	"	III73I6	"	"	
	"	1005087	"	"	
	"	I45078	"	"	
	"	I3I8I4	"	"	
	"	I32661	"	"	
	"	1007886	"	"	
	"	I85025	"	"	
	"	I02I999	"	"	
	"	I028II6	"	"	
	estero	8405	"	"	
	FS	I87689	"	"	
	"	8I002I	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	F.S.	I83001	Fc	carico	
	Estero	190436	F	"	
	F.S.	I56586	"	"	
	"	I001381	"	"	
	estero	83778	F	"	
	F.S.	475774	L	vuoto	
	"	77432014	"	"	
	estero	20283	"	"	
	F.S.	7475736	"	"	
	"	460227	"	"	
	"	47[illegible]51	"	"	
	estero	3[illegible]39	"	"	
	F.S.	45[illegible]377	"	"	
	"	497140	"	"	
	"	415565	"	"	
	"	41I061	"	"	
	"	499356	"	"	
	"	7492[illegible]60	"	"	
ORTONA	"	183827	"	carico	
	"	I0II800	Fc	"	
	"	III4363	F	"	
	"	7901622	M	"	
	"	7903670	"	"	
	"	7902831	"	"	
	"	950I09	"	"	
	"	920264	"	"	
	"	950I89	"	"	
	"	7I00735	"	"	
	"	44498I	P	"	
	"	661677	"	vuoto	
	estero	939638	"	"	
	"	7749048	L	carico	
	estero	3571O	"	"	
	"	4469I	"	"	
	F.S.	48I98	"	vuoto	
	"	479795	"	"	
	"	4I3505	"	"	
	"	462[illegible]2X	"	"	
	"	462427	"	"	

229

Declassified E.O. 12356 Section 3.3/NND No. 785021

FOGGIA	F.S.	I8300I	Fc	carico	
	Estero	I90436	F	"	
	F.S.	I96586	"	"	
	"	IC0I38I	E	"	
	estero	83778	F	"	
	F.S.	475774	L	vuoto	
	"	774320I4	"	"	
	estero	20283	"	"	
	F.S.	7457736	"	"	
	"	460287	"	"	
	"	47I15I	"	"	
	estero	31950	"	"	
	F.S.	45I377	"	"	
	"	497I40	"	"	
	"	415965	"	"	
	"	42I06I	"	"	
	"	499356	"	"	
	"	7402460	"	"	
	"	183827	"	carico	
ORTONA	"	30II800	Dc	"	
	"	VIII4363	F	"	
	"	7902622	M	"	
	"	7902870	"	"	
	"	7902831	"	"	
	"	950I09	"	"	
	"	920264	"	"	
	"	950I09	"	"	
	"	7I00735	"	"	
	"	444981	P	"	
	"	661677	"	vuoto	
	estero	939638	"	"	
	"	7749048	L	carico	
	estero	357I0	"	"	
	"	4469I	"	"	
	F.S.	48I98	"	vuoto	
	"	479795	"	"	
	"	4I4505	"	"	
	"	48xx2x	"	"	
	"	462427	"	"	
	"	I0I0777	"	"	
	"	I906I4	E	"	
	estero	595I2	F	"	
	F.S.	494I0I	L	carico	
	estero	9I595	"	"	
	F.S.	7270I04	G	"	
	"	4453I3	L	"	
	"	495I53	"	"	
	estero	29947	F	"	
	F.S.	48604I	L	"	

229

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
ORTONA	F.S.	486041	L	vuoto	
	"	419410	"	"	
	"	469926	"	"	
	"	201076	G	carico	
	estero	I36 I	[illegible]	vuoto	
	"	276193	"	"	
	F.S.	I88674	"	"	
	estero	II942	"	vuoto	
	F.S.	181028	"	"	
	"	252017	"	"	
	"	II26140	"	"	
	"	186456	"	"	
	"	4104036	Ec	"	
	"	I6II4	F	"	
	"	II24106	"	"	
	"	II20189	"	"	
	"	427205	L	"	
	"	I003157	E	"	
	estero	38331	L	"	
	"	56100	F	"	
	F.S.	484970	"	"	
	"	I90882	"	"	
	estero	7883I	F	"	
	F.S.	645440	"	"	
	"	651964	"	vuoto	
	"	646896	"	"	
	"	7109597	F	carico	
	estero	I3835	"	"	
	"	547I9	"	"	
	F.S.	443108	L	"	
	"	408347	"	"	
	"	492I26	"	"	
	estero	II719	"	"	
	"	33535	"	"	
	F.S.	I43I8I	"	vuoto	
	"	II096I	Fi	"	
	"I	I60075	Fc	"	
	"	II4717	"	"	
	"	I8I862	Fi	"	
	"	260351	Gc	"	
	"	I001076	Ec	"	
	"	39I539	Hc	"	
	"	652I79	P	carico	
	"	6[illegible]	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

estero	I36 I	I	vuoto	
"	276193	"	"	
F.S.	I88674	"	"	
estero	II942	"	vuoto	
F.S.	181028	"	"	
"	252017	"	"	
"	II26140	"	"	
"	186456	"	"	
"	4104036	Ec	"	
"	I6II4	F	"	
"	II24I06	"	"	
"	II20I89	"	"	
"	427205	E	"	
"	I003I57	E	"	
estero	58351	L	"	
"	56109	F	"	
F.S.	484970	"	"	
"	I90882	"	"	
estero	7883I	F	"	
F.S.	545440	"	"	
"	651964	"	vuoto	
"	646896	"	"	
"	7109597	F	carico	
estero	I3635	"	"	
"	547I9	"	"	
F.S.	443I0IG	L	"	
"	408347	"	"	
"	492I26	"	"	
estero	II719	"	"	
"4	33535	"	"	
F.S.	I43I8I	"	vuoto	
"	II096I	Fi	"	
"I	I60075	Fc	"	
"	II4717	"	"	
"	I8I862	Fi	"	
"	260351	Gc	"	
"	I001076	Ec	"	
"	391539	HC	"	
"	652I79	P	carico	
"	657329	"	"	
"	657585	"	"	
estero	4222	"	"	
F.S.	645204	"	"	
"	470836	L	"	
estero	4549I	F	"	
F.S.	II2739	Fc	"	
"	I005043	Ec	vuoto	
"	I2III8	Fc	carico	
"	III874	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
GIOVINAZZO	FS	1014408	E	CARICO	
	"	302083	O	"	
	"	I087337	F	"	
	"	I0086342	"	"	
	"	II33702	"	"	
	"	170869	"	"	
	"	I008700	"	"	
	"	260I05	"	"	
	"	I28786	"	"	
	"	7I06047	"	"	
	estero	5945	"	"	
	FS	I024506	"	"	
	"	7719502	"	"	
	"	I009498	"	"	
	"	I024324	"	"	
	"	I029310	"	"	
	"	I0275I0	"	"	
	"	I0I6509	"	"	
	"	II9335	"	"	
	"	I74424	"	"	
	"	II28I33	"	"	
	"	I020453	"	"	
	"	464435	"	"	
	"	I0I6520	"	"	
	"	252318	"	"	
	"	I007885	"	"	
	"	I90018	"	"	
	"	I004200	"	"	
	"	I007814	"	"	
	estero	36835	"	"	
	"	39220	"	"	
	FS	407360	"	"	
	"	420401	"	"	
	"	40395	"	"	
	estero	15835	"	"	
	FS	I004210	"	"	
	"	I007804	"	"	
	estero	35835	"	"	
	"	28239	"	"	

228

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

GIOVINAZZO	FS	1024608	E	Carloo	
	"	002083	"	"	
	"	I087357	"	"	
	"	I006342	"	"	
	"	II55702	"	"	
	"	I70569	"	"	
	"	I008700	"	"	
	"	200105	"	"	
	"	I28785	"	"	
	"	7I06047	"	"	
	estero	5645	"	"	
	FS	I024506	"	"	
	"	7710502	"	"	
	"	I009498	"	"	
	"	1024324	"	"	
	"	I029310	"	"	
	"	I027510	"	"	
	"	I016609	"	"	
	"	II9336	"	"	
	"	I74424	"	"	
	"	II28138	"	"	
	"	1620453	"	"	
	"	464493	"	"	
	"	I0I5520	"	"	
	"	252318	"	"	
	"	I007885	"	"	
	"	I90015	"	"	
	"	I004200	"	"	
	"	I007814	"	"	
	estEro	36835	"	"	
	"	29220	"	"	
	FS	407360	"	"	
	"	410402	"	"	
	"	40395	"	"	
	estEro	15835	"	"	
	FS	I004210	"	"	
	"	I007804	"	"	
	estero	35835	"	"	
	"	28729	"	"	
	FS	407360	"	"	
	"	455401	"	"	
	"	II0393	"	"	
	estefo	I9835	"	"	
	FS	604374	"	"	
	"	654943	"	"	
	"	752923	"	"	
	"	646749	"	"	
	"	5I4I49	"	"	
	"	568I25	"	"	
	"	569402	"	"	

228

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
GIOVINAZZO	FS	7749008	F	carico	
	"	4IIII5	L	"	
	estero	II845	"	"	
	"	3056	"	"	
	"	I052I	"	"	
	estero	308820	Ma	"	
	"	50025I	"	"	
	"	I001920	Do	"	
	"	3I873I	Ma	"	
	"	I0I4624	F	"	
	"	I20190	"	"	
	"	432944	L	"	
	"	203842	G	"	
	"	7406548	"	"	
	"	485383	L	"	
	"	420336	"	"	
	"	445759	"	"	
	"	477831	"	"	
	"	413544	"	"	
	"	4I0203	"	"	
	estero	I886I	"	"	
	FS	458294	"	"	
	"	465999	"	"	
	estero	22683	"	"	
	FS	468409	"	"	
	"	45II55	"	"	
	"	4I7228	"	"	
	"	409167	"	"	
	estero	I9404	"	"	
	FS	490525	"	"	
	"	480II4	"	"	
	"	457I44	"	"	
	"	I3973	"	"	
	"	77I92037	"	"	
	"	307763	HG	"	
	"	390659	"	"	
	"	I005274	"	"	
	"	300363	"	"	
	"	656987	"	"	
	"	645208	"	"	
	"	648109	"	"	
	"	644566	"	"	
	"	647253	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Giovinazzo	FS	474183	L	carico	
	"	653143	P	"	
	"	477771	L	"	
	"	429447	"	"	
	"	413050	"	"	
	"	407523	"	"	
	estero	13326	"	"	
	FS	161972	"	"	
	"	652072	P	"	
	"	654933	"	"	
	estero	67342	"	"	
	FS	77 9826	R	"	
	"	114157	P	"	
	"	624763	P	"	
	"	652141	"	"	
	"	740I724	"	"	
	"	662259	"	"	
	"	401006	"	"	
	"	756035	P	"	
	estero	69770	"	"	
	FS	53116	"	P	
	"	I32603	"	"	
	"	131430	"	"	
	estero	8708	"	"	
	FS	456082	L	"	
	"	7403415	"	"	
	"	1000708	"	"	
	"	476664	"	"	
	"	780I462	"	"	
	"	123949	"	"	
	estero	67680	"	"	
	FS	109161I	"	"	
	"	702077	"	"	
	"	764608	"	"	
	"	7749330 35	"	"	
	estero	4482	"	"	
	FS	466711	L	"	
	estero	51702	"	P	
	FS	644116	P	"	

227

Declassified E.O. 12356 Section 3.3/NND No. 785021

Cicria	P.C.	471165	L	Chicago
	"	553743	P	"
	"	477171	L	"
	"	470447	"	"
	"	433050	"	"
	"	497525	"	"
	estero	45126	"	"
	FS	761772	"	"
	"	662072	P	"
	"	558953	"	"
	estero	85542	"	"
	FS	771 9826	R	"
	"	771197	P	"
	"	624763	P	"
	"	652141	P.	"
	"	748I724	L	"
	"	488259	"	"
	"	401006	"	"
	"	756033	P	"
	estero	69770	"	"
	"	53116	"	P
	FS	132603	"	"
	"	131430	"	"
	estero	8778	"	"
	FS	465082	T.	"
	"	7405415	"	"
	"	1000709	"	"
	"	476564	"	"
	"	740I468	"	"
	"	123949	"	"
	estero	87620	"	"
	FS	109161	"	"
	"	1023077	"	"
	"	764608	"	"
	"	7749330035	"	"
	estero	482	"	I
	FS	466711	I	"
	estero	51702	"	P
	FS	644116	P	"
	"	660888	"	"
	"	646473	"	"
	"	7408707	"	"
	"	402679	L	"
	"	1030079	E	P
	estero	9080	"	"
	"	1043I9	"	"
	"	1910974	"	"
	"	1006993	"	"
	"	102II98	"	"
	"	400240	"	"

227

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Giovinazzo	estero	400240	L	carico	
	"	I478I	"	"	
	IS	276592	C	"	
	"	476243	L	"	
	"	473484	"	"	
	"	463488	"	"	
	"	411442	"	"	
	"	434317	"	"	
	"	481105	"	"	
	"	356460	"	"	
	estero	58703	P	vuoto	
	"	29526	"	"	
	"	3619	"	"	
	FS	646684	P	"	
	"	655521	"	"	
	estero	83691	P	"	
	FS	647672	"	"	
	"	651632	"	"	
	"	654144	"	"	
	"	523211	"	"	
	"	651214	"	"	
	"	652327	"	"	
	"	654172	"	"	
	"	524372	"	"	
	estero	20878	"	"	
	"	20881	"	"	
	FS	498883	L	"	
	"	542352	"	"	
Lebba	FS	661413	P	riparando	
	"	620860	"	vuoto	
	"	650982	"	"	
	"	654857	"	"	
	"	658869	"	"	
	"	620589	"	riparando	
	"	651107	"	vuoto	
	"	622146	"	riparando	
	"	650911	"	"	
	"	653720	"	"	
	"	622169	"	carico	
	"	623125	"	"	
	"	640413	"	"	
	"	623681	"	"	
	"	650173	"	"	
	"	623503	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	173454	"	"
	"	463933	"	"
	"	II1446	"	"
	"	431313	"	"
	"	481103	"	"
	"	359460	"	"
	esterno	68703	P	vuoto
	"	29526	"	"
	"	3619	"	"
	FS	045684	P	"
	"	553521	"	"
	esterno	83691	"	"
	FS	647672	"	"
	"	651632	"	"
	"	651144	"	"
	"	623071	"	"
	"	651214	"	"
	"	652327	"	"
	"	654172	"	"
	"	624372	"	"
	esterno	20678	"	"
	"	20981	"	"
	FS	498865	L	"
L E B B A	"	454252	"	"
	FS	661418	I	rigarando
	"	620360	"	vuoto
	"	650962	"	"
	"	654857	"	"
	"	658669	"	"
	"	620580	"	riparando
	"	651107	"	vuoto
	"	622146	"	riparando
	"	650911	"	"
	"	653720	"	"
	"	622168	"	carico
	"	623125	"	"
	"	640413	"	"
	"	623[illegible]81	"	"
	"	650173	"	"
	"	623505	"	"
	"	654321	"	"
S q u i n z a n o	FS	I02037	I	riparando
	"	I56511	"	"
	"	7I70183	"	"
	"	I59821	"	"
	"	I50670	"	"
	"	I79643	"	"
	"	IOI9040	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Squinzano	FS	I0I9040	E	riparando	
	"	I7I625	F	"	
	"	III5I9	"	"	
	"	I8[illegible]850	"	"	
	"	351369	Hg	"	
	"	346227	"	"	
	"	251655	G	"	
	"	203687	"	"	
	"	251995	"	"	
	"	I00I326	E	"	
	estero	I40I3	F	"	
	"	37998	"	"	
	"	2566	"	"	
	"	46715	"	"	
	"	I89II	"	"	
	F.S.	4I985	L	"	
	"	366332	Hg	"	
	"	464213	L	"	
	"	451312	"	"	
	"	043502	"	"	
	"	490679	"	"	
	"	463048	"	"	
	"	47II87	"	"	
	"	04III9	"	"	
	"	477I58	"	"	
	"	466I97	"	"	
	"	478661	"	"	
	"	413660	"	"	
	"	401695	"	"	
	"	652790	P	"	
	"	692407	"	"	
	"	605001	"	"	
	"	590213	Mv	"	
	"	9582093	Mc	"	
	"	582806	"	"	
	"	524563	"	"	
	"	5I4448	"	"	
	"	54I80I	"	"	
Montenero Petacciato	"	7448013	E	carico	
	estero	40788	"	"	

226

Declassified E.O. 12356 Section 3.3/NND No. 785021

Squinzano	FS	IOI9040	E	riparando	
	"	I7I625	F	"	
	"	III5I9	"	"	
	"	I83850	"	"	
	"	351369	Hg	"	
	"	346227	"	"	
	"	251655	G	"	
	"	203687	"	"	
	"	251995	"	"	
	"	I00I826	E	"	
	estero	I40I3	"	"	
	"	37998	"	"	
	"	2566	"	"	
	"	46715	"	"	
	"	I89II	"	"	
	F.S.	41965	L	"	
	"	366352	Hg	"	
	"	464213	L	"	
	"	451312	"	"	
	"	043502	"	"	
	"	490679	"	"	
	"	463048	"	"	
	"	471187	"	"	
	"	041II9	"	"	
	"	477158	"	"	
	"	466197	"	"	
	"	478661	"	"	
	"	413860	"	"	
	"	401695	"	"	
	"	652790	P	"	
	"	692407	"	"	
	"	695001	"	"	
	"	590213	Mv	"	
	"	9582093	Mc	"	
	"	582806	"	"	
	"	524563	"	"	
	"	5I4448	"	"	
	"	54I80I	"	"	
Montenero Petacciato	"	7448013	E	carico	
	estero	40788	"	"	
	"	20780	"	"	
	"	93II3	"	"	
	"	46122	"	"	
	"	24030	"	"	
	FS	472365	L	"	
	"	470097	"	"	
	"	4429I0	"	"	
	estero	32545	"	"	
	"	32325	"	"	
	FS	4I25I4	L	"	

226

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Montenero Petacciato	FS	410340	L	carico	
	"	413392	"	"	
	"	481893	"	"	
	estero	I342	"	"	
	FS	472807	"	"	
	"	499384	"	"	
	"	456518	"	"	
	"	479658	"	"	
	"	471508	"	"	
	estero	25999	"	"	
	FS	474256	"	"	
	estero	41255	"	"	
	FS	411022	"	"	
	estero	20797	"	"	
	FS	477355	"	"	
BARLETTA	FS	459506	L	"	
	"	478934	"	"	
	"	650558	P	"	
	"	623559	"	"	
	"	623117	"	"	
	"	650101	"	"	
	estero	8261 2	"	"	
	FS	7402648	E	"	
	"	771930 10	"	"	
	"	650027	P	"	
	"	553989	"	"	
	"	480587	L	"	
	Privato	1	"	"	
	FS	490391	"	"	
	"	460067	"	"	
	estero	70449	"	"	
	FS	478187	L	"	
	"	484117	"	"	
	"	7470583	"	"	
	"	747I046	"	"	
	"	410604	"	"	
	"	418864	"	"	
	"	469338	"	"	
	"	490998	"	"	
	"	472273	"	"	
	estero	I4902	"	"	
	"	I8942	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	estero	I342	"	"
	FS	472007	"	"
	"	499384	"	"
	"	456516	"	"
	"	479053	"	"
	"	471508	"	"
	estero	25999	"	"
	FS	474256	"	"
	estero	41255	"	"
	FS	411022	"	"
	estero	20797	"	"
	FS	477355	"	"
BARLETTA	FS	459506	L	"
	"	478934	"	"
	"	650558	P	"
	"	623559	"	"
	"	623117	"	"
	"	650101	"	"
	estero	82812	"	"
	FS	7402648	L	"
	"	771930101	"	"
	"	650027	P	"
	"	653989	"	"
	"	480587	L	"
	Privato	1	"	"
	FS	490391	"	"
	"	460067	"	"
	estero	70449	"	"
	FS	478187	L	"
	"	184117	"	"
	"	7470583	"	"
	"	747I046	"	"
	"	10604	"	"
	"	418864	"	"
	"	469338	"	"
	"	490998	"	"
	"	472273	"	"
	estero	I4902	"	"
	"	I8942	"	"
	FS	474343	"	"
	"	470852	"	"
	"	452745	"	"
	"	405562	"	"
	estero	I6806	"	"
	FS	468745	"	"
	"	411441	"	"
	"	477554	"	"
	"	483986	"	"
	"	446715	"	"
	"	7470888	"	"
	"	I026359	"	"
	"	I005106	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del ~~24~~ Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BRINDISI	estero	I708504	F	carico	
	FS	I003557	F	"	
	"	I00766	"	"	
	"	I031485	"	vuoto	
	"	654246	I	carico	
	estero	I4679	L	vuoto	
	FS	932344	P	"	
	"	I41604	Fl	"	
	"	478669	L	"	
	estero	3179	P	"	
	FS	77066?7	Q	"	
	estero	2604	P	"	
	"	49953	F	carico	
	"	69I6I	"	"	
	"	75201	"	"	
	~~FS~~	654908	"	"	
	estero	38734	G	"	
	FS	I0II215	P	"	
	"	560807	IV	vuoto	
	"	2196II7	L	carico	
	"	416851	"	"	
	"	48I934	"	"	
	estero	91756	"	"	
	FS	406146	"	"	
	"	654680	F	vuoto	
	"	412583	L	carico	
	"	653664	P	"	
	"	670359	"	carico	
	estero	21649	"	vuoto	
	FS	412425	L	carico	
	"	7470484	L	vuoto	
	estero	92780	"	"	
	"	35600	"	"	
	FS	491773	"	"	
	"	417159	"	carico	
	"	460438	"	"	
	"	410890	"	"	
	"	434796	"	"	

225

0206
Declassified E.O. 12356 Section 3.3/NND No. 785021

B R I N D I S I	estero	I708504	F	carico		
	FS	I003557	F	"		
	"	I00766	"	"		
	"	I03148 5	"	vuoto		
	"	654246	F	carico		
	estero	I4679	L	vuoto		
	FS	332344	LP	"		
	"	I41604	FL	"		
	"	478669	L	"		
	estero	1119	F	"		
	FS	7700237	Q	"		
	estero	2667	P	"		
	"	49053	F	carico		
	"	69161	"	"		
	"	75201	"	"		
	"	654908	"	"		
	estero	38734	G	"		
	FS	I01I215	F	"		
	"	560807	LV	vuoto		
	"	2106II7	L	carico		
	"	4I6851	"	"		
	"	482934	"	"		
	estero	91756	"	"		
	FS	406146	"	"		
	"	654680	F	vuoto		
	"	41-583	L	carico		
	"	653664	F	"		
	"	650359	"	carico		
	estero	2a40	"	vuoto		
	FS	412425	L	carico		
	"	7470484	L	vuoto		
	estero	92760	"	"		
	"	5600	"	"		
	FS	491773	"	"		
	"	417159	"	carico		
	"	460438	"	"		
	"	410890	"	"		
	"	484196	"	"		
	"	493559	"	"		
	"	415993	"	"		
	"	411771	"	"		
	"	4I0I60	"	"		
	"	7471285	"	vuoto		
	estero	20154	"	carico		
	FS	7404619	"	"		
	"	III4156	Fc	"	Lecce	
	"	I000404	E	"	"	
	"	200210	G	"		
	"	I34009	F	carico		

22 cr

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONI
BRINDISI	FS	7719290	F	carico	
	"	I000560	"	"	
	"	IOI4435	E	"	
	"	I88393	Pi	"	Puglie
	estero	23640	"	"	"
	FS	471914	L	vuoto	
	estero	26588	F	"	
	FS	I003228	E	"	
	"	I4I426	P	"	
	"	11[illegible]194	F	"	
	"	I0I9032	E	"	
	"	IIII4985	F	"	
	"	I92776	E	"	
	"	575469	F	"	
	"	II3545	F	"	
	"	III4152	"	"	
	"	II5583	"	"	
	"	I0029[illegible]4	F	"	
	USA	222703	"	"	
	estero	2154	"	"	
	FS	7I7[illegible]324	"	"	
	estero	35790	"	"	
	FS	115634	"	"	
	"	196164	"	"	
	"	I00084	F	"	
	"	493497	L	"	
	"	I34609	F	"	
	"	I63164	"	"	
	"	4I7434	L	"	
	estero	I9I5	F	"	
	FS	III[illegible]094	Fc	"	
	estero	5228	L	"	
	FS	I7[illegible]71	F	"	
	"	I04	E	carico	
	"	I0I48I3	F	"	
	"	II8935	F	"	
	"	I02145	E	"	
	"	I[illegible]00639	"	"	
	"	I027II5	E	"	
	"	232534	G	"	
	"	201056	"	vuoto	
	"	I57988	F	carico	
	estero	20653	G	vuoto	
	"	3012	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0209

Declassified E.O. 12356 Section 3.3/NND No. 785021



FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BRINDISI	FS	I72234	F	carico	
	"	I82486	"	"	
	"	I023219	E	"	
	"	409303	L	"	
	"	479184	"	"	
	estero	I5732	"	"	
	FS	I026307	E	"	
	"	I59843	F	"	
	"	I000043	E	"	
	"	7404717	"	"	
	"	I009338	"	"	
	"	464857	L	"	
	"	647186	F	"	
	"	652193	"	vuoto	
	estero	25506	L	"	
	FS	548313	NV	"	
	"	508157	"	"	
	"	I000651	E	carico	
	"	I003320	E	"	
	estero	361270	L	"	
	"	24576	G	"	
	FS	I009855	E	"	
	"	499376	L	"	
	"	402807	L	"	
	"	419617	"	"	
	"	477219	"	"	
	"	404354	"	"	
	"	404778	"	"	
	"	444788	"	"	
	estero	I4261	"	"	
	FS	III9538	F	"	
	"	I025759	F	"	
	estero	34088	"	"	
	FS	I008471	F	"	
	estero	97717	"	"	
	"	I26660	"	"	
	"	23307	"	"	
	"	48924	"	"	
	FS	I44997	"	"	

224

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

BRINDISI	FS	17134	E	"
	"	I82486	"	"
	"	I023219	E	"
	"	408303	L	"
	"	479184	"	"
	estero	I5732	"	"
	FS	I026307	E	"
	"	I59843	F	"
	"	I000043	E	"
	"	7404717	"	"
	"	I009338	"	"
	"	464857	L	"
	"	647186	P	"
	"	652193	"	vuoto
	estero	25506	L	"
	FS	548313	MV	
	"	508157	"	"
	"	I000651	E	carico
	"	I003320	E	"
	estero	361270	L	"
	"	24576	G	"
	FS	I009855	E	"
	"	499376	L	"
	"	402807	L	"
	"	419617	"	"
	"	477219	"	"
	"	404354	"	"
	"	404778	"	"
	"	444788	"	"
	estero	I4261	"	"
	FS	III9538	F	"
	"	I025759	F	"
	estero	3408	"	"
	FS	I008471	E	"
	estero	97717	"	"
	"	I26660	"	"
	"	23307	"	"
	"	48924	"	"
	FS	II4997	"	"
	"	I007I32	F	"
	"	650757	P	"
	"	I00395	F	" Lecce
	"	567017	Mi	vuoto "
	"	I026965	E	vuoto
	estero	20958	G	"
	FS	I50I0I	Fc	"
	estero	I3529	P	carico
	"	3613	POS	"
	"	I57159	"	"
	"	7692	"	"
	FS	77696005	P	"

224

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B R I N D I S I	FS	541485	Mv	vuoto	
	"	568176	"	"	
	"	508135	"	"	
	"	597404	"	"	
	"	9530083	Ma	"	
	"	953239	"	"	
	"	530753	"	"	
	"	9570352	Mpr	"	
	estero	840010	Mo	"	
	FS	942539	"	"	
	"	55I? 52	"	"	
	"	981337	Mp	"	
	"	599868	Mo	"	
	"	534668	Mop	"	
	"	598726	MPR	"	
	"	568213	Mo	"	
	"	528213	"	"	
	"	IOII4[illegible]80	E	"	
	"	I4I60 6	Fi	"	
	"	952001?	M	"	
	"	654089	P	riparando	
	"	645540	"	"	
	"	91762	Q	"	
	"	9988I7	Mo	vuoto	
	estero	I8867	P	"	
	FS	77695500	"	"	
	"	670002	"	"	
	estero	39465	"	"	
	FS	I007977	E	"	
	"	I02I885	E	carico	
	"	I009818	F	vuoto	
	estero	I34[illegible]7	F	carico	
	"	67573	"	"	
	F.S.	771930I?	"	"	
	Estero	7962	"	"	
	F.S.	I02II0I	"	"	
	"	II2I910	"	"	
	"	I002526	"	"	
	"	I024351	"	"	
	Estero	I0533	G	"	
	F.S.	I9585	F	"	
	"	I8I470	"	"	
	"	I28505	"	"	
	"	I00602	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	953239	"	"
	"	530753	"	"
	"	9570352	Mpr	"
	estero	840010	Mo	"
	FS	942539	"	"
	"	55I2 52	"	"
	"	98I337	Mp	"
	"	599368	Mo	"
	"	534668	Mcp	"
	"	598726	MPR	"
	"	5682I3	Mo	"
	"	5282I3	"	"
	"	I0II4280	E	"
	"	I4I60 6	Fi	"
	"	9520019	M	"
	"	654089	P	riparando
	"	645540	"	"
	"	9I762	Q	"
	"	998817	Mo	vuoto
	estero	I8867	P	"
	FS	77695500	"	"
	"	670092	"	"
	estero	39465	"	"
	FS	I007977	E	"
	"	I02I885	E	carico
	"	I009818	F	vuoto
	estero	I3407	F	carico
	"	67673	"	"
	F.S.	7719301I	"	"
	Estero	7962	"	"
	F.S.	I02II0I	"	"
	"	II2I9I0	"	"
	"	I002526	"	"
	"	I024351	"	"
	Estero	I0533	G	"
	F.S.	I9585	F	"
	"	I8I470	"	"
	"	I28505	"	"
	"	I00602	"	"
	"	I23I69	"	"
	"	50I258	Ma	vuoto
	"	I008808	Ec	"
	"	I028327	E	"
	"	I4388I0	"	"
	"	II35?2I	Fc	"
	"	468015	L	"
	"	408I29	"	"
	"	698447	P.O.S.	"
	Estero	2592	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Orta Nova	FS	101742	E	ripar.	
	"	7170385	F	"	
	"	1138535	F	"	
	"	493549	L	"	
Trinitapoli	"	807358	grù	carico	
	"	681996	P	"	
	estero	8211	"	"	
	FS	38698	P	"	
	"	652793	P	vuoto	
	"	456021	L	"	
	francese	15544	L	"	
	FS	1118358	F	"	
	"	1126551	F	"	
	"	7104305	F	"	
	"	ZRRI027507	F	"	
	"	1009856	E	ripar.	
	"	1008126	F	"	
	DR	77368	"	"	
	"	9396	F	carico	
	"	77002	P	"	
	FS	645835	P	"	
	"	648334	P	"	
	DR	48193	P	"	
	FS	657115	P	"	
	"	657578	P	"	
	"	516015	MV	vuoto	
S.Vito Norm.	"	645293	P	ripar.	
	"	476325	L	"	
	"	7102103	F	"	
	"	650718	F	"	
	"	165834	F	"	
	"	145008	F	"	
	"	181049	F	"	
	"	118920	F	"	
	"	7701176	L	"	
	estero	20977	F	"	
	FS	112182	G	"	
	"	252070	L	"	
	"	486758		"	

223

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

Orta Nova	FS	101742	E	ripar.	
	"	7I70385	F	"	
	"	I132535	F	"	
	"	433549	L	"	
Trinitapoli	"	807358	grù	carico	
	"	631986	P	"	
	cattaro	821I	P	"	
	FS	38698	P	"	
	"	652793	P	vuoto	
	"	456021	L	"	
	francese	I5544	L	"	
	FS	1116398	F	"	
	"	I126551	F	"	
	"	7104305	F	"	
	"	1001027307	F	"	
	"	I009856	L	ripar.	
	"	I008126	L	"	
	BR	77368	F	"	
	"	9396	"	"	
	"	77002	P	carico	
	FS	645235	P	"	
	"	648334	P	"	
	BR	48493	P	"	
	FS	657115	P	"	
	"	657578	P	"	
	"	516015	MV	vuoto	
S.Vito Norm.	"	645293	P	ripar.	
	"	476325	L	"	
	"	7I02103	F	"	
	"	657718	F	"	
	"	I65834	F	"	
	"	I45008	F	"	
	"	I81049	F	"	
	"	I18920	F	"	
	"	7I6II76	F	"	
	cattaro	20977	L	"	
	FS	112I82	F	"	
	"	252076	G	"	
	"	466497	L	"	
	"	468335	L	"	
	"	7479936	L	"	
	"	5670III	R	"	
	"	479878	F	"	
	"	661486	F	"	
	"	132420	L	"	
	"	I13978	L	"	
	"	7I0II76	L	"	
	"	466850	L	"	
	"	477273	L	"	
	"	476714	L	"	

223

Declassified E.O. 12356 Section 3.3/NND No. 785021

0216

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
S.Vito Nova.	FS	11920	F	vuoto.	
	assegno	71211176	F	"	
	25	20977	L	"	
		11-9315	F	"	
		52070	G	"	
		465747	E	"	
		469335	L	"	
		7470936	L	"	
		3670111	M	"	
		475883	L	"	
		651486	P	"	
		1124430	F	"	
		1123578	F	"	
		466850	L	"	
		477273	L	"	
		4727714	L	"	
		7469147	MA	vuoto	
		350557	"	"	
		3046005	"	"	
		581509	MO	"	
		9827158	"	"	
		7500834	G	"	
		9813217	MO	"	
		953364	L	"	
		203585	G	"	
		4941147	L	"	
		4513717	L	"	
		4130059	L	"	
		434340	F	"	
		49 I46	L	"	
		412463	L	"	
		412416	L	"	
		47034187	L	"	
		466222	L	"	
		493346	L	"	
		452945	L	"	
		49-374	L	"	
		2158	Z	"	
		83435	L	"	
		4168878	L	"	
		4724245	L	"	
		4183527	L	"	
		413264	L	"	
		463434	L	"	
		77496007	L	"	
		17414	L	"	
	assegno				
	FS				
	esterno				

	"	466747	L	"	
	"	408335	L	"	
	"	747[illegible]936	L	"	
	"	567[illegible]III	L	"	
	"	479883	L	"	
	"	661486	L	"	
	"	[illegible]2420	L	"	
	"	123978	L	"	
	"	466850	L	"	
	"	477273	L	"	
	"	478714	L	"	
	"	7408147	L	"	
	"	950057	MA	vuoto	
	"	534606	"	"	
	"	581609	"	"	
	"	982158	MC	"	
	"	7500834	"	"	
	"	921317	MO	"	
	"	533364	L	"	
	"	203385	G	"	
	"	494147	L	"	
	"	484317	L	"	
	"	413029	L	"	
	estero	234840	F	"	
	FS	49 I46	L	"	
	"	413403	L	"	
	"	412446	L	"	
	"	470348	L	"	
498	"	466922	L	"	
	"	498346	L	"	
	"	462845	L	"	
	"	492374	L	"	
	estero	2158	L	"	
	"	83455	L	"	
	FS	418878	L	"	
	"	471245	L	"	
	"	418327	L	"	
	"	413364	L	"	
	"	463494	L	"	
	"	77496007	L	"	
	estero	I74I4	L	"	
	FS	543880	Hg	carico	
	"	4I0480	L	"	
	"	II6899	F	"	
	"	I003816	E	vuoto	
	"	I009107	E	"	
	"	479489	L	"	
	"	498871	L	"	
	"	494149	L	"	
	"	II5992	F	"	
	"	7448312	L	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
S.Vito NorM;	estero	32062	L	vuoto	
	"	I8I9I	L	"	
	FS	463737	L	"	
	"	477365	L	"	
	"	4I5706	L	"	
	"	045778	L	"	
	"	222635	G	"	
	"	I480I7	F	"	
	estero	27802	L	"	
	"	38438	L	carico	
	"	I6986	F	"	
	FS	I87880	F	vuoto	
	estero	98I4	E	"	
	FS	4I5128	L	"	
	"	I66506	F	"	
	"	I000686	E	"	
	"	I0III9I	E	"	
	estero	31785	L	"	
	"	I5003	P	carico	
	FS	752349	Q	"	
	estero	83352	P	"	
	FS	II8389	P	"	
	estero	07017	P	"	
	FS	80886	P	"	
	FS	I05255	F	"	
	estero	22742	F	carico	
	FS	I0I4607	F	"	
	"	494I47	L	"	
	"	4I6652	L	"	
	estero	10338	L	"	
	FS	453364	L	vuoto	
	"	404355	L	carico	
	"	489I5I	L	"	
	"	7405561	L	"	
	"	774930I0	L	"	
	"	419435	L	"	
	"	466543	L	"	
	"	445546	L	"	Bari

222

Declassified E.O. 12356 Section 3.3/NND No. 785021

0219

Declassified E.O. 12356 Section 3.3/NND No. 785021

S.Vito NorM;	estero	32062	L	vuoto		
	"	18191	L	"		
	FS	463737	L	"		
	"	477365	L	"		
	"	415706	L	"		
	"	045778	L	"		
	"	202635	G	"		
	"	148017	F	"		
	estero	27802	L	"		
	"	38438	L	carico		
	"	16988	F	"		
	FS	187680	F	vuoto		
	estero	9814	L	"		
	FS	415128	L	"		
	"	166506	F	"		
	"	1000686	E	"		
	"	1011191	E	"		
	estero	31785	L	"		
	"	15603	P	carico		
	FS	752349	Q	"		
	estero	83852	P	"		
	FS	118389	F	"		
	estero	9701 7	F	"		
	FS	80886	P	"		
	FS	185255	F	"		
	estero	28742	F	carico		
	FS	1014607	F	"		
	"	494147	L	"		
	"	416632	L	"		
	estero	20338	L	"		
	FS	453364	L	vuoto		
	"	404355	L	carico		
	"	489151	L	"		
	"	7405561	L	"		
	"	774930I0	L	"		
	"	419435	L	"		
	"	466543	L	"		
	"	445546	L	"	Bari	
	"	165302	F	"	Roma	
	"	647359	P	vuoto		
	"	684976	P	"		
	"	621471	P	"		
	"	408587	L	"		
	"	412637	L	"		
	"	648464	P	carico	Montero undinf	
FOGGIA	FS	1007804	E	vuoto ripar.		
	"	626308	P	ripar.		
	"	134822	F	"		
	"	692289	POZ	"		
	"	647161	P	"		

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	FS	4I9462	L	ripar.	
	"	470844	L	"	
	"	749I793	L	"	
	"	457996	L	"	
	"	469751	L	"	
	"	446902	L	"	
	"	460580	L	"	
	"	49I459	L	"	
	"	412421	L	"	
	"	459960	L	"	
	"	484949	L	"	
	"	466218	L	"	
	"	653745	P	"	
	"	4784I9	L	"	
	"	4I4431	L	"	
	FS	616066	P	"	
	"	654I83	P	"	
	"	660305	P	"	
	"	4I0408	L	"	
	"	4I7245	L	"	
	"	685I32	P	"	
	"	46I990	L	"	
	FS	720I55I	G	"	
	"	458883	L	"	
	"	7II0702	F	"	
	"	478586	L	"	
	"	IB008I7	E	"	
	"	687I00	P	carico	
	"	652I80	P	ripar.	
	"	642586	L	"	
	"	605I06	P	"	
	"	7403547	L	"	
	"	I0III20	F	vuoto	
	"	I0I4404	F	carico	
	"	660461	P	ripar.	
	"	I005494	E	"	
	"	I606I6	F	"	
	"	I84020	F	"	
	"	I8I020	F	"	
	"	419467	L	"	
	"	646490	P	"	
	"	411326	L	"	
	"	I025III	F	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"		450580	L	"	
"		49I459	L	"	
"		412421	L	"	
"		4I9960	L	"	
"		484949	L	"	
"		466218	L	"	
"		653745	L	"	
"		4784I9	L	"	
	"	4I4431	L	"	
	PS	646066	P	"	
	"	654I83	P	"	
	"	660305	P	"	
	"	4I0408	L	"	
	"	4I7245	L	"	
	"	685I32	L	"	
	"	46I990	L	"	
	PS	720I55I	L	"	
	"	458883	L	"	
	"	7II0702	L	"	
	"	478586	L	"	
	"	I000817	L	"	
	"	647I00	L	carico	
	"	652I80	L	ripar.	
	"	642586	L	"	
	"	605I06	L	"	
	"	7401547	L	"	
	"	I0III20	L	vuoto	
	"	I0I4404	L	carico	
	"	660461	L	ripar.	
	"	I005494	L	"	
	"	I606I6	L	"	
	"	I84020	L	"	
	"	I8I020	L	"	
	"	419467	L	"	
	"	646490	L	"	
	"	411326	L	"	
	"	I085III	L	"	
	"	I00999	L	"	
	"	694030	POZ	"	
	"	[illegible]3	L	"	
	"	655354	P	"	
	"	306927	M	"	
	"	65[illegible]654	P	carico	
	PS	657917	P	"	
	"	652994	P	ripar.	
	"	[illegible]			
	PS	752766	Q	ripar.	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BRINDISI	F.S.	965418	P.O.Z.	vuoto	
	"	470313	L	"	
	"	514453	Mv	"	
	"	1121529	F	carico	
	"	7104607	"	"	
	Estero	212892	G	vuoto	
	F.S.	482930	L	"	
	"	524383	Mv	carico	
	"	514420	"	"	
	"	508095	"	"	
	"	568466	"	"	
	"	568290	"	"	
	Estero	152834	"G	carico	
	Estero	1113565	"	vuoto	
	F.S.	698604	P.O.Z.	carico	
	Estero	12690	"	"	
	F.S.	692209	"	"	
	Estero	91228	"	"	
	F.S.	694648	"	"	
	Estero	7298,	"	"	
	F.S.	695616	"	"	
	"	624241	"	"	
	"	7696009	"	"	
	"	49899I	L	vuoto	
	Estero	47125	"	carico	
	F.S.	476293	"	"	
	"	488643	"	"	
	"	401060	"	"	
	"	402468	"	"	
	Estero	31083	"	"	
	F.S.	131960	F	"	
	"	7270029	"	"	
	"	260550	"	"	
	"	181869	"	"	
	"	478837	L	"	
	"	645885	P	"	
	"	660695	"	"	
	"	752322	"	"	
	"	65759 8	"	"	
	"	651941	"	"	
	"	650702	"	"	

221

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	II2I529	F	carico
"	7I04607	"	"
Estero	2I2892	E	vuoto
F.S.	482930	L	"
"	524383	Ev	carico
"	5I4420	"	"
"	508096	"	"
"	568466	"	"
"	568290	"	"
Estero	I52834	"G	carico
Estero	XXXI3565	"	vuoto
F.S.	698694	P.O.Z.	carico
Estero	I2690	"	"
F.S.	692209	"	"
Estero	9I228	"	"
F.S.	694648	"	"
Estero	7298,	"	"
F.S.	695I6	"	"
"	62424I	"	"
"	7769600	"	"
"	49899I	L	vuoto
Estero	47I25	"	carico
F.S.	476293	"	"
"	488643	"	"
"	40I060	"	"
"	402468	"	"
Estero	3I083	"	"
F.S.	I3I960	F	"
"	7270023	"	"
"	260550	"	"
"	I8I869	"	"
"	478837	L	"
"	645885	P	"
"	660695	"	"
"	752322	"	"
"	65759 8	"	"
"	65I94I	"	"
"	650702	"	"
"	65I992	"	"
"	I70655	"	"
Estero	4I27	L	"
F.S.	458499	"	"
"	4050I50	"	"
"	43957I	"	"
"	4I3869	"	"
Estero	I0480	F	"
F.S.	II2I76I	"	"

2 1 2

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BRINDISI	F.S.	7I06804	F	carico	
	"	230514	G	"	
	Estero	2954	F	"	
	F.S.	76I96353	"	"	
	Estero	3I925	"	"	
	F.S.	I000626	"	"	
	"	47[illegible]48	"	"	
	Estero	68915	L	"	
	"	I8I29	"	"	
	F.S.	II35956	"	"	
	"	I029356	"	"	
	" "	I02I759	"	"	
	"	II20180	"	"	
	"	450948	"	"	
	"	4I4784	"	"	
	"	720510	"	vuoto	
	"	I007676	F	"	
	"	II0069	"	"	
	"	II[illegible]959	"	"	
	Estero	I4 633	G	"	
	F.S.	7I70196	F	carico	
	"	I0I356	"	"	
	Estero	36272	G	"	
	F.S.	I003705	"	"	
	"	535219	Mo	vuoto	
	"	0500062	Mop	"	
	"	924720	Mp	"	
	"	[illegible]			
	"	0500034	Mb	"	
	"	944721	"	"	
	"	I54560	F	carico	
	"	94[illegible]2I	M	vuoto	
	"	III9333	F	"	
	"	602694	Poz	"	
	"	I40657	F	carico	
	"	582804	Mv	vuoto	
	"	I0I6688	F	carico	
	"	4I5234	L	"	
	"	740462I	"	"	
	estero	4I632	G	"	
	FS	452486	L	"	
	"	045130	"	"	
	"	486890	"	"	
	"	II622I	"	"	
	"	99I656	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

F.S.	I000626	"	"	
"	47?I46	"	"	
Esterp	689I5	L	"	
"	I8I29	"	"	
F.S.	II35956	"	"	
"	I029536	"	"	
" "	I02I759	"	"	
"	II20180	"	"	
"	450948	"	"	
"	4I4784	"	"	
"	7205I0	"	vuoto	
"	I007670	F	"	
"	II0069	"	"	
"	II[illegible]959	"	"	
Estero	I4 6[illegible]3	G	"	
F.S.	7I70196	F	carico	
"6	I0I356	"	"	
Estero	36272	G	"	
F.S.	I003705	"	"	
"	535219	Mo	vuoto	
"	0500062	Mop	"	
"	924820	Mp	"	
"	[illegible]			
"	0500034	Mb	"	
"	944721	"	"	
"	I54560	F	carico	
"	94?I2I	M	vuoto	
"	III9333	F	"	
"	502694	Poz	"	
"	I40657	F	carico	
"	582804	Mv	vuoto	
"	I0I6688	F	carico	
"	4I5234	L	"	
"	740462I	"	"	
estero	4I632	G	"	
FS	452486	L	"	
"	045I30	"	"	
"	48689[illegible]	"	"	
"	II622I	"	"	
"	99I656	"	"	
"	740I[illegible]65	L	"	Lecce
estero	[illegible]			
	4667	"	"	
FS	4I4I55	"	"	
"	5I3696	"	"	
"	5I43I5	"	"	
"	524376	"	"	
[illegible]	5I4330	"	"	
"	I42348	"	carico	Brindisi

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FOGGIA	FS	615441	F	riper.	
	"	412945	L	"	
	"	605007	F	"	
	"	605135	F	"	
	"	499503	L	"	
	"	468582	L	"	
	"	476816	L	"	
	"	XXXXXX		•	
	"	46[illegible]68	L	carico	
	"	467048	"	"	
	"	4[illegible]397	"	"	
	"	496407	"	riperando	
	"	408955	"	"	
	"	7[illegible]7506	"	"	
	"	7I7I462	F	"	
	"	79 I630	"	"	
	"	501252	"	"	
	"	550956	Mo	"	
	"	647144	P	"	
	"	498129	L	"	
	"	49I767	"	"	
	"	799735	"	curic.	
	"	II33391	F	rip.randa	
	"	II45I3	"	"	
	"	40I813	L	"	
	"	493III	"	"	
	"	471740	"	"	
	"	49I33	"	"	
	"	740I457	"	"	
	"	I27359	F	"	
	"	695073	P.O.Z.	"	
	"	463736	L	"	
	"	466005	"	"	
	"	203819	G	"	
	"	497923	L	"	
	"	484344	"	"	
	"	465237	"	"	
	"	698691	P.O.Z.	"	
	"	III5071	F	"	

220

Declassified E.O. 12356 Section 3.3/NND No. 785021

FOGGIA	PS	615441	P	riper.	
	"	412945	L	"	
	"	605007	P	"	
	"	605135	P	"	
	"	499503	L	"	
	"	460582	L	"	
	"	476816	L	"	
	"	[illegible]		"	
	"	469568	L	carico	
	"	467048	"	"	
	"	466597	"	"	
	"	496407	"	riparando	
	"	408955	"	"	
	"	707506	"	"	
	"	717462	F	"	
	"	791630	M	"	
	"	501252	"	"	
	"	950956	Mo	"	
	"	647144	P	"	
	"	498129	L	"	
	"	491767	"	"	
	"	799735	"	carico	
	"	II33391	F	riparando	
	"	II45I3	"	"	
	"	401813	L	"	
	"	493III	"	"	
	"	471740	"	"	
	"	49133	"	"	
	"	7401457	"	"	
	"	I27359	F	"	
	"	695073	P.O.Z.	"	
	"	463736	L	"	
	"	466005	"	"	
	"	283819	G	"	
	"	487923	L	"	
	"	494344	"	"	
	"	465237	"	"	
	"	698691	P.O.Z.	"	
	"	IIII5071	F	"	
	"	417325	L	"	
	"	414447	"	"	
	"	694473	P.O.Z.	"	
	"	479180	L	"	
	"	477780	"	"	
	"	494136	"	"	
	"	47[illegible]060	"	"	
Est.Po		38859	"	"	
	"	I6503	"	"	
	P.S.	14244	"	"	
	"	270953	F	"	

220

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B R G G I A	Estero	43797	L	rip rando	
	"	I4344	"	"	
	F.S.	30174	"	"	
	Estero	16 942	M	"	
	"	I3I2	01	"	
	F.S.	[illegible]			
	Estero	95928	F	carico	
	"	9757I	"	riparando	
	F.S.	[illegible]			
	Estero	20693	L	carico	
	"	334993	"	"	
	FS	505	"	ripar.	
	"	807126	Grà	"	
	"	130815	F	"	
	"	493532	L	vuoto	
	"	497558	"	"	
	"	920186	Ma	"	
	estero	58319	H	ripar.	
	FS	1021041	Fc	vuoto	
	"	1001544	E	carico	
	"	648766	P	ripar.	
	estero	205706	KKv	"	
	"	33114	Ka	"	
	FS	950165	Ma	vuoto	
	"	5670478	"	"	
	"	950187	"	"	
	"	5320246	"	"	
	"	950220	"	"	
	"	920198	"	"	
	"	693430	Poz	"	
	"	692003	"	"	
	"	698699	"	"	
	estero	353507	Hg	"	
	"	17721	F	"	
	"	353535	Hg	"	
	"	213	Fv	"	
	"	299	"	"	
	"	287	"	"	
	FS	698416	Poa	"	
	"	77695524	"	"	
	estero	353495	Hg	"	
	"	353961	"	"	
	FS	468663	L	carico	
	"	487341	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Estero	16 942	K	"
"	13I2	Ol	"
F.S.	~~123xxx~~		
Estero	95928	F	carico
"	97571	"	riparando
F.S.	~~xxxxx~~		
Estero	20693	L	carico
"	334902	"	"
FS	505	"	ripar.
"	807126	Grù	"
"	130815	F	"
"	493532	L	vuoto
"	497558	"	"
"	920186	Ma	"
estero	58319	H	ripar.
FS	1021041	Fc	vuoto
"	1001544	E	carico
"	648766	P	ripar.
estero	205706	KKv	"
"	33114	Ka	"
FS	950165	Ma	vuoto
"	5670478	"	"
"	950187	"	"
"	5320246	"	"
"	950220	"	"
"	920198	"	"
"	693430	Poz	"
"	692003	"	"
"	698699	"	"
estero	353507	Hg	"
"	17721	F	"
"	353535	Hg	"
"	213	Fv	"
"	299	"	"
"	287	"	"
FS	698416	Poz	"
"	77695524	"	"
estero	353495	Hg	"
"	353561	"	"
FS	468663	L	carico
"	487341	"	"
"	661492	P	vuoto
"	668365	"	"
"	622568	"	"
"	951002	Ma	"
estero	36051	V	carico
FS	621637	P	"
"	622538	"	"
"	604372	"	"
estero	12655	Fbg	ripar.

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 AGOSTO *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BRINDISI	FS	7203II7	G	carico	
	"	487221	L	"	
	"	475569	L	"	
	"	477259	L	"	
	estero	4302	L	ripar.	
	FS	476389	L	carico	Lecce
	"	II33934	F	"	Ostuni
	"	514132	Mv	vuoto	
	"	I007295	E	carico	Ostuni
	estero	34061	L	"	"
	FS	77499005	L	"	"
	"	7479007	L	"	"
	"	456867	L	"	"
	"	492559	L	"	"
	"	417178	L	"	"
	"	1016872	E	"	"
	"	7105783	E	"	"
	FSE	6105	P	ripar.	Francavilla
	FS	418228	L	carico	
	"	482166	L	vuoto	
	"	494942	L	"	
	"	452106	L	"	
	"	469053	L	"	
	"	445158	L	ripar.	
	"	148681	F	"	
	estero	7486	POZ	carico	
	"	3414	"	"	
	FS	693813	"	"	
	"	697010	"	"	
	"	695016	"	"	
	"	694644	"	"	
	"	694604	"	"	
	estero	16867	"	"	
	"	8651	"	"	
	"	92207	"	"	
	FS	251400	G	"	
	"	694013	POZ	vuoto	
	"	695030	"	"	
	"	695092	"	"	
	"	698084	"	"	

219

Declassified E.O. 12356 Section 3.3/NND No. 785021

BRINDISI	FS	7203II7	G	carico		
	"	487221	L	"		
	"	478559	L	"		
	"	477259	L	"		
	estero	4302	L	ripar.		
	FS	476389	L	carico	Lecce	
	"	II33934	F	"	Ostuni	
	"	5I4I32	Mv	vuoto		
	"	I007283	E	carico	Ostuni	
	estero	3406I	L	"	"	
	FS	774920O5	L	"	"	
	"	7479007	L	"	"	
	"	456867	L	"	"	
	"	492559	L	"	"	
	"	4I7I78	L	"	"	
	"	I0I6872	E	"	"	
	"	7I05783	E	"	"	
	FSE	6E05	P	ripar.	Francavilla	
	FS	4I8229	L	carico		
	"	482I66	L	vuoto		
	"	494942	L	"		
	"	452I06	L	"		
	"	469063	L	"		
	"	443I58	L	ripar.		
	"	I4868I	F	"		
	estero	7486	POZ	carico		
	"	3414	"	"		
	FS	693813	"	"		
	"	692OI0	"	"		
	"	695OI6	"	"		
	"	694644	"	"		
	"	694504	"	"		
	estero	I6867	"	"		
	"	865I	"	"		
	"	92207	"	"		
	FS	25I400	G	"		
	"	694OI3	POZ	vuoto		
	"	695030	"	"		
	"	695292	"	"		
	"	698084	"	"		
	estero	333292	L	carico		
	FS	III8587	F	"		
	"	III43I0	F	"		
	"	I008859	B	"		
	estero	I3357	L	"		
	FS	I84406	F	"		
	"	7404760	L	"		
	"	488933	E	"		
	estero	26525	L	"		
	"	84I47	L	"		
	FS	4847II	L	"		

219

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi	FS	479455	L	carico	
	estero	78650	L	"	
	FS	I008339	[illegible]	"	
	"	133868	F	vuoto	
	Francia	270376	F	"	
	USA	206713	G	"	
	FS	417488	L	"	
	"	1883[illegible]8	L	"	
	estero	2811[illegible]	L	"	
	FS	456[illegible]6	L	"	
	estero	I[illegible]71	"	"	
	FS	227003	G	"	
	"	480[illegible]60	L	"	
	"	[illegible]406019	L	"	
	"	481571	L	"	
	"	447144	L	"	
	"	456571	L	"	
	"	I024379	E	carico	Bari
	"	260150	G	"	"
	"	I4044I	F	vuoto	
	"	333[illegible]8	HE	"	
	"	I[illegible]8127	F	"	
	"	III43I0	F	"	
	"	I008819	F	"	
	estero	I3337	F	"	
	FS	710[illegible]17	F	"	
	"	I[illegible]345	Ec	"	
	"	98[illegible]6[illegible]6	Ebc	"	
	"	T50843	F	"	
	"	697401	Mv	carico	
	"	642[illegible]50	P	"	
	estero	0053	P	"	
	"	940404	P	"	
	"	34[illegible]6	P	"	
	"	83479	P	"	
	FS	7600[illegible]3	P	"	
	estero	8375	P	"	
	"	8732	P	"	
	"	6658	P	"	
	FS	I0[illegible]502	P	"	
	"	171773	P	"	
	"	931377	Hcf	vuoto	
	"	[illegible]85047	PCZ	"	
	estero	2542	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi	ESTERO	91674	P	vuoto	
	FS	77697025	P	"	
	estero	I5901	"	"	
	"	5707	"	"	
	"	I65I4	"	"	
	"	3I090	"	"	
	"	82035	"	"	
	"	I0468	"	"	
	"	56I95	"	ripar.	
	"	68965	"	"	
Brindisi Smist.	"	85479	L	carico	Bari
	"	8SI	P	"	"
	FS	I021976	E	"	"
	"	74079II	L	"	Turi
	"	I007489	E	"	"
	"	47335I	L	"	"
	"	456648	L	"	"
	"	482770	L	"	"
	"	40I6I3	L	"	"
	tedesco	50546	L	"	Bari
	FS	648796	P	"	"
	tedesco	8I0I0	P	"	"
	FS	650759	P	"	"
	"	604375	P	"	Taranto
	"	7675I0I	P	"	"
	"	408342	L	"	"
	"	44I0570	L	"	S. Giovanni 218
	"	I040590	L	"	"
	"	483476	L	"	Giovinazzo
	"	97I538	MO	"	Monopoli
	"	I7I773	F	"	"
	"	I82522	F	"	"
	estero	6658	L	"	Bari
	"	86332	L	"	"
	"	6375	L	"	"
	FS	7600223	P	"	"
	"	59740I	MV	"	Polignano
	"	I34406	F	"	Castellamare
	"	I003705	E	"	Taranto

Declassified E.O. 12356 Section 3.3/NND No. 785021

Brindisi	LSFERO	91674	P	vuoto		
	FS	77597025	P	"		
	estero	15984	P	"		
	"	5707	P	"		
	"	I65I4	P	"		
	"	3I090	P	"		
	"	92035	P	"		
	"	I0468	P	"		
	"	66I95	P	ripar.		
	"	68965	P	"		
Brindisi Smist.	"	83479	L	carico	Bari	
	"	86I	P	"	"	
	FS	I02I976	E	"	"	
	"	74079II	L	"	Turi	
	"	I007429	E	"	"	
	"	47335I	L	"	"	
	"	466648	L	"	"	
	"	482770	L	"	"	
	"	40I6I8	L	"	"	
	tedesco	50546	L	"	Bari	
	FS	648796	P	"	"	
	tedesco	8I0I0	P	"	"	
	FS	650750	P	"	"	
	"	604375	P	"	Taranto	
	"	7675I0I	P	"	"	
	"	408342	L	"	"	
	"	44I0570	L	"	S.Giovanni	218
	"	I040590	E	"	"	
	"	482476	L	"	Giovinazzo	
	"	97I538	MO	"	Monopoli	
	"	I7I773	P	"	"	
	"	182582	P	"	"	
	estero	6658	L	"	Bari	
	"	26372	L	"	"	
	"	8375	L	"	"	
	FS	7600223	P	"	"	
	"	597401	MV	"	Polignano	
	"	I84406	P	"	Castellamare	
	"	I003705	P	"	Taranto	
	estero	58072	G	"	"	
	FS	I0I356	P	"	"	
	"	7I70I96	P	"	"	
	"	I46633	P	"	"	
	"	I0II2I5	P	"	Francavilla	
	estero	I3529	G	"	S.Vito	
	"	23762	R	"	"	
	"	493	DR	"	Monopoli	
	FS	449I5I	L	"	"	
	"	25II00	G	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Brindisi Smist.	estero	9033	G	vuoto	
	"	8651	P	carico	
	"	92707	DR	"	
	"	7476	"	"	
	"	3414	"	"	
	FS	693812	POZ	"	S.Vito
	tedesco	I8896	L	"	"
	"	36440	DR	"	"
	FS	623186	P	"	Brindisi
	tedesco	I6867	"	"	"
	FS	692010	POZ	"	"
	"	692016	"	"	"
	"	694644	"	"	"
	"	694604	"	"	"
	"	443151	L	"	Cafidelluro
	"	473192	"	"	Francavilla F.
	"	I501039	F	"	"
	tedesco	49076	G	"	"
	FSE	I809	F	"	"
	tedesco	9779	L	"	"
	"	4697	"	"	"
	"	53406	"	"	"
	FS	407964	"	"	"
	estero	47606	"	"	"
	"	9583	"	"	"
	FS	471543	L	"	"
	"	440897	"	"	"
	"	7406373	"	"	"
	"	451453	"	"	Brindisi
	"	446129	"	"	"
	"	465337	"	"	"
	"	498136	"	"	"
	"	480372	"	"	"
	"	478563	"	"	"
	"	5096I4	MV	"	Isernia
	"	400408	L	"	"
	"	5096I3	MV	"	"
	"	572800	"	"	Bitetto
	"	506351	"	"	Barletta
	"	524361	"	"	"
	"	9581079	"	"	"
	"	I59073	F	"	"
	"	536082	Mo	"	"
	"	43670	I	"	Trani

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	9[illegible]707	DR	"		
"	7476	"	"		
"	3414	"	"		
FS	69[illegible]I2	POZ	"		
tedesco	I8896	L	"	S.Vito	
"	36440	DR	"	"	
FS	623I86	F	"	"	
tedesco	I6867	"	"	Brindisi	
FS	690I0	POZ	"	"	
"	690016	"	"	"	
"	694644	"	"	"	
"	694604	"	"	"	
"	443I5I	L	"	"	
"	473I92	"	"	Caffelarro	
"	I90I039	P	"	Francavilla F.	
tedesco	49076	G	"	"	
FSE	I809	F	"	"	
tedesco	9779	L	"	"	
"	4697	"	"	"	
"	53406	"	"	"	
FS	407964	"	"	"	
estero	47606	"	"	"	
"	9583	"	"	"	
FS	471543	L	"	"	
"	410097	"	"	"	
"	7408379	"	"	"	
"	451453	"	"	"	
"	446I29	"	"	Brindisi	
"	465337	"	"	"	
"	498I36	"	"	"	
"	480372	"	"	"	
"	472563	"	"	"	
"	5096I4	Mv	"	Isernia	
"	400408	L	"	"	
"	5096I3	Mv	"	"	
"	572200	"	"	Bitetto	
"	506351	"	"	Barletta	
"	524361	"	"	"	
"	958I079	"	"	"	
"	I69073	F	"	"	
"	536022	Mo	"	"	
"	472330	L	"	Trani	
"	410886	L	"	Altamura	
"	434I74	L	"	Grottaglie	
"	047315	L	"	S.Spirito	
"	97I0267	F	"	"	
"	4I4474	L	"	"	
"	7400235	L	"	"	
"	650132	P	"	"	
"	650340	P	"	"	
"	I84202	F	"	"	
"	414I55	L	"	Lecce	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 4 Agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
TARANTO	Estero	4946	F	riparando	
	FS	7402652	L	vuoto	
	"	459525	"	"	
	"	416020	"	"	
	Estero	7719200	F	"	
	FSE	IIII9	"	carico	
	FS	II7I79	"	"	
	"	7500[illegible]14	M	vuoto	
	"	480I7[illegible]	L	"	
	Estero	36158	F	"	
	"	74031	F	carico	Monopoli
	FS	348318	F	"	Bari
	" "	445I93	L	"	"
	"	472[illegible]9I	"	"	Lecce
	"	II35563	F	"	Brindisi
	"	651931	F	vuoto	
	"	7I0I7I2	F	carico	
	"	442914	L	"	Bari
	"	490021	"	"	
	"	488577	"	"	
	"	7470335	"	"	
	"	479I38	"	"	
	"	445798	"	"	
	Estero	83479	"	"	
	"	5009	"	"	
	"	I87233	"	"	
	FS	496176	"	"	
	"	7471712	"	"	
	"	494339	"	"	
	"	I71I93	F	"	
	"	405448	L	"	Giovinazzo
	"	44I0949	L	"	
	Estero	22973	L	"	
	FS	646304	P	"	
	"	750I029	M	vuoto	
	"	499320	L	"	
	"	469446	L	"	
	"	493909	"	"	
	"	472983	"	"	

217

Declassified E.O. 12356 Section 3.3/NND No. 785021

TARANTO	Estero	4946	P	ripartenza	
	FS	7402658	L	vuoto	
	"	459525	"	"	
	"	416020	"	"	
	Estero	7719200	T	"	
	FSE	III9	"	carico	
	FS	II7173	"	"	
	"	7500[illegible]14	M	vuoto	
	"	480I[illegible]	L	"	
	Estero	36158	F	"	
	"	74031	F	carico	Monopoli
	FS	348318	B	"	Bari
	" "	445I93	L	"	"
	"	472791	"	"	Lecce
	"	II35560	F	"	Brindisi
	"	651931	P	vuoto	
	"	7I6I7I2	F	carico	Bari
	"	442914	L	"	
	"	490021	"	"	
	"	488577	"	"	
	"	7470335	"	"	
	"	479138	"	"	
	"	445798	"	"	
	Estero	83479	"	"	
	"	5009	"	"	
	"	I87233	"	"	
	FS	496176	"	"	
	"	747I71[illegible]	"	"	
	"	404339	F	"	
	"	I71I93	L	"	
	"	405448	L	"	Giovinazzo
	"	44I0940	P	"	
	Estero	22973	M	"	
	FS	646304	L	vuoto	
	"	750I020	"	"	
	"	499320	"	"	
	"	469446	"	"	
	"	493909	"	"	
	"	472983	"	"	
	"	I89269	F	carico	Bernalda
	"	967[illegible]I56	M	"	
	"	470881	L	"	
	"	II8541	T	"	
	"	7I0I547	B	"	
	"	II29357	"	"	
	"	II35944	G	"	
	"	26I37[illegible]	E	"	
	"	I0I0[illegible]5	"	carico	
	"	I0I.878	"	"	

217

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
T A R A N T O	FS	343057	Hg	carico	
	"	477578	L	"	
	Estero	71328	P	"	Valensano
	"	96520	F	"	
	FS	967QII5	M	vuoto	
	Estero	93469	F	carico	
	FS	7IC5588	F	"	
	"	I003181	"	"	
	Estero	875	L	"	
	FS	480I29	"	vuoto	
	"	654443	P	"	
	"	I0I6086	F	riparando	
	Estero	77495503	L	"	
	"	I2 I8	"	"	
	FS	I031675	E	"	
	"	300I04	Hg	vuoto	
	"	452354	L	carico	
	"	650252	P	carico	
	Estero	I6694	"	"	
	"	41447	"	"	Cimino
C	FS	646941	"	"	
	Estero	67645	P	"	Brindisi
	FS	351569	H	carico	"
	"	4I9797	L	"	Francavilla
	"	I0I6I49	E	"	Monopoli
	Estero	23915	F	"	" " "
	FS	III87I5	L	"	"
	"	I020II9	F	"	"
	"	7I05576	F	vuoti	
	"	77I9348	"	"	
	"	I030I05	"	"	
	"	I4I077	"	"	
	"	I09023	"	"	
	"	II35305	"	"	
	Estero	34394	"	"	
	"	85I96	"	"	
	FS	II35325	F	carico	
	"	474I50	L	"	
	"	I0I6468	F	"	
	Estero	62114	L	"	
	"	4I8I	"	"	
	FS	650225	P	vuoti	
	"	646609	"	"	
	"	650672	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	Estero	71328	P	"	Valenzano
	"	96520	F	"	
	FS	9670II5	R	vuoto	
	Estero	93469	F	carico	
	FS	7I05588	F	"	
	"	I003I8I	"	"	
	Estero	875	L	"	
	FS	480I29	"	vuoto	
	"	654443	P	"	
	"	I0I6086	F	riparando	
	Estero	77495503	L	"	
	"	I2 I8	"	"	
	FS	I031675	E	"	
	"	3[illegible]0I04	Hg	vuoto	
	"	452354	L	carico	
	"	650252	P	carico	
	Estero	I6694	"	"	
	"	41447	"	"	Cimino
C	FS	646941	"	"	
	Estero	67645	P	"	Brindisi
	FS	351569	H	carico	"
	"	4I9797	L	"	Francavilla
	"	I0I6I49	E	"	Monopoli
	Estero	23915	F	"	" " "
	FS	III87I5	L	"	"
	"	I020II9	F	"	"
	"	7I05576	F	vuoti	
	"	77I9348	"	"	
	"	I030I05	"	"	
	"	I4I077	"	"	
	"	I090237	"	"	
	"	II35305	"	"	
	Estero	34394	"	"	
	"	85I96	"	"	
	FS	II35325	P	carico	
	"	474I60	L	"	
	"	I0I6468	P	"	
	Estero	62114	L	"	
	"	4I8I	"	"	
	FS	650225	P	vuoti	
	"	646609	"	"	
	"	650672	"	"	
	"	623027	"	"	
	"	645833	"	"	
	"	648233	"	"	
	"	657516	"	"	
	Estero	3690	"	"	
	"	40045	"	"	
	"	21938	"	"	
	"	7I08I	"	"	
	"	68654	"	"	
	"	22070	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
T R A N I	FS	II2I4I	Bf	carico	
	"	7IOIOIO	"	vuoto	
	"	465296	L	carico	
	"	7400532	"	"	
	"	462810	"	"	
	"	446718	"	"	
	"	485774	"	"	
	Estero	6916	"	"	
	FS	646149	"	"	
	"	586610	"	"	
	"	586611	"	"	
Chieuti Serracap.	"	II3099I	"	"	
	"	I000701	"	"	
	"	I66188	"	"	
	"	I7I691	"	"	
	"	7I03588	"	"	
	Estero	58689	"	"	
	"	24993	"	vuoto	
	F.S.	I020057	"	vuoto	
B A R I PARCO SUD.	"	428805	L	carico	
	"	481800	"	"	
	Estero	I3863	"	"	
	F.S.	648089	P	"	
	"	644721	"	"	
	"	644732	"	"	
	"	[illegible]			
	"	656154	"	"	
	"	685123	"	"	
	"	646114	"	"	
	Estero	51	"	"	
	"	93941?	"	"	
	"	68410	"	"	
	F.S.	646860	"	"	
	"	661032	"	"	
	"	652789	"	"	
	"	604383	"	"	Candelaro
	Estero	5546	"	"	"
	"	I3589	"	"	"
	"	I654	"	"	"

216

Declassified E.O. 12356 Section 3.3/NND No. 785021

T R A N I	FS	II2I4I	BI	carico	
	"	7IOIOIO	"	vuoto	
	"	465296	L	carico	
	"	7400532	"	"	
	"	462810	"	"	
	"	446718	"	"	
	"	485774	"	"	
	Estero	6916	"	"	
	FS	646149	"	"	
	"	586610	"	"	
	"	586611	"	"	
Chieuti Serracap.	"	II3099I	"	"	
	"	I000701	"	"	
	"	I66188	"	"	
	"	I71691	"	"	
	"	7I03588	"	"	
	Estero	58689	"	"	
	"	24993	"	vuoto	
	F.S.	I020057	"	vuoto	
B A R I PARCO SUD.	"	428805	L	carico	
	"	481800	"	"	
	Estero	I3863	"	"	
	F.S.	648089	P	"	
	"	644721	"	"	
	"	644732	"	"	
	"	656656	"	"	
	"	656154	"	"	
	"	685123	"	"	
	"	646II4	"	"	
	Estero	5I	"	"	
	"	9394I2	"	"	
	"	6841O	"	"	
	F.S.	646860	"	"	
	"	651032	"	"	
	"	652789	"	"	
	"	604383	"	"	
	Estero	5546	"	"	
	"	I3589	"	"	
	"	I654	"	"	
	F.S.	7475300	"	"	
	"	40792I	"	"	
	"	4I8804	"	"	
	"	466971	"	"	
	"	462022	"	"	
	"	494729	"	"	
	"	458485	"	"	
	"	494575	"	"	
	"	4I0342	"	"	
	Estero	440739	"	"	
	"	6I603	"	"	

216

Candelaro

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I PARCO SUD	F.S.	I3443I	P	carico	Foggia
	"	7470829	L	"	Rignano
	"	48[illegible]4II	"	"	"
	"	463780	"	"	"
	"	4I0545	"	"	Giovinazzo
	"	478926	"	"	Modugno
	"	7674000	P.O.Z.	"	"
	"	065435	"	"	"
	"	I66988	F	"	"
	F.S.E.	II023	M	vuoto	Bari Sud Est
	Estero	2958I	F	carico	"
	F.S.	I02I33I	"	"	"
	"	I009423	"	"	Bari P.V.
	"	I66305	"	"	"
	"II	I87I8	"	"	Bari S. Giorgio
	"	I8828I	"	"	"
	"	I00422	"	"	"
	"	I007403n	"	"	"
	"	65344	P	"	"
	Estero	347I8	"	"	Bari C:le
	F.S.	55I093	Mo	vuoto	"
	"	25I9I7	G	carico	"
	"	4II486	L	"	"
	"	474945	"	"	"
	"	4I49I5	"	"	"
	"	4I2049	"	"	"
	"	476457	"	"	"
	"	4I4823	"	"	Deposito
	"	462268	"	"	"
	"	459969	"	"	"
	"	447958	"	"	Sospeso
	"	042574	"	"	"
	"	645305	"	"	
	Estero	II565	"	"	
	"	25260	"	"	
	"	25248	"	"	
	"	386686	P	"	
	"	35373	"	"	
	"	93778	"	"	
	"	I0067	"	"	
	"	399220	"	"	
	F.S.	7770245	"	"	
	"	474745	"	"	
	"	427307	"	"	

0244
Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	469780	"	"	"
	"	410545	"	"	Giovinazzo
	"	478926	"	"	Modugno
	"	7674800	P.O.Z.	"	"
	"	065435	"	"	"
	"	I66988	F	"	Bari Sud Est
	P.S.E.	II023	M	vuoto	"
	Estero	29581	F	carico	"
	F.S.	I621331	"	"	Bari P.V.
	"	I009423	"	"	"
	"	I66305	"	"	Bari S. Giorgio
	"	III87I8	"	"	"
	"	I88281	"	"	"
	"	I00422	"	"	"
	"	I007403	"	"	"
	"	65314	F	"	Bari C:le
	Estero	34718	"	"	"
	F.S.	551093	Mo	vuoto	"
	"	251917	G	carico	"
	"	4II486	L	"	"
	"	474945	"	"	"
	"	4I49I5	"	"	"
	"	4I2049	"	"	"
	"	476457	"	"	"
	"	4I4823	"	"	Deposito
	"	462268	"	"	"
	"	459969	"	"	"
	"	447958	"	"	Sospeso
	"	042574	"	"	"
	"	645305	"	"	
	Estero	II565	"	"	
	"	25260	"	"	
	"	25248	"	"	
	"	386686	P	"	
	"	55373	"	"	
	"	93778	"	"	
	"	I0067	"	"	
	"	399220	"	"	
	F.S.	7770245	"	"	
	"	474745	"	"	
	"	427307	"	"	
	"	446I64	"	"	
	"	48I656	"	"	
	"	4I0036	"	"	
	"	494307	"	"	
	"	04[illegible]348	"	"	
	"	4I6223	"	"	
	"	4I0976	"	"	
	"	470263	"	"	
	"	495564	L	"	Brindisi

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A RI PARCO SUD 3	Estero	397	L	carico	Brindisi
	"	51355	"	"	"
	"	37924	"	"	"
	F.S.	462665	"	"	"
	"	487127	"	"	"
	"	418170	"	"	"
	"	7769000	P.O.Z.	riparando	"
	Estero	91396	L	carico	"
	"	14679	P	"	"
	F.S.	412590	L	"	"
	"	660522	P	vuoto	
	"	654053	"	"	
	"	7769601 3	"	"	
	"	645643	"	"	
	"	654939	"	"	
	"	414677	L	"	
	"	402145	"	"	
	"	~~xxxxx~~			
	"	489129	"	"	
	"	477464	"	"	
	"	463716	"	"	
	"	405172	"	"	
	"	740305	"	"	
	"	406918	"	"	
	"	480564	"	"	
	"	414055	"	"	
	Estero	47256	"	"	
	"	32921	"	"	
	"	117916	"	"	
	"	110455	"	"	
	"	10103118	"	"	
	"	127370	"	"	
	"	170415	"	"	
	F.S.	10210110	F	"	
	"	185240	"	"	
	"	39141 4	Hg	"	
	"	131635	"	"	
	Estero	32208	"	"	
	F.S.	647391	P	"	

215

Declassified E.O. 12356 Section 3.3/NND No. 785021

B A RI PARCO SUD 3	Estero	397	L	carico	Brindisi	
	"	5I355	"	"	"	
	"	37924	"	"	"	
	F.S.	462665	"	"	"	
	"	487I27	"	"	"	
	"	4I8I70	"	"	"	
	"	7769000	P.	.Z.	riparando	"
	Estero	9I396	L	carico	"	
	"	I4679	P	"	"	
	F.S.	4I2590	L	"	"	
	"	660522	P	vuoto		
	"	654053	"	"		
	"	776960I3	"	"		
	"	645643	"	"		
	"	654939	"	"		
	"	4I4677	L	"		
	"	402I45	"	"		
	"	[illegible]				
	"	489I29	"	"		
	"	477464	"	"		
	"	4637I6	"	"		
	"	405172	"	"		
	"	740305	"	"		
	"	4069I8	"	"		
	"	480564	"	"		
	"	4I4055	"	"		
	Estero	47256	"	"		
	"	32921	"	"		
	"	II79I6	"	"		
	"	II0455	"	"		
	"	I0I03I8	"	"		
	"	I27370	"	"		
	"	I704I5	"	"		
	F.S.	I02I0I0	F	"		
	"	I85240	"	"		
	"	39I4I4	Hg	"		
	"	I3I635	"	"		
	Estero	32208	"	"		
	F.S.	647391	P	"		
	"	752935	Q	"		
	"	4I4320	L	"		
	"	654329	P	"		
	"	648506	"	"		
	"	652290	"	"		
	"	65379I	"	"		
	"	64538I	"	"		
	"	622509	"	"		
	"	645035	"	"		
	"	650286	"	"		
	"	65I306	"	"		

215

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I PARCO SUD	Estero	35432	P	vuoto	
	"	43912	"	"	
	F.S.	465286	L	riparando	
	"	434867	"	"	
	"	7497329	"	"	
	"	464624	"	"	
	"	434707	"	"	
	"	445197	"	"	
	"	77195008	"	"	
	"	201636[illegible]	"	vuoto	
	Estero	11277	"	"	
	F.S.	173178	"	""	
	Estero	91732	P.S.Z.	"	
	F.S.	646370	P	"	
	"	651742	"	"	
	"	622949	"	"	
	"	645448	"	"	
	"	646993	"	"	
	"	621713	"	"	
	"	622132	"	"	
	"	656355	"	"	
	"	660563	"	"	
	"	647191	"	"	
	Estero	77696502	"	"	
	"	580	"	"	
	"	10605	"	"	
	"	4168	"	"	
	"	78129	"	"	
	"	61230	"	"	
	F.S.	06[illegible]55	"	"	
	Estero	81196	"	"	
	"	72315	"	"	
	"	3677	"	"	
	"	203491	"	"	
	F.S.	77645512	"	"	
	"	645544	"	"	
	"	652900	"	"	
	"	625504	"	"	
	"	655538	"	"	
	"	657391	"	"	
	"	646793	"	"	
	"	645518	"	"	
	"	346590	"	"	
GROTTAGLIE	Estero	15774	F	avendo carico	Cioè Colle
	F.S.	260590	Co		

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	7407329	"	"	
	"	464624	"	"	
	"	434787	"	"	
	"	445197	"	"	
	"	77795608	"	"	
	"	I0I6360	"	vuoto	
	Estero	II277	"	"	
	F.S.	I73I78	"	"	
	Estero	9I732	P. O. Z.	"	
	F.S.	646370	P	"	
	"	65I742	"	"	
	"	622949	"	"	
	"	645448	"	"	
	"	646993	"	"	
	"	621713	"	"	
	"	642332	"	"	
	"	656355	"	"	
	"	66 563	"	"	
	"	647I9I	"	"	
	Estero	77696502	"	"	
	"	580	"	"	
	"	I0605	"	"	
	"	4I68	"	"	
	"	78I29	"	"	
	"	67230	"	"	
	F.S.	06 I05	"	"	
	Estero	8I196	"	"	
	"	72315	"	"	
	"	3677	"	"	
	"	203469I	"	"	
	F.S.	77645512	"	"	
	"	645544	"	"	
	"	652990	"	"	
	"	629504	"	"	
	"	655538	"	"	
	"	657391	"	"	
	"	646793	"	"	
	"	645518	"	"	
	"	346590	"	"	
	Estero	I5774	F	avando	Gioia Colle
GROTTAGLIE	F.S.	260590	Gc	carico	
	"	I0II99	F	"	
	"	405594	L	"	
	"	651392	P	"	
	"	651259	"	"	
	"	648910	"	"	
	Estero	5I82I	L	"	Campomarino
	F.S.	I2I505	Fc	"	"
	"	I020384	E	"	"
	"	I022444	Ec	"	"
	"	541900	MV	vuoto	Grottaglie

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24/8 *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
TARANTO	estero	68237	P	vuoto	
	"	33655	"	"	
	"	18083	"	"	
	"	22913	"	"	
	"	49016	"	"	
	"	44715	"	"	
	"	16579	"	"	
	"	10796	"	"	
	"	25077	DR	carico	
	"	74069	L	"	
	"	45504	"	"	
	FS	192952	E	"	
	"	1028142	"	"	
	"	407769	L	vuoto	
	"	589635	M	"	
	"	589631	"	"	
	"	589625	"	"	
	"	589612	"	"	
	"	589614	"	"	
	"	589619	"	"	
	FSE	1702	E	"	
	FS	7403304	L	"	
	"	434109	"	"	
	"	7448997	"	"	
	"	480121	"	"	
	"	452754	"	"	
	"	413954	"	carico	
	"	7401966	"	"	
	"	469643	"	"	
	"	045520	"	"	
	"	476274	"	"	
	"	410711	"	"	
	"	407541	"	"	
	"	411522	"	"	
	"	1133172	E	vuoto	
	"	1005317	"	"	
	"	169052	"	"	
	"	1005998	"	"	
	"	251508	"	"	

214

Declassified E.O. 12356 Section 3.3/NND No. 785021

TARANTO	estero	68237	P	vuoto	
	"	33655	"	"	
	"	18083	"	"	
	"	22913	"	"	
	"	49016	"	"	
	"	44715	"	"	
	"	16579	"	"	
	"	10796	"	"	
	"	25077	DR	carico	
	"	74069	L	"	
	"	45504	"	"	
	FS	192952	E	"	
	"	1028142	"	"	
	"	407769	L	vuoto	
	"	589635	M	"	
	"	589631	"	"	
	"	589625	"	"	
	"	589612	"	"	
	"	589614	"	"	
	"	589619	"	"	
	FSE	1702	E	"	
	FS	7403304	L	"	
	"	434108	"	"	
	"	7448997	"	"	
	"	480121	"	"	
	"	452754	"	"	
	"	413954	"	carico	
	"	7401966	"	"	
	"	469643	"	"	
	"	045520	"	"	
	"	476274	"	"	
	"	410711	"	"	
	"	407541	"	"	
	"	411522	"	"	
	"	1133172	E	vuoto	
	"	1005317	"	"	
	"	169052	"	"	
	"	1005998	"	"	
	"	251508	"	"	
	estero	258180	"	"	
NASISI	FS	166193	P	"	
	"	647189	"	"	
	estero	58066	"	"	
	FS	685122	"	"	
	estero	15410	"	"	
	"	60917	"	"	
	FS	654822	"	"	
	"	653688	"	"	

214

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
N A S I S I	FS	77645516	P	vuoto	
	estero	31945	"	"	
	FS	645161	"	"	
	"	553512	"	"	
	"	660721	"	"	
	"	623361	"	"	
	"	660721	"	"	
	"	645945	"	"	
	"	647225	"	"	
	"	623040	"	"	
	"	620330	"	"	
	estero	6089	"	"	
	"	65431	"	"	
	FS	650801	"	"	
	estero	77460	"	"	
	FS	450337	"	"	
	"	660530	"	"	
	"	644796	"	"	
	"	652431	"	"	
	"	7770337	"	"	
	estero	28049	"	"	
	FS	623339	"	"	
	estero	34253	"	"	
	FS	645360	"	"	
	"	684014	"	"	
	"	648307:	"	"	
	estero	31681	"	"	
	FS	627524	"	"	
	estero	9345	"	"	
	FS	623907	"	"	
	"	752128	"	"	
	"	660207	"	"	
	estero	56900	"	"	
	FS	651913	"	"	
	estero	8745	"	"	
	FS	1131983	"	"	
	"	1131981	"	"	
	"	625144	"	"	
	"	604743	"	"	
	estero	78646	"	"	
	FS	645745	"	"	
	"	652412	"	"	
	"	652145	"	"	
	"	653641	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0253

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	"	"
"	"	"	"
"	"	"	"

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del ..... 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BASILI	FS	7470345	L	vuoto	
	"	I027170	E	"	
	"	I8I8I2	P	"	
	"	920417	M	"	
	"	648551	P	carico	Brindisi
	"	645793	P	"	"
	estero	15574	P	"	"
	FS	I23980	P	"	"
	estero	23I82	P	"	"
	FS	156445	P	"	"
	"	04I131	L	"	"
	estero	I7953	L	"	"
	FS	472135	L	"	"
	"	I50679	F	"	"
	"	477944	L	"	"
	"	I0I464I	E	"	"
	"	47069I	L	"	"
	"	77493054	L	"	"
	"	413937	L	"	"
	"	46I388	L	"	"
	estero	25772	L	"	"
	FS	252747	G	"	"
	"	487856	L	"	"
	"	489367	L	"	"
	estero	3821	L	"	"
	FS	482475	L	"	"
	"	498I00	L	"	"
	"	747065I	L	"	"
	"	I022803	E	"	"
	"	489935	L	"	"
	"	7407325	L	"	"
	estero	34236	F	"	"
	FS	7448776	L	"	"
	"	476919	L	"	"
	estero	94727	F	"	"
	FS	476464	L	"	"
	"	405724	Hz	"	"
	"	306880	"	"	"
	"	300624	"	"	"
	"	300777	"	"	"

213

Declassified E.O. 12356 Section 3.3/NND No. 785021

PARIS	FS	747033	L	Vuoto	
	"	I027170	E	"	
	"	I8I8I2	F	"	
	"	920417	M	"	
	"	648551	P	ostico	Brindisi
	"	645793	P	"	"
	estero	15574	P	"	"
	FS	I23980	F	"	"
	estero	23I82	F	"	"
	FS	156445	F	"	"
	"	04I131	L	"	"
	estero	I7953	L	"	"
	FS	472135	L	"	"
	"	I50679	F	"	"
	"	477944	L	"	"
	"	I0I464I	E	"	"
	"	470691	L	"	"
	"	77493054	L	"	"
	"	413937	L	"	"
	"	46I388	L	"	"
	estero	25772	L	"	"
	FS	252747	G	"	"
	"	487856	L	"	"
	"	489367	L	"	"
	estero	3821	L	"	"
	FS	482475	L	"	"
	"	498I00	L	"	"
	"	747065I	L	"	"
	"	I022803	E	"	"
	"	489935	L	"	"
	"	7407325	L	"	"
	estero	24236	F	"	"
	FS	7448776	L	"	"
	"	476919	L	"	"
	estero	94727	F	"	"
	FS	476464	L	"	"
	"	405724	L	"	"
	"	308880	HS	"	"
	"	300624	"	"	"
	"	300777	"	"	"
	"	657354	P	"	"
	"	II0570	F	"	"
	estero	8558	F	"	"
	FS	541805	M	"	"
	"	541826	M	"	"
	estero	68852	M	"	"
	FS	I23569	F	"	"
	BR	22415	L	"	"
	FS	493585	L	"	"
	"	645519	P	"	"
	estero	49619	L	"	"

0255
Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
NASISI	FS	480770	L	carico	
	"	488002	L	"	
	"	304429	Hg	"	
	estero	88416	F	"	
	FS	7170162	F	"	
	"	476888	L	"	
	"	255719	Hg	"	
	"	2090886	E	carico	
	"	7106398	F	"	
	"	575403	K	"	
	"	575404	"	"	
	"	71193029	F	"	
	"	106258	Hg	"	
	estero	16881	F	"	
	FS	202032	G	"	
	DR	97677	L	"	
	FS	307773	Hg	"	
	"	343062	"	"	
	"	315451	"	"	
	"	543090	M	"	
	"	306594	Hg	"	
	"	300503	"	"	
	"	306992	"	"	
	"	300894	"	"	
	"	815819	M	"	
	"	932407	Hg	vuoto	
	"	301029	"	"	
	"	307211	"	"	
	"	408737	L	"	
	"	654570	P	"	
	"	1000712	E	"	
	"	406536	L	"	
	"	485534	L	"	
	estero	11829	F	"	
	"	34580	F	"	
	"	49316	F	"	
	"	19728	F	"	
	FS	694069	Poz	"	
	estero	252	F	"	
	FS	1031272	E	"	
	"	1014861	F	"	
	"	306558	Hg	"	
	"	306974	"	"	
	"	308762	"	"	
	"	306435	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

estero	88416	F	"
FS	7I70I62	F	"
"	476888	L	"
"	255719	Hg	"
"	E090806	E	carico
"	7I06398	F	"
"	575403	M	"
"	575404	"	"
"	7II93029	F	"
"	206258	Hg	"
estero	16881	F	"
FS	202032	G	"
DR	97677	L	"
FS	307773	Hg	"
"	343062	"	"
"	31545I	"	"
"	543090	M	"
"	306594	Hg	"
"	300503	"	"
"	306992	"	"
"	300094	"	"
"	8I58I9	M	"
"	932407	Hg	vuoto
"	30I029	"	"
"	307311	"	"
"	408737	L	"
"	654570	P	"
"	I000712	E	"
"	406536	L	"
"	485534	L	"
estero	II829	F	"
"	34580	F	"
"	49316	F	"
"	I9728	F	"
FS	694069	POZ	"
estero	252	F	"
FS	I93129	E	"
"	I0I486I	P	"
"	306558	Hg	"
"	306974	"	"
"	308762	"	"
"	300435	"	"
"	30I290	"	"
"	306725	"	"
"	315156	"	"
"	486328	L	"
estero	4708I	E	"
FS	4I8202	L	"
"	464042	L	"
"	4I8I52	L	"
"	66I479	P	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 **Agosto** *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
GROTTAGLIE	F.S.	54I426	Fc	vuoto	
	"	524540	Mv	carico	
	"	5I3004	"	"	
	"	5I36I0	"	"	
	"	7400546	L	riparando	
	"	I8I66I	Mv	"	
	"	9550257	L	vuoto	
	Estero	5452	"	carico	
	F.S.	49I546	"	"	
	"	44III09	"	"	
	"	4I666I	"	"	
	"	455485	"	"	
	"	459360	L	"	
	Estero	90903	"	"	
	"	I5498	"	"	
	"	42333	"	"	
	F.S.	7403496	"	"	
	"	656I60	"	"	
	"	65I987	"	"	
	Estero	702I9	"	"	
	"	20010	"	"	
	"	5858	"	"	
	"	I903	"	"	
	"	474965	"	"	
	"	499355	"	"	
	"	36942	"	"	
LATIANO	F.S.	7404228	"	vuoto	
MESAGNE	"	653714	P	carico	
	"	650628	"	"	
	"	661870	"	"	
	"	654004	"	"	
	"	651768	"	"	
	"	647374	"	"	
	"	654299	"	"	
	"	623981	"	"	
	"	657563	"	"	
	"	652414	"	"	
	"	465827	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	carro	carro	carro		
GROTTAGLIE	F.S.	541426	Fc	vuoto	
	"	524540	Mv	carico	
	"	513004	"	"	
	"	513610	"	"	
	"	7400546	L	riparando	
	"	181661	Mv	"	
	"	9550257	L	vuoto	
	Estero	5452	"	carico	
	F.S.	491546	"	"	
	"	441II09	"	"	
	"	416661	"	"	
	"	455485	"	"	
	"	459360	L	"	
	Estero	90903	"	"	
	"	15498	"	"	
	"	42333	"	"	
	F.S.	7403496	"	"	
	"	656160	"	"	
	"	651987	"	"	
	Estero	70219	"	"	
	"	20010	"	"	
	"	5858	"	"	
	"	1903	"	"	
	"	474965	"	"	
	"	499355	"	"	
	"	36942	"	"	
LATIANO MESAGNE	F.S.	7404228	P	vuoto	
	"	653714	"	carico	
	"	650628	"	"	
	"	661870	"	"	
	"	654004	"	"	
	"	651768	"	"	
	"	647374	"	"	
	"	654299	"	"	
	"	623981	"	"	
	"	657563	"	"	
	"	652414	"	"	
	"	465227	"	"	
	"	416961	Mv	"	
	Estero	520017	"	"	
	F.S.	511220	"	"	
	"	574901	"	"	
	"	7405111	"	"	
	"	568015	"	"	
	Estero	18703	L	"	
	F.S.	1133709	F	"	
	Estero	23578	"	"	
	"	1795	"	"	
	"	479039	"	"	
	"	119123	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
LECCE	F.S.	I67093	F	riparando	
	"	I33986	"	"	
	"	25I73I	3	"	
	"	I025073	F	"	
	"	I[illegible]5I5	"	"	
	"	7202995	G	"	
	"	I678I9	F	"	
	Estero	I6320	"	"	
	"	93438	"	"	
	"	I3788[illegible]	"	"	
	F.S.	I56758	"	"	
	"	IOI4049	"	"	
	"	I34874	"	"	
	"	I87662	"	"	
	"	I84655	"	"	
	"	204277	G	"	
	"	I001459	E	"	
	"	I002220	"	"	
	"	II1529	P	"	
	"	I40207	Fl	"	
	"	250597	G	"	
	"	252I78	"	"	
	"	205427	"	"	
	"	I3[illegible]447	F	"	
	Estero	65I9I	"	"	
	"	68I	L	"	
	"	I2558	"	"	
	"	95525	"	"	
	F.S.	436281	"	"	
	"	470560	"	"	
	"	424386	"	"	
	Estero	7I6456	"	"	
	"	I579	"	"	
	F.S.	488468	"	"	
	"	490595	"	"	
	"	491688	"	"	
	"	740II93	"	"	
	"	467I3	"	"	
	"	413491	"	"	
	"	7406I34	"	"	
	"	040II8	"	"	
	Estero	7205906	"	"	
	"	29II	"	"	

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

"	I025075	F	"
"	I00515	"	"
"	7202995	G	"
"	I67819	F	"
Estero	I6320	"	"
"	93438	"	"
"	I3788X	"	"
F.S.	I56758	"	"
"	I014049	"	"
"	I34874	"	"
"	I87662	"	"
"	I64655	"	"
"	204077	G	"
"	I001459	E	"
"	I002220	"	"
"	II1529	P	"
"	I40207	F1	"
"	250597	G	"
"	252178	"	"
"	205427	"	"
"	I30447	F	"
Estero	65191	"	"
"	681	L	"
"	I2558	"	"
"	95525	"	"
F.S.	436281	"	"
"	470560	"	"
"	424386	"	"
Estero	716456	"	"
"	I579	"	"
F.S.	488468	"	"
"	490595	"	"
"	491688	"	"
"	740I193	"	"
"	46713	"	"
"	413491	"	"
"	7406134	"	"
"	040118	"	"
Estero	7205906	"	"
"	29911	"	"
"	50505	P	"
RFI.	755347	L	"
"	467982	"	"
F.S.	7470796	P	"
"	654417	"	"
"	648396	"	"
Privati	589633	M	"
"	589636	"	vuoto
"	514446	Mv	"
"	509058	"	ripassando

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
LECCE	Privati	5I4462	P	riparando	
	"	508089	"	"	
	"	5I4269	"	"	
	"	548372	"	"	
	"	508244	Mv	"	
	"	5I4408	"	"	
	"	568607	"	"	
	"	568355	"	"	
	"	54I486	"	"	
	"	5I4404	"	"	
	"	568[illegible]88	"	"	
	"	5I5654	"	"	
	"	5I2502	"	"	
	F.S.	9550847	M	vuoto	
	"	350203	"	"	
	Privato	508049	Mv	"	
	Estero	4I258	L	"	
	F.S.	427538	"	carico	
	"	490519	"	"	
	"	479688	"	"	
	"	46I447	"	"	
	"	48I379	"	"	
	Estero	26I40	"	"	
	F.S.	485304	"	"	
	"	4I7399	"	"	
	"	7470614	"	"	
	"	422372	"	"	
	"	465993	"	"	
	"	94750	"	"	
	"	40I027	"	"	
	"	475441	"	"	
	Estero	78057	"	"	
	F.S.	486760	"	"	
	"	4II[illegible]0	"	"	
	"	4I[illegible]760	"	"	
	"	465035	"	"	
	"	043928	"	"	
	Estero	23077	"	"	
	F.S.	3I993	"	"	
	"	45562	"	"	

Declassified E.O. 12356 Sec. Section 3.3/NND No. 785021

"	5I4269	"	"	
"	548372	"	"	
"	508244	Mv	"	
"	5I4408	"	"	
"	568607	"	"	
"	568355	"	"	
"	54I486	"	"	
"	5I4404	"	"	
"	568888	"	"	
"	5I5654	"	"	
"	5I2502	"	"	
F.S.	9550847	M	vuoto	
"	850203	"	"	
Privato	508049	Mv	"	
Estero	4I258	L	"	
F.S.	427538	"	carico	
"	490519	"	"	
"	479688	"	"	
"	46I447	"	"	
"	48I399	"	"	
Estero	26I40	"	"	
F.S.	485304	"	"	
"	4I7399	"	"	
"	7470614	"	"	
"	492372	"	"	
"	465999	"	"	
"	94750	"	"	
"	40I027	"	"	
"	47544I	"	"	
Estero	78057	"	"	
F.S.	486760	"	"	
"	4II[illegible]0	"	"	
"	4I[illegible]760	"	"	
"	465035	"	"	
"	043928	"	"	
Estero	23077	"	"	
F.X.	3I993	"	"	
"	43562	"	"	
F.S.	462865	"	"	
"	4I3564	"	"	
"	4I8694	"	"	
"	II0578	"	"	
"	204055	"	"	
"	20448I	"	"	
"	I43886	"	"	
"	I02I235	"	"	
Estero	703I	"	"	
F.S.	II28306	"	"	
"	I007080	"	"	

211

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
L E C C E	Estero	30512	F	vuoto	
	"	I3980	"	"	
	F.S.E.	2007	G	carico	
	F.S.	I0II386	E	"	
	"	I004I09	"	"	Lecce
	"	I44039	F	"	"
	"	I003378	E	"	"
	"	II7788	F	"	"
	tedesco	5054	P	vuoto	
	"	648072	P	"	
	FS	740[illegible]88	L	"	
	"	II5451	F	"	
	tedesco	5262I	L	"	
	FS	46I22I	L	"	
	"	I006535	E	"	
	II3II87	II3II87	F	"	
	estero	2I402	G	carico	Roma
	FS	I005836	E	"	"
	"	20I0200	G	"	"
Barletta Mar.	FS	7200592	G	"	Bari
	"	II27509	F	"	"
	"	II30985	F	"	"
	"	II2986	F	"	"
	"	II28I4I	F	"	"
	estefo	9478I	F	"	"
	FS	7I09477	F	"	"
	"	646288	P	"	"
	estero	774965	L	"	"
	FS	II779	F	"	"
	"	270425	G	"	"
	"	478687	L	"	Candelaro
	"	7404I68	L	"	"
	"	48390I	L	"	"
	estero	I3099	E	"	"
	"	9842I	L	"	"
	FS	472737	L	"	"
	"	4I7989	L	"	"
	"	477696	L	"	"
	"	436707	L	"	"
	"	4I6203	L	"	"
	"	492776	L	"	"
	estero	3I968	L	"	"
	FS	494I68	L	"	"
	estero	87494	P	"	"
	"	26714	P	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	I44039	P	"	"	
	"	I003378	E	"	"	
	"	II7788	F	"	"	
	tedesco	5064	P	vuoto		
	"	648078	P	"		
	FS	740[illegible]88	L	"		
	"	II545I	F	"		
	tedesco	5262I	L	"		
	FS	46I22I	L	"		
	"	I006535	E	"		
	[illegible]	[illegible]	F	"		
	estero	2I402	G	carico	Roma	
	FS	I005836	E	"	"	
	"	20I0200	G	"	"	
Barletta Mar.	FS	7200592	O	"	Bari	
	"	II27509	F	"	"	
	"	II30985	F	"	"	
	"	II2986	F	"	"	
	"	II28I4I	F	"	"	
	estero	94781	F	"	"	
	FS	7I09477	F	"	"	
	"	646288	P	"	"	
	estero	774965	L	"	"	
	FS	II779	F	"	"	
	"	270425	G	"	"	
	"	478687	L	"	Candelaro	
	"	7404I68	L	"	"	
	"	48390I	L	"	"	
	estero	I3099	E	"	"	
	"	9842I	L	"	"	
	FS	472737	L	"	"	
	"	4I7989	L	"	"	
	"	477696	L	"	"	
	"	436707	L	"	"	
	"	4I6203	L	"	"	
	"	492776	L	"	"	
	estero	3I968	L	"	"	
	FS	494I68	L	"	"	
	estero	87494	P	"	"	
	"	76714	P	"	"	
	FS	474574	L	"	Bari	
	estero	I9947	L	"	Barletta	
	"	II295	L	"		
	"	29599	L	"		
	FS	I73878	F	"		
	"	I00I58[illegible]	F	"		
	"	I0I0449	E	"		
	"	II5I87	F	"		
	estero	I95437	F	"		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
NASISI	ESTERO	52938	F	vuoto	
	FS	474937	L	"	
	estero	15419	F	"	
	FS	463732	L	"	
	"	631242	P	"	
	estero	18197	L	"	
	FS	114570	F	"	
	"	7645519	F	"	
	estero	5990	L	"	
	FS	487629	L	"	
	"	457352	"	"	
	estero	18992	F	"	
	FS	7600742	F	"	
	"	491342	L	"	
	"	I6I073	F	"	
	"	575501	M	"	
	"	575405	"	"	
	"	300402	Hg	"	
	"	303037	"	"	
	"	39I37I	"	"	
	"	326028	"	"	
	"	307372	"	"	
	"	308995	"	"	
	"	370059	"	"	
	"	300217	"	"	
	"	306215	"	"	
	"	306064	"	"	
	"	307I08	"	"	
	"	304083	"	"	
	"	315066	"	"	
	"	303I08	"	"	
	"	306380	"	"	
	"	303472	"	"	
	"	316896	"	"	
	"	390213	"	"	
	"	315942	"	"	
	"	315466	"	"	
	"	302424	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

N A S I S I	ESTERO	52938	F L	vuoto
	FS	474937	F L	"
	estero	15419	F L	"
	FS	463732	P L	"
	"	631242	F L	"
	estero	18197	F L	"
	FS	114570	F L	"
	"	7645519	L "	"
	estero	5990	F L	"
	FS	487629	F L	"
	"	457352	F L	"
	estero	18992	F L	"
	FS	7600742	F L	"
	"	491342	F L	"
	"	I6I073	F L	"
	"	575501	F L	"
	"	575405	F L	"
	"	300402	Hg "	"
	"	303037	" "	"
	"	39I37I	" "	"
	"	326028	" "	"
	"	307372	" "	"
	"	308995	" "	"
	"	370059	" "	"
	"	300217	" "	"
	"	305215	" "	"
	"	306064	" "	"
	"	307I08	" "	"
	"	304083	" "	"
	"	315066	" "	"
	"	303I08	" "	"
	"	306380	" "	"
	"	303472	" "	"
	"	316896	" "	"
	"	390213	" "	"
	"	315942	" "	"
	"	315466	" "	"
	"	302424	" "	"
	"	3I15674	" "	"
	"	4I5283	L F	"
	estero	2028I	" "	"
	"	83002	" "	"
	"	50066	" "	"
	FS	488512	L	"
	estero	16492	F	"
	"	209942	" E	"
	FS	I009585	F	"
	"	128505	Hg	"
	"	3040I5	"	"
	"	344215	"	"

210

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
FASISI	[illegible]	343087	Hg	vuoto	
	FS	300203	"	"	
	"	300930	"	"	
		301299	"	"	
	"	306788	"	"	
	"	300039	"	"	
	estero	9369I	F	"	
	FS	I021025	F	"	
	estero	9277I	F	"	
	"	3300I	"	"	
	FS	I86030	F	"	
	"	490836	L	"	
	"	77492025	L	"	
	"	7744551	L	"	
	"	I022I52	E	"	
	"	I0I0275	E	"	
	"	77I9501O	F	"	
	"	122376	E	"	
	"	I0I4298	E	"	
	"	I0I0264	E	"	
BRINDISI	"	7470601	L	"	
	"	538271	Mtv	"	
	"	8I04I3	Ver	attrezzi	
	"	550858	M	vuoto	
	"	9678464	MCTV	"	
	"	I72744	F	[illegible]ipe rado	
	FSE	1422	F	"	
	"	168365	"	"	
	"	7408964	"	"	
	Estero	6509	F	"	
	FS	7700510	Q	"	
	"	4I0155	L	"	
	Estero	2536	F	"	
	FS	752729	"	"	
	"	7404729	L	"	
	"	7770I0I	Q	"	
	"	457243	L	"	
	"	485I0I	L	"	
	"	7470397	"	"	
	"	7901030	Mo	"	
	estero	21942	F	buono	
	"	2171I3	P	"	
	FS	7706I19	G	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

		"	306783	"	"	
		"	300059	"	"	
		estero	93691	F	"	
		FS	I021026	F	"	
		estero	92771	F	"	
		"	33014	F	"	
		FS	186030	P	"	
		"	490686	L	"	
		"	774924025	L	"	
		"	7744551	L	"	
		"	I022192	L	"	
		"	I010275	E	"	
		"	7719501O	F	"	
		"	122376	F	"	
		"	I0I4298	E	"	
		"	I010264	E	"	
BRINDISI		"	7470601	L	"	
		"	532871	Mtv	"	
		"	810413	Ver	attrezzi	
		"	550858	M	vuoto	
		"	9678464	MSEV	"	
		"	276714	F	alberando	
		FSE	1422	F	"	
		"	168165	"	"	
		"	7408964	"	"	
		Estero	6509	P	"	
		FS	7706510	Q	"	
		"	410155	L	"	
		Estero	2530	F	"	
		FS	752729	"	"	
		"	7404729	L	"	
		"	7770101	Q	"	
		"	457523	L	"	
		"	485181	L	"	
		"	7470397	"	"	
		"	7901030	Lo	"	
		estero	1942	P	bucco	
		"	21713	P	"	
		FS	7706149	Q	"	
		"	698032	P	"	
		estero	91601	"	"	
		FS	I7.1593	F	cerico	Cerignola
		"	I022830	"	"	Barletta
		"	I43I37	"	"	Brindisi
		"	I0I0580	"	"	"
		estero	I708504	"	"	
		FS	I003557	"	"	
		"	I00766	"	"	
		"	I031425	"	"	
		"	654246	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
MOLFETTA	estero	5681	L	carico	
	FS	481299	L	"	
	"	417988	L	"	
	"	478158	L	"	
	estero	27282	L		
	FS	488532	L	vuoto	
	"	488637	L	"	
	"	472180	L	"	
	"	400675	L	carico	
	"	479852	L	"	
	"	460587	L	"	
	"	4777750	L	"	
	"	481089	L	"	
	"	353236	Hg	"	
	"	7279000	G	vuoto	
	"	7106402	F	"	
	"	103102?	E	"	
	"	1013677	E	"	
	estero	595		carico	
	FS	1004679	E	"	
	"	134854	F	"	
	"	188272	E	"	
	"	1004191	F	vuoto	
	"	172542	F	"	
	"	1133543	F	"	
	"	187897	F	"	
	"	7719?004	G	carico	
	estero	16808	F	"	
	FS	181077	F	"	
	"	186411	G	"	
	estero	29169	F	"	
	FS	7719504	Hg	"	
	"	309372	F	"	
	"	7170315	F	"	
	estero	1847	G	"	
	"	77074	G	"	
	FS	7202947	G	"	
	estero	3256			

Declassified E.O. 12356 Section 3.3/NND No. 785021

M O L F E T T A	estero	568I	L	carico
	FS	48I[illegible]99	L	"
	"	4I7988	L	"
	"	478I58	L	"
	estero	[illegible]7282	L	vuoto
	FS	488532	L	"
	"	488537	L	"
	"	47[illegible]I80	L	carico
	"	400675	L	"
	"	479852	L	"
	"	460587	L	"
	"	4777750	L	"
	"	48I089	L	"
	"	353236	Hg	vuoto
	"	7[illegible]79000	G	"
	"	7I06402	F	"
	"	I05I027	E	carico
	"	I0I3677	E	"
	estero	595	E	"
	FS	I004679	F	"
	"	I34854	F	"
	"	I88272	E	vuoto
	"	I004I9I	F	"
	"	I72542	F	"
	"	II33543	F	"
	"	I87897	F	carico
	"	77I93004	G	"
	estero	I6808	F	"
	FS	I8I077	G	"
	"	I864II	F	"
	estero	29I69	G	"
	FS	7719304	F	"
	"	309522	Hg	"
	"	7I70315	F	"
	estero	I847	F	"
	"	77074	G	"
	FS	7[illegible]02947	G	"
	estero	3956I	G	"
	FS	I43269	F	"
	"	35I339	Hg	"
	"	I024596	E	"
	"	406907	L	"
	"	4I3I84	L	"
	estero	I33I7	L	"
	FS	474085	L	vuoto
	"	40I464	L	carico
	"	644599	P	vuoto
	"	6445[illegible]22	P	carico
	"	648252	P	"
	estero	7260	P	"
	"	45980	L	"

209

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
G rumo App.	FS	304601	Hg	vuoto	
M O N O P O L I	USA	223374	G	"	
	FS	I167381	F	carico	
	estero	21444	G	"	
	"	2103	G	"	
	FS	7105346	F	"	
	ester	32703	H	"	
	FS	150691	F	"	
	"	7448052	L	"	
	estero	35922	H	"	
	"	77347	L	"	
	FS	660123	P	"	
	"	652713	P	"	
	"	962048	M	vuoto	
	"	982974	M	"	
	"	958279	"	"	
	"	958203	"	"	
	"	958II80	"	"	
	"	557007	"	"	
	"	582919	"	"	
	"	507013	"	"	
	"	566400	"	"	
	"	566401	"	"	
	"	558400	"	"	
	"	546350	Hg	"	
	"	582008	M	"	
	"	581068	"	"	
	"	982035	"	"	
	"	567066	"	"	
	"	958II8	"	"	
FERRANDINA	FS	475797	L	carico	Montalto
	"	413968	L	"	"
	"	477624	L	"	"
	"	416473	L	"	"
	"	414949	L	"	"
	"	490401	L	"	"
	"	495465	L	"	"
	"	416613	L	"	"
	"	471426	L	"	"
	DR	I2461	F	"	"
	"	I9042	G	"	"
	"	95561	My	"	"
	"	92421	"	"	"
	FS	I64482	F	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

0 2 7 3

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	2I03	G	"	
	FS	7I05346	P	"	
	esterr	32703	H	"	
	FS	I5069I	F	"	
	"	7448052	L	"	
	estero	35922	H	"	
	"	77347	L	"	
	FS	660I23	P	"	
	"	652713	P	"	
	"	982048	M	vuoto	
	"	988974	M	"	
	"	958279	"	"	
	"	958203	"	"	
	"	558II80	"	"	
	"	557007	"	"	
	"	582919	"	"	
	"	507013	"	"	
	"	566400	"	"	
	"	566401	"	"	
	"	558400	"	"	
	"	546350	Hg	"	
	"	582008	M	"	
	"	581068	"	"	
	"	982035	"	"	
	"	567066	"	"	
	"	958II8	"	"	
FERRANDINA	FS	475797	L	carico	Montalto
	"	413968	L	"	"
	"	477624	L	"	"
	"	416473	L	"	"
	"	414949	L	"	"
	"	498041	L	"	"
	"	495465	L	"	"
	"	416615	L	"	"
	"	471426	L	"	"
	DR	I2461	F	"	"
	"	I9042	G	"	"
	"	95561	MV	"	"
	"	92421	"	"	"
	FS	I64482	F	"	"
	"	IOII88	F	"	"
	DR	I8284	F	carico	Taranto
	"	71265	F	"	"
	FS	453031	L	"	"
	"	418765	L	"	"
	"	465934	L	"	"
	"	475292	L	"	"
CAROVIGNO	FS	646515	P	carico	Grottaglie
	"	651359	P	"	"
	"	660016	P	"	"
	"	647589	P	"	"
	"	651977	P	"	"

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
CAROVIGNO	FS	473409	L	vuoto	
	"	I025511	E	ripar.	
	"	I021919	E	"	
	"	7101507	E	"	
	estero	4475	L	"	
	"	4066	"	"	
	"	95833	L	"	
	"	20442	G	"	
	"	43620	B	"	
	"	4620	L	"	
Salandra -Grottole	FS	4I0206	L	carico	Rossano Cal.
	"	465642	"	"	"
	BR	97896	L	"	"
	FS	465604	L	"	"
	"	475495	L	"	Monastarace
	"	461496	L	"	"
S.Pietro Vern.	FS	[illegible]	Mx		
	"	513805	Mv	ripar.	
	"	541004	"	"	
	"	538041	"	"	
	"	548469	"	"	
	DR	I0II3	L	vuoto	
	"	26396	L	"	
	FS	4I6209	L	"	
	"	77492020	L	"	
	"	I84I03	F	"	Bari
	"	491930	L	"	"
	BR	I40I7	F	"	
Francavilla F.	FS	7448738	L	carico	
	"	4694II	L	"	
	"	475005	L	"	
	"	473577	L	"	
	"	446551	L	"	
	"	749I25	L	"	
	"	I62379	F	"	
	"	II0550	F	"	
	"	496387	L	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	I0?55II	E	ripar.	
	"	I0?I9I9	E	"	
	"	7I0I507	E	"	
	est&rc	4475	L	"	
	"	4066	"	"	
	"	95833	L	"	
	"	20442	G	"	
	"	43620	R	"	
	"	4620	L	"	
Salandra -Grottole	PS	4I0206	L	carico	Rossano Cal.
	"	465642	"	"	"
	BR	97896	L	"	"
	PS	465604	L	"	"
	"	475495	L	"	Monastarace
	"	46I496	L	"	"
S.Pietro Vern.	PS	[illegible]	Mx	"	
	"	5I3805	Mv	ripar.	
	"	54I004	"	"	
	"	538044	"	"	
	"	548469	"	"	
	DR	I0II3	L	vu&to	
	"	26396	L	"	
	PS	4I6?09	L	"	
	"	77492020	L	"	
	"	I84I03	P	?	Bari
	"	49I930	L	"	"
	BR	I40I7	F	"	
Francavilla F.	PS	7448738	L	carico	
	"	4694II	L	"	
	"	475005	L	"	
	"	473577	L	"	
	"	446551	L	"	
	"	749I25	L	"	
	"	I62379	F	"	
	"	II0550	F	"	
	"	496387	L	"	
	"	459777	L	"	
	"	468874	L	"	
	"	I84200	F	"	
	"	I004832	E	"	
	"	77I93007	F	"	
	"	4I0443	L	"	
	"	486850	L	"	
	"	497484	L	"	
	"	77495579	L	"	
	"	65759?	P	"	
	"	65I228	P	"	
	"	646I57	P	"	
	"	648278	P	"	
	"	476484	L	"	
	"	35I35I	Hg	"	

298

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Fra cavilla F.	FS	I02343	F	carico	
	"	20262I	G	"	
	nBTErs	I707	F	"	
	DR	I0000	F	"	
	FS	651937	P	"	
	"	5I3517	Mv	"	Empoli
	"	I007935	E	"	"
	"	I002554	E	"	"
	"	I62670	F	"	"
	"	IIII38	F	"	"
	"	I02432	E	"	"
	"	4I8345	L	vuoto	
	"	494I46	L	"	
	"	47II99	L	"	
	"	495778	L	carico	
	"	466779	L	"	
	"	446585	L	"	
	"	77495522	L	vuoto	
	estero	73255	L	"	
	FS	I02576	F	carico	
	DR	32279	L	"	
	"	I4689	F	"	
	FS	4I4569	L	"	
	DR	88934	F	"	
	FS	457983	L	"	
	"	4I6955	L	"	
	"	4II966	L	"	
	"	459870	L	"	
	"	4I5308	L	"	
	"	46I950	L	"	
	"	4I6309	L	"	
	"	4I2485	L	"	
Ofantino	"	I94840	F	vuoto	
	"	455097	L	carico	
	"	I85093	F	"	
	"	77195045	F	"	
	"	790I8I7	MA	"	Gravina
Gravina	"	I259	L	vuoto	
	FS	468254	L	"	
	"	450058	M	carico	
	"	II76I9	F	"	
Trepuzzi	estero	I303	F	"	
	FS	553800	Mv	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	DR	12000	P	"		
	FS	651937	P	"		
	"	5I35I7	Mv	"		Empoli
	"	I007935	E	"		"
	"	I002554	E	"		"
	"	I62570	F	"		"
	"	IIII38	F	"		"
	"	I02482	E	"		"
	"	4I8345	L	vuoto		
	"	494I46	L	"		
	"	47II99	L	"		
	"	495778	L	carico		
	"	466779	L	"		
	"	446585	L	"		
	"	77495522	L	vuoto		
	estero	73255	L	"		
	FS	I02576	F	carico		
	DR	32279	L	"		
	"	I4689	F	"		
	FS	4I4569	L	"		
	DR	68934	P	"		
	FS	457983	L	"		
	"	4I6955	L	"		
	"	4II966	L	"		
	"	459870	L	"		
	"	4I5308	L	"		
	"	46I959	L	"		
	"	4I6309	L	"		
	"	4I2485	L	"		
Ofantino	"	I94840	F	vuoto		
	"	455097	L	carico		
	"	I85093	F	"		
	"	77I95045	F	"		
	"	790I8I7	MA	"		Gravina
Gravina	"	I250	L	vuoto		
	FS	468254	L	"		
	"	950058	M	carico		
	"	II76I9	F	"		
Trepuzzi	estero	I303	F	"		
	FS	553800	Mv	"		
	"	5I4463	"	"		
	"	5I4322	"	"		
	"	5285I4	"	"		
	"	982087	MO	vuoto		
Ostuni	"	7274295	F	carico		Incoronata
	"	9550875	MA	"		
Fasano	"	9670482	MA	vuoto		
	"	9670I03	"	"		
Mola di B.	estero	I295	L	carico		Bitetto
Ortonava	FS	493306	L	vuoto		
	"	7I03615	F	ripar.		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/le	Esteri	I7722	L	carico	
	"	856I9	"	"	
	F.S.	655126	P	"	
	"	II31980	Fo	"	
	"	659705	P	"	
	"	5I46I6	L	vuoto	
	"	533003	"	"	
	"	508658	"	"	
	"	546601	"	"	
	"	0990I64	"	"	
	Esteri	XXXXX			
	"	72566	"	ripsrando	
	"	46270	"	"	
	"	480	"	"	
	"	99765	"	"	
	"	49706	"	"	
	"	324I4	"	"	
	"	69652	"	"	
	F.S.	474393	"	"	
	"	492552	"	"	
	"	473078	"	"	
	"	44I0I54	"	"	
	"	77II00II	"	carico-Rip.	
	"	4I342I	"	"	
	"	463616	"	"	
	"	48884I	"	"	
	"	4I693I	"	vuoto	
	"	4I9056	"	"	
	"	486358	"	"	
	"	300II6	Hg	carico	FSE
	"	304741	"	"	
	"	I023086	F	"	
	"	III5793	"	"	
	"	I028762	"	"	
	"	I002221	"	"	
	"	I008942	"	"	
	"	I003293	"	"	
	"	I0028779	"	"	

207

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	856I9	"	"	
F.S.	653126	P	"	
"	II3I980	Fo	"	
"	650705	P	"	
"	5I4616	L	vuoto	
"	533003	"	"	
"	508658	"	"	
"	546601	"	"	
"	090I64	"	"	
Estero	XXXXX			
	72566	"	riperando	
"	46270	"	"	
"	480	"	"	
"	99765	"	"	
"	49706	"	"	
"	324I4	"	"	
"	69652	"	"	
F.S.	474393	"	"	
"	492552	"	"	
"	473078	"	"	
"	44I0I54	"	"	
"	77II00II	"	carico-Rip.	
"	4I342I	"	" " "	
"	463616	"	" " "	
"	48884I	"	" " "	
"	4I693I	"	vuoto	
"	4I9056	"	"	
"	486358	"	"	
"	300II6	Hg	carico	FSE
"	30474I	"	"	
"	I02308	F	"	
"	III5793	"	"	
"	I028762	"	"	
"	I00222I	"	"	
"	I008942	"	"	
"	I003293	"	"	
"	I0028779	"	"	
"	II29928	"	"	
"	I678I6	"	"	
"	I00763	"	"	
Estero	I2823	"	vuoto	
"	6I6I4	"	"	
"	38855	"	carico	
"	66420	"	"	
"	22272I	U.S.A.	vuoto	
"	279695	estero	"	
"	229I79	"	"	
"	I579I	"	"	

207

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I C le	estero	I927	estero	carico	
	"	I9539	"	vuoto	
	"	I9647	"	carico	
	"	5I765	"	"	
	"	27827	"	"	
	"	262I00	"	"	
	"	30394	"	"	
	"	34898	"	"	
	"	7704650I	"	carico	
	"	40318	"	"	
	"	48789	"	"	
	"	6471I8	"	vuoto	
	"	90436	"	"	
	"	I3432	"	carico	
	"	99677	"	"	
	"	9I964	"	"	
	"	29275	"	vuoto	
	"	34609	"	"	
	"	270740	"	"	
	"	3I32	"	"	
	"	32285	"	carico	
	"	60725	"	"	
	"	25278	"	"	
	"	94537	"	"	
	F.S.	I04I0	V8c	carro attrezzi	
	"	44II0	"	"	
	"	457I92	L	riparando	
	"	7470064	"	"	
	"	9402005	"	"	
	"	473I64	"	"	
	"	7470218	"	"	
	"	466555	"	"	
	FSB	4254	"	carico	
	"	4257	"	"	
	"	4207	"	"	
	FS	464253	I	vuoto-Rip.	
	estero	II583	"	carico	
	"	4836I	"	riparando	
	"	3787I	"	"	
	"	0961	"	"	
	"	6944I	"	"	
	"	25446	"	"	
	"	27939	P	vuoto	
	"	78897	"	"	
	"	6257	"	riparando	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	5I765	"	"	
	"	27827	"	"	
	"	262I00	"	"	
	"	30394	"	"	
	"	34898	"	"	
	"	7704650I	"	carico	
	"	403I8	"	"	
	"	48789	"	"	
	"	647I8	"	vuoto	
	"	90436	"	"	
	"	I3432	"	carico	
	"	99677	"	"	
	"	9I964	"	"	
	"	29275	"	vuoto	
	"	34609	"	"	
	"	270740	"	"	
	"	3I32	"	"	
	"	32285	"	carico	
	"	60725	"	"	
	"	25278	"	"	
	"	94537	"	"	
	F.S.	I04I0	Vso	carro attrezzi	
	"	44II0	"	"	
	"	457I92	L	riparando	
	"	7470064	"	"	
	"	8402005	"	"	
	"	473I64	"	"	
	"	7470218	"	"	
	"	466555	"	"	
	FSB	4254	"	carico	
	"	4257	"	"	
	"	4207	"	"	
	FS	464253	L	vuoto-Rip.	
	estero	II583	"	carico	
	"	4836I	"	riparando	
	"	3787I	"	"	
	"	96I	"	"	
	"	6944I	"	"	
	"	25446	"	"	
	"	27939	P	vuoto	
	"	78897	"	"	
	"	5257	"	riparando	
	"	I3796	"	"	
	"	76784	"	"	
	"	80845	"	"	
	"	4277	L	carico	
	"	97832	"	"	Modugno
	"	63869	"	"	
	"	20033	"	"	
	"	23368	"	"	
	"	29207	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 17 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I C16	Estero	81293	F	carioc	Matera
	"	5474	"	" "	"
	"	24673	"	" "	"
	"	181881	"	" "	Brindisi
	"	29116	"	"	"
	"	222937	"	"	"
	"	11941	"	"	Capurso
	"	11573		"	Copertino
	"	53409	"	"	"
	"	8340	"	vuoto	"
	"	224313	"	"	"
	"	10573	"	"	"
	"	61412	"	"	"
	"	266512	"	"	"
	"	22633	"	"	"
	"	221276	"	"	"
	"	52201O	"	riparando	"
	"	34204	"	carico	Bari
	"	26274	"	"	Bari
	"	4669	"	"	Brindisi
	"	33566	"	"	"
	"	81129	"	"	Giovinazzo
	"	96388	"	"	Barletta
	"	52646	L	"	"
	I6008	I6008	"	riparando	
	"	357722	"	"	
	"	94755	"	"	
	"	484I3	P	vuoto	
	"	I2261	"	"	
	"	70040	"	"	
	"	8708	"	"	
	"	I97059	"	"	
	"	353443	"	riparando	
	"	3922	"	"	
	"	2269	L	carico	
	"	4843I	"	"	
	"	20028	"	"	
	Estero	55I05	" x	vuoto	
	F.S	524722	Ha	carico	

206

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	6474	"	"	"	"
"	24673	"	"	"	"
"	15188I	"	"	"	Brindisi
"	29II6	"	"	"	"
"	222937	"	"	"	"
"	II94I	"	"	"	Capofino
"	II573	"	"	"	Capofino
"	53409	"	"	"	"
"	8340	"	vuoto	"	"
"	224313	"	"	"	"
"	I0573	"	"	"	"
"	6I4I2	"	"	"	"
"	266512	"	"	"	"
"	22533	"	"	"	"
"	22I276	"	"	"	"
"	522010	"	riparando	"	"
"	34204	"	carico	Bari	
"	26274	"	"	Bari	
"	4669	"	"	Brindisi	
"	33566	"	"	"	
"	8II29	"	"	Giovinazzo	
"	96388	"	"	Barletta	
"	52645	"	"	"	
I600	I6008	"	ripa[illegible]ando		
"	357722	"	"		
"	94755	"	"		
"	484I3	P	vuoto		
"	I2261	"	"		
"	70040	"	"		
"	8708	"	"		
"	I97059	"	"		
"	353443	"	ri[illegible]arando		
"	3922	"	"		
"	2269	L	carico		
"	4843I	"	"		
"	20028	"	"		
Estero	55I05	" x	vuoto		
F.S	524722	Ma	carico		
"	943341	"	"		
"	98I255	"	"		
"	9034I5	"	"		
"	5I4304	"	"		
"	5670710	"	"		
Estero	928I40	"	"		
F.S.	300805	Bg	carico	Napoli	
"	30I[illegible]89	"	"	"	
"	390051	"	"	"	
"	30300	"	"	"	

206

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I C/Le	F.S.	300009	Hg	carico	Napoli
	"	306097	"	"	"
	"	796I00I	Mo	vuoto	
	"	66I059	P	carico	Parco Sud
	"	655594	"	"	
	"	655325	"	"	
	"	651885	"	riparando	
	"	62339I	"	"	
	"	645886	"	"	
	"	654616	"	carico	Foggia
	"	627I30	P	"	Vasto
	"	604443	L	riparando	
	"	4I7836	"	"	
	"	4I0I32	"	"	
	Estero	I8I69	"	"	
	"	9I90	"	"	
	"	97366	"	"	
	F.S.	480206	"L	"	
	Estero	I646	"	riparando	
	"	353502	"	"	
	"	24587	"	"	
	"	I988	"	"	
	"	I56I4	"	"	
	"	55276	"	"	
	FS	77I920I3	"	"	
	"	I539[illegible]6	F	"	
	"	I002[illegible]9	"	"	
	"	I022[illegible]5	"	"	
	"	I005844	"	"	
	Estero	400	"	"	
	"	72973	"	"	
	"	65729	"	"	
	F.S;E.	II006	Ma	carico	B A R I
	F.S.	487062	L	carico	
	"	4I9372	"	"	
	"	477344	"	"	
	"	77496024	"	"	
	"	456398	"	"	
	"	4I6667	"	"	
	"	47I255	"	"	
	"	486680	"	"	
	"	400227	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	661059	P	carico	Parco Sud	
"	655594	"	"		
"	655325	"	"		
"	651885	"	riparando		
"	623391	"	"		
"	645886	"	"		
"	654616	"	carico	Foggia	
"	627130	P	"	Vasto	
"	604433	L	riparando		
"	417836	"	"		
"	410132	"	"		
Estero	18169	"	"		
"	9190	"	"		
"	97366	"	"		
F.S.	480206	"L	"		
Estero	1646	"	riparando		
"	353502	"	"		
"	24587	"	"		
"	1988	"	"		
"	15614	"	"		
"	55276	"	"		
FS	771920[illegible]3	"	"		
"	153916[illegible]	F	"		
"	100298[illegible]	"	"		
"	102275	"	"		
"	1005844	"	"		
Estero	400	"	"		
"	72973	"	"		
"	65729	"	"		
F.S;E.	11006	Ma	carico	BARI	
F.S.	487062	L	carico		
"	419372	"	"		
"	477344	"	"		
"	77496024	"	"		
"	456398	"	"		
"	416607	"	"		
"	471255	"	"		
"	486680	"	"		
"	400227	"	"		
"	740033	"	"		
"	469974	"	"		
"	459660	"	"		
"	472220	"	"		
"	485[illegible]12	"	"		
"	412598	"	"		
Esteri	91705	"	"		
"	24662	"	"		
"	16318	"	"		
"	17813	"	"		
"	62294	"	"		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/le	E.C.	752927	P	carico	Giovinazzo
	"	652964	"	"	Leverano
	"	646649	"	"	"
	"	IT3I978	"	vuoto	
	"	622701	"	"	
	"	646341	"	"	
	"	648120	"	"	
	"	655035	"	"	
	"	657962	"	vuoto	
	"	646473	"	vuoto Rip-	
	"	645073	"	vuoto	
	"	776550I	"	"	
	"	7600700	"	"	
	"	623584	"	"	
	"	667396	"	"	
	"	694273	P.O.Z.	carico	
	"	699063	"	vuoto	
	"	699062	"	"	
	"	693699	"	"	
	"	694287	"	"	
	"	698069	"	"	
	"	931700	M	carico	Altamura
	"	925818	"	"	"
	"	551605	"	vuoto	
	"	560405	"	"	
	"	9581123	"	"	
	"	91273I	"	"	
	"	0500658	"	"	
	"	943381	"	"	
	"	930656	"	"	
	"	945199	"	"	
	"	990072	"	"	
	"	I22387	P	carico	
	"	771965I8	"	"	
	"	I8726I	"	"	
	"	II23786	"	"	
	"	I866I8	"	"	
	"	I00226	"	"	

205

Declassified E.O. 12356 Section 3.3/NND No. 785021

BARI C/le	P.S.	752927	P	carico Gravellona	
	"	652964	"	"	Leverano
	"	646649	"	"	"
	"	113I978	"	vuoto	
	"	622701	"	"	
	"	646541	"	"	
	"	648I20	"	"	
	"	655035	"	"	
	"	657962	"	vuoto	
	"	646473	"	vuoto Rip-	
	"	645073	"	vuoto	
	"	776550I	"	"	
	"	7600700	"	"	
	"	623584	"	"	
	"	657396	"	"	
	"	694273	P.O.Z.	carico	
	"	699063	"	vuoto	
	"	699062	"	"	
	"	695699	"	"	
	"	694287	"	"	
	"	698069	"	"	
	"	931700	M	carico	Altamura
	"	925818	"	"	"
	"	551605	"	vuoto	
	"	560405	"	"	
	"	9581I23	"	"	
	"	9I273I	"	"	
	"	0500658	"	"	
	"	943381	"	"	
	"	930656	"	"	
	"	945I99	"	"	
	"	990072	"	"	
	"	I22387	P	carico	
	"	77I965I8	"	"	
	"	I8726I	"	"	
	"	II23786	"	"	
	"	I866I8	"	"	
	"	I00226	"	"	
	"	39I445	"	vuoto	
	"	I749I2	"	"	
	"	00I276	"	"	
	"	I82605	"	"	
	"	39I607	"	"	
	"	77I96049	"	"	
	"	308566	"	"	
	"	30656I	"	"	
	"	39I479	"	"	
	"	30342	"	"	
	"	3I5204	"	"	
	"	39I407	"	"	

205

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/Le	F.S.	303240	F	vuoto	
	"	304279	"	"	
	"	300647	"	"	
	"	300044	"	"	
	"	100320	"	"	
	"	306353	"	"	
	"	315314	"	"	
	"	749303	L	"	
	"	455162	"	"	
	"	491673	"	"	
	"	495923	"	"	
	"	477902	"	"	
	"	489930	"	"	
	"	413195	"	"	
	"	478392	"	"	
	"	487059	"	"	
	"	490789	"	"	
	"	7448386	"	"	
	"	410497	"	"	
	"	406581	"	"	
	"	410907	"	"	
	"	408166	"	carico	
	"	710471O	F	"	Matera
	"	307557	"	"	"
	"	308181	"	"	"
	"	300712	"	"	"
	"	162788	"	"	Foggia
	"	502408	"	"	"
	"	7719601 7	"	"	"
	"	111912 6	"	"	"
	"	750316 4	"	"	"
	"	92II00	Ma	vuoto	
	"	981300	"	"	
	"	591038	"	"	
	"	930123	"	"	
	"	7109973	FK	"	
	"	7101365	F	"	
	"	7719602 1	"	"	
	"	1090651	"	"	
	"	710272 1	"	"	
	"	173201	"	"	
	"	159741	"	"	
	"	202867	G	"	
	"	351370	H	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	300044	"	"		
"	I00320	"	"		
"	306353	"	"		
"	3I5 I4	"	"		
"	74930I3	L	"		
"	495I62	"	"		
"	49I073	"	"		
"	495923	"	"		
"	477902	"	"		
"	489930	"	"		
"	4I3I95	"	"		
"	478392	"	"		
"	487059	"	"		
"	490789	"	"		
"	7448386	"	"		
"	4I0497	"	"		
"	40658I	"	"		
"	4I0907	"	"		
"	408I66	"	"		
"	7I047I0	F	carico		
"	307557	"	"	Matera	
"	308I9I	"	"	"	
"	300712	"	"	"	
"	I62788	"	"	"	
"	502408	"	"	"	
"	77I96017	"	"	Foggia	
"	I II9I26	"	"		
"	7303I64	"	"		
"	92II00	Ra	vuoto		
"	98I300	"	"		
"	59I038	"	"		
"	930I23	"	"		
"	7I09973	FX	"		
"	7I0I365	F	"		
"	77I9602I	"	"		
"	I09068I	"	"		
"	7I0272I	"	"		
"	I732 0I	"	"		
"	I5974I	"	"		
"	202867	G	"		
"	35I370	H	"		
"	I02I425	F	"		
"	I36I4I	"	"		
"	I72I280	"	"		
"	434I89	L	carico	Teverola	
"	774960I	"	"	S.Giovanni Barra	
"	645940	P	vuoto		
"	464565	L	"		
"	495537	"	"		
"	473I79	"	"		
"	495700	"	carico		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/le	F.S.	7[illegible]6[illegible]	L	Carico	
BARI C/le	Esteri	29207	L	Carico	
	"	I8547	"	"	
	"	77497	"	"	
	"	II890	"	vuoto	
	"	9445	"	carico	
	"	I9223	"	"	
	"	27889	"	buono	
	"	23693	"	"	
	"	I7898	"	"	
	"	51876	"	carico	
	"	51701	"	vuoto	
	"	I709	"	carico	
	"	4274	"	"	
	"	61385	"	vuoto	
	"	I0970	"	carico	
	"	5249	"	"	
	"	2I06	"	"	
	"	33I98	"	"	
	"	673	"	"	
	"	29837	"	"	
	FS	9582236	M	vuoto	
	"	9582023	"	"	
	"	9532034	"	"	
	"	807335	grù	"	
	"	982269	Ma	"	
	"	98223I	"	"	
	"	982003	"	"	
	"	308589	Hg	"	
	"	982009	M	"	
	"	30I2I3	Hg	ripafando	
	"	39I423	"	"	
	"	306986	"	"	
	"	39I523	"	vuoto	
	"	30I497	"	riparando	
	"	952405	Ma	vuoto	
	"	990238	M	"	
	"	9590276	"	"	
	"	990200	"	"	
	"	9590068	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

B A R I C/le	P.S.	7[illegible]6I6	L	Carico
B A R I C/le	Esteri	29207	I	Carico
"	"	I8547	"	"
"	"	77497	"	"
"	"	II890	"	vuoto
"	"	9445	"	carico
"	"	I9223	"	"
"	"	27889	"	bueno
"	"	23693	"	"
"	"	I7898	"	"
"	"	5I876	"	carico
"	"	5I70I	"	vuoto
"	"	I703	"	carico
"	"	4274	"	"
"	"	6I385	"	vuoto
"	"	I0970	"	carico
"	"	5249	"	"
"	"	2I06	"	"
"	"	33I98	"	"
"	"	675	"	"
"	"	29837	"	"
"	PS	9582236	M	vuoto
"	"	9582023	"	"
"	"	9582034	"	"
"	"	807335	grù	"
"	"	982269	Ma	"
"	"	982231	"	"
"	"	982003	"	"
"	"	308589	Hg	"
"	"	982009	M	"
"	"	30I2I3	Hg	ripafando
"	"	39I423	"	"
"	"	306986	"	"
"	"	39I523	"	"
"	"	30I497	"	vuoto
"	"	932405	Ma	riparando
"	"	990238	M	vuoto
"	"	9590276	"	"
"	"	990200	"	"
"	"	9590068	"	"
"	"	98II6I	"	"
"	"	552218	"	"
"	"	0900009	"	"
"	"	982073	"	"
"	"	900024	"	"
"	"	900I45	"	"
"	"	598863	"	"
"	"	52II72	"	"
"	"	9II257	"	"
"	"	958I083	"	"
"	"	0600I54	"	"

294

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I Cle	FS	598709	M	vuoto	
	"	98I2I7	"	"	
	"	7902807	"	"	
	"	300203	Hg	ripafando	
	"	509616	"	"	
	"	925810	M	"	
	"	9300137	"	"	
	"	7402616	L	carico	
	"	4I3867	"	"	
	"	467872	"	"	
	"	4I8I49	"	"	
	"	447363	"	"	
	"	40I287	"	"	
	"	466921	"	"	
	"	4I7853	"	"	
	"	7470I64	"	"	
	"	77495517	"	"	
	"	482935	"	"	
	"	482567	"	"	
	"	409972	"	"	
	"	4I6300	"	"	
	"	491744	"	"	
	"	4I740I	"	"	
	"	40974I	"	"	
	"	4I6757	"	"	
	"	4I3332	"	"	
	"	77495526	"	"	
	"	4I5269	"	"	
	"	4I5846	"	"	
	"	042I76	"	"	
	"	7407944	"	"	
	"	478488	"	"	
	"	486I67	"	"	
	"	4I5490	"	"	
	"	488487	"	"	
	"	4I5949	"	"	
	"	I029II0	E	vuoto	
	"	I0I4470	"	"	
	"	I0II53I	"	"	
	"	I005772	"	"	
	"	I008273	"	"	
	"	I020224	"	"	
	"	I0I6622	"	"	
	"	I0I0447	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	300203	Hg	riparato
"	509616	"	"
"	925810	E	"
"	9300137	"	"
"	7402616	E	carico
"	413867	"	"
"	467572	"	"
"	418149	"	"
"	447363	"	"
"	401287	"	"
"	466921	"	"
"	417853	"	"
"	7470164	"	"
"	77495517	"	"
"	482935	"	"
"	482567	"	"
"	409972	"	"
"	416300	"	"
"	491744	"	"
"	417401	"	"
"	409741	"	"
"	416757	"	"
"	413332	"	"
"	77495526	"	"
"	415269	"	"
"	415846	"	"
"	042176	"	"
"	7407944	"	"
"	478488	"	"
"	486167	"	"
"	415490	"	"
"	488487	"	"
"	415949	"	"
"	1029110	E	vuoto
"	101 4470	"	"
"	1011531	"	"
"	1005772	"	"
"	1008273	"	"
"	1020224	"	"
"	101 6622	"	"
"	1010447	"	"
"	102791I	"	riparando
"	101 6027	"	"
"	1002156	"	"
"	101 6589	"	"
"	1005304	"	"
"	604374	P	carico
"	654943	"	"
"	597882	"	"
"	646749	"	"
"	752923	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 22 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I Clo	F.S.	I59179	F	Vuoto	
	"	I53483	"	"	
	"	II7923	"	"	
	"	260393	"	"	
	"	252158	"	"	
	"	III4768	"	"	
	"	300162	"	"	
	"	251886	"	"	
	"	418962	"	"	
	"	001001	"	"	
	"	343013	"	"	
	"	315095	"	"	
	"	300293	"	"	
	"	203266	"	"	
	"	I013417	L	carico	
	"	I017098	"	"	
	"	I015096	"	"	
	"	II31935	"	"	
	"	I[illegible]3869	"	"	
	"	I031272	"	"	
	"	I0I2[illegible]35	"	"	
	"	I0[illegible]8I4	"	"	
	"	I00I[illegible]63	"	"	
	"	I009204	"	Vuoto	
	"	I0I6414	"	"	
	"	445572	L	carico	
	"	408990	"	"	
	"	490386	"	"	
	"	456780	"	"	
	"	4104I0	"	"	
	"	467894	"	"	
	"	473500	"	"	
	"	040435	"	"	
	"	459I60	"	"	
	"	414195	"	"	
	"	487I35	"	"	
	"	493560	"	"	
	"	464897	"	"	
	"	495701	"	"	

203

Declassified E.O. 12356 Section 3.3/NND No. 785021

B A R I Clc	F.S.	I59170	F	vuoto
	"	I53483	"	"
	"	II7923	"	"
	"	260393	"	"
	"	252155	"	"
	"	III4768	"	"
	"	300162	"	"
	"	251886	"	"
	"	418962	"	"
	"	001001	"	"
	"	343013	"	"
	"	315095	"	"
	"	300203	"	"
	"	203266	"	"
	"	I01[illegible]417	M	carico
	"	I017998	"	"
	"	I015096	"	"
	"	II31935	"	"
	"	I[illegible]2369	"	"
	"	I031272	"	"
	"	I012436	"	"
	"	I0[illegible]1	"	"
	"	I001365	"	"
	"	I009204	"	vuoto
	"	I015414	"	"
	"	445572	L	carico
	"	408990	"	"
	"	490386	"	"
	"	456780	"	"
	"	410410	"	"
	"	467894	"	"
	"	473500	"	"
	"	040435	"	"
	"	459160	"	"
	"	414195	"	"
	"	487135	"	"
	"	493560	"	"
	"	454897	"	"
	"	49570I	"	"
	"	469197	"	"
	"	480042	"	"
	"	410354	"	"
	"	410430	"	"
	"	444769	"	"
	"	479925	"	"
	"	4020I4	"	"
	"	465152	"	"
	"	482789	"	"
	"	465915	"	"
	"	498592	"	"

203

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I Cle	~~FS~~	~~FS~~ 416684	I	carico	
	"	26030	G	vuoto	
	"	I0C2211	F	"	
	"	I0I93 5	"	"	
	"	I5I65	"	"	
	"	III5[illegible]3	"	"	
	"	I36I46	"	"	
	"	7I70511	"	"	
	"	I52439	"	"	
	"	I0I9045	"	"	
	"	I8687[illegible]	"	"	
	"	I00I853	"	"	
	"	7100377	"	"	
	"	I005455	"	"	
	"	111785	"	"	
	"	159954	"	"	
	"	418841	"	"	
	"	460495	"	"	
	"	488584	"	"	
	"	486788	"	"	
	"	496577	"	"	
	"	4II593	"	"	
	"	040I02	"	"	
	"	447782	"	"	
	"	4I7331	"	"	
	"	479531	"	"	
	"	4I7314	"	"	
	"	040I99	"	"	
	"	490221	"	"	
	"	482877	"	"	
	"	040954	"	"	
	"	478505	"	"	
	"	472I87	"	"	
	"	487719	"	"	
	"	486793	"	"	
	"	453397	"	"	
	"	409I72	"	"	
	"	495I30	"	"	
	"	444[illegible]184	"	"	
	"	49I6[illegible]	"	"	
	"	411680	"	"	
	"	490I20	"	"	
	"	417683	"	"	
	"	478683	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	"	1115[illegible]3	"	"	
"	"	336146	"	"	
"	"	7170511	"	"	
"	"	102439	"	"	
"	"	119045	"	"	
"	"	136871	"	"	
"	"	100[illegible]835	"	"	
"	"	7100377	"	"	
"	"	1005455	"	"	
"	"	111725	"	"	
"	"	155954	"	"	
"	"	418841	"	"	
"	"	460495	"	"	
"	"	488584	"	"	
"	"	486788	"	"	
"	"	496588	"	"	
"	"	411593	"	"	
"	"	040192	"	"	
"	"	447782	"	"	
"	"	417331	"	"	
"	"	475531	"	"	
"	"	417314	"	"	
"	"	040195	"	"	
"	"	490221	"	"	
"	"	482377	"	"	
"	"	040954	"	"	
"	"	478505	"	"	
"	"	472187	"	"	
"	"	487719	"	"	
"	"	486793	"	"	
"	"	453397	"	"	
"	"	409172	"	"	
"	"	495130	"	"	
"	"	444[illegible]184	"	"	
"	"	491[illegible]	"	"	
"	"	411680	"	"	
"	"	450150	"	"	
"	"	417683	"	"	
"	"	478683	"	"	
"	"	486901	"	"	
"	"	439324	"	"	
"	"	444131	"	"	
"	"	463241	"	"	
"	"	434160	"	"	
"	"	416322	"	"	
"	"	468885	"	"	
"	"	462514	"	"	
"	"	454487	"	"	
"	"	470960	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24-8 *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Parco Nord	FS	551285	MO	vuoto	
	"	599603	"	"	
	estero	934747	MF	"	
	FS	980079	"	vuoto	
	estero	0990656	"	"	
	FS	982270	MO	"	
	"	941936	"	"	
	"	9581252	MP	"	
	"	9581241	"	"	
	"	905496	"	"	
	"	944037	"	"	
	"	930640	"	"	
	estero	985041	"	"	
	FS	945929	"	"	
	"	958136	"	"	
	"	93II09	"	"	
	"	958813	"	"	
	"	931432	"	"	
	"	9580096	"	"	
	estero	0590496	MV	"	
	FS	551096	MO	"	
	estero	553239	"	"	
	FS	944341	MO	"	
	"	931333	"	"	
	"	958II89	"	"	
	"	958II37	"	"	
	estero	902I76	"	"	
	"	928546	"	"	
	FS	943042	"	"	
	estero	580853	MP	"	
	FS	510269	MO	"	
	"	987625	MP	carico	
	estero	859II9	"	vuoto	
	FS	921380	M	carico	
	"	I90040	F	tiper.	
	estero	550765	MP	"	
	FS	958853	MO	vuoto	
	estero	I03628	MP	"	
	FS	560432	"	"	
	"	560423	"	"	

202

Declassified E.O. 12356 Section 3.3/NND No. 785021

Bari Turco Ford	Fs	593269	[illegible]	"	"
	"	599803		"	"
	estero	934747	MF	"	vuoto
	Fs	980479	"	"	"
	estero	0500656	"	"	"
	Fs	982279	"	80	"
	"	941036	"	"	"
	"	9581263	"	MD	"
	"	9581211	"	"	"
	"	503496	"	"	"
	"	944337	"	"	"
	"	930640	"	"	"
	estero	925941	"	"	"
	Fs	945929	"	"	"
	"	9581167	"	"	"
	"	931109	"	"	"
	"	596813	"	"	"
	"	931432	"	"	"
	"	9580096	"	"	"
	estero	0500496	"	MV	"
	Fs	592096	"	MO	"
	estero	553239	"	"	"
	Fs	943541	"	MD	"
	"	931332	"	"	"
	"	9581109	"	"	"
	"	9581197	"	"	"
	estero	902170	"	"	"
	"	926946	"	"	"
	Fs	943042	"	"	"
	estero	580853	"	MP	"
	Fs	510269	"	MO	"
	"	951625	"	MP	carico
	estero	950119	"	"	vuoto
	Fs	921380	"	M	carico
	"	150040	"	"	tiper.
	estero	550705	"	MP	"
	Fs	596653	"	MO	vuoto
	estero	103648	"	MP	"
	Fs	560432	"	"	"
	"	560443	"	"	"
	"	548215	"	MO	"
	"	550651	"	"	"
	estero	775020	"	"	"
	"	7759307	"	"	"
	"	7759307	"	"	"
	Fs	942318	"	MB	"
	estero	553232	"	"	"
	Fs	9822[illegible]6	"	"	"
	"	982071	"	"	"
	estero	926304	"	"	"

202

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Punto Nord	FS	931979	Mp	vuoto	
	"	9581336	"	"	
	"	941789	"	"	
	"	921566	MO	"	
	"	913297	Mb	"	
	"	930691	Mp	"	
	"	945145	"	"	
	estero	0500427	Mp	"	
	FS	906812	"	"	
	estero	9531106	Me	"	
	"	909406	Mo	"	
	"	943644	Mr	"	
	"	950687	"	"	
	FS	906504	"	"	
	"	9581212	Mp	"	
	"	941683	Mo	"	
	"	932168	Me	"	
	"	908571	"	"	
	FL	950822	M	"	
	"	9581634	Mp	"	
	"	945932	"	"	
	"	941367	"	"	
	ester	953215	"	"	
	"	902386	"	"	
	"	0500809	Mp	"	
	"	941156	Mc	"	
	FS	9032119	Mc	"	
	FS	941358	"	"	
	"	9581277	M	"	
	FS	0500208	Mp	"	
	"	0500493	"	"	
	"	902527	Mo	"	
	"	909455	"	"	
	"	9581232	Mp	"	
	"	931027	Mo	"	
	estero	926306	"	"	
	FS	943032	"	"	
	estero	925586	"	"	
	FS	951421	Mb	"	
	"	9581138	Mp	"	
	"	9500300	"	"	
	"	9581324	Mp	"	
	"	9581359	"	"	
	"	931042	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

	"	521566	Mo	"
	"	943297	Mp	"
	"	930691	Mp	"
	"	945145	"	"
	estero	9500427	Mp	"
	Es	509812	"	"
	estero	9531106	Mc	"
	"	959406	Mo	"
	"	943644	MV	"
	"	950887	"	"
	Es	509504	"	"
	"	9581212	Mp	"
	"	951683	Mo	"
	"	942168	Mc	"
	"	948571	"	"
	Es	550222	M	"
	"	9581034	Mp	"
	"	943932	"	"
	"	941367	"	"
	enter	955215	"	"
	"	902586	"	"
	"	0500809	Mp	"
	"	941256	Mc	"
	"Es	9832119	Mc	"
	Es	941358	"	"
	"	954277	M	"
	Es	0500208	Mp	"
	"	0500493	"	"
	"	902527	Mo	"
	"	999455	"	"
	"	9581232	Mp	"
	"	937027	Mc	"
	estero	925306	"	"
	Es	943032	"	"
	est"ro	925586	"	"
	Es	951021	Mo	"
	"	9581138	Mp	"
	"	9500300	M"	"
	"	9581324	Mp	"
	"	9581350	"	"
	"	951032	Mo	"
	"	934191	Mp	"
	"	9501319	"	"
	"	941233	"	"
	"	0500157	Mcp	"
	estero	953206	Mo	"
	Es	9581218	Mp"	"
	"	95812I0	"	"
	"	930925	"	"
	estero	931503	"	"
	"	925157	"	"
	"	900019	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
S? SEVERO	F.S.	0506856	Np	vuoto	
	F.S.	530681	"	"	
	"	455242	"	"	
	"	417539	L	"	
	"	415389	"	"	
	"	476974	"	"	
	Estero	3417	"	"	
	F.S.	412877	"	"	
	"	416316	"	"	
	"	413277	"	"	
	Estero	2954[illegible]	"	"	
	"	74[illegible]3	"	"	
	F.S.	448[illegible]335	"	"	
	"	485551	"	"	
	"	488641	"	"	
	"	489199	"	"	
	Estero	8764	"	"	
	F.S.	524509	W	"	
	"	514272	"	"	
	"	509018	"	"	
	"	506011	"	"	
CAMPOMARINO	"	I 14035	K	carico	Copertino
	"	I 04080	P	"	Copertino
	"	I 13543	"	"	"
	"	52161	G	"	"
	"	455081	L	"	"
	"	486326	"	"	
	"	IG189	"	"	
	"	4406723	"	"	
	"	460353	"	"	
	"	552056	"	"	
	"	981518	"	"	
	"	594400	"	"	
TERMOLI	Estero	I5716	L	"	Lebba
	P.S.	7407154	"	"	"
	"	414749	"	"	"
	Estero	46892	"	"	"
	F.S.	7449465	"	"	"
	Estero	5172	"	"	"
	"	49253	"	"	Non ancro Petacciato

201

Declassified E.O. 12356 Section 3.3/NND No. 785021

S? S E V E R O		530681				
	Est	455202				
	"	417539				
	"	415510				
	"	476971				
	Estero	3417				
	U. S.	412817				
	"	41656				
	"	413377				
	Estero	2954[illegible]				
	"	74[illegible]3				
	F. S.	486535				
	"	488551				
	"	468641				
	"	493199				
	Est ro	8764				
	F.S.	524508				
	"	5[illegible]4572				
	"	509[illegible]18				
	"	508[illegible]11				
CAMPOMARINO	"	I [illegible]4089			carico	Copertino
	"	I[illegible]4 80				Copertino
	"	I[illegible]3543				"
	"	52161				"
	"	453[illegible]31				"
	"	4[illegible]53 6				"
	"	I6IB9				
	"	4406723				
	"	486333				
	"	55[illegible]058				
	"	98[illegible]315				
	"	594400				Lebba
TERMOLI	Estero	I5716				"
	F.S.	7407154				"
	"	414749				"
	Estero	46892				"
	F. S.	7[illegible]48465				"
	Estero	5171				Non emero Petacciato
	"	49[illegible]52				"
	F. S.	4[illegible]7318				"
	"	4[illegible]0530				"
	"	479[illegible]106				"
	"	41[illegible]2143				"
	"	4[illegible]07830				"
	"	49[illegible]I0I				"
	"	41[illegible]398I				"
	"	7[illegible]403786				"
	"	41[illegible]8520				"
	"	4I[illegible]338				"
	Estero	98[illegible]56				"

201

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
T E R M O L I	Estero	20[illegible]06	L	carico	Montenero Petacciato
	F.S.	490909	"	"	"
	Estero	490907	"	"	"
	"	49867	"	"	
	"	I5I9	"	vuoto	
	"	31640	"	"	
	"	7[illegible]030	"	"	
	"	I5[illegible]80	"	"	
	"	66080	"	"	Poggia
	"	2II	"	"	Termoli
	"	36692	"	"	"
	"	42437	"	"	Poggia
	"	I3940	"	"	"
	F.S.	66[illegible]580	P	"	Termoli
	"	I[illegible]8694	Bc	"	"
	"	I7[illegible]5I0	L	"	"
	"	20[illegible]0I	G	"	"
	"	205416	"	"	"
	"	[illegible]20I454	"	"	"
	"	II9543	L	"	"
	U.S.A.	222229	G	"	"
	Estero	42457	L	"	Foggia
	"	I[illegible]940	"	"	"
	P.	47[illegible]828	"	"	"
	"	7400I70	"	"	"
	"	4I6839	"	"	"
	"	460286	"	"	"
	"	7749303	"	"	"
	"	426438	"	"	"
	"	493I48	"	"	"
	"	477I47	"	"	"
	"	7749009	"	"	"
	"	497218	"	"	"
	"	488205	"	"	"
	"	4[illegible]6739	"	"	"
	"	474859	"	"	"
	"	474987	"	"	"
	"	479I94	"	"	"
	"	476045	"	"	"
	"	467461	"	"	"
	"	493318	"	"	"
	"	647313	P	"	"
	"	I[illegible]8979	P	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	49867	"	"		
"	I5I9	"	vuoto		
"	31640	"	"		
"	7:030	"	"		
"	I5280	"	"		
"	66080	"	"	Foggia	
"	2II	"	"	Termoli	
"	36692	"	"	"	
"	42427	"	"	Foggia	
"	I3940	"	"	"	
"	66:580	P	"	Termoli	
"	I:66694	Do	"	"	
"	I7 510	L	"	"	
"	20 01	C	"	"	
"	205416	"	"	"	
"	2:1464	"	"	"	
"	I19548	L	"	"	
U.S.A.	222229	G	"	"	
Estero	42457	L	"	Foggia	
"	I3940	"	"	"	
F.	47:808	"	"	"	
"	7400I70	"	"	"	
"	416839	"	"	"	
"	460286	"	"	"	
"	7749303?	"	"	"	
"	426439	"	"	"	
"	49:I48	"	"	"	
"	477I47	"	"	"	
"	7749009	"	"	"	
"	4672I8	"	"	"	
"	488205	"	"	"	
"	406739	"	"	"	
"	474859	"	"	"	
"	474987	"	"	"	
"	479I94	"	"	"	
"	476046	"	"	"	
"	452461	"	"	"	
"	4935I8	"	"	"	
"	6473I3	P	"	"	
"	II18979	F	"	"	
"	40:498	L	"	"	
"	457I26	"	"	"	
"	720640	"	"	"	
"	654865	P	"	"	
"	405I49	L	"	"	
"	4527I3	"	"	"	
"	417033	"	"	"	
"	I00:2076	E	carico	Termoli	
"	0I0I23	F	"	"	
"	I02I:25027	E	"		
"	550264	Mv	"		
"	4I6960	L	vuoto		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 4-3-44 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Parco Nord	FS	2021658	2	carico	
	"	470191	1	"	
	"	697761	2	"	
	FSE	1103	2	"	
	FS	1031341	2	"	
	DR	34317	"	"	
	"	79001	"	"	
	FS	4534405	2	"	
	"	2020990	2	"	
	"	2117912	2	"	
	"	121784	2	"	
	estero	74933	2	vuoto	
	"	377	"	"	
	FS	530040	2	carico	Roma Tib.
	"	1994105	2	"	"
	DR	15342	2	"	"
	FS	4582010	2	"	"
	"	2010505	2	"	"
	"	2004020	2	"	"
	"	211972	2	"	"
	"	2116393	2	"	"
	"	77292030	2	"	"
	"	1213665	2	"	"
	"	476693	2	"	"
	estero	77765	2	"	"
	FS	2035918	2	"	"
	"	2003150	2	"	"
	FSE	4293	2	"	"
	"	4103	2	"	"
	FS	2700038	2	"	"
	"	1211595	2	"	"
	187438	187438	2	"	"
	"	535442	2	"	"
	"	66150	2	"	"
	"	2700030	2	"	"
	Francia	2820087	2	"	"
	FS	2037562	2	"	"
	"	4811566	2	"	"
	"	4410963	2	"	"
	"	2117665	2	"	Anic
	"	2117665	2	"	"
	"	2117665	2	"	"
	"	2117665	2	"	"

Bari Porto Nord	FS	102,666	Diretto	carico	
"	"	470151	"	"	
"	"	497761	"	"	
"	FSS	1103	"	"	
"	FS	101341	"	"	
"	DR	94317	"	"	
"	"	79361	"	"	
"	FS	45e405	"	"	
"	"	2[illegible]0900	"	"	
"	"	1117928	"	"	
"	"	1[illegible]784	"	"	
"	ostiense	74933	"	vuoto	
"	"	[illegible]577	"	"	
"	FS	2[illegible]040	Espresso	carico	Roma Tib.
"	"	190825	"	"	"
"	DR	15948	"	"	"
"	FS	4[illegible]810	"	"	"
"	"	1[illegible]385	"	"	"
"	"	1[illegible]010	"	"	"
"	"	111972	"	"	"
"	"	1115393	"	"	"
"	"	7712[illegible]039	"	"	"
"	"	1[illegible]665	"	"	"
"	"	456693	"	"	Anio
"	ostiense	47[illegible]765	"	"	"
"	FS	1[illegible]5818	"	"	"
"	"	1[illegible]3150	"	"	"
"	FSS	[illegible]453	"	misc.	
"	"	[illegible]403	"	carico	
"	FS	170038	"	"	
"	"	[illegible]21515	"	"	
"	"	187438	"	"	
"	"	[illegible]65244	"	vuoto	
"	"	66 [illegible]99	"	"	
"	"	[illegible]20650	"	"	
"	France	[illegible]81007	"	"	
"	FS	[illegible]67586	"	"	
"	"	491556	"	"	
"	"	[illegible]11983	"	"	
"	DR	[illegible]51436	"	"	
"	FS	[illegible]5173[illegible]	"	"	
"	"	[illegible]65198	"	"	
"	DR	[illegible]3241	"	"	
"	FS	[illegible]01866	"	"	
"	"	160720	"	"	
"	"	[illegible]77164	"	"	
"	"	[illegible]64165	"	carico	
"	"	[illegible]10624	"	"	
"	"	[illegible]09578	"	vuoto	
"	"	1121961	"	"	

230

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Parco Nord	DR	82452	F	vuoto	
	FS	I004153	F	"	
	estero	67894	L	"	
	FS	586684	P	"	
	"	495548	L	"	
	"	489374	L	"	
	"	415313	L	"	
	"	471855	L	"	
	"	447708	L	"	
	"	447935	L	"	
	"	454232	L	"	
	"	498933	L	"	
	"	1130974	F	"	
	"	I0I0548	F	vuoto	
	"	I008407	E	"	
	"	7I06781	E	"	
	"	411710	L	"	
	"	400220	L	"	
	"	I30467	F	"	
	estero	37965I	F	"	
	FS	206731	HG	"	
	"	300I5I	"	"	
	"	308328	"	"	
	"	II21I60	F	"	
	"	I020680	F	"	
	DR	97II88	F	"	
	FS	20I408	G	"	
	FS	I090644	E	"	
	"	4I3016	L	"	
	"	48I790	L	"	
	"	4I4933	L	"	
	estero	3991	P	"	
	FS	653921	P	"	
	"	660363	P	"	
	"	482756	L	"	
	"	I022299	F	"	
	FS	1656I9	F	"	
	"	I009257	F	"	
	"	485963	L	"	
	"	4I9038	L	"	
	"	4I7929	L	"	
	"	744253	L	"	
	"	202035	G	"	
	FS	ICI0039	E	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	409314	L	"	
"	415313	L	"	
"	471853	L	"	
"	447708	L	"	
"	447933	L	"	
"	454232	L	"	
"	498933	L	"	
"	1130974	F	"	
"	IOI0548	F	vuotc	
"	I008407	E	"	
"	7I06781	E	"	
"	411710	L	"	
"	400220	L	"	
"	I30467	F	"	
estefo	379651	F	"	
FS	206731	HG	"	
"	300I51	"	"	
"	308328	"	"	
"	II21I60	F	"	
"	I020680	F	"	
BR	971I88	F	"	
FS	201408	G	"	
FS	I090644	E	"	
"	413016	L	"	
"	481790	L	"	
"	414933	L	"	
estero	3991	P	"	
FS	653921	P	"	
"	660363	P	"	
"	482756	L	"	
"	I022299	F	"	
FS	165619	F	"	
"	I009257	F	"	
"	485963	L	"	
"	419038	L	"	
"	417929	L	"	
"	714253	L	"	
"	202035	G	"	
FS	IOI0039	E	"	
estero	13931	POZ	"	
FS	694258	POZ	"	
"	7I02670	F	"	
"	646696	POZ	"	
"	694678	POZ	"	
USA	358882	"	"	
"	353512	"	"	
"FS	698454	"	"	
"	693805	"	"	
"	692279	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/le	F.S.	660535	P	carico	
	"	655951	"	vuoto	
	"	64[illegible]200	"	carico	
	"	644717	"	vuoto	
	"	647205	"	carico	
	"	685164	"	"	
	"	675484	"	"	
	"	660162	"	"	
	"	618050	"	riparando	
	"	604326	"	"	
	"	647217	"	"	
	"	645205	"	carico	
	"	660532	"	riparando	
	"	7775[illegible]002	"	"	
	"	I027339	"	carico	
	"	I026716	"	"	
	"	I0[illegible]1905	"	"	
	"	I0[illegible]713	"	"	
	"	I016364	"	riparando	
	"	I022335	"	"	
	"	I001793	"	"	
	"	I002683	"	carico	
	"	I025242	"	"	
	"	I0019[illegible]2	"	"	
	"	III8978	"	"	
	"	I002845	"	riparando	
	"	I003823	"	"	
	"	I007678	"	"	
	"	I0[illegible]0564	"	"	
	"	I00860I	"	"	
	"	I0II2I4	"	"	
	"	I009IOI	"	"	
	"	I008455	"	"	
	"	I000819	"	carico	
	"	I0[illegible]1025	"	riparando	
	"	II[illegible]2300	P	"	
	"	126548	"	vuoto	
	"	I04578	"	"	
	"	I806I4	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

BARI C/le	F.S.	660535	P	carico
	"	655251	"	vuoto
	"	64[illegible]220	"	carico
	"	614787	"	vuoto
	"	647203	"	carico
	"	685164	"	"
	"	675434	"	"
	"	650169	"	"
	"	619050	"	ripiarando
	"	604326	"	"
	"	641217	"	"
	"	613203	"	carico
	"	660592	"	ripiarando
	"	7779[illegible]3002	"	"
	"	I027539	Bk	carico
	"	I0267 6	"	"
	"	I0II905	"	"
	"	I0027I3	"	"
	"	I0[illegible]6364	"	ripiarando
	"	I0[illegible]2335	"	"
	"	I001793	"	"
	"	I0026[illegible]85	"	carico
	"	I0[illegible]5242	"	"
	"	I0019 2	"	"
	"	III0978	"	"
	"	I0[illegible]845	"	ripiarando
	"	I0[illegible]823	"	"
	"	I007678	"	"
	"	I0[illegible]564	"	"
	"	I00360I	"	"
	"	I0[illegible]2I4	"	"
	"	I009I0I	"	"
	"	I00[illegible]455	"	"
	"	I000819	"	carico
	"	I0[illegible]I025	"	ripiarando
	"	I[illegible]2300	F	"
	"	126548	"	vuoto
	"	I04578	"	"
	"	I806I4	"	"
	"	7I7[illegible]152	"	"
	"	II3I352	"	"
	"	II[illegible]6195	"	"
	"	7I03546	"	"
	"	I8I440	"	"
	"	77I970[illegible]	"	"
	"	II8708	"	carico
	"	44I4I4	"	"
	"	I502[illegible]2	"	"
	"	I[illegible]6355	"	vuoto
	"	I41806	"	carico

199

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
B A R I c/le	F.S.	I84800	F	vuoto	
	F.S.E.	I819	"	"	
	F.S.	II28358	"	"	
	"	II35754	"	"	
	"	7719304[illegible]5	"	"	
	"	II19521	"	carico	
	"	I36I09	"	"	
	"	II8130	"	"	
	"	II24345	"	"	
	"	II19[illegible]3	"	"	
	"	I3[illegible]34	"	"	
	"	I13369	"	"	
	"	507658	"	vuoto	
	"	921230	"	"	
	"	578[illegible]02	"	"	
	"	56I870	"	"	
	"	943795	"	"	
	"	744503	"	"	
	"	954I48	"	"	
	"	599355	"	"	
	"	527899	"	"	
	"	95[illegible]5	"	"	
	"	952[illegible]II	"	"	
	"	96[illegible]I23	"	"	
	F.S.E.	II0I4	"	"	
	"	II[illegible]25	"	"	
	F.S.	802201	"	"	
	"	920I82	"	"	
	"	[illegible]75365	F	riparando	
	"	I0I502	"	"	
	"	I72[illegible]02	"	"	
	"	I024542	"	"	
	"	I00045	"	"	
	"	I60282	"	"	
	"	II0676	"	"	
	"	I68[illegible]03	"	"	
	"	II7785	"	"	
S. S E V E R O	"	7I70314	F	carico	
	"	I[illegible]I7772	Fc	"	
	"	I003259	Ec	"	
	Estero	29590	E	"	
	F.S.	I004665	F	"	
	"	I007304	"	"	
	"	I[illegible]	F	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

03131

Declassified E.O. 12356 Section 3.3/NND No. 785021

| | | |

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI Cle	FS	390469	HG	vuoto	
	"	306914	"	"	
	"	308921	"	"	
	"	300594	"	"	
	"	698802	Pcz	riparendo	
	"	346552	Hg	vuoto	
	"	303026	"	riparendo	
	"	304670	"	riparendo	
	"	553[illegible]	Ro	vuoto	
	"	346618	Hg	"	
	"	34644[illegible]	"	"	
	"	346024	"	"	
	"	340271	"	"	
	"	346[illegible]2	"	"	
	"	953[illegible]	"	"	
	"	790[illegible]20	"	"	
	"	7900448	"	"	
	"	328039	"	"	
	"	270234	"	"	
	"	280827	"	"	
	"	311303	C	"	
	"	26 618	"	"	
	PSE	2017	"	"	
	"	302477	"	"	
	FS	27[illegible]79	"	riparendo	
	"	260794	"	"	
	"	727[illegible]18	"	"	
	"	302498	"	"	
	"	72[illegible]527	"	"	
	"	7203141		vuoto	
	"	69[illegible]49	Ros	"	
	"	605465	"	"	
	"	603420	"	"	
	"	603417	"	"	
	"	605258	"	L	
	"	302463	Z	carico	
	"	I43103	"	"	
	"	I02620	"	vuoto	
	"	I89091	"	"	
	"	I[illegible]7954	"	carico	Bari Parco Nord
	"	I[illegible]7974	"	"	198
	"	I44098	"	riparendo	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	306921	"	"		
"	300554	"	"		
"	608808	Foz	ripercndo		
"	346532	Hg	vuoto		
"	303026	"	ripercu		
"	304676	"	ripercndo		
"	9530080	Ao	vuoto		
"	346618	Hg	"		
"	34644	"	"		
"	346024	"	"		
"	346271	"	"		
"	346223	"	"		
"	9530080	"	"		
"	7306420	"	"		
"	7306444	"	"		
"	8855030	"	"		
"	270234	"	"		
"	300527	"	"		
"	231103	C	"		
"	20 618	"	"		
FSE	4017	"	"		
"	222277	"	"		
FS	27379	"	ripercndo		
"	360704	"	"		
"	7270132	"	"		
"	654496	"	"		
"	7206217	"	"		
"	7203141	"	vuoto		
"	693349	Foz	"		
"	695465	"	"		
"	693120	"	"		
"	693467	"	"		
"	695288	"	"		
"	188465	I	carico		
"	143103	"	"		
"	182620	"	vuoto		
"	189051	"	"		
"	1127954	"	carico	Dori Parco Nord	
"	1137974	"	"		198
"	744091	"	ripercndo		
"	156050	"	"		
"	1033250	"	"		
"	19073	"	"		
"	1127577	"	carico	Francavilla	
"	198041	"	ripercndo		
"	1023626	"	"		
"	7106906	"	"		
"	127467	"	"		
"	111145 92	"	"		
"	155268	"	"		
"	171645	"	"		
"	167694	"	"		

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALE

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI Ole	FS	416222	X	vuoto	
"	"	460885	"	"	
"	"	462314	"	"	
"	"	451487	"	"	
"	"	47[illegible]60	"	"	
"	"	416[illegible]62	"	"	
"	"	41[illegible]823	"	"	
"	"	468467	"	"	
"	"	4[illegible]6398	"	"	
"	"	487176	"	"	
"	"	475780	"	[illegible]2160	
"	"	4[illegible]1555	"	vuoto	
"	"	4[illegible]0309	"	[illegible]arico	
"	"	492[illegible]39	"	"	
"	"	468265	"	"	
"	"	4[illegible]0587	"	"	
"	"	747[illegible]621	"	"	
"	"	4[illegible]2374	"	"	
"	"	4[illegible]4593	"	"	
"	"	4[illegible]4100	"	"	
"	"	4610[illegible]	"	[illegible]uoto	
"	"	7[illegible]90166	"	"	
"	"	4[illegible]7025	"	carico	
"	"	4[illegible]5162	"	vuoto	
"	"	[illegible]7750	"	carico	
"	"	4[illegible]0447	"	"	
"	"	465[illegible]73	"	vuoto	
"	"	445506	"	"	
"	"	[illegible]76852	"	"	
"	"	7[illegible]62569	"	"	
"	"	[illegible]70878	"	"	
"	"	[illegible]16715	"	"	
"	"	[illegible]62911	"	"	
"	"	[illegible]80453	"	"	
"	"	[illegible]73544	"	"	
"	"	[illegible]65160	"	"	
"	"	[illegible]7545514	"	rivarendo	
"	"	[illegible]61652	"	"	
"	"	[illegible]63473	"	"	
"	"	[illegible]62965	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0317

Declassified E.O. 12356 Section 3.3/NND No. 785021



STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/le	F.S.	482926	L	riparando	
	"	4I1480	"	"	
	"	482332	"	"	
	"	490698	"	"	
	"	40I055	"	"	
	"	4II346	"	carico	
	"	459060	"	"	
	"	040I6I	"	"	
	"	4I6228	"	"	
	"	462II8	"	riparando	
	"	459205	"	"	
	"	490414	"	"	
	"	476I99	"	vuoto	
	"	467408	"	"	
	"	49I205	"	"	
	"	472546	L	carico	
	"	496I63	"	"	
	"	7408I77	"	"	
	"	494I06	"	riparando	
	"	747II69	"	"	
	"	7II03873	"	"	
	"	4I8258	"	"	
	"	436909	"	carico	
	"	4362I7	"	riparando	
	"	479595	"	"	
	"	402662	"	"	
	"	747III4	"	"	
	"	4903I3	"	"	
	"	496764	"	"	
	"	7470I97	"	"	
	"	40I028	"	"	
	"	7450009	"	"	
	"	I00I9I2	"	carico	
	"	I00338	"	"	
	"	III7905	"	"	
	"	I0079II	"	"	
	"	I0I3362	"	"	
	"	II[illegible]944	"	"	
	"	I003347	"	vuoto	
	"	I007830	"	carico	
	"	I006145	"	"	
	"	I02594I	"	vuoto	
	"	I02I027	"	"	
	"	I00I896	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	4II346	"	c Fico
"	459060	"	"
"	040I6I	"	"
"	4I6228	"	riparando
"	462II8	"	"
"	459305	"	"
"	490414	"	vuoto
"	476I99	"	"
"	467408	"	"
"	491205	"	carico
"	472546	L	"
"	486I63	"	"
"	7408I77	"	riparando
"	494I06	"	"
"	74?II69	"	"
"	7II03873	"	"
"	4I8258	"	carico
"	436909	"	riparando
"	436217	"	"
"	479595	"	"
"	402662	"	"
"	747III4	"	"
"	490313	"	"
"	496764	"	"
"	7470197	"	"
"	401028	"	"
"	7450009	"	"
"	I00I9I2	F	carico
"	I00338	"	"
"	III7905	"	"
"	I0079II	"	"
"	I0I5362	"	"
"	II31944	"	"
"	I003347	"	vuoto
"	I007830	"	carico
"	I006I45	"	"
"	I02594I	"	vuoto
"	I02I027	"	"
"	I00I896	"	"
"	I004266	"	carico
"	I0II269	"	"
"	I02425I	"	"
"	I80637	"	vuoto
"	7I05829	"	"
"	655981	P	carico
"	644782	"	vuoto
"	645932	"	"
"	655537	"	riparando
"	644384	"	carico

197

Declassified E.O. 12356 Section 3.3/NND No. 785021

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE Staz. PIAZZALE

alle ore 18 del ..... 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
BARI C/le	F. S.	478129	I	carico	
	"	445 39	"	"	
	"	4I5004	"	vuoto	
	"	444958	"	carico	Adelfia
	"	496580	"	"	"
	"	475727	"	"	Molfetta
	"	4I4099	"	"	
	"	4I4066	"	"	
	"	472879	"	"	
	"	497817	"	"	
	"	473469	"	"	
	"	40I544	"	"	
	"	7470I38	"	"	
	"	4I30II	"	"	Bari Parco Sud
	"	I82418	F	"	"
	"	I0I576	"	"	Locorotondo
	"	7I70204	"	"	"
	"	I8I8I7	"	"	Adelfia
	"	I95239	"	"	Molfetta
	"	I0I5240	"	"	Napoli
	"	III09507	"	"	"
	"	7803705	"	"	"
	"	I02I830	"	"	"
	"	I027057	"	"	"
	"	I004872	"	"	"
	"	I028700	"	"	"
	"	I47532	"	"	"
	"	II30977	"	"	"
	"	I009364	"	"	"
	"	I027I7I	"	"	"
	"	452587	L	vuoto	Rip-
	"	40I07I	"	"	
	"	479974	"	"	
	"	406332	"	"	
	"	49II60	"	"	
	"	4II857	"	"	
	"	402I5	"	"	
	"	490I98	"	"	
	"	0473I5	"	"	
	"	7403360	"	"	Messina
	"	4I9644	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0321

Declassified E.O. 12356 Section 3.3/NND No. 785021



PAG. 1 0/0

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Parco Nord	FS	500163	Rp	vuoto	
	estero	900511	"	"	
	FS	941027	"	"	
	"	945170	"	"	
	FS	944500	"	"	
	estero	0500355	Rp	"	
	"	500433	"	"	
	FS	9561214	"	"	
	FS	981159	"	"	
	"	981026	"	"	
	"	944560	"	"	
	"	955096	"	"	
	"	983210	"	"	
	estero	553042	"	"	
	FS	555430	Ibo	"	
	"	551214	"	"	
	"	564204	"	"	
	estero	0500411	Rp	"	
	"	24663	"	"	
	FS	521645	"	"	
	"	5581115	"	"	
	"	551606	Ibo	"	
	"	564014	"	"	
	"	561107	"	"	
	"	5582419	Rp	"	
	estero	900472	"	"	
	FS	900709	"	"	
	"	560621	Ibo	"	
	"	0500425	"	"	
	"	941164	"	"	
	"	552492	"	"	
	estero	526545	Rp	"	
	"	560776	"	"	
	FS	5581106	"	"	
	"	5561108	"	"	
	"	5581356	"	"	
	"	581216	"	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

0323

Declassified E.O. 12356 Section 3.3/NND No. 785021

193

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
Bari Smis Ferr. centro		999261	Fc	viper.	
"		927957	"	vuoto	
"		981323	"		
"		0556816	"	"	
"		0500494	"	"	
"		981093	"	"	
centro		911980	"	"	
"		598657	"	"	
"		486593	"	carico	
"		442976	"	"	
"		7719603	"	"	
"		1132908	"	"	
centro		1007376	"	"	
"		1005926	"	"	
"		1003190	"	"	
"		4951	"	viper.	
"		4103	"	"	
"		170039	"	carico	
"		171595	"	"	
"		444257	"	vuoto	
"		469999	"	"	
centro		19147	"	"	
"		550040	"	viper.	
"		981265	"	vuoto	
"		497129	"	carico	
"		194521	"	"	
"		1.11970	"	"	
"		1.2155	"	"	
"		476364	"	"	
"		496517	"	"	
"		414460	"	"	
centro		54146	"	viper.	
"		13465	"	"	
"		10 3415	"	"	
"		576	"	"	
centro		5.014	"	"	
"		135049	"	"	
"		699429	"	vuoto	
centro		48068	"	viper.	
"		6[illegible]23	"	vuoto	
centro		17[illegible]	"	"	
"		1065[illegible]	"	viper.	
"		6[illegible]	"	vuoto	

TARANTO

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

"	0500454	"	"	
"	981093	"	"	
[illegible]	111980	"	"	
Fs	596617	[illegible]	"	
"	486913	L	[illegible]	
"	142976	L	"	
"	7TI06035	P	"	
"	2232962	Pc	"	
[illegible]	2073769	P	"	
Fs	[illegible]	D	"	
"	1003150	D	"	
Fs	593	Do	[illegible]	
"	4103	"	"	
Fs	170459	Fo	[illegible]	
"	121392	"	"	
"	144957	L	[illegible]	
"	4059999	L	"	
[illegible]	33147	L	"	
Fs	250040	P	[illegible]	
"	5221265	Po	[illegible]	
"	497129	L	[illegible]	
"	154321	L	"	
"	1133570	P	"	
"	232759	P	"	
"	476364	L	"	
"	496547	L	"	
"	414460	L	"	
[illegible]	54146	P	[illegible]	
"	13465	P	"	
Fs	1033146	Po	"	
"	576000	P	"	
[illegible]	93674	P	"	
Fs	1345449	P	"	
"	6994[illegible]5	Po2	[illegible]	
[illegible]	40060	P	[illegible]	
Fs	6[illegible]93	Po2	[illegible]	
[illegible]	27605602	P	"	
Fs	1085109	P	[illegible]	
"	854413	Pc	[illegible]	
"	3913211	"	"	
"	3046897	Pc	[illegible]	
Fs	306971	"	"	
"	306934	"	"	
"	306983	"	"	
"	3969[illegible]9	"	"	
"	309457	"	"	
"	3963596	"	"	
"	307190	"	"	
"	307982	"	"	
"	6850390	P	"	

TARANTO

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
TARANTO	FS	660829	F	vuoto	
	Olano	40065	F	"	
	"	45037	F	"	
	FS	66549	F	"	
	"	645377	F	"	
	"	66	F	"	
	estero	67	F	"	
	"	65	F	"	
	"	8	F	"	
	"	6	F	"	
	FS	647	F	"	
	"	64	F	"	
	"	64	F	"	
	"	651	F	"	
	"	653480	F	"	
	"	666564	F	"	
	"	413468	L	carico	Cosenza
	"	423556	L	"	"
	"	400317	L	"	"
	"	411	L	"	"
	"	411	L	"	"
	"	4	L	"	"
	"	4	L	"	"
	"	1	L	"	Francavilla F
	"	1	F	"	Rossi
	"	66	F	vuoto	
	estero	62	F	"	
	FS	65	F	"	
	"	64	F	"	
	"	66	F	"	
	"	1	L	carico	
	"	1	L	"	Narisi
	"	1	Ha	"	Potenza
	"	1	"	"	"
	"	1	"	"	"
	"	1	"	"	"
	"	1	"	"	
	"	1	"	"	Siderno
	FS	1	F	"	"

195

Declassified E.O. 12356 Section 3.3/NND No. 785021

TARANTO	FS	660829	P	vuoto		
	calcare	42167	I	"		
	"	45937	I	"		
	MS	65542	I	"		
	"	645377	I	"		
	"	66062	I	"		
	asfalto	67022	I	"		
	"	670647	I	"		
	"	6671	I	"		
	"	6683	I	"		
	FS	647361	I	"		
	"	6[illegible]72	I	"		
	"	669050	I	"		
	"	6691535	I	"		
	"	653480	I	"		
	"	666904	I	"		
	"	41,660	I	carico	Cosenza	
	"	439990	I	"	"	
	"	460317	I	"	"	
	"	6[illegible]33	I	"	"	
	"	411029	I	"	"	
	"	6[illegible]53	I	"	"	
	"	4[illegible]17	I	"	"	
	"	1[illegible]71	I	"	Francavilla F	
	"	1[illegible]516	I	"	Trani	
	"	66[illegible]62	I	vuoto		
	calcare	62193	I	"		
	MS	65.059	I	"		
	"	64[illegible]8	I	"		
	"	6[illegible]04	I	"		
	"	1[illegible]958	I	carico	Napoli	
	"	492[illegible]3	I	"	Potenza	
	"	3[illegible]38	I	"	"	
	"	3[illegible]370	I	"	"	
	"	3[illegible]704	I	"	"	
	"	4[illegible]42	I	"		
	"	1,[illegible]26	I	"	Siderno	
	MS	70[illegible]5	I	"	"	
	FS	1[illegible]520	I	"	"	
	"	1[illegible]465	I	"	Cosenza	
	"	1,1[illegible]45	I	vuoto		
	asfalto	34576	I	carico	Francavilla	
	MS	354[illegible]7	I	vuoto		
	asfalto	52493	I	rigur.		
	FS	31,2[illegible]4	Eg	"		
	asfalto	65[illegible]40	I	"		
	FS	7[illegible]3[illegible]5	Eg	"		
	FSS	11113	I	"		
	FS	4[illegible]14	I	"		
	"	11,1,1[illegible]8	I	"		
	"	7405760	L	"		

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
TARANTO	FS	044932	L	vuoto	
	"	208748	L	"	
	"	108525	[illegible]	"	
	[illegible]	1629	[illegible]	"	
	"	7110	L	"	
	FS	[illegible]		"	
	"	7476210	L	"	
	"	659067	P	"	
	"	657709	P	"	
	[illegible]	11262	P	vuoto	
	"	10245	P	"	
	"	35505	P	"	
	"	10826	P	"	
	"	16317	P	"	
	"	1490	P	"	
	"	10513	P	"	
	"	10529	P	"	
	"	1742	P	"	
	"	45567	P	"	
	"	47773	P	"	
	"	888	P	"	
	"	43731	P	"	
	"	92133	P	"	
	"	4067	P	"	
	"	82195	P	"	
	"	24574	P	"	
	"	93867	P	"	
	"	27655012	P	"	
	"	11695006	P	"	
	"	10524	P	"	
	FS	826453	P	"	
	"	7870127	P	"	
	"	968116	P	"	
	"	146059	P	"	
	"	20437	P	"	
	"	47174	L	carico	
	"	10565	L	"	
	FS	473292	L	"	
	"	165547	L	"	
	"	180418	L	"	
	"	146905	L	"	
	"	130236	L	"	
	FS	463077	L	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

0329

FERROVIE DELLO STATO
Sezione Movimento
BARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 Agosto *1944.*

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
T E R M O L I	Estero	351590	L	vuoto	
	F.S.	401264	"	"	
	"	465491	"	"	
	"	477109	"	carico	
	"	463606	"	"	
	"	7403087	"	"	
	"	499901	"	"	
	Estero	53864	"	vuoto	
	"	24559	"	"	
	"	98349	"	"	
	F.S.	477215	"	"	
	F.S.	425174	"	"	
	"	164659	"	carico	
	"	814009	"	"	
	"	112168	P.C.Z.	"	
	"	1475031	F	vuoto	
	Estero	901993	Mv	"	
	F.S.	6500218	"	"	
	"	644357	P	"	
	Estero	901994	Mv	carico	
	"	900001	"	"	
	F.S.	551230	"	"	
	"	102326	E	vuoto	
	"	102593	"	"	
	"	102807	"	"	
	"	100524	F	"	
	Estero	35201	P	carico	Lecce
	"	24148	"	"	Lecce
	"	64033	"	"	
VAGLIO LUCANO	F.S?	447321	L	"	Barile
	"	7405064	"	"	"
P I S T I C C I	"	101327?	Dc	vuoto	Taranto
	"	100292	"	"	"
	"	1003762	E	"	"
	"	170784	F	"	"
	"	112328	"	"	"
L U C E R A	"	7200549	G	carico	Capua
	"	201076	Gc	"	"
	Estero	12497	G	"	"

194

Declassified E.O. 12356 Section 3.3/NND No. 785021

E R [illegible] O L I	Estero	351590	L	vuoto	
	F.S.	401264	"	"	
	"	465491	"	"	
	"	477109	"	carico	
	"	463686	"	"	
	"	7403087	"	"	
	"	499601	"	"	
	Estero	53864	"	vuoto	
	"	24353	"	"	
	"	98349	"	"	
	F.S.	477215	"	"	
	F.S.	425174	"	"	
	"	I64669	"	carico	
	"	814009	"	"	
	"	112168	P.C.Z.	"	
	"	1475031	"	vuoto	
	Estero	901993	Mv	"	
	F.S.	0500218	"	"	
	"	644357	P	"	
	Estero	901004	Mv	carico	
	"	900001	"	"	
	F.S.	551230	"	"	
	"	I021326	E	vuoto	
	"	I021593	"	"	
	"	I012867	"	"	
	"	I00524	"	"	
	Estero	35201	"	carico	Lecce
	"	24148	"	"	Lecce
	"	64033	"	"	
VAGLIO LUCANO	F.S.	447321	L	"	Barile
	"	7406864	"	"	"
PISTICCI	"	I013273	Ec	vuoto	Taranto
	"	I001292	"	"	"
	"	I007762	E	"	"
	"	I70784	F	"	"
	"	II22328	"	"	"
LUCERA	"	7200549	G	carico	Capua
	"	201016	Gc	"	"
	Estero	I2497	G	"	"
	"	303580	E	"	"
	F.S.	I002449	E	"	Roccella Ionica
	"	II28767	Fc	"	" "
	"	I011921	E	"	" "
	"	I014094	"	"	Guglionesi P.
	"	I44851	F	"	"
	"	2010682	E	"	Foggia
GRASSANO	Estero	47533	F	"	Monasterace
	F.S.	I016540	E	"	"
	"	II32533	Fc	"	"
	Estero	I7657	L	vuoto	Grassano

194

Declassified E.O. 12356 Section 3.3/NND No. 785021

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
G R.A S A N O	F.S.	49[illegible]270	L	carico	Napoli
	"	437395	"	"	"
	"	I0081[illegible]36	E	"	Monasterace
	"	4I[illegible]882	L	"	Bari
	"	4I[illegible]418	"	"	"
	"	I00[illegible]380	Bo	"	Monasterace
	Esteri	[illegible]10	P	"	"
	F.S.B.	[illegible]001	"	"	"
	F.S.	II[illegible]951	Fc	"	"
	"	[illegible]65212	F.C.S.	vuoto	
	"	[illegible]32852	F	carico	Grisignano
	"	[illegible]60129	"	"	"
	"	[illegible]45669	"	"	"
	"	[illegible]53789	"	"	"
	Ester	[illegible]0701	F.C.S.	vuoto	"
	F.S.	[illegible]99091	"	"	
	Esteri	[illegible]2742	L	carico	Frattamaggiore
	F.S.	[illegible]090II4	E	"	Napoli
		II[illegible]543	Fc	"	"
	"	I[illegible]24393	E	"	"
	Esteri	[illegible]2106	P	"	"
	"	[illegible]2778	"	"	"
	"	[illegible]75807	"	"	"
	"	[illegible]4624I	"	"	"
	F.S.	[illegible]9[illegible]60I	I.C.S.	"	"
	"	[illegible]443II	L	"	"
	"	[illegible]90[illegible]653	P.C.Z.	"	"
	"	[illegible]6[illegible]405	"	"	"
	Esteri	[illegible]3210	P	"	"
	"	[illegible]33547	"	"	"
	"	[illegible]50756	"	"	"
	"	[illegible]7563	"	"	"
	"	[illegible]49II6	"	"	"
	F.S.	[illegible]65[illegible]092	"	"	"
	"	[illegible]193365	L	"	"
	Esteri	[illegible]82895	E	"	Teverola
	"	[illegible]I9[illegible]I3	L	"	Napoli
RIGNANO GARGANICO	"	[illegible]9788	P.C.Z.	"	
	"	97455	P	"	
	F.S.	[illegible]8I172	L	"	
	"	[illegible]95794	"	"	
	"	[illegible]82918	"	"	
AFRICENA	"	I[illegible]42I6	Flc	"	

Declassified E.O. 12356 Section 3.3/NND No. 785021

		"	478418	"	"	"
		"	I009380	Na	"	Monastereee
		Esterc	513	P	"	"
		F.S.E.	3041	"	"	"
		F.S.	II38951	Na	"	"
		"	063212	P.O.Z.	vuoto	
		"	653852	P	carico	Grieignano
		"	656129	"	"	"
		"	645569	"	"	"
		"	653709	"	"	"
		Ester	I870I	P.O.Z.	vuoto	"
		F.S.	652691	"	"	
		Ester	52742	L	carico	Frattamaggiore
		F.S.	1000114	P	"	Napoli
			II73943	Na	"	"
		"	I004303	P	"	"
		Ester	62106	P	"	"
		"	2778	"	"	"
		"	73207	"	"	"
		"	46241	"	"	"
		F.S.	6[illegible]2I	P.O.Z.	"	"
		"	444311	L	"	"
		"	6[illegible]657	P.O.Z.	"	"
		"	646406	"	"	"
		Ester	3290	P	"	"
		"	53347	"	"	"
		"	50756	"	"	"
		"	7363	"	"	"
		"	45116	"	"	"
		F.S.	650692	"	"	"
		"	493566	L	"	"
		Ester	62895	P	"	Teverola
		"	19413	L	"	Napoli
RIGNANO CARCARIC		"	9728	P.O.Z.	"	
		"	97455	P	"	
		F.S.	481172	L	"	
		"	495794	"	"	
		"	492918	"	"	
APPICCIA		"	I44216	Pic	"	
		"	II29721	Po	"	
		"	495786	L	"	
ARPI		"	I34601	P	"	
		Ester	10978	"	"	
TRANI		F. S	I0I3[illegible]2	chiuso	"	Roma
		"	I009165	"	"	Napoli
		"	I0[illegible]58I	"	"	"
		"	I3I6I2	"	"	"
		"	I704I2	"	"	Palermo
		"	II3735	"	"	Napoli
		"	I67I72	"	"	"

Declassified E.O. 12356 Section 3.3/NND No. 785021

Declassified E.O. 12356 Section 3.3/NND No. 785021

...LO STATO
...ovimento
...ARI

SITUAZIONE PIAZZALI

alle ore 18 del 24 agosto 1944.

STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto	DESTINAZIONE
1 TARANTO	FS	18228[illegible]	F	carico	
	"	490101	L	vuoto	
	"	420002	"	"	
	"	406195	L	"	
	"	7403506	"	"	
	estero	3236	"	"	
	"	94022	"	"	
	FS	434503	"	"	
	estero	13111	"	"	
	"	11936	"	"	
	FS	466354	"	"	
	estero	3690	"	"	
	FS	445358	"	ripar.	
	estero	11864	"	"	
	FS	1003946	G	"	
	estero	13578	L	"	
	"	35164	"	"	
	"	27425	"	"	
	FS	642381	L	vuoto	
	"	444122	"	"	
	"	411624	"	ripar.	
	"	7470598	"	"	
	"	426156	"	"	
	"	344215	"	"	
	"	932051	"	"	
	"	300040	"	"	
	"	930152	"	"	
	estero	10896	L	vuoto	
	FS	301206	"	"	
	"	476140	L	ripar.	
	"	653172	"	"	
	"	932008[illegible]	"	"	
	"	17[illegible]21	"	"	
	"	7471[illegible]25	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	FS	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	
	"	[illegible]	"	"	

193

0335

Declassified E.O. 12356 Section 3.3/NND No. 785021



STAZIONE	Serie del carro	Numero del carro	Tipo del carro	Carico o vuoto		
TARANTO	tedesco	980[illegible]	F	vuoto		
	"	4[illegible]907	F	"		
	francese	21[illegible]663	F	"		
	FS	10[illegible]936	F	"		
	"	448318	L	"		
	"	45[illegible]193	L	"		
	"	40[illegible]197	L	"		
	"	47[illegible]484	L	"		
	"	15-[illegible]63[illegible]	F	"		
	"	[illegible]784	F	carico		
	"	[illegible]4[illegible]84	F	"		
	"	48,[illegible]06[illegible]	L	"		
	tedesco	[illegible]796	L	"		
	FS	[illegible]7[illegible]	F	"		
	"	4,[illegible]795	L	"		
	tedesco	[illegible]8679	G	"		
	FS	7[illegible]5,6,	L	"		
	"	45[illegible]193	L	"		
	"	47[illegible]507	L	"		
	"	[illegible]5[illegible]0[illegible]	F	"		
	"	[illegible]4[illegible]5[illegible]	F	"		
	"	[illegible]4[illegible]5[illegible]	F	"		
	"	[illegible]4[illegible]5[illegible]	F	"		
	"	[illegible]4[illegible]5[illegible]	F	"		
	tedesco	[illegible]1128	F	"		
	FS	[illegible]4[illegible]5[illegible]	F	vuoto		
	"	[illegible]5[illegible]48[illegible]	F	"		
	"	[illegible]03171	L	"		
	"	[illegible]11[illegible]76	L	"		
	"	[illegible]46214	L	"		
	"	[illegible]4[illegible]4[illegible]87	L	"		
	"	[illegible]4[illegible]5[illegible]20	L	"		
	Estero	[illegible]2[illegible]22	L	carico		
	"	[illegible]3140	L	vuoto		
	FS	[illegible]4[illegible]4023	L	"		
	"	[illegible]4[illegible]0[illegible]92	L	"		
	"	[illegible]5[illegible]9[illegible]22	Ry	"		
	"	[illegible]6[illegible]8[illegible]32	F	carico	Cosenza	
	"	[illegible]4[illegible]4[illegible]20	F	vuoto		
	Estero	[illegible]7[illegible]02	F	carico	Potenza	
	FS	[illegible]4[illegible]5[illegible]27	L	"		
	"	[illegible]4[illegible]5[illegible]96	L	vuoto		
	Estero	[illegible]4[illegible]5[illegible]	L	"		

Declassified E.O. 12356 Section 3.3/NND No. 785021

0337

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 65

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
AREZZO YARDS:								
70271	German	LS Gon	Yes				B.O.Shop	1/2 decking, 15' from track
15454	German	HW Gon	Yes			24.5	B.O.Shop	30' from track, 1/4 side 4 pcs decking, sill step
401	Italian	HW Gon	Yes			18	B.O.Shop	Lded cement, end, 10' from track
2187	German	LW Gon	Yes			15	B.O.Shop	1/4 decking, needs sw & track
Scrap-13 gondolas same track, B.O.Shop								
Scrap-10 cars, blown journals.								
The following cars had journal, pedestal or wheels dynamited and are unfit for service. All cars are either very heavy repairs or scrap due to explosives and fire.								
Scrap-20 cars north at bridge, 80 cars from bridge to station.								
72840	German	LS Gon	Yes				OK Sve	Loaded I beams
498940	Italian	HS Gon	No brakes		Yes		B.O.Shop	Straighten sides.
417008	Italian	HW Gon		Yes	No		Light Rprs	Shackle bolt on spring missing Car loaded castings.
920036	German	Tank				46	B.O.Shop	Hole in end & end sill blown
410241	Italian	HW Gon		Yes	No	18	Light Rprs	One end fire.
462439	Italian	HW Gon		Yes	Yes	18	Light Rprs	Draw bar missing
62290	Italian	HW Gon		Yes	Yes		Light Rprs	1/2 car sides, fire
Scrap - 10 box tank & Gon across from station, journals blown & fire.								
222 KM from Rome:								
11571	German	Flat	Yes				OK Sve.	
652953	Italian	LW Gon	No brakes		Yes	19	Light Rprs	1 buffer missing, move to trk 6.

Declassified E.O. 12356 Section 3.3/NND No. 785021

232-A/2

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
Scrap - 13 Box, Gons. Fire & no wood, no switch, located between tracks.								
219 KM from Rome:								
15 Gons loaded scrap, journals blown, 9 box blown up, fire.								
215 KM from Rome:								
Scrap - 2 box, fire, on siding,switch blown								
FIORENTINO 209 KM from Rome:								
20367	German	HW Gon	Yes			24.5	Light Rprs	Journal box & spring check, also journal brass
18187	German	Box	No brakes		Yes	15	B.O.Shop	Patch roof, repair end 15' from track.
Scrap - 17 cars, journals blown, one french fair but off track on switch closed, 44585 Frenc Gen.								
CORTONA - TERONTOLA YARDS, 193 KM from Rome:								
9127	German	Box	Yes			15	B.O.Shop	1 end repairs, wood.
Scrap - 1 box								
67597	German	Pass					B.O.Shop	Int & Ext repairs
4280	German	HW Gon	Yes			20	B.O.Shop	Repairs to sides
15985	German	HW Gon	Yes			20	B.O.Shop	Repairs to sides
4823	German	HW Gon	Yes			20	B.O.Shop	Repairs to sides & doors
4410529	Italian	HS Gon	Yes			22	OK Sve	
402817	Italian	HS Gon		Yes	Yes	22	Light Rprs	Reprs to decking, 4 boards.
13792	German	Box	No brakes		Yes	15	OK Sve	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
459956	Italian	HW Gon				18	OK Sve	Loaded one lathe
35CZ30473	Italian	Coach					B.C.Shop	3rd Class, Int & Class
9283	German	LW Gon	Yes			15	OK Sve	
56159	German	Box	Yes			15	Light Rprs	Patch roof & siding
183018	Italian	Box	Yes			17	Light Rprs	1 buffer missing, patch siding
Scrap - 1 3rd Class coach, shot up, 36057 Italian.								
36590		Coach					B.O.Shop	Hosp train, 3rd Class coach
36563		Coach					B.C.Shop	" " "
36665		Coach					B.O.Shop	" " "
92169		Baggage					B.O.Shop	" "
22545	German	HW Gon	Yes			20	Light Rprs	Decking patch, open track
215546	French	Box	Yes			20	Light Rprs	Patch one end, open track
14542	German	Box	Yes			15	Light Rprs	4 pcs decking, open track
81052	German	HW Gon	Yes			20	OK Sve	Open track
59432	German	Box	Yes			15	OK Sve	Open track
22716	German	Box	No brakes		Yes	15	B.C.Shop	Roof caved in.
240819	French	Box	Yes			20	B.C.Shop	1 side and roof repairs
7459	German	Refr	Yes			15	B.C.Shop	Roof caved in, repr siding
20130	German	Box	No brakes		Yes	15	B.C.Shop	Roof caved in
157653	Belgium	Box	Yes			15	B.C.Shop	Roof & patch sides
Scrap - 262121 French box								
21288	German	HW Gon	No brakes		Yes	15	OK Sve	Track blocked by string of scrap
128338	French	HS Gon	Yes			20	OK Sve	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
21156	German	HW Gon	Yes			20	Light Rprs	Patch siding
Scrap - 3 box & 3 coaches, fire								
409315	Italian	HS Gon	Yes			22	OK Sve	Loaded ties
30785	German	HW Gon	Yes			24.5	OK Sve	Loaded coal
Scrap - 20 burnt boxes								
Cars will be OK if lumber is available.								
Above 31 cars all 6' from main line on dead track.								
189 KM from Rome:								
472743	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded tanck tracks
6296	German	HW Gon	Yes			24.5	OK Sve	" " "
19360	German	HW Gon	Yes			24.5	OK Sve	" " "
4225	French	HW Gon	Yes			20	B.O.Shop	Loaded tank tracks, siding
3185	German	HW Gon	Yes			20	OK Sve	Loaded tank tracks
90653	German	Box	No brakes		Yes	15	B.O.Shop	1/2 decking & 1 end repair
457845	German	HW Gon	No brakes		Yes	15	OK Sve	
45377I	German	HW Gon	No brakes		Yes	15	OK Sve	
96758	German	HW Gon	Yes			15	Ok Sve	
140	German	HW Gon	Yes			20	OK Sve	
17471	German	HW Gon	No brakes		Yes	15	OK Sve	
16945	German	HW Gon	Yes			24.5	OK Sve	
486051	Italian	HW Gon	Yes			18	OK Sve	
7408500	Italian	HW Gon	No brakes		No	15	Light Rprs	One end bent out
414065	Italian	HW Gon		Yes	No	18	OK Sve	
40644	German	Flat	No brakes		Yes	15	OK Sve	
4662	German	LS Gon	Yes			20	OK Sve	
48433	German	Flat	No brakes		Yes	15	OK Sve	
6905	German	Flat	Yes			15	OK Sve	
48342	German	Flat		Yes	Yes	15	OK Sve	
11840	German	Flat	Yes			15	OK Sve	
51268	German	Flat	Yes			15	OK Sve	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
54011	German	Flat	Yes			15	Light Rprs	Brake shoe missing
13381	German	Flat	Yes			20	OK Sve	
43320	German	Flat	No brakes		Yes	15	OK Sve	
43979	German	Flat	Yes			15	OK Sve	
45670	German	Flat	Yes			15	OK Sve	
46029	German	Flat	No brakes		Yes	15	OK Sve	
55498	German	Flat	Yes			15	Light Rprs	End boards patch, H.B. broken
53022	French	LW Gon	Yes			20	OK Sve	
3889	German	Flat	Yes			25	OK Sve	
445256	German	Flat	Yes			15	OK Sve	
819	German	Flat		Yes	Yes	15	OK Sve	
33453	German	Flat	Yes			15	OK Sve	
698613	Italian	Flat		Yes	No	40	OK Sve	Trucks
36989	German	Flat	Yes			15	OK Sve	
368160	German	LW Gon	No brakes		Yes	15	Light Rprs	Journal box repair
32559	German	Flat	No brakes		Yes	15	OK Sve	
50133	German	Flat	Yes			15	OK Sve	
7402278	Italian	HW Gon		Yes	No	15	Light Rprs	Spring shackle
463978	Italian	HW Gon	No brakes		No	18	Light Rprs	Coupler broken
183 KM - Four burnt gons, scrap.								
PANICALE 179 KM from Rome:								
227739	French	Box	Yes			20	Light Rprs	Shackles on springs repr, patch ends.
28679	German	Box	No brakes		Yes	15	Light Rprs	Patch roof
111916	Italian	Box	No brakes		Yes	20	OK Sve	
95969	German	Box	Yes			15	B.O.Shop	Cyl shot up & holes in sides
80326	German	Box	Yes			15	B.O.Shop	Journal box shot 1 hole, patch roof
40455	German	Box	Yes			15	OK Sve	
391619	Italian	Refr	Yes			15	B.O.Shop	Off track
3 Scrap, 4 lengths rail blown.								
1412	German	HW Gon	Yes			20	OK Sve	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
180131	French	HW Gon	Yes			20	Light Rprs	Buffer spring broken
485853	Italian	HS Gon		Yes	No	19	OK Sve	
464880	Italian	HW Gon		Yes	No	18	OK Sve	
479863	Italian	HW Gon	Yes			18	Light Rprs	Coupler hook broken
464953	Italian	HW Gon	No brakes		Yes	18	OK Sve	
144211	Belgique	HW Gon	Yes			20	OK Sve	
21754	H	HW Gon	No brakes		Yes	20	OK Sve	
57182	German	HW Gon	Yes			20	CK Sve	
181890	French	HW Gon	Yes			20	Light Rprs	Brake hanger Repair
7448081	Italian	HW Gon		Yes	Yes	15	OK Sve	1 bolt missing on buffer
						20	OK Sve	
27233	German	HW Gon	Yes		Yes	15	B.O.Shop	roof caved in, bullet holes sides
15167	German	Box	No brakes					

Above cars 10' from main line. No switch from storage to main line, 2 burnt scrap box.

CHIUSI 165 KM from Rome:							
933850	German	Flat	No brakes	Yes	15	B.O.Shop	1/4 decking burnt
84979	German	LS Gon	Yes		15	B.O.Shop	1/4 decking missing sw 2' blown

Four Gons scrap, fire
90 scrap burnt cars.
35 Burnt & scrap cars at 159 KM from Rome.
25 Burnt & scrap cars at 158 KM from Rome.

1001271	Italian	Box	Yes	18	B.O.Shop	Patch roof & sides
270079	Italian	ST Box		18	OK Sve	
3456	German	LW Gon	Yes	24.5	OK Sve	Loaded 1 German tank
73601	German	LS Gon	Yes	15	OK Sve	Loaded 1 German tank.

Track is blown & needs switch 6' from main line.

CITTA' DELLA PIEVE 156 KM from Rome:			Yes	No	13	B.O.Shop	Car water tank, bullet holes
9520294	Italian	Tank					

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
950429	Italian	Tank		Yes	No	16	B.O.Shop	Water tank, bullet holes
7900049	Italian	Tank		Yes	Yes	16	B.O.Shop	Water tank, bullet holes
154 KM from Rome:								
1129927	Italian	ST Box	Yes			19	B.O.Shop	Doors repair & top
722	German	Box	Yes			15	B.O.Shop	Patch end & 1/5 decking
13515	German	Box	Yes			15	B.O.Shop	Roof & end Repair
111194	Italian	Box	No brakes		Yes	19	B.O.Shop	1 end & 1/2 side burnt
25 Burnt scrap cars in line with above 4 cars.								
307573	Italian	Refr	Yes			15	B.O.Shop	Small rprs Int & Ext.
1143664	Italian	Box	Yes			17	B.O.Shop	Repr doors & Windows
57 Scrap cars in one line on siding.								
42411	German	LW Gon	Yes			15	OK Sve	
49638	German	LW Gon	Yes			15	OK Sve	
412121	Italian	HW Gon	No brakes		No	18	OK Sve	
6210	German	HW Gon	Yes			20	OK Sve	
474740	Italian	HW Gon	No brakes		No	18	OK Sve	
13942	German	Flat	Yes			40	OK Sve	Trucks
6953	German	Flat	Yes			15	Light Rprs	Brake beam damaged
13368	German	Flat	Yes			40	OK Sve	
75693	German	HW Gon	Yes			20	OK Sve	
46068	German	HW Gon	Yes			20	OK Sve	
6211	German	HW Gon	Yes			20	OK Sve	
1509	German	Flat	Yes			24.5	OK Sve	
131310	German	Box					Scrap	No wood, burnt

Above 13 cars 153 KM from Rome, cars to be moved to main track.

186

0544

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
FICULLE 148 KM from Rome:								
8973	German	Flat	Yes			24.5	OK Sve	
15205	German	Flat	Yes			24.5	OK Sve	
19533	German	Flat	Yes			24.5	OK Sve	
1938	German	Flat	Yes			20	OK Sve	
16304	German	Flat	Yes			20	OK Sve	
1446	German	Flat	Yes			24.5	OK Sve	
4200	German	Flat	Yes			20	OK Sve	
12103	German	Flat	Yes			24.5	OK Sve	
14814	German	Flat	Yes			24.5	OK Sve	
4607	German	Flat	Yes			20	OK Sve	
6085	German	Flat	Yes			24.5	OK Sve	
3987	German	Box	No brakes		Yes	15	B.O.Shop	Roof loose at end
18876	German	HW Gon	No brakes		Yes	20	OK Sve	Loaded stone
33450	German	LW Gon	Yes			15	OK Sve	
68891	German	LS Gon	Yes			15	OK Sve	
Scrap - 2 Gons bombed. Above cars 6' from main line, use crane								
42634	France	HW Gon	Yes			20	B.O.Shop	End decking 1/4
411980	Italian	HW Gon	No brakes		No	18	OK Sve	
447341	Italian	HW Gon	No brakes		No		OK Sve	
Scrap - 24 cars, bombed & fire.								
130 KM from Rome:								
92353	German	LW Gon	No brakes		Yes	12	B.O.Shop	Needs decking & siding
44078	French	HW Gon	Yes			20	B.O.Shop	Decking
94414	German	HW Gon				30	B.O.Shop	Trucks, one side wood
18788	German	HW Gon	Yes				B.O.Shop	Siding caved in
14253	German	Well	Yes			50	OK Sve	
472200	Italian	HW Gon	Yes			18	OK Sve	
170291	Italian	Box	Yes			22	OK Sve	
495142	Italian	HS Gon	No brakes		Yes	19	OK Sve	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Conditions	Remarks
475220	Italian	HW Gon	Yes			18	OK Sve	
48340	German	HW Gon	Yes			24.5	OK Sve	2 decking boards, patch
410492	Italian	HW Gon		Yes	No	18	Light Rprs	Decking
693459	Italian	Flat		Yes	No	40	OK Sve	Loaded steel forms, trucks
112569	Italian	Box	No brakes		Yes	20	B.O.Shop	1/2 decking patch roof & end
1118517	Italian	ST Box	Yes			19	OK Sve	
1127324	Italian	ST Box	Yes			19	OK Sve	
99599	Bagg & Poste						OK Sve	
14597	German	Box	Yes			15	OK Sve	
97462	German	Box	Yes			15	B.O.Shop	1 side repair
14803	German	Box	Yes			15	OK Sve	
41534	German	Box	Yes			15	Light Rprs	Patch 2 boards siding
22915	German	HW Gon	Yes			20	OK Sve	1 end missing
2674	German	HW Gon	Yes			24.5	OK Sve	Loaded stone
92711	German	HW Gon	No brakes		Yes	20	B.O.Shop	Loaded stone
6634	German	HW Gon	Yes			20	B.O.Shop	Loaded stone, 1 side & end Rpr
99814	French	HW Gon		Yes	No	20	B.O.Shop	Loaded stone
490078	Italian	HS Gon		Yes		19	OK Sve	Loaded stone
470717	German	HW Gon	No brakes		Yes	20	B.O.Shop	Lded steel frames Rpr decking sides and ends.
494566	Italian	HS Gon	No brakes		Yes	19	OK Sve	Loaded stone
50732	German	HW Gon	Yes			20	OK Sve	Loaded stone
821027 } 821003 }		Dump	Yes			40	OK Sve	2 cars, loaded stone
22897	German	HW Gon		Yes	Yes	20	OK Sve	Loaded stone
464130	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded stone

Above cars in about 1/4 on switch with 52 scrap cars.

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
8065	German	HW Gon	No brakes		Yes	20	OK Sve	
481281	Italian	HW Gon	Yes			18	Light Rprs	Brake hanger & shoe repair
821004		Dump				40	OK Sve	Jack & set on track 6' from main
3928	German	LW Gon	Yes				B.O.Shop	Fire, no wood
807506	Italian		Yes			10	OK Sve	Hand 10 ton crane
16289	German	Flat					Light Rprs	Lded cement mixer (2), broken cylinder link
44767	German	Flat	Yes			15	B.O.Shop	No decking
Scrap - 12 Cars								
251688	Italian	Box	No brakes		Yes	17	B.O.Shop	Rprs door & roof
529654	Italian	Refr	Yes			15	B.O.Shop	Rprs 1/4 siding, coupler broken
275318	French	Box	Yes			20	B.O.Shop	Rprs door, patch roof
651762	Italian	LW Gon	No brakes		No	19	OK Sve	Loaded rail
655127	Italian	LW Gon	No brakes		No	19	OK Sve	Loaded rail)4 cars
25684	German	Flat	No brakes		No	15	OK Sve	Loaded rail
644358	Italian	IST Gon	Yes			20	OK Sve	Loaded rail
1129728	Italian	ST Box	Yes			19	OK Sve	
Above 8 cars on switch same as 12 scrap cars.								
Cars below are at 130 KM from Rome:								
19539	German	Box					Scrap	Roof, sides & ends
1014498	Italian	Box					Scrap	Roof & side
29531	German	Box	No brakes		Yes	15	Scrap	
1011790	Italian	Box	No brakes		Yes	19	OK Sve	
1293	German	Box	Yes			20	OK Sve	
128718	Italian	ST Box	Yes			19	OK Sve	
96375	German	Box	No brakes		Yes	15	OK Sve	
1006443	Italian	Box	Yes			18	OK Sve	
14931	German	Box	Yes			15	OK Sve	

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
1117350	Italian	Box	Yes			19	B.O.Shop	1/2 decking out
308178	Italian	Refr	Yes			15	OK Sve	
1020595	Italian	Box	No brakes		No	19	OK Sve	
1119994	Italian	ST Box	Yes			19	OK Sve	
Scrap - 2 Cars.								
316040	Italian	Refr	Yes				Light Rprs	Floor burnt small patches
415584	Italian	HW Gon		Yes	No	18	OK Sve	Loaded ties
413964	Italian	HW Gon	No brakes		No	18	OK Sve	
491769	Italian	HS Gon	No brakes		No	19	OK Sve	Loaded ties
20103	Nederland	Box	Yes			17.5	Light Rprs	Rprs 1 door,bent.
32532	German	Box	Yes			15	Light Rprs	Repr 1 door, loose lded ties
131222	Italian	Box	Yes			15	Light Rprs	Patch roof,loaded ties
36944	German	Box	Yes			15	OK Sve	Loaded ties
47881	German	Box	Yes			15	B.O.Shop	Patch door, roof & ends
35471	German	Box	No brakes		Yes		Light Rprs	Repr door
38080	German	Box	Yes			15	Light Rprs	Loaded ties,Repr sides
172663	French	Box	Yes			20	Light Rprs	Door & siding patch
1012432	Italian	Box	Yes			18	OK Sve	Loaded ties
4 Scrap								
12345	German	Box	No brakes		Yes	15	OK Sve	
43545	German	Box	Yes			15	B.O.Shop	Burnt 1/2 side & 5 pcs decking
99063	German	Box	No brakes		Yes	15	Light Rprs	Repr door
16213	German	Box	No brakes		Yes	15	OK Sve	
2127	German	Box	Yes			15	OK Sve	
2549	German	Box	No brakes		Yes	15	OK Sve	
82735	German	Box	Yes			15	B.O.Shop	Check journal

Above cars on siding at 130 KM from Rome.

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
BASCHE 118 KM from Rome:								
24641	German	HW Gon	Yes			20	B.C.Shop	Load coal, journal oil pan & wick missing, no journal lids
258300	German	Box	Yes			15	B.C.Shop	End, fire
Scrap - 25 cars								
114 KM from Rome:								
4 water tanks								
3 Gons								
1 Passgr								
2 Box								
Across river & valley from Road.- 111 KM from Rome:								
93134	German	LW Gon	Yes			15	B.O.Shop	1 side & 1 end boards missing 6 deck boards off.
13790	German	Flat	Yes			40	B.O.Shop	Trucks, journal
16900	German	Flat				40	B.O.Shop	Trucks, juornal, lids off journal boxes
TWO cars have 75' I beam loaded on cars.								
61080	German	HW Gon	Yes			20	B.O.Shop	I end 1/2 side, fire damage
91350	German	Flat	No brakes		No	15	OK Sve	
Above car is for moving rail etc, has swivel in center of car								
80496	German	Flat	Yes			40	OK Sve	Loaded I beams
159341	French	Flat				40	B.O.Shop	Decking, check trucks
5300	German	LS Gon	Yes				OK Sve	Loaded ties & steel
66191	German	LS Gon	Yes			15	OK Sve	I beams loaded on car
10450	German	Flat	Yes			15	OK Sve	" " " " "
91170	German	LW Gon		Yes	Yes	15	Light Rprs	12 pcs decking missing
660394	Italian	LS Gon	Yes			20	OK Sve	
50996	German	LW Gon	Yes			15	B.O.Shop	Lded steel, 8 pcs deck, one end fire damage

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
041939	Italian	HW Gon	No brakes		Yes	17	B.O.Shop	1/2 siding, fire damage
6201	German	HW Gon	No brakes		Yes	20	B.O.Shop	1 end damage, fire
Scrap - 20 cars								
ALVIANO 104 KM from Rome:								
13805	German					40	Scrap	Frame 1 end blown, trucks damaged
7900022	Italian	Tank Wtr		Yes	Yes	15	B.O.Shop	1 valve missing, coupler broke
ORTE 84 KM from Rome:								
27537	German	LW Gon	No brakes		Yes	20	OK Sve	Lded 2 boilers
80798	German	HW Gon	Yes			20	B.O.Shop	1/2 car damaged, fire
8448	German	HW Gon	No brakes		Yes	20	OK Sve	
15715	German	Flat	No brakes		Yes	15	OK Sve	Lded two furnaces
58648	German	HW Gon	Yes			20	OK Sve	Lded machinery
31115	German	HW Gon	Yes			20	B.O.Shop	Loaded steel, 1/2 car fire
42309	German	Flat	Yes			15	OK Sve	Lded one water tank.
22564	German	HS Gon	No brakes		Yes		Light Rprs	Coupler bent
627539	Italian	LW Gon	No brakes		Yes	16	Light Rprs	Lded steel scrap, one end
86452	German	LS Gon	Yes			15	OK Sve	Loaded machinery
7403883	Italian	HW Gon		Yes	Yes	20	OK Sve	
43019	German	LW Gon	Yes			15	B.O.Shop	Lded machinery, 1 end fire
46794	German	HW Gon	Yes			20	B.O.Shop	2 ends fire damage
481390	Italian	HW Gon	No brakes		No		OK Sve	Lded machinery
415091	Italian	HW Gon		Yes	No	18	B.O.Shop	2 ends fire damage
463318	Italian	HW Gon	No brakes		Yes	18	Light Rprs	1 end fire, coupler broke

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
498934	Italian	HS Gon	No brakes		Yes	19	OK Sve	
33329	German	HW Gon	No brakes		Yes	20	B.O.Shop	1/2 side,fire
4357	German	HW Gon	Yes			20	B.O.Shop	Loaded steel
6203	German	HW Gon	Yes			24.5	OK Sve	Loaded pipe
44156	German	HW Gon	Yes			24.5	OK Sve	Lded bar steel, various sizes
30734	German	HS Gon	No brakes		Yes		OK Sve	Lded 1"x6"x3' steel
24378	Nederland	Box	Yes			15	B.O.Shop	Lded machinery
63123	German	HW Gon	Yes			20	B.O.Shop	Lded mac,1 end fire
486293	Italian	HW Gon		Yes	Yes	18	OK Sve	
434108	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded steel
99765	German	HW Gon		Yes	Yes	15	B.O.Shop	Loaded steel, 1 end fire
411445	Italian	HW Gon		Yes	No	18	B.O.Shop	Loaded steel,1 end fire
17507	German	HW Gon	No brakes	X	Yes	20	B.O.Shop	4 deck boards, 3 side boards
30278	German	HW Gon	Yes			20	B.O.Shop	Fire damage 1/2 siding, 1/5 decking
43629	German	HW Gon	Yes			24.5	B.O.Shop	1/4 decking, 1/4 sides
93513	German	HW Gon	No brakes		Yes	20	OK Sve	
43746	German	HW Gon	Yes			20	B.O.Shop	Repr decking,check journal
85907	German	HW Gon	Yes			20	OK Sve	
40786	German	HW Gon	Yes			24.5	OK Sve	
220	German	HW Gon	Yes			20	Light Rprs	Brake hanger check shoe off
8637	German	HW Gon	Yes			20	OK Sve	
62132	German	HW Gon	Yes			20	B.O.Shop	1 end fire damage
22920	German	HW Gon	Yes			20	OK Sve	
11129	German	HW Gon	Yes			20	B.O.Shop	1 end fire damage
13775	German	HW Gon	Yes			20	B.O.Shop	1 end fire damage

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
Scrap - 37 cars in above line								
Above cars at Orte between 84 & 83 KM.								
1115741	Italian	S Box	Yes			19	OK Sve	Bunk cars 794th M.P.Bn.
1014284	Italian	Box	Yes			18	OK Sve	Bunk car
1122326	Italian	S Box	Yes			19	OK Sve	Bunk car
169393	Italian	Box	No brakes		No	18	OK Sve	Bunk car
251528	Italian	Box	No brakes		Yes	18	OK Sve	Bunk car
7719301	Italian	Box	Yes			15	OK Sve	Bunk car
2[illegible]194	Italian	ST Box	Yes			19	OK Sve	Bunk car
1004880	Italian	Box	Yes			18	OK Sve	Bunk car
1029570	Italian	Box	No brakes		Yes		OK Sve	Bunk car
1118707	Italian	S Box	Yes			19	OK Sve	
45609	German	Box	Yes			15	OK Sve	Bunk car
FSAZ10050		Pass					B.O.Shop	1st Cl. Fair condition, Int. & Ext.
FSAZ11009		Pass					B.O.Shop	1st Cl. Bunk car 759th
FSCZ32611		Pass					B.O.Shop	3rd Cl. Bunk car
No number		Pass					B.O.Shop	3rd Cl. Bunk car
200893	Italian	Caboose	Yes			14	OK Sve	
118103	Italian	S Box	Yes			19	OK Sve	Bunk car
4[illegible]324	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded coal
409916	Italian	HW Gon	No brakes		Yes		OK Sve	Loaded coal
ORTE south of station in yards, 81 KM.								
411924	Italian		No brakes		No	18	OK Sve	6' from open track
1115151	Italian	ST Box	Yes			19	B.O.Shop	Drawbar broken, spring shackle broke, loaded lumber
806933	Italian	LW Gon	No brakes		No		OK Sve	Snow plow, loaded stone.

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
1006411	Italian	Box	Yes			18	CK Sve	
Following cars set on siding, journal trouble.								
35517	German	HW Gon	No brakes		Yes	20	B.O.Shop	
52039	German	HW Gon	Yes			24.5	B.O.Shop	
17792	German	HW Gon	No brakes		Yes	20	B.O.Shop	
91415	German	Flat	No brakes		Yes	15	B.O.Shop	
3046	German	LW Gon	Yes			15	B.O.Shop	Brace underframe, broke
43535	German	HW Gon	Yes			20	B.O.Shop	
71	German	Flat	No brakes		Yes	15	B.O.Shop	For handling long steel swivel in center
45597	German	HW Gon	Yes			24.5	B.O.Shop	
52606	German	HW Gon	Yes			20	B.O.Shop	
25419	German	Box	Yes			15	B.O.Shop	
78345	German	S Gon	Yes			15	B.O.Shop	Pedestal bent
4707	German	Box	Yes			15	OK Sve	Loaded machinery
33806	German	HW Gon	Yes			24.5	OK Sve	" "
133758	German	Box	Yes			15	OK Sve	
162655	Italian	Box	Yes			17	OK Sve	
Above 4 cars same track as bad journals.								
Dispatch car at 81 KM from Rome not in use, coach stencilled R.C.E.								
Scrap - 40 cars in yards, fire damage.								
CIVITA CASTELLANA - 71 KM from Rome:								
1135188	Italian	ST Box	Yes			19	OK Sve	5' off track, one end
1010556	Italian	Box	No brakes		Yes		B.O.Shop	Trn line, patch 1 end & doors, off track, one car
204208	Italian	Box	Yes			17	B.O.Shop	Buffer off & repr brake hanger off track 1 car

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
Scrap - 3 cars.								
STIMIGLIANO:								
474684		Gon	Yes				OK Sve	
10610	German	Box			Yes	15	B.O.Shop	Roof & side
53443	German	Box	Yes				B.O.Shop	1 end fire
295507	French	Box		Yes	Yes		B.O.Shop	1 end fire
33518	German	Box	Yes			15	OK Sve	
45293	German	Box	Yes			15	OK Sve	
25496	German	LW Gon	Yes			15	B.O.Shop	Loaded truck, 1 end fire
74208	German	LS Gon	Yes			15	B.O.Shop	Decking, loaded
9866			No brakes		Yes	15	B.O.Shop	Loaded
5494	German		Yes			15	OK Sve	Loaded
3335	German		Yes			15	B.O.Shop	Decking, loaded truck
1 Passenger coach								
12183		Coach					B.O.Shop	Int & Ext
37179		Coach					B.O.Shop	3rd Cl.
17248	German	Box	No brakes		Yes	15	B.O.Shop	Coupler
045367			No brakes		Yes	15	B.O.Shop	Coupler broken
740060		Coach						
740087		Coach						
741648		Coach						
741285		Coach						
259619	German	Box					B.O.Shop	
740161		Coach						
740761		Coach						
740977		Coach						
741011		Coach						
741016		Coach						
740038		Coach						
741809	German	Coach, 3rd Cl.						
740026	German	Box	Yes			15	OK Sve	

176

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
740424	German	Box	Yes			15	B.O.Shop	Roof
740427	German	Box	Yes			15	OK Sve	
68629	German	Box	Yes			15	B.O.Shop	Door, patch roof
28163	German	HW Gon	Yes			20	B.O.Shop	Fire damage, 1 side
3567	German	HW Gon	Yes			20	B.O.Shop	Fire sides, ends
45350	German	HW Gon	Yes			15	B.O.Shop	Fire damage, 1 end
97915	German	HW Gon	Yes			20	B.O.Shop	Fire damage
516	German	HW Gon	Yes			20	B.O.Shop	Fire damage one end
19858	German	HW Gon	Yes			24.5	B.O.Shop	Fire damage
9173	German	HW Gon	Yes			24.5	B.O.Shop	Fire
411047	Italian	HW Gon	Yes			18	B.O.Shop	Fire
22905	German	HW Gon	Yes			24.5	B.O.Shop	Fire
212955	French	Box	Yes			20	B.O.Shop	Fire damage, small
24099	German	Box	Yes			15	B.O.Shop	Fire
278317	French	Box	No brakes		Yes		B.O.Shop	Repr roof
40104	German	LW Gon	Yes			15	B.O.Shop	Small fire damage, lded tank
29532	German	HST Gon	No brakes		Yes	15	B.O.Shop	Lded tanks, water, doors
87130	German	HW Gon	Yes			20	B.O.Shop	Lded, one end fire
3022	German	HW Gon	Yes			15	OK Sve	Loaded tanks
27070	German	LW Gon	Yes			15	B.O.Shop	Loaded, one end fire
23386	German	LW Gon	Yes			15	B.O.Shop	Lded tanks, decking 1 end
37028	German	HW Gon	Yes			20	B.O.Shop	Fire damage
17989	German	HW Gon	Yes			20	B.O.Shop	Damage one end
7403427	Italian	HW Gon				17	B.O.Shop	Brake hanger & coupler repr
12565	French	LW Gon				30	B.O.Shop	Trucks, decking 1/5 & Coupler

175

Above string of cars start at 55 KM and run to 58 KM north.
48 KM from Rome, Poggio Mirteto - Scrap 7 cars, 2 prs roller bearing trucks

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
50304		Pass					B.O.Shop	Int & Ext reprs
38 KM - on adjoining track, Fara Sabina								
176876	French	Box	Yes			20	OK Sve	
310019	French	Box				15	OK Sve	
14102	German	Box	No brakes		Yes	15	OK Sve	
921672	German	Tank	Yes			18	OK Sve	
121029	German	Box		Yes	Yes	15	OK Sve	
11645	German	Box	No brakes		Yes	15	OK Sve	
1027336	Italian	Box	No brakes		Yes	19	Light Rprs	Roof patch
1135136	Italian	ST Box	Yes			19	OK Sve	
115983	Italian	Box ST	Yes			19	OK Sve	
20339	German	LW Gon	Yes			15	OK Sve	
2311	German	Box	Yes			15	OK Sve	
1145159	Italian	ST Box	Yes			19	OK Sve	
4407	German	Box	Yes			15	B.O.Shop	Roof
309257	French	Box	No brakes		Yes	15	B.O.Shop	Siding
12943	German	Box	Yes			15	OK Sve	
CZ41865	Italian	Pass					B.O.Shop	3rd Cl.
153513	Belgium	Box	Yes			15	OK Sve	
62933	French	Box	Yes			10	B.O.Shop	Roof patch repr.
52726	German	HW Gon	Yes			20	OK Sve	
357742	French	HW Gon	No brakes		Yes	20	OK Sve	
1001055	Italian	Box	Yes			18	B.O.Shop	Repair roof
54140	German	HW Gon	Yes			20	OK Sve	
20502	German	HW Gon	Yes			24.5	B.O.Shop	Lded loco wheels, 1 end damaged
47637	German	HW Gon	No brakes		Yes	15	OK Sve	Lded loco wheels
57017	German	HW Gon	Yes			20	OK Sve	Lded loco wheels
30260	German	HW Gon	Yes			15	OK Sve	Lded loco wheels
39790	German	Box	Yes			15	B.O.Shop	Repair doors & sides
30347	German	~~Box~~	No brakes		Yes	15	B.O.Shop	Doors & sides, patch roof

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
62830	German	Box	Yes			15	B.O.Shop	Repair doors & roof
5222	German	Box	No brakes		Yes	15	OK Sve	
20972	German	Box	Yes			15	Light Rprs	Repair door
4928	German	Box	No brakes		Yes	15	B.O.Shop	Body repairs
24681	German	Box	No brakes		Yes	15	B.O.Shop	Roof & doors repair
2505	German	Box	No brakes		Yes	15	B.O.Shop	Repair roof & doors
24020	French	Box	Yes			14	B.O.Shop	Repair sides, roof & door
76123	German	LS Gon	Yes			15	B.O.Shop	Bullet hole in journal box
467287	Italian	HW Gon		Yes	No		B.O.Shop	Lded dirt, 1 end & side repr
94631	French	LW Gon	No brakes		Yes		Scrap	Broken frame
694429	Italian	Flat		Yes	No	40	B.O.Shop	Trucks, loaded pipe
650782	Italian	LW Gon	No brakes		No	19		
472583	Italian	HW Gon	No brakes		No	18	Light Rprs	Coupler links missing
36 KM from Rome:								
21549	German	Box	No brakes		Yes	15	B.O.Shop	Side & door, loaded mach
19254	German	HW Gon	Yes			20	B.O.Shop	
7979	German	HW Gon	Yes			20	B.O.Shop	1 end damaged, load steel
406101	Italian	ST Gon	Yes			22	OK Sve	
21244	German	HW Gon	No brakes		Yes	20	OK Sve	Load steel
84072	French	LW Gon	No brakes		No		OK Sve	Load mach
77343	German	HW Gon	Yes			20	OK Sve	
93947	German	HW Gon	Yes			20	Light Rprs	Doors, lded 1" steel rods

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
93454	German	LW Gon	No brakes		Yes	15	OK Sve	Boiler load
1546	German	Box	Yes			15	OK Sve	Loaded mach parts
11914	German	Box	Yes			15	B.O.Shop	Rpr door & roof
27 Km from Rome:								
67569	German	Box	Yes			15	B.O.Shop	Repr 1 end.
840075	German	Box	Yes			15	B.O.Shop	Repair sides & roof
12037	German	Box	No brakes		Yes	15	B.O.Shop	Roof repairs & doors
84409	German	Box	Yes			15	B.O.Shop	Roof repairs
1002566	Italian	Box	No brakes		Yes	19	B.O.Shop	Roof repairs
34981	German	Box	Yes			15	B.O.Shop	Roof repairs
29038	German	Box	Yes			15	B.O.Shop	Roof repairs
145220	Italian	Box	Yes			17	OK Sve	
94842	German	Box	Yes			15	B.O.Shop	Roof repairs
71433	German	Box	Yes			15	B.O.Shop	Roof repairs
79704	German	Box	Yes			15	B.O.Shop	Roof repairs
18980	German	Box	Yes			15	B.O.Shop	Roof & repairs
1005230	Italian	Box	Yes			18	B.O.Shop	Roof repairs
320983	Italian	Box	No brakes		Yes		B.O.Shop	Roof repairs
265987	French	Box	Yes			20	B.O.Shop	Roof repairs
61731	French	Box	Yes			10	B.O.Shop	Roof repairs
Scrap - 4 cars, cars above on adjoining track of main line 6' away.								
26 KM from Rome:								
101541	Italian	Box	No brakes		Yes	19	OK Sve	
58841	French	Box	No brakes		Yes	12	B.O.Shop	Roof repairs & end
1028562	Italian	Box	No brakes		Yes	19	OK Sve	
300800	Italian	Box	Yes			15	B.O.Shop	Roof repairs
170976	Italian	Box	No brakes		Yes	18	B.O.Shop	Repairs roof
29828	German	Box	Yes			15	B.O.Shop	Roof repairs
275899	French	Box	Yes			20	B.O.Shop	Roof repairs
19189	German	Box	Yes			15	B.O.Shop	Roof repairs

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
25 KM from Rome, MONTEROT:								
26 cars damaged with scrap trucks, autos etc.								
25 KM from Rome:								
205252	Belgium	No brakes			Yes	20	B.O.Shop	Siding & roof repairs
12 cars & 3 coaches								
16 KM from Rome:								
10 cars back of station.								

Typing completed 9/7/44.

1271

/mb

Declassified E.O. 12356 Section 3.3/NND No. 785021

0360

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - Line 50

Car No.	Country	Type	Air Brakes	Hand Brakes	Air Line	Tons	Condition
PALO-LAZIALE-48 KM							
130597		Box	No	No	Yes		
152370	Belgium	Box	Yes	No	No		B.O. Shop
33095	German	Box	No	No	Yes		Burnt
305585	French	Box	Yes	No			B.O.Shop
7647	German	Box	Brakes on car				Shop
12730	German LWS	Gon	Yes	No	No		OK for Sve.
660758	Italian ML	Gon	Yes	No		20	OK for Sve.
660756	Italian ML	Gon	Yes	No		20	Light Rprs.
652378	Italian LW	Gon	No	No	Yes	19	Hvy Repairs
195186	Belgium	Flat	Yes	No		19	OK for Sve.
92230	French	Flat	No Brakes		Yes	15	OK
685143	German	Flat	No Brakes		Yes	20	OK
654452	Italian LW	Gon	No	Yes	Yes		OK
14836	German	Flat	No Brakes		Yes	15	OK Sve.
645455	Italian LW	Gon	No Brakes		Yes	11	OK Sve.
10845	German LW	Gon	No Brakes		Yes	20	OK Sve.
4573	German LW	Gon	No Brakes		Yes	10	OK Sve.
81475	German LW	Gon	No Brakes		Yes	15	OK Sve.
87654	German LW	Gon	Yes			15	OK Sve.
30300	German	Box	Yes				B.O.Shop
7704847	Italian	Box	Yes				B.O.Shop
9564	German	Box	Yes		Yes		B.O.Shop
14965	German	Box	Yes				B.O.Shop
174484	French	Box	Yes				B.O.Shop
5162	German LW	Gon	Yes				B.O.Shop

Above cars are on siding at Palo-Laziale 48 KM from Rome - Open.

0361

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - Line 50

Type	Air Brakes	Hand Brakes	Air Line	Tons	Condition	Remarks
Box	No	No	Yes			OK for Svc, Siding trk open
Box	Yes	No	No		B.O. Shop	No wd on car-burnt Convert to flat.
Box	No	No	Yes		Burnt	No wd on car
Box	Yes	No			B.O.Shop	Part of roof, floor & ends burnt.
Box	Brakes on car				Shop	Car siding part miss)g, roof rpr, decking fair
Gon	Yes	No	No		OK for Svc.	Ided with rail
Gon	Yes	No		20	OK for Svc.	" " ") 110 lb
Gon	Yes	No		20	Tight Rprs.	" " " rail
Gon	No	No	Yes	19	Hvy Repairs	" " ")
Flat	Yes	No		19	OK for Svc.	" " " Old car trucks.
Flat	No Brakes		Yes	15	OK	Ided with rail)
Flat	No Brakes		Yes	20	OK	Ided with rail
Gon	No	Yes	Yes		OK	Ided with rail
Flat	No Brakes		Yes	15	OK Svc.	Ided with rail)
Gon	No Brakes		Yes	11	OK Svc.	Ided with rail
Gon	No Brakes		Yes	20	OK Svc.	Ided with rail)
Gon	No Brakes		Yes	10	OK Svc.	Ided with rail
Gon	Yes			15	OK Svc.	Ided with rail)
Gon	Yes			15	OK Svc.	Ided with rail
Box	Yes				B.O.Shop	Burnt-No wood on car
Box			Yes		B.O.Shop	" " " " "
Box	Yes				B.O.Shop	" " " " "
Box	Yes				B.O.Shop	" " " " "
Box	Yes				B.O.Shop	" " " " "
Gon					B.O.Shop	Decking & sides wd off.

ding at Palo-Leziele 48 KM From Rome - Cpen.

3241/1

0362

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand brks	Air Line	Tons	Condition
BURBANK STATION-57TH							
181254	Italian	Box		Yes	No	17	Light Rprs.
152252	French	LW Gon	No Brakes		Yes		OK Sve.
113640	German	Flat	Yes			10	OK Sve.
47959	German	Flat	Yes			15	OK Sve.
22765	German	LS Gon	No Brakes		Yes		OK Sve.
341880	German	Flat	Yes				OK Sve.
7229	German	LW Gon	Yes			20	OK Sve.
76760	German	LW Gon	Yes				OK Sve.
37247	German	LW Gon	Yes			15	Light Rprs.
475564	Italian	HW Gon				8	" "
717741	Italian	Box	Yes			19	B.O.Shop
42503	German	HW Gon	No brakes		Yes		B.O.Shop
1023230	Italian	Box	Yes				B.O.Shop
100880	Italian	Box		Yes	No		Good Cond.
SEVERAL- 63 MM Rome Yards - Open switch tracks							
2602	German	Flat	Yes			20	OK Sve.
7446443	Italian	HW Gon		Yes		20	Light Rprs.
1130527	Italian	Box	Yes			19	OK Sve.
12554	German	Box	No brakes		Yes		OK Sve.
56300	German	HW Gon	Yes			20	B.O.Shop
19298	German	HW Gon	No Brakes		Yes	20	B.O.Shop
Where are 5 burnt HW Gons and 5 Box cars on head end of track ahead of next listed cars.							
411856	Italian	HW Gon		Yes	No	18	B.O.Shop
474559	Italian	HW Gon	No brakes or air				OK Sve.
474303	Italian	HW Gon	No brakes or air			18	OK Sve.
473911	German	HW Gon	Yes				OK Sve.
202582	French	HW Gon	Yes				OK Rip

0 3 6 3

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 2)

	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
	Box		Yes	No	17	Light Rprs.	Cut journal
LW	Gon	No Brakes		Yes		OK Sve.	Lded with rail)
	Flat	Yes			10	OK Sve.	Lded with rail)
	Flat	Yes			15	OK Sve.	Lded with rail)
LS	Gon	No Brakes		Yes		OK Sve.	Lded with rail)
							Side board missing
Flat		Yes				OK Sve.	Loaded with rail
IW	Gon	Yes			20	OK Sve.	Loaded with rail
IW	Gon	Yes				OK Sve.	" " " Journal
IW	Gon	Yes			15	Light Rprs.	" " " Journal
HW	Gon				8	" "	Mty-Coupler missing
Box		Yes			19	B.O.Shop	One end bad-car shot up.
HW	Gon	No brakes		Yes		B.O.Shop	Loaded slack coal
Box		Yes				B.O.Shop	Burnt-no wood
Box			Yes	No		Wood Cond.	No trade.

Cars - Open switch tracks

Flat	Yes			20	Ok Sve.	
HW Gon		Yes		20	Light Rprs.	Loaded steel ½"x5"x4'.)
Box	Yes			19	OK Sve.	Needs little decking)
Box	No brakes		Yes		OK Sve.	
HW Gon	Yes			20	B.O.Shop	Decking & part siding
HW Gon	No Brakes		Yes	20	B.O.Shop	1/3 decking missing

Gons and 5 Box cars on head end of track ahead of next listed cars.

HW Gon		Yes	No	18	B.O.Shop	(Loaded with 12" pipe(Rip Trk.) (Siding boards end of car)
HW Gon	No brakes or air				OK Sve.	Lded Steel-1/2"xo"x7'
HW Gon	No brakes or air			18	OK Sve.	
HW Gon	Yes				OK Sve.	Lded steel-1/2"xo"x4'
HW Gon	Yes				OK Rip	Lded machinery, large belt wheels & Misc. Needs about 1/5 decking.

0364

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
343377	Belgium	HW Gon	Yes	Yes	Yes	20	B.O.Shop	Lded Me
109457	Italian	Box				17	OK Sve.	Loaded
1129114	Italian	Box	Yes			19	OK Sve.	Loaded
13110	German	HW Gon	Yes			20	OK Sve.	Lded Me
407593	Italian	HW Gon	Yes				OK Sve.	Lded bi
17920	German	HW Gon	No brakes		Yes	20	B.O.Shop	Lded co
09153	German	HW Gon	Yes			20	Shop	"
92240	German	Box	No brakes		Yes		B.O.Shop	cylin Lded Me deck
9554	German	HW Gon	Yes				OK Sve.	Loaded
24797	German	HW Gon	No brakes		Yes		Rip Trk Rprs.	Lded L
1027577	Italian	Box	No brakes		Yes		B.O.Heavy	Burnt-R
4782	German	HW Gon	No brakes		Yes		B.O.Heavy	Burnt-R

One Gon scrap to be removed from tracks to move balance of string of cars, one length of trac
remaining cars. Heat from fire damaged rails.

598702	Italian	Tank		Yes	Yes		OK Sve.	
482901	Italian	HW Gon	no brakes		Yes	18	OK Sve.	Lded s
486104	Italian	HW Gon	No brakes		Yes	18	OK Sve.	Lded s
7597	German	HW Gon	Yes			20	OK Sve.	Lded s
17834	German	HW Gon	Yes			20	OK Sve.	"
07900	German	HW Gon	Yes			20	OK Sve.	"
19071	German	HW Gon	Yes			24	B.O.Shop	"

Above on one track. Next car on adjoining track, five cars.

57350	German	HW Gon	Yes				B.O.Shop	Fi Ded in
485915	Italian	HW Gon	No brakes		No	18	B.O.Shop	Ded in ca

Then 3 scrap cars.

277893	French	HW Gon	Yes			20	OK Sve.	Loaded
24od	German	HW Gon	Yes			20	OK Sve.	Loaded
21069	German	HW Gon	Yes				OK Sve.	Loaded

38

0345

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - TIME 50 (Page 3)

Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
				20	B.O.Shop	Lded Machinery, siding & decking.
HW Gon	Yes	Yes	Yes	17	OK Sve.	Loaded & sealed.
Box				19	OK Sve.	Loaded rolls of paper.
Box	Yes			20	OK Sve.	Lded Mach. needs few decking
HW Gon	Yes				OK Sve.	Lded big rollers
HW Gon	Yes			20	B.O.Shop	Lded rollers, no decking
HW Gon	No brakes		Yes	20	Shop	" " , bad brake, cylinder shot up.
HW Gon	Yes				B.O.Shop	Lded Mach. Part of siding decking burnt.
Box	No brakes		Yes		OK Sve.	Loaded rollers.
HW Gon	Yes				Rip Trk Rprs.	Lded 1 big tank (Gas) End board burnt.
HW Gon	No brakes		Yes		B.O.Heavy	Burnt-no wood.
Box	No brakes		Yes		B.O.Heavy	Burnt-no wood.
HW Gon	No brakes					

removed from trucks to move balance of string of cars, one length of track needed to pull the
t from fire damaged rails.

Trk		Yes	Yes	OK Sve.	
HW Gon	no brakes		Yes	18 OK Sve.	Lded steel-1/2"xo"x4'
HW Gon	No brakes		Yes	18 OK Sve.	Lded steel-1/2"xo"x4'
HW Gon	Yes			20 OK Sve.	Lded steel-1/2"xo"x4'
HW Gon	Yes			20 OK Sve.	" " -1/2"xo"x4'
HW Gon	Yes			20 OK Sve.	" " -1/2"xo"x4'
HW Gon	Yes			24 B.O.Shop	" " -1/2"xo"x4'

ext car on adjoining track, five cars.

Fire Gon interior

HW Gon	Yes		B.O.Shop	Decking missing & part of sides.
HW Gon	No brakes	No	18 B.O.Shop	Decking one end one side of car from floor, B.O.
HS Gon	Yes		20 OK Sve.	Loaded coal
HW Gon	Yes		20 OK Sve.	Loaded coal
HW Gon	Yes		OK Sve.	Loaded coal. Completes track.

35 8

0366

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air brks	Hand Brks	Air Line	Tons	Condition	Remarks
70 Cars very heavy repairs, burnt. Loaded 30 cars of cement burnt.								
47o129	Italian	HW Gon	No brakes		No	10	Light Rprs.	Needs decking - B
473731	Italian	HW Gon	No brakes		No		E.O.Rip	Drew bar.
S.MARTELLA STATION, Side track.								
4402197	Italian	H Gon	No brakes		No	10	B.O.Shops	Buffer, one end (needs wrecker
						20	B.O.Shops	Car Load cement damaged.
118273	German	Box	Yes			12	Light Rprs.	Idea steel rail
5 Scrap cars at open switch track have been burnt								
3798	German	Flat	Yes				Light Rprs.	" " "
o50831	Italian	LW Gon		Yes	Yes		Shop	2nd hand ties
45?243	Italian	HW Gon		Yes			B.O.Shop	" " "
30838	German	HS Gon	No brakes		Yes			
15 Scrap box cars on fire they had been loaded with R.R. ties.								
33700	German	HS Gon	No brakes				S.O.Shop	Loaded ties -
2021o	German	HW Gon	Yes		Yes		B.O.Shop	" "
23915	German	Box	No brakes				B.O.Jrnls	Loaded ties
3991	German	Box	Yes				B.O.Jrnls	Loaded ties
50190	German	Box	Yes				S.O.Jrnls	Loaded ties
9550099	Italian	Wtr Tnk	No brakes		Yes		OK Svc.	
950096	Italian	" "		Yes	Yes	15	OK Svc.	
480128	Italian	HW Gon	No brakes		No	18	B.O.Shop	Journal - Loa
41413	German	Box	Yes				B.O.Shop	" "
30084	Italian	Refr	Yes			14	B.O.Shop	
391301	Italian	Refr		Yes	Yes		B.O.Shop	
# 30103	German	LW Gon	Yes					
# 23039	German	LW Gon	Yes					
# 16293	German	LW Gon	Yes					
# 21255	German	Flat	Yes					

0367

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LIFE 50 (page 4)

Type	Air brks	Hand brks	Air Line	Tons	Condition	Remarks
y repairs, burnt. Loaded 30 cars of cement burnt.						
HW Gon	No brakes		No	10	Light Rprs.	Needs decking-End of 24 cars scrap
HW Gon	No brakes		No		B.O.Rip	Drew bar.
M, Side track.						
H Gon	No brakes		No	10	B.O.Shops	Buffer, one end car off trk, (needs wrecker to get on trk)
Box	Yes			20	B.O.Shops	Car Ided cement. Roof caved in one side damaged.
en switch track have been burnt						
Flat	Yes			12	Light Rprs.	Ided steel rails
LW Gon		Yes	Yes		Light Rprs.	" " "
HW Gon		Yes			Shop	2nd hand ties ided journals.
HS Gon	No brakes		Yes		B.O.Shop	" " " " "
on fire they had been loaded with R.R. ties.						
HS Gon	No brakes		Yes		B.O.Shop	Loaded ties - journals.
HW Gon	Yes				B.O.Shop	" " "
Box	No brakes		Yes		B.O.Jrnls	Loaded ties
Box	Yes				B.O.Jrnls	Loaded ties
Box	Yes				B.O.Jrnls	Loaded ties
Wtr Trk	No brakes		Yes		OK Sve.	
" "		Yes	Yes	15	OK Sve.	
HW Gon	No brakes		No	18	B.O.Shop	Journal - Loaded coal
Box	Yes				B.O.Shop	" " "
Refr	Yes			14	B.O.Shop	
Refr		Yes	Yes		B.O.Shop	
LW Gon	Yes					
LW Gon	Yes					
LW Gon	Yes					
Flat	Yes					

497

0368

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (page 5)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
+82512	German	LW Gon	Yes					
+78061	German	LW Gon	Yes					
+082	German	Flat	Yes					
+17278	German	LW Gon	Yes					

+ - Above 8 cars have had charges placed at pedestals - wheels, pedestals and springs have
Cars loaded with rail.

TARQUINIA STATION - 100 KM

490134	Italian	HW Gon	No brakes		Yes		OK Svc.	Loaded wi
479359	Italian	HW Gon	No brakes		No		B.O.Shop	Lded pipe,
480925	Italian	HW Gon	No brakes		No		OK Svc.	Loaded pip
409772	Italian	HW Gon	Yes			20	OK Svc.	Dump trac
473784	Italian	HW Gon	No brakes		No	18	OK Svc.	Loaded scr
499827	Italian	HW Gon		Yes	No		OK Svc.	Lded small
480997	Italian	HW Gon	No brakes		Yes	18	Light Rprs.	1 spring sh
456453	Italian	HW Gon		Yes	Yes	18	OK Svc.	Loaded wi
17055	German	Box	Yes				Hvy Rprs	Loaded ti
11902	German	HW Gon	No brakes		Yes	15	OK Svc.	Loaded sc
499373	Italian	HW Gon	No brakes		Yes		OK Svc.	Loaded 2"

Three cars to scrap are loaded but have been on fire. Electrical equipment, water tank and l

101749	French	HW Gon	Yes			20	OK Svc	Loaded mad
391434	Italian	Refr	Yes				Hvy Rprs.	Doors sidi
30192	German	Box	Yes				Hvy Rprs.	Loaded mad
480084	German	HW Gon	Yes			20	Hvy Rprs.	Loaded mad
								Part s

Scrap 4 Box Cars. Cars were on fire.

73797	German	Box	Yes				Hvy Rprs	Loaded st
								replac
208224	French	Box	Yes				Hvy Rprs	Fire-roof,

Two cars scrap - 1 flat and 1 box.

7105367	Italian	Box	No brakes		Yes		B.O.Shop	Fire-sides
154	German	HW Gon	Yes				B.O.Shop	Journal ba

3611

0369

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (page 5)

Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
GB Gon	Yes					
GB Gon	Yes					
Flat	Yes					
GW Gon	Yes					

had charges placed at pedestals - wheels, pedestals and springs have been damaged.
rail.

00 KM						
HM Gon	No brakes		Yes		OK Svc.	Loaded with 1-3/4" pipe
HW Gon	No brakes		No		B.O.Shop	Lded pipe, ½ of 1 side,new siding
HW Gon	No brakes		No		OK Svc.	Loaded pipe
HM Gon	Yes			20	OK Svc.	Dump truck-car loaded.
HW Gon	No brakes		No	18	OK Svc.	Loaded scrap metal.
HW Gon		Yes	No		OK Svc.	Lded small blocks red tile.
HW Gon	No brakes		yes	18	Light Rprs.	1 spring shackle-Lded scrap.
HW Gon		Yes	Yes	18	OK Svc.	Loaded with scrap
Box	Yes				Hvy Rprs	Loaded tile & Misc.
HM Gon	No brakes		Yes	19	OK Svc.	Loaded scrap
HM Gon	No brakes		Yes		OK Svc.	Loaded 2" pipe

re loaded but have been on fire. Electrical equipment,water tank and 12" valves.

HM Gon	Yes			20	OK Svc	Loaded machinery
Refr	Yes				Hvy Rprs.	Doors siding need repair
Box	Yes				Hvy Rprs.	Loaded machinery,doors,roof & sides.
HW Gon	Yes			20	Hvy Rprs.	Loaded machinery, car been on fire. Part siding ded.

s were on fire.

box Yes

Box	Yes				Hvy Rprs	Loaded stone,fire-siding & decking replace
let and 1 box.					Hvy Rprs	Fire-roof,siding
Box	No brakes		Yes		B.O.Shop	Fire-sides
HM Gon	Yes				B.O.Shop	Journal bad

156

0370

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air brks	Hand brks	Air Line	Tons	Condition	Remarks
315867	Italian	Refr	Yes			15	B.O. Shop	Roof & doors.
52455	German	Box	Yes				OK Sve.	
485523	Italian	HS Gon	No brakes		No		OK Sve.	Loaded scrap
7641	German	Box	Yes			20	OK Sve.	
One box car fire - scrap.								
451378	Italian	HW Gon	No brakes		Yes	20	OK Sve.	Loaded tile
259618	French	Box	No brakes		Yes		Light Rprs	Loaded scrap
20585	German	HW Gon	No brakes		Yes	15	Light Rprs	Needs 6 sides & metal
480426	Italian	HW Gon	Yes			18	OK Sve	Ided factory
One Gon burnt - scrap.								
8918	German	Lg Flat	Yes			40	OK Sve	Ided 2 field
8759	German	Gon		Yes (1 set trucks)	Yes	35	OK Sve	Loaded 2 fiel
477000	Italian	HW Gon	Yes				OK Sve	Loaded stone
461674	Italian	HW Gon		Yes	No		B.O.Shop	Loaded tanks One end
Scrap - One coach, on fire								
Scrap - Two box, on fire								
34758	German	Box	Yes				Light Rprs	Hole in roof
32837	German	HW Gon	Yes			24	OK Sve	Ided pipe & s
494308	Italian	HS Gon	No brakes		Yes		OK Sve	Ided small ht
117752	French	HW Gon	Yes			30	Light Rprs	Loaded I bean
131055	Italian	Box	Yes			19	Light Rprs	Loaded Ll ock
304701	French	HS Gon	Yes				OK Sve	Loaded vari ou
One Refr scrap - Fire								
3494	German	HW Gon	Yes				Hvy Rprs	Ided tank st
15929	German	Box	Yes				B.O.Shop	Patch sides
28138	German	Box	Yes				Hvy Rprs	Decking
100450	Italian	Box	Yes			18	B.O.Shop	Sides & ends

On another track - Page 7.

Sept. 43

0371

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 6)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
	Yes			15	B.O. Shop	Roof & doors.Car wd decks
	Yes				OK Sve.	
on	No brakes		No		OK Sve.	Loaded scrap metal
	Yes			20	OK Sve.	
rap.						
on	No brakes		Yes	20	OK Sve.	Loaded tile
	No brakes		Yes		Light Rprs	Loaded scrap metal.New car sides in part
on	No brakes		Yes	15	Light Rprs	Needs 6 side boards.Lded bolts,lag screws & metal scrap
on	Yes			18	OK Sve	Lded factory Vent.system.
flat	Yes			40	OK Sve	Lded 2 field guns & 2 Ammo carts
		Yes (1 set	Yes trucks)	35	OK Sve	Loaded 2 fiel guns.
on	Yes				OK Sve	Loaded stone
ion		Yes	No		B.O.Shop	Loaded tanks liquid & large wheels. One end end side.
fire						
re						
	Yes				Light Rprs	Hole in roof
on	Yes			24	OK Sve	Lded pipe & angle iron,various sizes.
on	No brakes		Yes		OK Sve	Lded small tile
on	Yes			30	Light Rprs	Loaded I beams & steel
	Yes			19	Light Rprs	Loaded black cork
on	Yes				OK Sve	Loaded various sizes
on	Yes				Hvy Rprs	Lded tank steel & pipe
	Yes				B.O.Shop	Patch sides
	Yes				Hvy Rprs	Decking
	Yes			18	B.O.Shop	Sides & ends fire

0312

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
272822	French	HS Gon	Yes			20	B.O.Shop	Lded 2" Cable-3 rolls missing, brk hngr hn
33390	German	HW Gon	Yes				OK Sve	Loaded crane parts
209785	French	Box	Yes				Light Rprs	to roof. Lded fire b
90090	German	Box	Yes				OK Sve	Lded Mtl-12"x9⅝"xo"x
19151	German	Box	Yes				OK Sve	Loaded fire brick
150890	French	Box	Yes				Light Rprs	Loaded fire brick 12 side board 12⅝" lg.
26578	German	Box	No brakes		Yes		Light Rprs	Lded 4"x5"x9" & arch 4 boards
96057	German	Box	No brakes		Yes		Light Rprs	Lded fire brick - Do
452324	Italian	HW Gon	No brakes		Yes		OK Sve	Lded pipe & bolts
38501	German	Box(fire)	No brakes		Yes		Hvy Rprs	Make flat, Lded fire
53941	German	HW Gon	No brakes		Yes		Hvy Rprs	Lded diamond plate
Scrap two Refrs. Fire - loaded fire brick								
307379	Italian	Rfr	Yes			15	Light Rprs	Lded fire brick - Do
306374	Italian	Refr	Yes			15	Light Rprs	Lded fire brick
307514	Italian	Refr	Yes			15	Light Rprs	Lded fire brick
23077	German	HW Gon	Yes			20	OK Sve	Lded Pipe 20" 1⅝"-2
158750	German	Box	No brakes		Yes		OK Sve	Loaded fire brick
245540	French		Yes				Light Rprs	Loaded fire brick &
Scrap - one box. fire. loaded cement hard								
Cars located 1/2 mile from station 2 cars, box & gon scrap.								
409164	Italian	HW Gon	No brakes		Yes	10	OK Sve	Loaded scrap metal
7703	German	HW Gon	Yes				OK Sve	Loaded fin type radi
54995	German	HW Gon	No brakes		Yes		OK Sve	Loaded one ventilato
Scrap - one Gon - Fire.								
490900	Italian	Gon	No brakes		Yes	19	OK Sve	Loaded cable, Elect

0373

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 7)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
on	Yes			20	B.O.Shop	Lded 2" Cable -3 rolls,1 end bent Brake shoe missing, brk hngr hng
					OK Sve	Loaded crane parts
on	Yes				Light Rprs	to roof. Lded fire brick 6"x9"x13½
	Yes				OK Sve	Lded mtl-12"x9½"x6"x7-3/4"
	Yes				OK Sve	Loaded fire brick
	Yes				Light Rprs	Loaded fire brick 12" wd x 5" th 1 door &
	Yes					side board 12½" lg.
		No brakes	Yes		Light Rprs	Lded 4"x5"x9" & arch brick. Door & siding 4 boards
		No brakes	Yes		Light Rprs	Lded fire brick - Door
on		No brakes	Yes		OK Sve	Lded pipe & bolts
(fire)		No brakes	Yes		Hvy Rprs	Make flat, Lded fire brick
on		No brakes	Yes		Hvy Rprs	Lded diamond plate 1/4" - Fire
- loaded fire brick						
	Yes			15	Light Rprs	Lded fire brick - Duck boards
r	Yes			15	Light Rprs	Lded fire brick
r	Yes			15	Light Rprs	Lded fire brick
on	Yes			20	OK Sve	Lded Pipe 20" 1½"-5 & 1 beams
	No brakes		Yes		OK Sve	Loaded fire brick
	Yes				Light Rprs	Loaded fire brick & cork. Patch roof & siding
. loaded cement hard						
from station 2 cars, box & gon scrap.						
on	No brakes		Yes	16	OK Sve	Loaded scrap metal
on	Yes				OK Sve	Loaded fin type radiator
on	No brakes		Yes		OK Sve	Loaded one ventilator
re.						
n	No brakes		Yes	19	OK Sve	Loaded cable, Elect. 2"

1451

0374

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 8)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
37927	German	HW Gon				15	Light Rprs	Lded 2" Elec Cable-
							Light Rprs	Lded mach. - patch
11649	German	HW Gon	Yes					Loaded 2" Elect Cal
489987	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded 2 big tanks
466220	Italian	HW Gon		Yes	Yes		OK Sve	
69182	German	HW Gon	Yes			20	B.O.Shop	Lded 2 sq tanks, 8'
								Fire
Scrap Gon loaded radiators & Cable - Fire								
Cars located switch adjoining station (Over								
35877	German	HW Gon	Yes				B.O.Shop	Lded pipe-various
Scrap - 2 Box								
20017	German	HW Gon	Yes			20	OK Sve	Loaded tank & pipe
20481	German	HW Gon	Yes				B.O.Shop	Lded wtr tank part
82668	German	HW Gon	Yes			20	OK Sve	Lded I Beams-1"x3-
411726	Italian	HW Gon	No brakes		No	18	OK Sve	Lded angle, channe
Scrap - 3 Box, Fire								
4290	German	Box	Yes				Light Rprs	Patch roof, end,
Scrap - 1 Box, two tank frame, no tank on frame.								
920138	Italian	wtr Tank	No brakes		Yes		B.O.Shop	Rifle holes in ta
9670120	Italian	2 wtr Tank		Yes	Yes		Shop	One frame, heavy
9545005	Italian	Loco Tank	No brakes					
Scrap - 1 Tank car - German flat								
2061	German	Flat	Yes				OK Sve	Lded scrap metal,
							OK Sve	Lded 3/8"x3'x8' s
465089	Italian	W Gon		Yes	No		OK Sve	Lded work tracks
419131	Italian	HW Gon	No brakes		No	18	Light Rprs	Lded masonite loc
8810	German	Box	No brakes		Yes		Light Rprs	Lded scrap iron
477395	Italian	HW Gon	No brakes		No	18	Light Rprs	Lded fire brick
175601	French	Box	Yes				Light Rprs	Lded fire brick
309342	French	Box	Yes				OK Sve	Trucks, steel fo
824	German	Flat	Yes			30	Shop	Trucks, Lded ang
137910	French	LW Gon	Yes			19	OK Sve	
118342	Italian	Box	Yes				Shop	Patch decking. C
17152	German	HW Gon	Yes					

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 8)

pe	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
Gon				15	Light Rprs	Lded 2" Elec Cable-Patch side
					Light Rprs	Lded mach. - patch siding
Gon	Yes					
Gon	No brakes		Yes	18	OK Sve	Loaded 2" Elect Cable
Gon		Yes	Yes		OK Sve	Loaded 2 big tanks square
Gon	Yes			20	B.O.Shop	Lded 2 sq tanks, 8" valves, end & decking - Fire
iators & Cable - Fire						
edjoining station (Over						
Gon	Yes				B.O.Shop	Lded pipe-various sizes-Siding one side
				20	OK Sve	Loaded tank & pipe
Gon	Yes				B.O.Shop	Lded wtr tank parts-Decking end side-Fire
Gon	Yes			20	OK Sve	Lded I Beams-1"x3-1/4"x15'
Gon	Yes			18	OK Sve	Lded angle, channel strap steel 3/8"x1/2"x2"
Gon	No brakes		No			
					Light Rprs	Patch roof, end, sides
ox	Yes					
ank frame, no tank on frame.						
tr Tank No brakes			Yes		B.O.Shop	Rifle holes in tank
tr Tank		Yes	Yes		Shop	One frame, heavy holes
oco Tank No brakes						
- German flat						
lat	Yes				OK Sve	Lded scrap metal, trucks
Gon		Yes	No		OK Sve	Lded 3/8"x3'x8' sheet iron
W Gon	No brakes		No	18	OK Sve	Lded work tracks
ox	No brakes		Yes		Light Rprs	Lded masonite locker doors
W Gon	No brakes		No	18	Light Rprs	Lded scrap iron
ox	Yes				Light Rprs	Lded fire brick - Buffer
ox	Yes				Light Rprs	Lded fire brick 2"x4"x8", roof side
					OK Sve	Trucks, steel for tanks
lat	Yes			30	Shop	Trucks, Lded angle iron jack on end off.-end
W Gon	Yes			19	OK Sve	
ox	Yes				Shop	Patch decking. Car is off track jack on track
W Gon	Yes					

0576

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE (Page 9)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
							Light Rprs	Lded brown paper, do
1001804	Italian	Box	Yes				OK Sve	
192339	Italian	ST Box	Yes					
Scrap - 3 Box - Fire								
115301	Italian	ST Box	Yes			19	OK Sve	Lded paper
1130706	Italian	ST Box	Yes			19	OK Sve	Lded paper
44559	German	HW Gon	Yes				OK Sve	Lded pipe & Misc-Mac
097002	Italian	Well car		Yes	Yes	40	OK Sve	3 Whl trucks, Lded I
98511	German	HW Gon	No brakes		Yes		OK Sve	Lded steel tank
23381	German	Box	No brakes	Yes			Light Rprs	Lded bags chemicals
0179	German	HW Gon	Yes			26	OK Sve	Oxygen tanks, acetyl
41081	German	HW Gon	Yes			20	OK Sve	Lded large tank
32380	German	HS Gon	No brakes		Yes		OK Sve	Loaded pipe
30448	German	HW Gon	Yes			25	OK Sve	Loaded pipe
8772	German	HW Gon	Yes				B.O.Shop	Lded tank, fire, dec
021077	Italian	LW Gon		Yes	Yes		OK Sve	Lded tank
920222	Italian	Wtr tank		Yes	Yes		B.O.Shop	Bullet holes
7502052	Italian	Wtr Tank		Yes	No	13	B.O.Shop	Bullet holes
900210	Italian	Wtr Tank		Yes	Yes	13	B.O.Shop	Bullet holes
245437	French	Box	Yes			20	B.O.Shop	Patch roof, Lded fi
354022	French	Box	Yes				B.O.Shop	Roof, side-Lded fir
303573	French	Box	No brakes		Yes		Light Rprs	Lded fire brick, bu
7105023	Italian	Box		Yes	Yes	15	OK Sve	Lded fire brick
260723	Italian	ST Box	Yes			19	OK Sve	Lded fire brick
47751	German	Box	No brakes		Yes		Light Rprs	Lded fire brick-pat
309524	French	Box	Yes				B.O.Shop	Lded fire brick-1/2
409000	Italian	HW Gon		Yes	No		B.O.Shop	Bad pedestal-Lded t
415988	Italian	HW Gon	No brakes		No	18	OK Sve	Lded large pipe
40214	German	Flat	Yes				OK Sve	Lded tank steel
1021073	Italian	Box	No brakes		Yes	18	Light Rprs	Roof
110342	Italian	ST Box	Yes			19	Light Rprs	Roof

Cars are being unloaded for chemical company. Above cars.
Dynamite Joint Stock Co, Cartiera di Tarquinia) Nobel.

0377

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE (Page 9)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
	Yes				Light Rprs	Lded brown paper, door patch, end
ox	Yes				OK Sve	
				19	OK Sve	Lded paper
ox	Yes			19	OK Sve	Lded paper
ox	Yes				OK Sve	Lded pipe & Misc-Mach.
on	Yes					
car		Yes	Yes	40	OK Sve	3 Whl trucks, Lded large transformer
on	No brakes		Yes		OK Sve	Lded steel tank
	No brakes	Yes			Light Rprs	Lded bags chemicals - Roof
				26	OK Sve	Oxygen tanks, acetylene tanks
on	Yes			20	OK Sve	Lded large tank
on	Yes				OK Sve	Loaded pipe
on	No brakes		Yes		OK Sve	Loaded pipe
on	Yes			25	B.O.Shop	Lded tank, fire, decking part, side & end
on	Yes				OK Sve	Lded tank
on		Yes	Yes		B.O.Shop	Bullet holes
tank		Yes	Yes		B.O.Shop	Bullet holes
Tank		Yes	No	13	B.O.Shop	Bullet holes
Tank		Yes	Yes	13	B.O.Shop	Patch roof, Lded fire brick
	Yes			20	B.O.Shop	Roof, side-Laed fire brick
	Yes				Light Rprs	Lded fire brick, bullet holes
	No brakes	Yes	Yes	15	OK Sve	Lded fire brick
				19	OK Sve	Lded fire brick
Box	Yes				Light Rprs	Lded fire brick-patch bds side
	No brakes		Yes		B.O.Shop	Lded fire brick-1/2 car new wood needed
	Yes				B.O.Shop	Bad pedestal-Lded track,small
on		Yes	No	18	OK Sve	Lded large pipe
on	No brakes		No		OK Sve	Lded tank steel
at	Yes			16	Light Rprs	Roof
	No brakes		Yes	19	Light Rprs	Roof
Box	Yes					

ded for chemical company. Above cars.
Co, Cartiera di Tarquinia) Nobel.

0374

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
S.A. Cartiere di Tarquinia -Paper-								
Station Yards - Montalto di Castro. - 110 Km from Rome								
1011280	Italian	Box	Yes			18	B.O.Shop	End & decking, patch
121320	German	Box	Yes			20	B.O.Shop	Decking part roof, do
38541	German	Box	Yes				Hvy Rprs	Body & decking
Scrap - 2 Box, Fire - Air hose on most cars.								
5006	German	HW Gon	Yes			20	B.O.Shop	Decking & 1/2 car sid
71399	German	HW Gon	Yes			20	B.O.Shop	Needs 4 decking 1/2-1
13309	German	HW Gon	Yes			20	B.O.Shop	Needs 3/4 decking, 1
22005	German	LW Gon	Yes				B.O.Shop	Needs 1 end, 1/4 new
35090	German	HW Gon	Yes			20	B.O.Shop	Needs 3/4 decking
50321	German	HW Gon	Yes			20	B.O.Shop	Needs 3/4 decking & 1
98095	French	HS Gon		Yes	Yes		B.O.Shop	Needs 3' decking, rep
27009	German	Box	Yes				B.O.Shop	Complete wood - Fire
29476	German	HS Gon	No brakes		Yes		B.O.Shop	Needs decking & door
71700044	Italian	Box	No brakes		Yes		B.O.Shop	Bad Journal, no brass
53256	German	HW Gon	Yes				B.O.Shop	Repair sides & 4' dec
043323	Italian	HW Gon	No brakes		No	18	B.O.Shop	End side, fire. Patch
Scrap- 1 Box, German								
480253	French	Box	Yes				B.O.Shop	Patch roof, decking &
4980	German	HW Gon	Yes			20	B.O.Shop	One side, fire
61121	German	HW Gon	Yes				B.O.Shop	Fire, needs wood side
4100	German	HW Gon	No brakes		Yes		B.O.Shop	5' decking 1 end 1 si
457023	Italian	HW Gon		Yes	Yes		B.O.Shop	Needs 1/2 decking 1/3
34404	German	Box	Yes			15	B.O.Shop	Patch roof side & end
213120	French	Box	Yes				B.O.Shop	Needs 1/2 car sides,
48220	German	Box	Yes				B.O.Shop	Patch siding, roof, en
(°) 466276	Italian	HW Gon	No brakes		No		B.O.Shop	Needs siding, part de
68734	French	Box	No brakes		Yes	15	Light Rprs	Shackle broke. Spring
27542	German	HW Gon	No brakes		Yes		B.O.Shop	One side & 1/2 decki
5207	German	LW Gon	Yes			15	OK Sve	Loaded rail)
1397	German	LW Gon	Yes			15	OK Sve	Loaded rail)

(°) Scrap - One box car, fire

1961

0379

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page10)

ype	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
arquinia -Paper-						
ntalto di Castro. - 110 Km from Rome						
ox	Yes			16	B.O.Shop	End & decking, patch
ox	Yes			20	B.O.Shop	Decking part roof, doors, patch siding
ox	Yes				Hvy Rprs	Body & decking
e - Air hose on most cars.						
W Gon	Yes			20	B.O.Shop	Decking & 1/2 car sides
W Gon	Yes			20	B.O.Shop	Needs 4 decking 1/2-1 end siding
W Gon	Yes			20	B.O.Shop	Needs 3/4 decking, 1 side decking
W Gon	Yes				B.O.Shop	Needs 1 end, 1/4 new decking
W Gon	Yes			20	B.O.Shop	Needs 3/4 decking
W Gon	Yes			20	B.O.Shop	Needs 3/4 decking & 1/2 sides
S Gon		Yes	Yes		B.O.Shop	Needs 3' decking, repair doors
ox	Yes				B.O.Shop	Complete wood - Fire
S Gon	No brakes		Yes		B.O.Shop	Needs decking & door repair
ox	No brakes		Yes		B.O.Shop	Bad Journal, no brass, door rpr
W Gon	Yes				B.O.Shop	Repair sides & 4' decking
W Gon	No brakes		No	16	B.O.Shop	End side, fire. Patch decking
an						
ox	Yes				B.O.Shop	Patch roof, decking & side
W Gon	Yes			20	B.O.Shop	One side, fire
W Gon	Yes				B.O.Shop	Fire, needs wood sides, decking & end
W Gon	No brakes		Yes		B.O.Shop	5' decking 1 end 1 side
W Gon		Yes	Yes		B.O.Shop	Needs 1/2 decking 1/3 sides
ox	Yes			15	B.O.Shop	Patch roof side & ends
ox	Yes				B.O.Shop	Needs 1/2 car sides, roof deck.
ox	Yes				B.O.Shop	Patch siding, roof, ends. Decking doors
W Gon	No brakes		No		B.O.Shop	Needs siding, part deck & doors
ox	No brakes		Yes	15	Light Rprs	Shackle broke. Spring
W Gon	No brakes		Yes		B.O.Shop	One side & 1/2 decking
W Gon	Yes			15	OK Sve	Loaded rail
W Gon	Yes			15	OK Sve	Loaded rail
r, fire						

191

0380

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 11)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
21342	German	LW Gon	No brakes		Yes		OK Sve	Loaded rail)
73933	German	LS Gon	Yes				OK Sve	Loaded rail
22030	German	LW Gon	Yes				OK Sve	Loaded rail)
3830	German	LW Gon	No brakes		Yes		OK Sve	" ")
0805	German	LW Gon	No brakes		Yes		OK Sve	" ")- 4 ca
04795	German	LW Gon	Yes				OK Sve	" ")
5074	German	LW gon	Yes				OK Sve	Loaded rail)
43052	German	LW Gon	Yes				OK Sve	" "
27759	German	LW Gon	Yes				OK Sve	" ") Needs
11569	German	LW Gon	No brakes		Yes		B.O.Shop	" ") Needs
07553	German	LS Gon	Yes				OK Serv	Loaded rail)
51599	German	Flat	Yes				OK Sve	" "
046197	Italian	LW Gon	No brakes		Yes		OK Sve	" ")
35200	German	LW Gon	Yes				OK Sve	" ")
07539	German	LS Gon	Yes				OK Sve	Loaded rail) (St
5290	German	Flat	Yes				OK Sve	" "
151710	French	Flat	No brakes		Yes		OK Sve	" ") 4
13709	German	LW Gon	No brakes		Yes		OK Sve	" ")
55733	German	HW Gon	Yes				B.O.Shop	Siding & end repai
3470	German	HW Gon	No brakes		Yes		B.O.Shop	1 siding & part de
34009	German	Box	Yes				B.O.Shop	Needs decking
Scrap - 2 Box. Above car (34009) on track no outled.								
4780	German	HW Gon	No brakes		Yes		B.O.Shop	Decking & siding
3431	German	HW Gon	Yes				B.O.Shop	Lded pipe, needs
405150	Italian	HW Gon	No brakes		Yes		B.O.Shop	Needs siding & dec

CHIARONE STATION - 130 Km from Rome.

Scrap - 1 Gon

044986	Italian	HW Gon	No brakes		Yes		B.O.Shop	Broken shackle
00091	German	HW Gon	Yes			20		No track out, end
Scrap - 2 water tank full of holes, 4 lengths track out								
9550800	Italian	Wtr tank		Yes	No	19	Hvy Rprs	Holes, Track OK o

CAPALBO 137 Km from Rome Scrap 1 Gon 468019 - HW Gon.

156

0381

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 11)

Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
LW Gon	No brakes		Yes		OK Sve	Loaded rail)
LS Gon	Yes				OK Sve	Loaded rail)
LW Gon	Yes				OK Sve	Loaded rail)
LW Gon	No brakes		Yes		OK Sve	" ")
LW Gon	No brakes		Yes		OK Sve	" ")- 4 cars
LW Gon	Yes				OK Sve	" ")
LW Gon	Yes				OK Sve	Loaded rail)
LW Gon	Yes				OK Sve	" ")
LW Gon	Yes				OK Sve	" ") Needs 1/5 deck. fire
LW Gon	No brakes		Yes		B.O.Shop	" ") Needs all deck, fire
LS Gon	Yes				OK Serv	Loaded rail)
Flat	Yes				OK Sve	" ")
LW Gon	No brakes		Yes		OK Sve	" ")
LW Gon	Yes				OK Sve	" ")
LS Gon	Yes				OK Sve	Loaded rail) (Steel)
Flat	Yes				OK Sve	" ")
Flat	No brakes		Yes		OK Sve	" ") 4
LW Gon	No brakes		Yes		OK Sve	" ")
HW Gon	Yes				B.O.Shop	Siding & end repair
HW Gon	No brakes		Yes		B.O.Shop	1 siding & part deck
Box	Yes				B.O.Shop	Needs decking
bove car (34009) on track no outled.						
HW Gon	No brakes		Yes		B.O.Shop	Decking & siding
HW Gon	Yes				B.O.Shop	Lded pipe, needs 1/2 decking
HW Gon	No brakes		Yes		B.O.Shop	Needs siding & decking
- 130 Km from Rome.						
HW Gon	No brakes		Yes		B.O.Shop	Broken shackle
HW Gon	Yes			20		No track out, end caved in.
ank full of holes, 4 lengths track out						
Wtr tank		Yes	No	19	Hvy Rprs	Holes, Track OK out
om Rome Scrap 1 Gon 488019 - HW Gon.						

1500

0382

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
ORBETELLO STATION & YARDS, 150 Km from Rome								
Cars blown at this station								
146551	French	Trucks Flat		Yes	Yes	30	B.O.Shop	1 Truck 1 wheel dam
13911	German	Flat	Yes			40	B.O.Shop	One truck blown
Two above cars requires switch and a few section rail to move after repairs to one truck per								
12043	German	Flat	Yes				B.O.Shop	2 trucks blown, sma
2090	French	Caboose	One pedestal blown, old car - Scrap					
42421	French	Flat	Yes	Off track, hit by bomb, trucks - Scrap				
208731	French	Box	Yes	Can not get to car account of above scrap - Scrap				
764	German	Well		Yes	Yes	50	Scrap	Center whle of 3 wh
982108	Italian	Tank					Scrap	Small olive oil tan
								blown
48066	German	Box	Yes				Scrap	Fed blown, car wood
62635	German	Box	Yes				Scrap	Fed blown, " "
31325	German	Box	No brakes		Yes		Scrap	" " , decking
173654	French	Box	Yes				Scrap	" " , wood dam
82110	German	Box	Yes				Scrap	2 Fed blown, deckin
409191	Italian	HS Gon	Yes					Fed blown, loaded c
477038	Italian	HW Gon		Yes	Yes		Scrap	Fed blown, loaded c
470408	Italian	HW Gon	Yes			18		" " "
1050	German	HW Gon	No brakes		Yes			" " "
6108	German	HW Gon	Yes					" " "
480045	Italian	HW Gon	Yes				OK Sve	Loaded coal
30079	German	HW Gon	Yes			20		Fed blown, loaded
67124	German	HW Gon	Yes					" " "
39909	German	HW Gon	Yes			20		" " "
4412102	Italian	HW Gon	Yes					" " "
480470	Italian	HW Gon				18		" " "
487419	Italian	HW Gon						" " "
4410314	Italian	HS Gon	Yes			22		" " "
487226	Italian	HW Gon	Yes			18		" " "
72388	German	HW Gon	Yes			20		" " "

C.R. 50

0384

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 12)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
S, 150 Km from Rome					
on					
lat		Yes	Yes	30	B.O.Shop	1 Truck 1 wheel damaged
	Yes			40	B.O.Shop	One truck blown
switch and a few section rail to move after repairs to one truck per car.					
	Yes				B.O.Shop	2 trucks blown, small damage track open
e	One pedestal blown, old car - Scrap					
	Yes	Off track, hit by bomb, trucks - Scrap				
	Yes	Can not get to car account of above scrap - Scrap				
		Yes	Yes	50	Scrap	Center whle of 3 wheeled trucks blown,Open track
					Scrap	Small olive oil tank car,no tanks on car, 1 ped blown
	Yes				Scrap	Ped blown, car wood damaged
	Yes				Scrap	Ped blown, " " "
	No brakes		Yes		Scrap	" " , decking roof sides dam.
	Yes				Scrap	" " , wood damaged badly
	Yes				Scrap	2 Ped blown, decking & sides dam.
	Yes					Ped blown, loaded coal
		Yes	Yes		Scrap	Ped blown, loaded coal
n	Yes			18		" " " "
n	No brakes		Yes			" " " "
n	Yes					" " " "
n	Yes				OK Sve	Loaded coal
n	Yes			20		Ped blown, loaded coal
n	Yes					" " " "
n	Yes			20		" " " "
n	Yes					" " " "
n				18		" " " "
n						" " " "
n	Yes			22		" " " "
n	Yes			18		" " " "
n	Yes			20		" " " "

1 CR 25

Declassified E.O. 12356 Section 3.3/NND No. 785021

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
13716	German	HW Gon	Yes			20		Ped blown, loaded
71579	German	HW Gon	Yes			20		" " "
19030	German	HW Gon	No brakes		Yes	20		" " "
400049	Italian	HS Gon		Yes	Yes	22		" " "
43770	German	HW Gon	No brakes		Yes	20		" " "
78967	German	HW Gon	Yes			20		" " "
7470392	Italian	HW Gon	No brakes		Yes	15		" " "
One large flat, trucks blown, no number, loaded large tank								
77700	German	Box	Yes				Hvy Rprs	Loaded stone, bo
8583	German	Box	Yes					Ped blown
11384	German	Box						Blown up
28200	German	Box						" " , lded f
60593	German	Box						" "
20423	German	Box						Ped blown, loade
78846	German	HW Gon	Yes					" "
1003078	Italian	Box	Yes			18		" " , lded
88509	German	Hw Gon	Yes					" "
27239	German	Box	Yes					" " , lded
9936	German	HW Gon	Yes					" "
15719	German	Gon						" " , lded
492708	Italian	HS Gon	No brakes					
192922	Italian	Box	Yes					Ped blown, lded
488033	Italian	Hw Gon	No brakes		Yes			" "
22501	German	Hw Gon	Yes					
473408	Italian	HW Gon		Yes	Yes			" " lded
409232	Italian			Yes				Ped blown
12595	German	Flat		Yes				Trucks blown, 2
459943	Italian	HW Gon						Ped blown
490079	Italian	HW Gon						" "
13987	German	Box	Yes				Light Rprs	Loaded fire bric
304170	French	Box	No brakes		Yes		B.O.Shop	Roof & door

0385

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 13)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
				20		Ped blown, loaded coal
on	Yes			20		" " " "
on	Yes			20		" " " "
on	No brakes		Yes	20		" " " "
on		Yes	Yes	22		" " " "
on			Yes	20		" " " "
on	No brakes			20		" " " "
on	Yes					
on	No brakes		Yes	15		
	blown, no number, loaded large tank					
	Yes				Hvy Rprs	Loaded stone, bomb damage
	Yes					Ped blown
						Blown up
						" " , lded fire brick, arck
						" "
						Ped blown, loaded large fire brick
on	Yes					" "
	Yes					" " , lded fire brick
on	Yes					" "
	Yes					" " , lded fire brick
on	Yes					" "
						" " , lded large tank
on	No brakes					Ped blown, lded fire brick
	Yes					" "
on	No brakes		Yes			
on	Yes					" " lded pipe
on		Yes	Yes			Ped blown
		Yes				Trucks blown, 2 large tanks
		Yes				Ped blown
at						" "
on						
on					Light Rprs	Loaded fire brick, roof
x	Yes				B.O.Shop	Roof & door
x	No brakes		Yes			

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 14)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
43563	German	Box			Yes			Fed blown, lded fi
116925	Italian	Box SI	Yes				B.O.Shop	Door,roof
17240	German	Box	Yes					Fed blown, lded fi
160477	Italian	Box	Yes				Light Rprs	
9295	German	Gon	Yes					Fed blown, loaded
1006086	Italian	Box						" "
301472	Italian	Refr	Yes					" " , lded fi
95540	German	Box	Yes					" "
1009162	Italian	Box	No brakes		Yes			" "
7551	German	Box	Yes					" "
1010925	Italian	Box	No brakes		Yes			" "
90531	German	Box	No brakes		Yes			" "
25557	German	Hw Gon						" "
47057	German	Box	Yes					" "
74865	German	LS Gon	Yes					" " loaded
20003	German	Box						" "
31902	German	Lw Gon	Yes					" " loaded
94758	German	Box						" "
717353	German	Hw Gon						" "
74083	German	Hw Gon						" "
11109	German	Flat						1 Truck blown
022915	Italian	Lw Gon						Fed blown, loaded
050507	Italian	Lw Gon						" " "
000560	Italian	Lw Gon						" " "
447747	Italian	Hw Gon						" " "
01208	German	Hw Gon						" " "
409630	Italian	Hw Gon						" " "
52466	German	Box						" " fire des
Box car no number, loaded motors and grinders, car damaged - Pedestal blown								
150433	Italian	Box						" " Mach & T
79457	German	Box						" " loaded m
81094	German	Box						" " " w
39362	German	Box						" " " s

Car 2

0387

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 14)

Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
Box			Yes			Ped blown, lded fire brick
Box St	Yes				B.O.Shop	Door,roof
Box	Yes					Ped blown, lded fire brick
Box	Yes				Light Rprs	
Gon	Yes					Ped blown, loaded pipe
Box						" "
Refr	Yes					" " , lded fire brick
Box	Yes					" "
Box	No brakes		Yes			" "
Box	Yes					" "
Box	No brakes		Yes			" "
Box	No brakes		Yes			" "
W Gon						" "
Box	Yes					" "
S Gon	Yes					" " loaded tanks
Box						" "
W Gon	Yes					" " loaded tanks
Box						" "
W Gon						" "
W Gon						" "
Flat						1 Truck blown
W Gon						Ped blown, loaded mach.
W Gon						" " " "
W Gon						" " " "
W Gon						" " " Elec. Cable
W Gon						" " " tank
W Gon						" " " mach
Box						" " fire destroyed car
loaded motors and grinders, car damaged - Pedestal blown						
Box						" " mach & rolls paper
Box						" " loaded mach
Box						" " " wood 1" sq 1/2"
Box						" " " scales

21 CR

0388

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 15)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
22765	German	Box						Fed Blown, switch motors & wood 1/2
120167	Italian	Refr						Fed blown, damage
192731	Italian	Box						" " , deckin
178721	French	Box						" " , 1 scal
31445	German	Box						" " , lded r
00857	French	Box						" " , brass brass
35707	German	Box						Fed blown, elec m
201833	Italian	Box						Fed blown, 2 larg
20892	German	Box						Fed blown, elec m
48423	German	Box						" " , machin
10311	German	Box						" " , damage
00819	German	Box						" " , lded r
27073	German	HW Gon						Fed blown, lded c
7877	German	HW Gon						" " , lded c
413290	Italian	HW Gon						" " , lded c
404370	Italian	HW Gon					OK Sve	Loaded dirt
410091	Italian	Hw Gon						Fed blown, lded d
206234	French	Box						" " , lded m
99370	German	Box					Light Rprs	1 scale & mach, s
104518	Italian	Box					Light Rprs	lded wood squares
203019	Italian	Box					Light Rprs	Lded elec equipme
48520	German	LW Gon						Car bombed, mach
85075	German	Box						" " Alum
10402	German	Box	Yes				OK Sve	Lded mach
151394	German	Box		Yes	Yes		OK Sve	Lded 1' sq 1/2 wo
1009804	Italian	Box	Yes	car			OK Sve	
440137	German	LW Gon	Yes	53			OK Sve	Lded 1" pipe
17027	German	Box	No brakes		Yes		OK Sve	Lded mach
80710	German	LS Gon	Yes				OK Sve	Lded mach
31749	German	HS Gon	No brakes		Yes		OK Sve	Lded barbed wire

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 15)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
					Fed blown, switch box damaged, loaded elec motors & wood 1/2"
					Fed blown, damaged roof & sides
					" " , decking, bad ends
					" " , 1 scale, alum pipe 4"
					" " , lded rols 3' paper
					" " , brass tubing 1/2" to 2" 4 sheets brass 3'x5' 1/4 to 1/2"
					Fed blown, elec motors, pipe 1" to 2" 75 pieces
					Fed blown, 2 large elec motors sheet
					Fed blown, elec motors
					" " , machinery
					" " , damaged, time clocks
					" " , lded rolls paper
on					Fed blown, lded coal
on					" " , lded coal
on					" " , lded dirt
on				OK Sve	Loaded dirt
on					Fed blown, lded dirt
					" " , lded motors & mach
				Light Rprs	1 scale & mach, siding patch
				Light Rprs	lded wood squares
				Light Rprs	Lded elec equipment
on					Car bombed, mach
					" " Alum wire 1/8" to 1/4" rolls
	Yes			OK Sve	Lded mach
		Yes	Yes	OK Sve	Lded 1' sq 1/2 wood
	Yes			OK Sve	
on	Yes			OK Sve	Lded 1" pipe
	No brakes		Yes	OK Sve	Lded mach
on	Yes			OK Sve	Lded mach
on	No brakes		Yes	OK Sve	Lded barbed wire & fence posts

0890

Declassified E.O. 12356 Section 3.3/NND No. 785021

	Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
	1009533	Italian	Box	No brakes		Yes		OK Sve	Lded few mines
	1926	German	Box	Yes				OK Sve	3 mines in car
	153001	Belgium	Box	Yes				OK Sve	
(°)	Above 11 cars on siding about 2 blocks northeast of station.								
	290353		Box	Yes			10	OK Sve	Sulphur Plant
	1014861	Italian	Box	Yes			15	OK Sve	
	111937	Italian	Box	No brakes		Yes		OK Sve	
	Track blown each end of above cars. Cars in yard of station								
	90882	German	Box	No brakes		Yes		Light Rprs	1/2 decking missi
	023532	Italian	LW Gon	No brakes		Yes		OK Sve	Dead end track
	Above cars at station								
	ALBINIA STATION, 15o from Rome.								
	37748	German	LW Gon	No brakes		Yes		OK Sve	Open track
	00512	Italian	Coach	Fire destroyed, 2 pr trucks (OK trucks only)					
	77193033	Italian	Box	Yes			15	OK Sve	Car 25' from rail to rails. (161 K
	TALAMONE STATION, 164 Km from Rome.								
	418608	Italian	HW Gon		Yes		18	OK Sve	Loaded ties
	7007	German	HW Gon	No brakes		Yes		OK Sve	Loaded ties
	480409	Italian	HW Gon	Yes			18	OK Sve	Loaded ties
	477039	Italian	HW Gon		Yes	Yes	18	OK Sve	Loaded ties
	30518	German	HW Gon	Yes			24.5	OK Sve	Loaded ties
	479140	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded ties
	477902	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded ties
	440133	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded ties
	77407	German	LS Gon	Yes			15	OK Sve	Loaded rail)
	40573	German	Flat	No brakes		Yes	15	OK Sve	" " } 4
	45599	German	LW Gon	Yes			15	OK Sve	" ")
	21359	German	LW Gon	Yes			15	OK Sve	" "
	42330	German	Passgr					Hvy Rprs	3rd Class Pass C
	201808	German	Coach					Hvy Rprs	2nd Class Int t
(°)	1010036	Italian	Box	Yes				OK Sve	

0391

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 16)

e	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
	No brakes		Yes		OK Sve	Lded few mines
	Yes				OK Sve	3 mines in car
	Yes				OK Sve	
ng about 2 blocks northeast of station.						
	Yes			10	OK Sve	Sulphur Plant
	Yes			18	OK Sve	
	No brakes		Yes		OK Sve	
of above cars. Cars in yard of station						
	No brakes		Yes		Light Rprs	1/2 decking missing
Gon	No brakes		Yes		OK Sve	Dead end track
from Rome.						
Gon	No brakes		Yes		OK Sve	Open track
ch	Fire destroyed, 2 pr trucks (OK trucks only)					
	Yes			15	OK Sve	Car 25' from rails can be wenched and jacked to rails. (161 Km)
Km from Rome.						
Gon		Yes		18	OK Sve	Loaded ties
Gon	No brakes		Yes		OK Sve	Loaded ties
Gon	Yes			18	OK Sve	Loaded ties
Gon		Yes	Yes	18	OK Sve	Loaded ties
Gon	Yes			24.5	OK Sve	Loaded ties
Gon	No brakes		No	18	OK Sve	Loaded ties
Gon	No brakes		No	18	OK Sve	Loaded ties
Gon	No brakes		Yes	18	OK Sve	Loaded ties
Gon	Yes			15	OK Sve	Loaded rail)
at	No brakes		Yes	15	OK Sve	" " } 4
Gon	Yes			15	OK Sve	" ")
Gon	Yes			15	OK Sve	" "
ssgr					Hvy Rprs	3rd Class Pass Coach, glass & seats broken
ach					Hvy Rprs	2nd Class int torn up, no glass
	Yes				OK Sve	

0392

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 17)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
098028	Italian	Flat		Yes		40	OK Sve	Loaded rail (40 Ton
11172	German	LW Gon	No brakes		Yes	20	OK Sve	Loaded rail)
78779	German	LS Gon	Yes			15	OK Sve	" ") 4
8003	German	Flat	Yes			15	OK Sve	" ")
10950	Italian	LS Gon		Yes	Yes	20	OK Sve	
87401	German	LW Gon	No brakes		Yes	15	B.O.Shop	Decking & end
87205	French	LW Gon	No brakes		Yes	10	OK Sve	
Buffers caught on buffers car above car, needs jacking up.								
21878	German	HW Gon	Yes			15	OK Sve	Loaded gravel
8770	German	HW Gon	Yes			20	OK Sve	Loaded gravel
3047	German	HW Gon	Yes			20	OK Sve	Loaded gravel
52062	German	HW Gon	Yes			20	OK Sve	Loaded gravel
10442	German	HW Gon	Yes			20	OK Sve	Loaded gravel
400105	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded gravel
488443	Italian	HW Gon		Yes	No	18	OK Sve	Loaded gravel
407784	Italian	HS Gon	Yes			22	OK Sve	Loaded gravel
401017	Italian	HW Gon		Yes	No	18	OK Sve	Loaded gravel
1243	German	HW Gon	Yes			20	OK Sve	Loaded gravel
413655	Italian	HW Gon		Yes	No	18	OK Sve	Loaded gravel
400034	Italian	HS Gon		Yes	Yes		OK Sve	Loaded gravel
440112	Italian	LW Gon	No brakes		No	15	OK Sve	Loaded gravel
413441	Italian	HW Gon		Yes	No	18	OK Sve	Loaded gravel
40000	German	HW Gon	Yes			15	OK Sve	Loaded gravel
478529	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded gravel
401451	Italian	HW Gon	Yes			18	OK Sve	Loaded gravel
440512	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded gravel
475113	Italian	HW Gon	No brakes			18	OK Sve	Loaded gravel
404304	Italian	HS Gon	Yes			22	OK Sve	Loaded gravel
474245	Italian	HW Gon	Yes			18	OK Sve	Loaded gravel
7403607	Italian	HW Gon		Yes	No	15	OK Sve	Loaded gravel
414534	Italian	HW Gon	No brakes		Yes(Brk)	18	OK Sve	Loaded gravel
401024	Italian	HW Gon	Yes			18	OK Sve	Loaded gravel

0393

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 17)

e	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
		Yes		40	OK Sve	Loaded rail (40 Ton trucks)
t			Yes	20	OK Sve	Loaded rail)
Gon	No brakes			15	OK Sve	" ") 4
Gon	Yes			15	OK Sve	" ")
t	Yes			20	OK Sve	" ")
Gon		Yes	Yes	15	B.O.Shop	Decking & end
Gon	No brakes		Yes	10	OK Sve	
Gon	No brakes					
fers car above car, needs jacking up.						
				15	OK Sve	Loaded gravel
Gon	Yes			20	OK Sve	Loaded gravel
Gon	Yes			20	OK Sve	Loaded gravel
Gon	Yes			20	OK Sve	Loaded gravel
Gon	Yes			20	OK Sve	Loaded gravel
Gon	Yes			20	OK Sve	Loaded gravel
Gon	No brakes		Yes	18	OK Sve	Loaded gravel
Gon		Yes	No	18	OK Sve	Loaded gravel
Gon	Yes			22	OK Sve	Loaded gravel
Gon		Yes	No	18	OK Sve	Loaded gravel
Gon				20	OK Sve	Loaded gravel
Gon	Yes			18	OK Sve	Loaded gravel
Gon		Yes	No		OK Sve	Loaded gravel
Gon		Yes	Yes	15	OK Sve	Loaded gravel
Gon	No brakes		No	18	OK Sve	Loaded gravel
Gon		Yes	No	15	OK Sve	Loaded gravel
Gon	Yes			18	OK Sve	Loaded gravel
Gon	No brakes		No	10	OK Sve	Loaded gravel
Gon	Yes			18	OK Sve	Loaded gravel
Gon	No brakes			22	OK Sve	Loaded gravel
Gon	Yes			18	OK Sve	Loaded gravel
Gon	Yes		Yes	15	OK Sve	Loaded gravel
Gon		Yes	No	18	OK Sve	Loaded gravel
Gon	No brakes		Yes(Brk)	18	OK Sve	Loaded gravel
Gon	Yes					

0394

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 10)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
ALBERESE STATION YARDS, 172 Km from Rome. - Open track switch								
201423	Italian	Box	Yes			17	OK Sve	
473455	Italian	HW Gon		Yes	Yes	18	OK Sve	Loaded freight boxe
640424	Italian	LS Gon		Yes	Yes	20	OK Sve	Loaded freight boxe
35057	German	HW Gon	Yes			20	OK Sve	Loaded ties
12892	German	Flat	Yes			20		
Loaded rail car shead blown pedestal. Car will have to be unloaded and coupler nut taken off								
60667	German	L Gon					Scrap	Ped blown, loaded r
19553	German	Flat					Scrap	" " , "
48403	German	LW Gon	Yes			15	OK Sve	Loaded ties
49072	German	LW Gon	Yes			15	OK Sve	Loaded ties
9147	German	Flat	Yes			40	B.O.Shop	Lded I' beams bent,
17405	German	Flat					Scrap	Ped blown
10080	German	Flat				40	OK Sve	Loaded I beams, tru
91891	German	Flat					Scrap	Blown axel
10851	German	Flat				40	Scrap	Lded I beams, I set
40748	French	Flat	Yes			40	B.O.Shop	No decking, fire
20279	German	LW Gon		Yes	Yes		B.O.Shop	No decking
10455	German	40T Frame				40	B.O.Shop	Frame bent center s damage
22218	German	Flat	Yes			15	B.O.Shop	
10049	German	Flat				40	Scrap	Lded I beams, blown
33101	German	Flat	No brakes		Yes	15	B.O.Shop	Decking
Above cars are on siding-elevated. Loads & cars can be overtuned in ditch.								
Located at Station:								
23093	German	Box	Yes				B.O.Shop	Fire, no wood
80352	German	Box	Yes			15	B.O.Shop	Decking, roof, one
30419	German	HW Gon	Yes				B.O.Shop	Fire, no wood
Large Gon, no number, fire, no wood - Shop								
50475	German	HW Gon	Yes			15	B.O.Shop	Fire
13292	German	HW Gon	Yes				B.O.Shop	Fire, no wood
453430	Italian	HW Gon		Yes	Yes	19	B.O.Shop	One end & decking
7440363	Italian	HW Gon	No brakes		Yes	15	OK Sve	Loaded rail wire

0395

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 16)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
172 Km from Rome. - Open track switch					
Yes			17	OK Sve	
on	Yes	Yes	18	OK Sve	Loaded freight boxes
on	Yes	Yes	20	OK Sve	Loaded freight boxes
on Yes			20	OK Sve	Loaded ties
Yes			20		
blown pedestal. Car will have to be unloaded and coupler nut taken off to uncouple two cars					
on				Scrap	Fed blown, loaded rail
				Scrap	" " , " "
on Yes			15	OK Sve	Loaded ties
on Yes			15	OK Sve	Loaded ties
Yes			40	B.O.Shop	Lded I' beams bent, blown. Side sill
				Scrap	Fed blown
			40	OK Sve	Loaded I beams, trucks
				Scrap	Blown axel
			40	Scrap	Lded I beams, I set trucks OK
Yes			40	B.O.Shop	No decking, fire
on	Yes	Yes		B.O.Shop	No decking
eme			40	B.O.Shop	Frame bent center and I end, I truck small damage
Yes			15	B.O.Shop	
			40	Scrap	Lded I beams, blown sills, 2 trucks OK
No brakes		Yes	15	B.O.Shop	Decking
ng-elevated. Loads & cars can be overtuned in ditch.					
Yes				B.O.Shop	Fire, no wood
Yes			15	B.O.Shop	Decking, roof, one end new wood
on Yes				B.O.Shop	Fire, no wood
fire, no wood - Shop					
on Yes			15	B.O.Shop	Fire
on Yes				B.O.Shop	Fire, no wood
on	Yes	Yes	19	B.O.Shop	One end & decking one end
on No brakes		Yes	15	OK Sve	Loaded rail wire

0396

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 19)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
3306	German	LW Gon	No brakes		Yes	15	OK Sve	
Large box trucks, fire no wood. Air brakes - Shop								
4257	German	Flat	Yes			30	Scrap	Sill blown, one truck
839412	German	LW Gon					Scrap	Sill blown
Abz52130		Passgr					Scrap	1st Class, fire, truc
20493	German	HW Gon	No brakes		Yes	20	OK Sve	Loaded coal
257280	Belgium	Box	Yes			15	B.O.Shop	Part end & side new w
122128	Italian	Box	Yes			19	OK Sve	Steel - 1/2 load of c
179664	Italian	Box		Yes	No	17	OK Sve	Loaded Elec cable
495119	Italian	HS Gon	No brakes		Yes	19	OK Sve	Loaded Elec cable
16506	German	HW Gon	Yes			20	B.O.Shop	Fire, loaded cable
Scrap - 1 Italian Box								
37415	German	HW Gon	Yes			24.5	OK Sve	
Scrap - 6 box cars, Fire								
3570	German	Box	Yes			15	B.O.Shop	Roof, patch & decking
10396	German	Box	Yes			15	B.O.Shop	Roof, sides & decking
24903	German	Box	Yes				B.O.Shop	Fire, no wood
Scrap - Box, fire. Above track open								

GROSSETO YARDS - A-Yard:

Scrap - 3 coaches at south end of yard - Fire								
19931	German	HW Gon	Yes			20		Lded coal, end boards
25401	German	HW Gon	Yes			20	OK Sve	Loaded coal
95514	German	HW Gon	Yes			20	OK Sve	Loaded coal
401029	Italian	HS Gon		Yes	Yes		OK Sve	
10223	German	HW Gon	Yes			24.5	OK Sve	
12251	German	HW Gon	Yes				B.O.Shop	Shot up bad
99905	Italian	Caboose		Yes		6	OK Sve	
13870	German	Box	Yes			15	OK Sve	Lded empty ammo boxes
10978	German	Box	Yes			15	OK Sve	Lded empty ammo boxes
363900	French	Box	Yes			20	OK Sve	Loaded ammo boxes
20403	German	Box	Yes			15	OK Sve	Loaded ammo boxes

0397

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 19)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
on	No brakes		Yes	15	OK Sve	
	no wood. Air brakes - Shop					
	Yes			38	Scrap	Sill blown, one truck good
					Scrap	Sill blown
on					Scrap	1st Class, fire, trucks OK
gr				20	OK Sve	Loaded coal
on	No brakes		Yes	15	B.O.Shop	Part end & side new wood
	Yes			19	OK Sve	Steel - 1/2 load of coal
	Yes			17	OK Sve	Loaded Elec cable
		Yes	No	19	OK Sve	Loaded Elec cable
			Yes	20	B.O.Shop	Fire, loaded cable
on	No brakes					
on	Yes			24.5	OK Sve	
on	Yes					
re				15	B.O.Shop	Roof, patch & decking
	Yes			15	B.O.Shop	Roof, sides & decking
	Yes				B.O.Shop	Fire, no wood
	Yes					
ove	track open					

d:

outh	end of yard - Fire					
on	Yes			20		Lded coal, end boards burnt
on	Yes			20	OK Sve	Loaded coal
on	Yes			20	OK Sve	Loaded coal
on		Yes	Yes		OK Sve	
on	Yes			24.5	OK Sve	
on	Yes				B.O.Shop	Shot up bad
oose		Yes		6	OK Sve	
	Yes			15	OK Sve	Lded empty ammo boxes
	Yes			15	OK Sve	Lded empty ammo boxes
	Yes			20	OK Sve	Loaded ammo boxes
	Yes			15	OK Sve	Loaded ammo boxes

0398

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 20)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
5946	German	Box	Yes			15	OK Sve	Loaded ammo boxes
8304	German	HW Gon	No brakes		Yes	20	OK Sve	
2oo302	French	HS Gon	Yes			20	OK Sve	
4o4828	Italian	HW Gon	No brakes			18	Scrap	
4o4221	Italian	HW Gon		Yes	No		B.O.Shop	One end & bent draw b
Scrap - 9 Box - Fire								
37o61	Italian	Coach					B.O.Shop	3rd Class-seats, glas
Scrap - 1 coach, 2 Box, 1 coach & 1 Passgr-baggage, fire								
132480	Italian	Box	Yes			19	OK Sve	
1o8726	Italian	Box	No brakes		Yes		B.O.Shop	1/2 car damaged
4o7891	Italian	HW Gon		Yes	Yes		B.O.Shop	1/2 car missing
497389	Italian	HW Gon	No brakes		Yes	19	B.O.Shop	Decking missing, fire
122355	Italian	Box	Yes				B.O.Shop	Roof & part decking -
101o264	Italian	Box	Yes			18	Light Rprs	Patch roof and door
36227	German	HW Gon	Yes			20	OK Sve	
418281	Italian	HW Gon		Yes	No		Light Rprs	Draw bar missing
412o1o	Italian	HW Gon		Yes	No	18	B.O.Shop	Fire, no wood
1127577	Italian	Box	Yes				B.O.Shop	Fire, steel
1o358	German	LW Gon	No brakes		Yes	15	OK Sve	
448526	Italian	HS Gon	No brakes		Yes	15	Light Rprs	Bad journal
158575	Italian	Box	Yes				B.O.Shop	Roof, buffer, no draw

C-Yard:
The following cars are burnt and scrap, no track -- 18o scrap cars burnt, no outlet.

B- Yard:
Scrap - 13 cars in yard scrap, balance in service.

65o319	Italian	LW Gon	No brakes	No	B.O.Shop	Decking, side & end
44o787	Italian	HW Gon	No brakes	Yes	B.O.Shop	Lded coal, needs sid
99532		Caboose			Scrap	Grenade shot interio
DCR62841	Italian	Baggage			Scrap	1/2 of car damaged
DU196loo		Mail			Shop	1/2 damaged

0399

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 20)

pe	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
t	Yes			15	OK Sve	Loaded ammo boxes
Gon	No brakes		Yes	20	OK Sve	
Gon	Yes			20	OK Sve	
Gon	No brakes			16	Scrap	
Gon		Yes	No		B.O.Shop	One end & bent draw bar
ach					B.O.Shop	3rd Class-seats, glass & buffer
ox, 1 coach & 1 Passgr-baggage, fire						
t	Yes			19	OK Sve	
t	No brakes		Yes		B.O.Shop	1/2 car damaged
Gon		Yes	Yes		B.O.Shop	1/2 car missing
Gon	No brakes		Yes	19	B.O.Shop	Decking missing, fire
t	Yes				B.O.Shop	Roof & part decking - steel
t	Yes			18	Light Rprs	Patch roof and door
Gon	Yes			20	OK Sve	
Gon		Yes	No		Light Rprs	Draw bar missing
Gon		Yes	No	18	B.O.Shop	Fire, no wood
t	Yes				B.O.Shop	Fire, steel
Gon	No brakes		Yes	15	OK Sve	
Gon	No brakes		Yes	15	Light Rprs	Bad journal
	Yes				B.O.Shop	Roof, buffer, no draw hook, track blown

re burnt and scrap, no track -- 186 scrap cars burnt, no outlet.

rd scrap, balence in service.

Gon	No brakes	No	B.O.Shop	Decking, side & end
Gon	No brakes	Yes	B.O.Shop	Lded coal, needs siding, ends some decking
oose			Scrap	Grenade shot interior, holes
gage			Scrap	1/2 of car damaged
l			Shop	1/2 damaged

0400

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 21)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
UT1090		Mail					Shop	Damaged interior
69997	German	IS Gon	Yes					Needs 1 pr wheels, j
199 Km from Rome:								
One passenger coach and gondola, HW, on siding - no track to move								
GIUNCARICO - 207 Km from Rome on siding. Move to Grosseto Aug. 24th.								
30957	German	Gon	Yes			24.5	OK Sve	Lded 4 sheets 3" cur
455015	Italian	HW Gon		Yes	Yes		OK Sve	Lded 8" pipe
1343455T	German	Well		Yes	Yes	50	OK Sve	Lded large casting
Scrap - 1 Refr, fire								
35729	German	Box	No brakes	No	Yes		OK Sve	Lded large fire bric
090353	Italian	Well		Yes		19	OK Sve	Lded overhead crane
235872	French	HS Gon	Yes			20	OK Sve	Loaded 1 Beams
02512	German	HW Gon	Yes			20	OK Sve	Loaded 2 large valve
259503	French	HW Gon	No brakes		Yes		OK Sve	Loaded misc
2393	German	HW Gon	Yes			20	OK Sve	Loaded valves
0332135	Coach						Hvy Rprs	3rd Class, Interior
DU190070		Postal					B.O.Shop	
7471430	Italian	HW Gon		Yes	No		Light Rprs	Broken draw bar
950496	Italian	Wtr Tanks		Yes	No	19	B.O.Shop	Shot holes
920258	Italian	Wtr Tanks		Yes	Yes	13	B.O.Shop	Holes
950032	Italian	Wtr Tanks		Yes	No	19	B.O.Shop	Holes
950173	Italian	Wtr Tank	No brakes		No	18	B.O.Shop	Holes
9520217	Italian	Wtr Tank		Yes	No	12	B.O.Shop	Holes
950400	Italian	Wtr Tank	No brakes		No	19	B.O.Shop	Holes
022333	Italian	LW Gon	No brakes		No	13	B.O.Shop	Spring schackle miss
7175100	Italian	Box	No brakes		Yes	14	B.O.Shop	Buffers, one end
GAVORRANO YARDS - 214 Km from Rome.								
208519	French	Box	Yes			20	OK Sve	Lded 2 Elec motors &
415266	Italian	HW Gon		Yes	No		OK Sve	Loaded
5207	German	HW Gon	Yes			20	OK Sve	Loaded

0401

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 21)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
				Shop	Damaged interior
Yes					Needs 1 pr wheels, journal boxes, brass & packing

ondola, HW, on siding - no track to move

Rome on siding. Move to Grosseto Aug. 24th.

Yes			24.5	OK Sve	Lded 4 sheets 3" curved steel
	Yes	Yes		OK Sve	Lded 8" pipe
	Yes	Yes	50	OK Sve	Lded large casting
No brakes	No	Yes		OK Sve	Lded large fire brick
	Yes		19	OK Sve	Lded overhead crane frame
Yes			20	OK Sve	Loaded I Beams
Yes			20	OK Sve	Loaded 2 large valves
No brakes		Yes		OK Sve	Loaded misc
Yes			20	OK Sve	Loaded valves
				Hvy Rprs B.O.Shop	3rd Class, Interior
	Yes	No		Light Rprs	Broken draw bar
nks	Yes	No	19	B.O.Shop	Shot holes
nks	Yes	Yes	13	B.O.Shop	Holes
nks	Yes	No	19	B.O.Shop	Holes
nk No brakes		No	18	B.O.Shop	Holes
nk	Yes	No	12	B.O.Shop	Holes
nk No brakes		No	19	B.O.Shop	Holes
No brakes		No	13	B.O.Shop	Spring schackle missing, 1 end out, buffer
No brakes		Yes	14	B.O.Shop	Buffers, one end

from Rome.

Yes			20	OK Sve	Lded 2 Elec motors & Equipt.
	Yes	No		OK Sve	Loaded
Yes			20	OK Sve	Loaded

04021

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 22)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
25205	German	HW Gon				15	OK Sve	Loaded
61513	German	HW Gon	Yes			20	OK Sve	Loaded
25929	German	HW Gon	Yes			20	OK Sve	Loaded
402057	Italian	HS Gon		Yes	Yes	22	OK Sve	Loaded
48141	German	HW Gon	No brakes		Yes	20	OK Sve	Loaded
60057	German	HW Gon	Yes			20	OK Sve	Loaded
61081	German	Hw Gon	Yes			20	OK Sve	Loaded
8559	German	HW Gon	Yes			20	Light Rprs	Loaded, Hole decking
727677	German	HW Gon	No brakes		Yes		OK Sve	Loaded
9469	German	HW Gon	Yes			24.5	OK Sve	Loaded
20859	German	Hw Gon	No brakes		Yes	20	Light Rprs	Buffer, one end
Scrap - 3 Gondolas blown up & track. Track repairs 3 pieces before next car can be moved.								
30000	German	Hw Gon	Yes			24.5	OK Sve	Loaded
363053	French	Box	Yes			20	OK Sve	Loaded
476503	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded
71502	German	HW Gon	Yes			20	OK Sve	Loaded
16917	German	HW Gon	Yes			20	OK Sve	Loaded
227626	French	HW Gon	Yes			20	OK Sve	Loaded
37557	German	Hw Gon	Yes			20	OK Sve	Loaded
20033	German	HW Gon	Yes			24.5	OK Sve	Loaded
475462	Italian	HW Gon	Yes			18	OK Sve	Loaded
19152	German	HW Gon		Yes	Yes	20	OK Sve	Loaded
22779	German	Hw Gon	No brakes		Yes	20	OK Sve	Loaded
13972	German	Hw Gon	Yes			20	OK Sve	Loaded
60747	German	HW Gon	Yes			24.5	OK Sve	Loaded
80555	German	Hw Gon	Yes			20	B.O.Shop	Side of car, switch
474003	Italian	Hw Gon	Yes			18	OK Sve	Loaded
17080	German	HW Gon	Yes			20	OK Sve	Loaded
3507	German	HW Gon	Yes			20.5	OK Sve	Loaded
96990	German	Hw Gon	No brakes		Yes	20	OK Sve	Loaded
60952	German	Hw Gon	Yes			20	OK Sve	Loaded
62440	German	Hw Gon	Yes			20	OK Sve	Loaded
Above cars loaded with heavy conveyor machinery and equipment. Siding blown needs 3 lengths r								

0403

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 22)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
			15	OK Sve	Loaded
			20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			22	OK Sve	Loaded
	Yes	Yes	20	OK Sve	Loaded
No brakes		Yes	20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			20	Light Rprs	Loaded, Hole decking & side
Yes				OK Sve	Loaded
No brakes		Yes	24.5	OK Sve	Loaded
Yes			20	Light Rprs	Buffer, one end
No brakes		Yes			

p & track. Track repairs 3 pieces before next car can be moved.

			24.5	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			18	OK Sve	Loaded
No brakes		No	20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			24.5	OK Sve	Loaded
Yes			18	OK Sve	Loaded
	Yes	Yes	20	OK Sve	Loaded
No brakes		Yes	20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			24.5	OK Sve	Loaded
Yes			20	B.O.Shop	Side of car, switch blown end of car Small
Yes			18	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			20.5	OK Sve	Loaded
Yes					
No brakes		Yes	20	OK Sve	Loaded
Yes			20	OK Sve	Loaded
Yes			20	OK Sve	Loaded

eavy conveyor machinery and equipment. Siding blown needs 3 lengths rail and switch to move cars.

0404

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 23)-

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
7902664	Italian	Wtr Tank		Yes	No		B.O.Shop	Tank fair, switc
434312	Italian	HW Gon	No brakes		Yes	20	Light Rprs	1 draw bar, swit
710432	German	HW Gon		Yes	Yes	20		Broken drawbar,
FOLLONICA STATION & YARDS, 230 Km from Rome. Yards blown up.								
459669	Italian	HW Gon		Yes	No	18	B.O.Shop	One end burnt
5600	German	HS Gon	No brakes		Yes		OK Sve	
34370	German	HW Gon	Yes				Scrap	Fed blown, loade
91550	German	HW Gon	No brakes		Yes	15	Scrap	Loaded, Fed blow
042577	Italian	HW Gon	No brakes		Yes	18	Scrap	Fed blown, loade
Unable to move above cars account of burnt cars and crooked rails								
Burnt scrap - 29 cars, no out let, take several lengths rail & switch.								
808910		Boiler car					Scrap	At Rdhse, boiler
1000852	Italian	Box	Yes				OK Sve	Located side of
								of track
Scrap - 5 cars at roundhouse, fire.								
98981	Italian	Caboose					B.O.Shop	Needs switch to
19041	German	HS Gon	No brakes		Yes	15	B.O.Shop	Decking & patch,
9704	German	Box					B.O.Shop	No wood, fire- n
Scrap - 5 cars at station, fire.								
The following cars are blocked at end. Need track & switch repair car at station.								
415173	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded stone
416515	Italian	HW Gon	No brakes		No	18	OK Sve	" "
412366	Italian	HW Gon	No brakes			18	OK Sve	No wood, loaded
482964	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded ore
7448779	Italian	HW Gon	No brakes		No	15	OK Sve	Loaded ore
486570	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded ore
7404956	Italian	HW Gon	No brakes		Yes	15	OK Sve	Loaded rock
488218	Italian	HW Gon	Yes			18	Light Rprs	Loaded stone, br
496903	Italian	HS Gon	No brakes		Yes	18	OK Sve	Loaded stone
11039	German	HW Gon	Yes			24.5	OK Sve	Loaded stone
415205	Italian	HW Gon		Yes	No	∞	B.O.Shop	Loaded stone, on

0405

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 23)-

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
rank		Yes	No		B.O.Shop	Tank fair, switch blown
on	No brakes		Yes	20	Light Rprs	1 draw bar, switch blown
on		Yes	Yes	20		Broken drawbar, switch blown
RDS, 230 Km from Rome. Yards blown up.						
on		Yes	No	18	B.O.Shop	One end burnt
on	No brakes		Yes		OK Sve	
on	Yes				Scrap	Fed blown, loaded ore
on	No brakes		Yes	15	Scrap	Loaded, Fed blown
on	No brakes		Yes	18	Scrap	Fed blown, loaded ore
ars account of burnt cars and crooked rails						
no out let, take several lengths rail & switch.						
er car					Scrap	At Rdhse, boiler blown
	Yes				OK Sve	Located side of Rdhse, unable to move acc't of track
dhouse, fire.						
ose					B.O.Shop	Needs switch to move.
on	No brakes		Yes	15	B.O.Shop	Decking & patch, clean up tar
					B.O.Shop	No wood, fire- no switch
ion, fire.						
blocked at end. Need track & switch repair car at station.						
on	No brakes		No	18	OK Sve	Loaded stone
on	No brakes		No	18	OK Sve	" "
on	No brakes			18	OK Sve	No wood, loaded ore.
on	No brakes		Yes	18	OK Sve	Loaded ore
on	No brakes		No	15	OK Sve	Loaded ore
on	No brakes		No	18	OK Sve	Loaded ore
on	No brakes		Yes	15	OK Sve	Loaded rock
on	Yes			18	Light Rprs	Loaded stone, broken spring
on	No brakes		Yes	19	OK Sve	Loaded stone
on	Yes			24.5	OK Sve	Loaded stone
on		Yes	No	OC	B.O.Shop	Loaded stone, one end fire.

0406

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 24)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
6494	German	HW Gon	Yes			15	OK Sve	Loaded ore
468002	Italian	HW Gon		Yes		18	OK Sve	Loaded ore
18070	German	HW Gon	Yes			20	B.O.Shop	Loaded ore, loos
464123	Italian	HW Gon	No brakes		Yes		B.O.Shop	Lded ore, fire o
493550	Italian	ST Gon	No brakes		Yes		Light Rprs	Lded stone, buff length
7400004	Italian	HW Gon		Yes	Yes	15	B.O.Shop	Fire one end sid
7101989	Italian	Box	No brakes		Yes		B.O.Shop	Fire, no wood
3512	German	Box	No brakes		Yes	15	B.O.Shop	Fire, 1 end deck
1133369	Italian	Box	Yes			19	Light Rprs	Fire, part decki
1133983	Italian	Box	Yes			19	B.O.Shop	Steel, fire inte
12783SST	German	Well	Yes				B.O.Shop	Trucks damaged
12703SST	German	Well	Yes				B.O.Shop	Trucks damaged
Tracks blown every length for city block								
69370	German	LS Gon	Yes			15	B.O.Shop	Lded wench, fire
442973	Italian	HW Gon	No brakes		No	18	B.O.Shop	Fire sides & deck
Cars in Elec yard adjacent station								
CAPUALIA - 247 KM from Rome								
DM99353	Italian	Po & Caboose		Yes		4	OK Sve	Needs switch at t
94975	German	HW Gon	Yes			20	OK Sve	
200126	French	HS Gon	Yes			20	OK Sve	
25279	German	HW Gon	Yes			20	OK Sve	
4816	German	HW Gon	Yes			15	OK Sve	
7790	German	HW Gon	Yes			20	OK Sve	
49930	French	HW Gon	Yes			20	OK Sve	
21425	German	HW Gon		Yes	Yes	20	B.O.Shop	1/2 Fire
413044	Italian	HW Gon		Yes	No	18	OK Sve	
093029	Italian	Flat		Yes		40	OK Sve	Trancks
Need two lengths rail & switch to move above cars.								
CM9998	Po & Caboose			Yes	Yes		B.O.Shop	
One box car fire, no wood, air brakes, needs 2 lengths track and switch Shop.								

0407

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 24)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
on	Yes			15	OK Sve	Loaded ore
on		Yes		18	OK Sve	Loaded ore
on	Yes			20	B.O.Shop	Loaded ore, loose wheel blown
on	No brakes		Yes		B.O.Shop	Lded ore, fire one side, end
on	No brakes		Yes		Light Rprs	Lded stone, buffer missing, track blown every length
on		Yes	Yes	15	B.O.Shop	Fire one end side, decking
	No brakes		Yes		B.O.Shop	Fire, no wood
	No brakes		Yes	15	B.O.Shop	Fire, 1 end decking
	Yes			19	Light Rprs	Fire, part decking (steel)
	Yes			19	B.O.Shop	Steel, fire interior
	Yes				B.O.Shop	Trucks damaged
	Yes				B.O.Shop	Trucks damaged
ngth for city block						
on	Yes			15	B.O.Shop	Lded wench, fire decking
on	No brakes		No	18	B.O.Shop	Fire sides & decking, load crane
acent station						
rom Rome						
& Caboose		Yes		4	OK Sve	Needs switch at track
on	Yes			20	OK Sve	
on	Yes			20	OK Sve	
on	Yes			20	OK Sve	
on	Yes			15	OK Sve	
on	Yes			20	OK Sve	
on	Yes			20	OK Sve	
on		Yes	Yes	20	B.O.Shop	1/2 Fire
on		Yes	No	18	OK Sve	
t		Yes		40	OK Sve	Trancks
& switch to move above cars.						
		Yes	Yes		B.O.Shop	
wood, air brakes, needs 2 lengths track and switch						Shop.

0408

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 25)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
CASTAGNETO - 266 Km from Rome								
7400027	Italian	HW Gon		Yes	No		B.O.Shop	Fire, no wood
13253	German	Box	No brakes		Yes		B.O.Shop	Fire, no wood
One Italian flat, fire no wood - One Italian box - Shop Above four cars, track blown at switch								
CIGINA 282 Km from Rome								
920070	Italian	Wtr Tnk		Yes		13	Scrap	Interior blown
7902665	Italian	Wtr Tnk		Yes		13	Scrap	Interior blown
9551000	Italian	Wtr Tnk	Yes			15	Scrap	Interior blown
3457	German	Gondola	No brakes		Yes	15	B.O.Shop	Lded coal, ped bl
VADA STATION 288 Km from Rome - Needs switch put in								
188400	Italian	Box		Yes	No	17	Scrap	Bent frame, rood
6700	German	Flat	Yes			35	Light Rprs	Lded 2 boilers, b
693039	Italian	Flat		Yes	No	40	OK Sve	Loaded boiler, tr
692489	Italian	Flat		Yes	No	40	OK Sve	Lded 3" steel boi
98635	French	Flat	Yes			40	OK Sve	Loaded, trucks
40198	French	Flat	Yes			40	OK Sve	Loaded, trucks
149591	French	Flat	Yes			40	OK Sve	Loaded, trucks
14000	German	Flat	Yes			40	OK Sve	Loaded, trucks
10389	German	Flat		Yes	Yes	40	OK Sve	Loaded boilers, t
15558	German	HW Gon	Yes			24.5	OK Sve	Loaded coal
471497	Italian	HW Gon		Yes	Yes	18	OK Sve	Loaded coal
441210	Italian	HS Gon	Yes			22	OK Sve	Loaded coal
477819	Italian	HW Gon	Yes			18	OK Sve	Loaded coal
475803	Italian	HW Gon	Yes			18	OK Sve	Loaded coal
475241	Italian	HW Gon	Yes			18	OK Sve	Loaded stones
405701	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded stone
400678	Italian	HW Gon		Yes	Yes		OK Sve	Loaded stone
730	German	LS Gon	Yes			24.5	OK Sve	Loaded rail
729	German	LS Gon	Yes			24.5	OK Sve	Loaded rail) - 3
722	German	LS Gon	Yes			24.5	OK Sve	Loaded rail)

0409

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 25)

pe	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
from Rome						
Gon		Yes	No		B.O.Shop	Fire, no wood
x	No brakes		Yes		B.O.Shop	Fire, no wood
re no wood - One Italian box - Shop						
ck blown at switch						
ome						
r Tnk		Yes		13	Scrap	Interior blown
r Tnk		Yes		13	Scrap	Interior blown
r Tnk	Yes			15	Scrap	Interior blown
dola	No brakes		Yes	15	B.O.Shop	Lded coal, ped blown, outlet track blown
from Rome - Needs switch put in						
x		Yes	No	17	Scrap	Bent frame, rood & outside dam.
at	Yes			35	Light Rprs	Lded 2 boilers, buffer
at		Yes	No	40	OK Sve	Loaded boiler, trucks
at		Yes	No	40	OK Sve	Lded 3" steel boiler, trucks
at	Yes			40	OK Sve	Loaded, trucks
at	Yes			40	OK Sve	Loaded, trucks
at	Yes			40	OK Sve	Loaded, trucks
at	Yes			40	OK Sve	Loaded, trucks
at		Yes	Yes	40	OK Sve	Loaded boilers, trucks
Gon	Yes			24.5	OK Sve	Loaded coal
Gon		Yes	Yes	18	OK Sve	Loaded coal
Gon	Yes			22	OK Sve	Loaded coal
Gon	Yes			18	OK Sve	Loaded coal
Gon	Yes			18	OK Sve	Loaded coal
Gon	Yes			18	OK Sve	Loaded stones
Gon	No brakes		Yes	18	OK Sve	Loaded stone
Gon		Yes	Yes		OK Sve	Loaded stone
Gon	Yes			24.5	OK Sve	Loaded rail)
Gon	Yes			24.5	OK Sve	Loaded rail) - 3
Gon	Yes			24.5	OK Sve	Loaded rail)

0 4 [0

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 20)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
New Gons, track blown, 4 lengths rail & switch to move								
1896	German	HW Gon	No brakes		Yes	15	B.O.Shop	1 end part side
92300	German	HW Gon	Yes			20	B.O.Shop	End, side, no track
43282	German	Box	Yes			15	B.O.Shop	Patch roof & side, se
97741	German	HW Gon	Yes			20	OK Sve	Loaded gravel
7058	German	HW Gon	Yes			20	OK Sve	Loaded gravel
158194	Italian	Box	Yes			18	B.O.Shop	End & patch door
62144	German	HW Gon	Yes			20	OK Sve	Loaded gravel
29030	German	HW Gon	Yes			20	OK Sve	Loaded coal
88854	French	HW Gon	Yes			20	OK Sve	Loaded gravel
2949	German	Hw Gon	Yes			15	OK Sve	Load Pill box
42004	German	LW Gon	Yes			19	OK Sve	Loaded gravel
495531	Italian	HS Gon	No brakes		Yes	20	OK Sve	Loaded coal
2190	German	HW Gon	Yes				OK Sve	Loaded coal
83000	German	HW Gon	Yes			18	OK Sve	Loaded coal
488079	Italian	HW Gon	Yes				Scrap	Frame bent
7470025	Italian	Wd Gon		Yes	Yes	18	OK Sve	Loaded gravel
464214	Italian	HW Gon		Yes	Yes	18	OK Sve	Loaded gravel
475050	Italian	HW Gon			No	18	OK Sve	Loaded gravel
471700	Italian	HW Gon	No brakes		Yes	18	OK Sve	Loaded gravel
443321	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded gravel
480752	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded gravel
415113	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded gravel
465832	Italian	HW Gon	No brakes				OK Sve	Lded empty cable sp
Scrap - 1 Gon, blown up					No	20	Light Rprs	Door repair & patch
485769	Italian	HS Gon	No brakes			18	OK Sve	Empty cable spools
245740	French	Box	Yes		No	15	OK Sve	" " "
478792	Italian	HW Gon	No brakes		No	19	OK Sve	" " "
7448300	Italian	HW Gon	No brakes		Yes			
490347	Italian	HS Gon	No brakes			10	B.O.Shop	Top sides & end pat
Scrap - 4 Gons, fire & bombing								
98108	French	Box	Yes					

0411

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 26)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
4 lengths rail & switch to move					
on No brakes		Yes	15	B.O.Shop	1 end part side
on Yes			20	B.O.Shop	End, side, no track
Yes			15	B.O.Shop	Patch roof & side, set on trk 1 end
on Yes			20	OK Sve	Loaded gravel
on Yes			20	OK Sve	Loaded gravel
Yes			18	B.O.Shop	End & patch door
on Yes			20	OK Sve	Loaded gravel
on Yes			20	OK Sve	Loaded coal
on Yes			20	OK Sve	Loaded gravel
on Yes			20	OK Sve	Loaded gravel
on Yes			15	OK Sve	Load Pill box
on No brakes		Yes	19	OK Sve	Loaded gravel
on Yes			20	OK Sve	Loaded coal
on Yes				OK Sve	Loaded coal
on Yes			18	OK Sve	Loaded coal
on				Scrap	Frame bent
on	Yes	Yes	18	OK Sve	Loaded gravel
on	Yes	Yes	18	OK Sve	Loaded gravel
on No brakes		No	18	OK Sve	Loaded gravel
on No brakes		Yes	18	OK Sve	Loaded gravel
on No brakes		No	18	OK Sve	Loaded gravel
on No brakes		No	18	OK Sve	Loaded gravel
on No brakes		No	18	OK Sve	Loaded gravel
up					
on No brakes		No		OK Sve	Lded empty cable spools
Yes			20	Light Rprs	Door repair & patch
on No brakes		No	18	OK Sve	Empty cable spools
on No brakes		No	15	OK Sve	" " "
on No brakes		Yes	19	OK Sve	" " "
& bombing					
Yes			10	B.O.Shop	Top sides & end patch

0412

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 27)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
483534	Italian	HW Gon	No brakes		No	18	OK Sve	Loaded cable spools
19727	German	Box	Yes			15	Light Rprs	Roof patch & side
30786	German	Box	Yes			15	OK Sve	
29590	German	Box	Yes			15	Light Rprs	Door & side patch
1023471	Italian	Box	Yes			18	Light Rprs	Sides patch
Scrap - 1 Box, blown								
048113	Italian	LS Gon	No brakes		Yes	20	OK Sve	Loaded gravel
Scrap - 2 Gons, off track, blown								
493795	Italian	HS Gon	No brakes		Yes	19	B.O.Shop	Set on track, buffe
15728	German	HW Gon	Yes			20	OK Sve	
487140	Italian	Hw Gon	No brakes		No	18	OK Sve	
7404010	Italian	HW Gon		Yes	No	20	OK Sve	Brake shoes, turned
405153	Italian	HW Gon	No brakes		Yes	18	OK Sve	
455005	Italian	HW Gon		Yes	Yes	19	OK Sve	
458520	Italian	HW Gon	No brakes		No	18	OK Sve	
470803	Italian	HW Gon	Yes			18	OK Sve	
Scrap - 2 Gons and box, bombed.								
021100	Italian	LW Gon	No brakes		No	16	OK Sve	
057908	Italian	LW Gon	No brakes		No	19	OK Sve	
120091	French	LW Gon	Yes			20	OK Sve	Lded gravel, Hander
70725	Belgium	LW Gon	No brakes		Yes		OK Sve	Loaded stone
040150	Italian	LS Gon	No brakes		Yes	20	OK Sve	Loaded stone
19594	French	LW Gon	Yes			20	OK Sve	Loaded stone
82994	French	LW Gon	Yes			20	OK Sve	Loaded stone
3114	German	LW Gon	No brakes		Yes	10	OK Sve	Loaded stone
050744	Italian	LW Gon	No brakes		Yes	19	OK Sve	Loaded stone
020198	Italian	LW Gon	No brakes		No	13	OK Sve	Loaded stone
021584	Italian	LW Gon	No brakes		No	13	OK Sve	Loaded stone
110299	French	LW Gon	Yes			30	OK Sve	Loaded stone, truc
7070134	Italian	LW Gon	No brakes		No	15	OK Sve	
044302	Italian	LS Gon	Yes			20	OK Sve	
048399	Italian	LS Gon	No brakes		Yes	20	OK Sve	

0413

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 27)

	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
n	No brakes		No	18	OK Sve	Loaded cable spools
	Yes			15	Light Rprs	Roof patch & side
	Yes			15	OK Sve	
	Yes			15	Light Rprs	Door & side patch
	Yes			18	Light Rprs	Sides patch
n	No brakes		Yes	20	OK Sve	Loaded gravel
ck, blown						
n	No brakes		Yes	19	B.O.Shop	Set on track, buffer & deck ptch
n	Yes			20	OK Sve	
n	No brakes		No	18	OK Sve	
n		Yes	No	20	OK Sve	Brake shoes, turned over
n	No brakes		Yes	18	OK Sve	
n		Yes	Yes	19	OK Sve	
n	No brakes		No	18	OK Sve	
n	Yes			18	OK Sve	
bombed.						
n	No brakes		No	16	OK Sve	
n	No brakes		No	19	OK Sve	
n	Yes			20	OK Sve	Lded gravel, Handegernade on top
n	No brakes		Yes		OK Sve	Loaded stone
n	No brakes		Yes	20	OK Sve	Loaded stone
n	Yes			20	OK Sve	Loaded stone
n	Yes			20	OK Sve	Loaded stone
n	No brakes		Yes	10	OK Sve	Loaded stone
n	No brakes		Yes	19	OK Sve	Loaded stone
n	No brakes		No	13	OK Sve	Loaded stone
n	No brakes		No	13	OK Sve	Loaded stone
n	Yes			30	OK Sve	Loaded stone, trucks
n	No brakes		No	15	OK Sve	
n	Yes			20	OK Sve	
n	No brakes		Yes	20	OK Sve	

0414

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 28)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
37770	German	LW Gon	No brakes		Yes	12.5	OK Sve	
85596	French	LW Gon	No brakes		Yes	10	B.O.Shop	Fed damaged
752912	Italian	LW Gon	No brakes		No	18	OK Sve	
752920	Italian	LW Gon	No brakes		No	18	OK Sve	
055033	Italian	LW Gon		Yes	Yes	19	OK Sve	
054929	Italian	LW Gon	No brakes		No	19	OK Sve	
055373	Italian	LW Gon	No brakes		No	19	OK Sve	
051304	Italian	LW Gon	No brakes		No	19	OK Sve	Loaded gravel, set 1
SOARLINO STATION 222 Km from Rome.								
497780	Italian	HS Gon	No brakes		Yes	19	OK Sve	Loaded ore
70359	German	HW Gon	Yes			20	B.O.Shop	Lded ore, 2 ends & p
127864	French	HS Gon	Yes			20	OK Sve	Loaded ore
7470080	Italian	HW Gon		Yes	No	21	B.O.Shop	Loaded ore, 1/2 car,
CIVITAVECCHIA - 80 Km from Rome								
10078	Italian	Coach	Yes				B.O.Shop	3rd class, has wood
90591		Coach	Yes				B.O.Shop	2nd class, int & gla
7203300	Italian	Box	No brakes		Yes		B.O.Shop	Needs roof, sides, e
70322	French	Box	Yes				B.O.Shop	Needs 2 sides & 1 en lengths rail
167275	Italian	Box		Yes			Scrap	Bombed 1 end
192791	Italian	St Box	Yes			17	B.O.Shop	Bad roof
315045	Italian	Rfr	Yes			15	OK Sve	
173024	Italian	Box		Yes	No		B.O.Shop	Doors, roof & sides
Scrap - 145056 Italian Box, bent frame								
118976	Italian	Box	Yes			19	B.O.Shop	Car off trk, 20', fa
112956	Italian	Box	No brakes		No		B.O.Shop	Patch roof, 20' off
133888	Italian	Box	Yes			18	B.O.Shop	Repair roof
167034	Italian	Box		Yes		17	B.O.Shop	Roof & patch deck

0415

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 28)

Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
No brakes		Yes	12.5	OK Sve	
No brakes		Yes	10	B.O.Shop	Fed damaged
No brakes		No	18	OK Sve	
No brakes		No	18	OK Sve	
	Yes	Yes	19	OK Sve	
No brakes		No	19	OK Sve	
No brakes		No	19	OK Sve	
No brakes		No	19	OK Sve	Loaded gravel, set 1 end on track
from Rome.					
n No brakes		Yes	19	OK Sve	Loaded ore
n Yes			20	B.O.Shop	Lded ore, 2 ends & part decking, fire
n Yes			20	OK Sve	Loaded ore
n	Yes	No	21	B.O.Shop	Loaded ore, 1/2 car, fire
rom Rome					
Yes				B.O.Shop	3rd class, has wood seats
Yes				B.O.Shop	2nd class, int & glass, BO
No brakes		Yes		B.O.Shop	Needs roof, sides, end
Yes				B.O.Shop	Needs 2 sides & 1 end & door, needs switch & 2 lengths rail
	Yes			Scrap	Bombed 1 end
x Yes			17	B.O.Shop	Bad roof
Yes			15	OK Sve	
	Yes	No		B.O.Shop	Doors, roof & sides needs switch
n Box, bent frame					
Yes			19	B.O.Shop	Car off trk, 20', fair steel
No brakes		No		B.O.Shop	Patch roof, 20' off track
Yes			18	B.O.Shop	Repair roof
	Yes		17	B.O.Shop	Roof & patch deck

0 4 1 6

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 29)

Car No.	Country	Type	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
179033	Italian	Box		Yes	No	17	B.O.Shop	Patch roof
82395	German	Box	Yes			15	B.O.Shop	Repair roof, door
22988	German	Box	Yes			15	B.O.Shop	Roof Repair, end
B320262	Coach-Italian						B.O.Shop	2nd class, passgr
03-32522	Italian	Coach					B.O.Shop	3rd class, passgr
80011	Italian	Baggage					B.O.Shop	Patch roof & int.

Reconnaissance made 8/23 thru 8/26/44

Typing completed 9/1/44

/mb

A.C.2

0417

Declassified E.O. 12356 Section 3.3/NND No. 785021

CAR RECONNAISSANCE - LINE 50 (Page 29)

e	Air Brks	Hand Brks	Air Line	Tons	Condition	Remarks
		Yes	No	17	B.O.Shop	Patch roof
	Yes			15	B.O.Shop	Repair roof, doors
	Yes			15	B.O.Shop	Roof Repair, end fire
n					B.O.Shop	2nd class, passgr
ch					B.O.Shop	3rd class, passgr
gage					B.O.Shop	Patch roof & Int.

/23 thru 8/26/44

/44

A 74

0418